

**(b) Affected ADs**

This AD replaces AD 2016–13–06, Amendment 39–18570 (81 FR 41432, June 27, 2016) (“AD 2016–13–06”).

**(c) Applicability**

This AD applies to Saab AB, Saab Aeronautics (formerly known as Saab AB, Saab Aerosystems) airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2), of this AD.

(1) Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes, serial numbers 004 through 138 inclusive, if Saab modification 1462 has been embodied in production, or Saab Service Bulletin 340–55–008 has been embodied in service, except those that have also embodied Saab modification 1793 in production, or Saab Service Bulletin 340–55–010 in service; and serial numbers 139 through 159 inclusive.

(2) Saab AB, Saab Aeronautics Model SAAB 340B airplanes, serial numbers 160 through 459 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 30, Ice and rain protection.

**(e) Reason**

This AD was prompted by reports of ruptured horizontal stabilizer de-icing boots. We are issuing this AD to detect and correct ruptured horizontal stabilizer de-icing boots, which could lead to complete loss of the de-icing function within its associated zone and severe vibrations, possibly resulting in reduced control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Revision of the Airplane Flight Manual (AFM), With No Changes**

This paragraph restates the requirements of paragraph (g) of AD 2016–13–06, with no changes. Within 30 days after August 1, 2016 (the effective date of AD 2016–13–06), revise the “Abnormal Procedures” section of the applicable Saab 340 AFM to incorporate the revision specified in paragraphs (g)(1) through (g)(3) of this AD.

(1) For Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes, revise AFM 340A 001 by incorporating Revision 57, dated March 27, 2015.

(2) For Saab AB, Saab Aeronautics Model SAAB 340B airplanes, revise AFM 340B 001 by incorporating Revision 35, dated March 27, 2015.

(3) For Saab AB, Saab Aeronautics Model SAAB 340B airplanes with extended wing tips, revise AFM 340B 010 by incorporating Revision 28, dated March 27, 2015.

**(h) Retained Inspection/Replacement, With No Changes**

This paragraph restates the requirements of paragraph (h) of AD 2016–13–06, with no changes. Within 400 flight hours or 6 months, whichever occurs first after August 1, 2016 (the effective date of AD 2016–13–06), do a detailed inspection for damage of the horizontal stabilizer de-icing boots, and existing repairs of horizontal stabilizer de-

icing boots, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–30–094, dated March 27, 2015. Repeat the inspection thereafter at intervals not to exceed 400 flight hours. If, during any inspection required by this paragraph, any damage or existing repair outside the limits specified in Saab Service Bulletin 340–30–094, dated March 27, 2015, is found, before further flight, repair or replace the horizontal stabilizer de-icing boots, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–30–094, dated March 27, 2015. Repair or replacement on an airplane of the horizontal stabilizer de-icing boots, as required by this paragraph, does not constitute terminating action for the repetitive inspections required by this paragraph for that airplane.

**(i) New Requirement of This AD: Modification**

Within 18 months after the effective date of this AD, modify the airplane by replacing the single stitched de-icing boots installed on the left-hand (LH) and right-hand (RH) horizontal stabilizers with double stitched de-icing boots and re-identify the LH and RH horizontal stabilizer leading edge, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–30–095, dated April 3, 2017.

**(j) Terminating Action**

Modification of the airplane as required by paragraph (i) of this AD, constitutes terminating action for the repetitive inspections required by paragraph (h) of this AD, for that airplane.

**(k) Other FAA AD Provisions**

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2017–0144, dated August 9, 2017, for related

information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0271.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206–231–3220.

(3) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE–581 88, Linköping, Sweden; telephone: +46 13 18 5591; fax: +46 13 18 4874; email: [saab340techsupport@saabgroup.com](mailto:saab340techsupport@saabgroup.com); internet: <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on March 30, 2018.

**Chris Spangenberg,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–07636 Filed 4–16–18; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2018–0142; Product Identifier 2018–NE–04–AD]**

**RIN 2120–AA64**

**Airworthiness Directives; General Electric Company CF34–8E Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all General Electric Company (GE) CF34–8E turbofan engines. This proposed AD was prompted by a report from GE regarding a quality escape of nonconforming thrust reverser fire seals. This proposed AD would require a one-time inspection of the gap between the core cowl seal and the pylon seal of the thrust reverser for correct gap width, and replacement of the seals, if needed. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by June 1, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; telephone 513-552-3272; email [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com). You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0142; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** David Bethka, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-

238-7129; fax: 781-238-7199; email: [david.bethka@faa.gov](mailto:david.bethka@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2018-0142; Product Identifier 2018-NE-04-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

**Discussion**

We received a report from the manufacturer about a fire seal gap quality escape on GE CF34-8E turbofan engines. Some thrust reverser fire seals, installed on thrust reverser part numbers (P/Ns) 15G0002-013, 15G0002-014, 15G0003-013, and 15G0003-014, were shipped from a supplier with nonconforming seal gaps.

An analysis by the manufacturer has shown that a gap between the 12 o'clock core cowl seal and pylon seal that is greater than the 1 mm design

requirement could result in fire outside the fire zone. This unsafe condition, if not addressed, could result in an uncontrolled fire, damage to the engine, and damage to the airplane.

**Related Service Information**

We reviewed GE CF34-8E Service Bulletin (SB) 78-0066 R00, dated December 11, 2017. The SB describes procedures for measuring the width of the RTV filled gap between the thrust reverser fire seals at the 12 o'clock core cowl seal and pylon seal installed on thrust reverser P/Ns 15G0002-013, 15G0002-014, 15G0003-013, and 15G0003-014, and replacing with parts eligible for installation, if needed.

**FAA's Determination**

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require a one-time inspection of the gap between the core cowl seal and the pylon seal of the thrust reverser for correct gap width, and replacement of the thrust reverser fire seals, if needed.

**Costs of Compliance**

We estimate that this proposed AD affects 936 engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection .....	0.25 work-hours × \$85 per hour = \$21.25 .....	\$0	\$21.25	\$19,890

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspection. We have no way of

determining the number of aircraft that might need these replacements:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Remove and replace thrust reverser fire seals .....	2.75 work-hours × \$85 per hour = \$233.75 .....	\$3,228	\$3,461.75

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**General Electric Company:** Docket No. FAA–2018–0142; Product Identifier 2018–NE–04–AD.

#### (a) Comments Due Date

We must receive comments by June 1, 2018.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all General Electric Company (GE) CF34–8E turbofan engines.

#### (d) Subject

Joint Aircraft System Component (JASC) Code 7830, Thrust Reverser.

#### (e) Unsafe Condition

This AD was prompted by a report from GE regarding a quality escape of nonconforming thrust reverser fire seal gaps. We are issuing this AD to inspect for nonconforming thrust reverser fire seal gaps that could result in a fire outside the fire zone. The unsafe condition, if not addressed, could result in an uncontrolled fire, damage to the engine, and damage to the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

(1) For all CF34–8E turbofan engines, before the engine accumulates 8,000 flight hours after the effective date of this AD, perform the following one-time inspection, and, if needed, replace the core cowl seal and pylon seal.

(i) Measure the width of the RTV filled gap between thrust reverser fire seals at the junction between 12 o'clock core cowl seal and pylon seal, at the following half thrust reverser locations: engine 1 left hand (LH) half thrust reverser, part number (P/N) 15G0002–013; engine 2 LH half thrust reverser, P/N 15G0002–014; engine 1 right hand (RH) half thrust reverser, P/N 15G0003–013; and engine 2 RH half thrust reverser P/N 15G0003–014.

(ii) If the gap width between the 12 o'clock core cowl seal and the pylon seal is greater than 1 mm, replace both seals with parts eligible for installation to form a new gap of 1 mm or less, prior to return to service.

(2) You may refer to GE CF34–8E Service Bulletin 78–0066 R00, dated December 11, 2017 for guidance on inspecting and replacing the thrust reverser fire seals.

#### (h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/Certificate Holding District Office.

#### (i) Related Information

(1) For more information about this AD, contact David Bethka, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7129; fax: 781–238–7199; email: [david.bethka@faa.gov](mailto:david.bethka@faa.gov).

(2) For service information identified in this AD, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; telephone 513–552–3272; email [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com). You may view this referenced service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781–238–7759.

Issued in Burlington, Massachusetts, on April 9, 2018.

**Robert J. Ganley,**

*Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.*

[FR Doc. 2018–07819 Filed 4–16–18; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2018–0276; Product Identifier 2017–NM–079–AD]

RIN 2120–AA64

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 747–100, –100B, –100B SUD, –200B, –200C, –200F, –300, –400, –400D, 747SP, and 747SR, and 747–8 series airplanes. This proposed AD was prompted by reports indicating that additional areas of Boeing Material Specification (BMS) 8–39 flexible urethane foam were found during an inspection required by a related AD. This proposed AD would require inspecting for BMS 8–39 flexible urethane foam insulation in the floor panel assemblies and the power drive unit (PDU) cover assemblies; doing applicable on-condition actions; modifying certain dripshields; and replacing BMS 8–39 foam strips on certain dripshields with BMS 8–371 foam strips. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by June 1, 2018.