

now increased to \$7.5 million due to adjustments for inflation, the 500-employee manufacturing size standard set at the inception of SBA has remained the same.

- Should SBA consider lowering its size standards? SBA receives periodic comments from the public that its standards are too high in certain industries or for certain types of Federal contracting opportunities. The comments generally concern the competitive edge that large small businesses have over the “truly small businesses” (a phrase heard frequently from commentators). This has always been a challenging issue, one that SBA has had to deal with over the years. SBA’s size standards appear large to the smallest of small businesses while larger small businesses often request even higher size standards. In the recently completed comprehensive size standards review, in view of weak economic conditions and various measures Federal Government implemented to stimulate employment and economic growth, SBA decided to not lower size standards even if the data supported lowering them. This issue is partly tied to Federal procurement trends of contracts getting larger over time, and they are often out of the reach of the “truly small businesses.”

- Should SBA size standards be specific, *i.e.*, to the precise dollar calculated based on the data and information it evaluates? Or should SBA recognize that there are other factors that go into establishing size standards, such as the fact that the data SBA evaluates is not static, industries change over the years, and even within a given year.

- Should SBA round off its calculated size standards for the various industries? If so, should SBA always round up? To what level? If not, what about those industries that do not get increases in size standards when others are? What should be the cut-off point for rounding either one way or the other?

- SBA’s new percentile approach to evaluating industry characteristics, which will replace the “anchor” size standards approach the Agency used in the past.

- Alternative methodologies for determining small business size standards.

- How SBA’s size standards impact competition in general and within a specific industry?

- Alternative or additional factors that SBA should consider.

- Whether SBA’s approach to small business size standards makes sense in the current economic environment.

- Whether there are gaps in SBA’s methodology because of the lack of comprehensive industry and Federal market data.

- Alternative or other factors or data sources SBA should consider when establishing, reviewing, or modifying size standards.

SBA encourages the public to review and comment on the Revised Methodology, which is available at <https://www.sba.gov/size-standards-methodology> as well as at <https://www.regulations.gov>. SBA will thoroughly evaluate and consider all comments and suggestions when finalizing the Revising Methodology, which the Agency will apply in the forthcoming, second five-five year review of size standards as required by the Jobs Act.

Dated: April 13, 2018.

**Linda E. McMahon,**  
Administrator.

[FR Doc. 2018-08418 Filed 4-26-18; 8:45 am]

**BILLING CODE 8025-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0301; Product Identifier 2017-NM-112-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Airbus Model A300 series airplanes, Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes), and Model A310 series airplanes. This proposed AD was prompted by a report of yellow hydraulic system failure, including both braking accumulators, due to failure of the parking brake operated valve (PBOV). This proposed AD would require replacement of a certain PBOV with a different PBOV. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by June 11, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0301; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0301; Product Identifier 2017-NM-112-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

**Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2017–0153, dated August 17, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A300 series airplanes, Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes), and Model A310 series airplanes. The MCAI states:

An occurrence was reported where yellow hydraulic system, including both braking accumulators, was lost. This was confirmed by ECAM [electronic centralized aircraft monitor] warnings and single chimes during taxiing. Normal braking on green hydraulic circuit was used until aeroplane stopped at parking position. A few seconds later, the aeroplane slowly accelerated, until colliding with a wall and a bus. The crew reported that

the parking brake was selected and full braking pedals were applied, but with no effect since normal braking was inhibited after Parking Brake was set to ON. Investigation results identified that this occurrence was due to failure of the parking brake operated valve (PBOV), Part Number (P/N) A25315–1.

This condition [parking brake failure], if not corrected, could lead to further incidents, possibly resulting in damage to the aeroplane and injury to persons on the ground.

Prompted by this event, Airbus issued Service Bulletin (SB) A300–32–0467, SB A310–32–2151, SB A300–32–6117 and SB A300–32–9023, as applicable, to provide instructions for in-service installation of the PBOV P/N A25315020–2 introduced by Airbus Modification 13201 for A300/A310/A300–600 and Airbus Modification 19601 for A300–600ST.

For the reason described above, this [EASA] AD requires replacement of the PBOV P/N A25315–1 by PBOV P/N A25315020–2.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0301.

**Related Service Information Under 14 CFR Part 51**

Airbus has issued Service Bulletin A300–32–0467, dated July 4, 2017; Service Bulletin A300–32–6117, dated

July 4, 2017; and Service Bulletin A310–32–2151, dated July 4, 2017. This service information describes procedures for replacing the PBOV. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**FAA’s Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

**Costs of Compliance**

We estimate that this proposed AD affects 147 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
PBOV replacement .....	6 work-hours × \$85 per hour = \$510 .....	\$4,764	\$5,274	\$775,278

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Airbus:** Docket No. FAA–2018–0301; Product Identifier 2017–NM–112–AD.

#### (a) Comments Due Date

We must receive comments by June 11, 2018.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1) through (c)(6) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes.

(2) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.

(3) Model A300 B4–605R and B4–622R airplanes.

(4) Model A300 F4–605R and F4–622R airplanes.

(5) Model A300 C4–605R Variant F airplanes.

(6) Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

#### (e) Reason

This AD was prompted by a report of yellow hydraulic system failure, including both braking accumulators, due to failure of the parking brake operated valve (PBOV). We are issuing this AD to prevent failure of the PBOV, which could result in no braking capability during ground operations, possibly leading to damage to the airplane and injury to people on the ground.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) PBOV Replacement

Within 60 months after the effective date of this AD, replace the PBOV having part number (P/N) A25315–1 with a PBOV having P/N A25315020–2, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300–32–0467, dated July 4, 2017; Airbus Service Bulletin A300–32–6117, dated July 4, 2017; or Airbus Service Bulletin A310–32–2151, dated July 4, 2017; as applicable.

#### (h) Parts Prohibition

(1) After modification of an airplane as required by paragraph (g) of this AD, do not

install any PBOV having P/N A25315–1 on that airplane.

(2) For an airplane that, as of the effective date of this AD, has a PBOV having P/N A25315020–2 installed: As of the effective date of this AD do not install any PBOV having P/N A25315–1 on that airplane.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017–0153, dated August 17, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0301.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice

Bellonte, 31707 Bagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on April 11, 2018.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–08653 Filed 4–26–18; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2018–0300; Product Identifier 2017–NM–134–AD]

RIN 2120–AA64

#### Airworthiness Directives; Airbus Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A318, A319, and A320 series airplanes; and Model A321–111, –112, –131, –211, –212, –213, –231, –232, –251N, –253N, and –271N airplanes. This proposed AD was prompted by a revision of an airworthiness limitations document that specifies more restrictive maintenance requirements and airworthiness limitations. This proposed AD would require revising the maintenance or inspection program, as applicable, to incorporate revised fuel airworthiness limitations. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by June 11, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.