

Commission titled “Staff Activities Related to the Evaluation of Materials Cyber Security Vulnerabilities” (ADAMS Accession No. ML15201A509). This memorandum informed the Commission of the ongoing evaluation to determine the cyber security risk to each of the four sets of digital assets for risk-significant radioactive materials licensees, and described the two-pronged approach focused on information gathering and consequence analysis that was used.

As part of the information gathering effort, the NRC staff distributed a voluntary survey, “Questionnaire on Cyber Security at Byproduct Materials Licensees” (ADAMS Accession No. ML15246A306) on April 29, 2016, to all NRC and Agreement State licensees that possessed Category 1 and 2 quantities of radioactive materials. The purpose of the questionnaire was to identify what key digital assets existed at each licensee type, how they were connected to internal/external networks and the internet, and what technical and procedural security measures were in place for protection and operation of these systems and devices. The NRC staff also conducted outreach to stakeholders to encourage completion of the questionnaire, and site visits to manufacturers and panoramic irradiator licensees.

The consequence analysis was conducted in parallel with the information gathering effort, and evaluated the potential for onsite and offsite consequences that could occur if the availability, integrity, or confidentiality of data or systems associated with nuclear materials were compromised by a cyber attack.

Given the regulatory responsibilities of the U.S. Food and Drug Administration (FDA), the NRC limited its evaluation of the software systems used in medical applications to the systems related to the radiation safety and physical protection authority of the NRC. The NRC has a memorandum of understanding with the FDA that clarifies the respective roles of each agency in regulating the safe use of radiopharmaceuticals and sealed sources, and other medical devices containing radioactive material (ADAMS Accession No. ML023520399). Additional information on the FDA’s activities, role, and expectations for the continued cyber security of medical devices can be found at <https://www.fda.gov/downloads/medicaldevices/digitalhealth/ucm544684.pdf>.

On February 28, 2017, the NRC staff provided an update to the Commission on the status of agency activities

pertaining to cyber security at licensee facilities in a Commission paper, SECY-17-0034, “Update to the U.S. Nuclear Regulatory Commission Cyber Security Roadmap” (ADAMS Accession No. ML16354A258). The update noted the NRC staff’s further consideration of cyber security requirements for radioactive materials licensees since the January 2016 memorandum.

Additionally, the paper stated that the working group planned to complete its evaluation of the questionnaire responses, consequence analysis, and any follow-up communication with stakeholders and develop recommendations for a path forward.

Subsequently, the NRC completed its evaluation of cyber security requirements for byproduct materials licensees in October 2017.

The NRC staff concluded that byproduct materials licensees that possess risk-significant quantities of radioactive material do not rely solely on digital assets to ensure safety or physical protection. Rather, these licensees generally use a combination of measures, such as doors, locks, barriers, human resources, and operational processes, to ensure security, which reflects a defense-in-depth approach to physical protection and safety. As a result, the staff concluded that a compromise of any of the digital assets identified in the January 6, 2016, Commission memorandum would not result in a direct dispersal of risk-significant quantities of radioactive material, or exposure of individuals to radiation, without a concurrent and targeted breach of the physical protection measures in force for these licensees.

Therefore, the NRC staff determined that the current cyber security threat and potential consequences do not warrant regulatory action. However, the NRC staff determined that it would be prudent to issue an Information Notice (IN) to communicate effective practices for cyber security to byproduct materials licensees possessing risk-significant quantities of radioactive material. The IN will provide licensees with a better understanding of contemporary cyber security issues and strategies to protect digital assets (e.g., computers, digital alarm systems), including those used to facilitate compliance with physical security requirements, such as those in 10 CFR part 37. The IN, which will reference existing cyber security guidance developed by the NRC’s Office of Nuclear Reactor Regulation and other Federal agencies, will be issued later in 2018.

II. Conclusion

For the reasons discussed in this document, the NRC is discontinuing rulemaking activity to develop cyber security requirements for byproduct materials licensees possessing risk-significant quantities of radioactive materials. In the next edition of the Unified Agenda, the NRC will update the entry for this rulemaking activity and refer to this document to indicate that the rulemaking has been discontinued. This rulemaking activity will appear in the “Completed Actions” section of the next edition of the Unified Agenda, but will not appear in future editions. If the NRC decides to pursue similar or related rulemaking activities in the future, it will inform the public through a new rulemaking entry in the Unified Agenda.

Dated at Rockville, Maryland, this 10th day of May, 2018.

For the Nuclear Regulatory Commission.

Victor McCree,

Executive Director for Operations.

[FR Doc. 2018-10358 Filed 5-14-18; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0410; Product Identifier 2018-NM-030-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A350-941 airplanes. This proposed AD was prompted by an inspection on the production line that revealed evidence of paint peeling on the forward and aft cargo frame forks around the hook bolt hole. This proposed AD would require a detailed visual inspection for any deficiency of the frame forks around the hook bolt hole on certain forward and aft cargo doors and applicable corrective actions. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by June 29, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: 202–493–2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email continued-airworthiness.a350@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0410; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800–647–5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3218.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA–2018–0410; Product Identifier 2018–NM–030–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018–0031, dated January 31, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A350–941 airplanes. The MCAI states:

Following an inspection on the production line, paint peeling was found on forward and aft cargo door frame forks around the hook bolt hole. Subsequent investigations determined this had been caused by incorrect masking method during application of primer, top coat and Tartaric Sulfuric Anodizing (TSA) layer. As the cargo doors are located in an area with high corrosion sensitivity, where a surface protection with primer, top coat and TSA is specified, in case of paint peeling off, galvanic corrosion could develop.

This condition, if not detected and corrected, could lead to cargo door failure, possibly resulting in decompression of the aeroplane and injury to occupants.

To address this potential unsafe condition, Airbus identified the affected parts and issued the SB [Airbus Service Bulletin (SB)

A350–52–P011, dated May 12, 2017] to provide inspection instructions.

For the reasons described above, this [EASA] AD requires a one-time detailed [visual] inspection (DET) of the affected parts [for discrepancies] and, depending on findings, accomplishment of applicable corrective action(s) [i.e., restoration of the anti-corrosion protection of frame forks of affected parts].

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0410.

Related Service Information Under 1 CFR Part 51

Airbus has issued Airbus Service Bulletin A350–52–P011, dated May 12, 2017. This service information describes procedures for a one-time detailed visual inspection of the frame forks around the hook bolt hole on the forward and aft cargo door, and applicable corrective actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 9 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	Up to 9 work-hours × \$85 per hour = \$765.	\$0	Up to \$765	Up to \$6,885.

We estimate the following costs to do any necessary on-condition actions that

would be required based on the results of the proposed inspection. We have no

way of determining the number of aircraft that might need this action:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Restoration	9 work-hours × \$85 per hour = \$765	\$50	\$815

According to the manufacturer, all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2018–0410; Product Identifier 2018–NM–030–AD.

(a) Comments Due Date

We must receive comments by June 29, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A350–941 airplanes certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by an inspection on the production line that revealed evidence of paint peeling on the forward and aft cargo frame forks around the hook bolt hole. We are issuing this AD to address paint peeling on the forward and aft cargo doors that could develop into galvanic corrosion, which could lead to cargo door failure and possibly result in decompression of the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

(1) For the purpose of this AD, the affected parts are forward cargo doors, part number (P/N) WG102AGAAAAF and P/N WG102AKAAAAF, serial number (S/N) UH10007 through UH10022 inclusive, except S/N UH10009; and aft cargo doors P/N WH102AHAAAAAC and P/N WH102ALAAAAAC, S/N UH10008 through UH10022 inclusive.

(2) For the purpose of this AD, a serviceable forward cargo door or a serviceable aft cargo door is a part that is not identified as an affected part, or is a part identified as an affected part on which a detailed visual inspection specified in Airbus Service Bulletin A350–52–P011, dated May 12, 2017, has been done and there were no findings.

(h) Inspection

Within 36 months since the date of issuance of the original standard airworthiness certificate or date of issuance of the original export certificate of airworthiness, or within 90 days after the effective date of this AD, whichever occurs later, accomplish a detailed visual inspection of each affected part for any deficiency (e.g., any paint peel-off of the hook bolt hole of the frame fork), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A350–52–P011, dated May 12, 2017.

(i) Corrective Actions

If, during any detailed visual inspection required by paragraph (h) of this AD, any deficiency is found, before next flight, restore the anti-corrosion protection of frame forks of the affected part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A350–52–P011, dated May 12, 2017, except as required by paragraph (j) of this AD.

(j) Exceptions to Service Information Specifications

Where Airbus Service Bulletin A350–52–P011, dated May 12, 2017, specifies contacting Airbus, and specifies that action as RC: This AD requires repair using a method approved in accordance with the procedures specified in paragraph (l)(2) of this AD.

(k) Parts Installation Limitation

From the effective date of this AD, it is allowed to install on an airplane a forward cargo door or an aft cargo door, provided the part is a serviceable forward cargo door or serviceable aft cargo door as defined in paragraph (g)(2) of this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0031, dated January 31, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0410.

(2) For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email continued-airworthiness.a350@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on May 7, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-10211 Filed 5-14-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0408; Product Identifier 2017-NM-146-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) 2016-13-16, which applies to all The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. AD 2016-13-16 requires an inspection or records check to determine if affected horizontal stabilizers are installed, related investigative actions, and, for affected horizontal stabilizers, repetitive inspections for any crack of the horizontal stabilizer rear spar upper chord, and corrective action if necessary. Since we issued AD 2016-13-16, we have determined that clarification of inspection areas and serial number information of the horizontal stabilizer is necessary. Therefore, this proposed AD would retain the requirements of AD 2016-13-16, with revised service information that clarifies the inspection areas and serial number information of the horizontal stabilizer. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by June 29, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0408.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0408; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Lu Lu, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3525; email: lu.lu@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2018-0408; Product Identifier 2017-NM-146-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.