

4. USCIS Form I-941

DHS is discontinuing the new USCIS Form I-941 (OMB Control Number 1615-0136).

List of Subjects*8 CFR Part 103*

Administrative practice and procedure, Authority delegations (Government agencies), Freedom of information, Immigration, Privacy, Reporting and recordkeeping requirements.

8 CFR Part 212

Administrative practice and procedure, Aliens, Immigration, Passports and visas, Reporting and recordkeeping requirements.

8 CFR Part 274a

Administrative practice and procedure, Aliens, Employment, Penalties, Reporting and recordkeeping requirements.

Accordingly, DHS is proposing to amend chapter I of title 8 of the Code of Federal Regulations as follows:

PART 103—IMMIGRATION BENEFITS; BIOMETRIC REQUIREMENTS; AVAILABILITY OF RECORDS

- 1. The authority citation for part 103 continues to read as follows:

Authority: 5 U.S.C. 301, 552, 552a; 8 U.S.C. 1101, 1103, 1304, 1356, 1365b; 31 U.S.C. 9701; Pub. L. 107-296, 116 Stat. 2135 (6 U.S.C. 1 *et seq.*); E.O. 12356, 47 FR 14874, 15557, 3 CFR, 1982 Comp., p.166; 8 CFR part 2; Pub. L. 112-54.

§ 103.7 [Amended]

- 2. Amend § 103.7 by removing paragraph (b)(1)(i)(KKK).

PART 212—DOCUMENTARY REQUIREMENTS; NONIMMIGRANTS; WAIVERS; ADMISSION OF CERTAIN INADMISSIBLE ALIENS; PAROLE

- 3. The authority citation for part 212 continues to read as follows:

Authority: 6 U.S.C. 202(4) and 271, 8 U.S.C. 1101 and note, 1102, 1103, 1182 and note, 1184, 1187, 1223, 1225, 1226, 1227, 1255, 1359; 8 U.S.C. 1185 note (section 7209 of Pub. L. 108-458); 8 CFR part 2.

§ 212.19 [Removed]

- 4. Remove § 212.19.

PART 274a—CONTROL OF EMPLOYMENT OF ALIENS

- 5. The authority citation for part 274a continues to read as follows:

Authority: 8 U.S.C. 1101, 1103, 1324a; 48 U.S.C. 1806; 8 CFR part 2; Pub. L. 101-410, 104 Stat. 890, as amended by Pub. L. 114-74, 129 Stat. 599.

- 6. Revise § 274a.2(b)(1)(v)(A)(5) to read as follows:

§ 274a.2 Verification of identity and employment authorization.

* * * * *

(b) * * *

(1) * * *

(v) * * *

(A) * * *

(5) In the case of an individual who is authorized to work for a specific employer incident to status, a foreign passport with an Arrival/Departure Record, Form I-94 (as defined in 8 CFR 1.4) or Form I-94A, bearing the same name as the passport and containing an endorsement of the alien's nonimmigrant status, as long as the period of endorsement has not yet expired and the employment is not in conflict with the individual's employment-authorized status and any restrictions or limitations identified on the Form;

* * * * *

- 7. Amend § 274a.12 by:

- a. Revising paragraph (b) introductory text;

- b. Removing paragraph (b)(37);

- c. Revising paragraph (c)(11); and

- d. Removing and reserving paragraph (c)(34).

The revisions read as follows:

§ 274a.12 Classes of aliens authorized to accept employment.

* * * * *

(b) *Aliens authorized for employment with a specific employer incident to status.* The following classes of nonimmigrant aliens are authorized to be employed in the United States by the specific employer and subject to the restrictions described in the section(s) of this chapter indicated as a condition of their admission in, or subsequent change to, such classification. An alien in one of these classes is not issued an employment authorization document by DHS:

* * * * *

(c) * * *

(11) An alien paroled into the United States temporarily for urgent humanitarian reasons or significant public benefit pursuant to section 212(d)(5) of the Act.

* * * * *

Kirstjen M. Nielsen,

Secretary of Homeland Security.

[FR Doc. 2018-11348 Filed 5-25-18; 8:45 am]

BILLING CODE 9111-97-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0454; Product Identifier 2017-NM-056-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A330-200 Freighter series airplanes, Airbus Model A330-200 and -300 series airplanes, and Airbus Model A340-200 and -300 series airplanes. This proposed AD was prompted by reports of cracked slat tracks at the location of the front stop attachment to the track. This proposed AD would require a detailed inspection, repetitive special detailed inspections, and corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 13, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

• *Fax:* 202-493-2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://>

www.regulations.gov by searching for and locating Docket No. FAA–2018–0454; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206–231–3229.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–0454; Product Identifier 2017–NM–056–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017–0060, dated April 7, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A330–200 Freighter series airplanes; Airbus Model A330–200 and –300 series airplanes; and Airbus Model A340–200 and –300 series airplanes. The MCAI states:

Several cases of cracked slat tracks at the location of front stop attachment to track have been reported by operators. Analysis of the affected slat tracks (Airbus pre-modification (mod) 45967 design) revealed that induced torque loads during normal installation of the front stop, in combination with an incorrect shaft length of the attachment bolts and geometry of the front stop, are the root cause.

This condition, if not detected and corrected, would affect the structural integrity of the slat surface, which could lead to detachment of an outer or inner slat surface, possibly resulting in reduced control of the aeroplane and/or injury to persons on the ground.

To address this potential unsafe condition, Airbus issued Service Bulletin (SB) A330–57–3123 and SB A340–57–4130, to provide inspection instructions.

For the reasons described above, this [EASA] AD requires a one-time detailed inspection (DET) of the front stop lateral and aft surfaces [for marks (dents or scratches),] and repetitive special detailed inspections (SDI) of the front stop attachment areas, of slat tracks number (No.) 5 to No. 16 inclusive, both left hand (LH) and right hand (RH) wings [for cracks], and, depending on findings, accomplishment of applicable corrective action(s) [corrective actions include rework, repair, and slat rigging].

This [EASA] AD also includes reference to an optional modification (Airbus mod 205378) of the affected slat tracks, for which the associated SBs (SB A330–57–3126 and SB A340–57–4133, as applicable) are expected to become available in July 2017, which constitutes terminating action for the repetitive inspections required by this [EASA] AD.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0454.

Related Service Information Under 1 CFR Part 51

Airbus has issued Service Bulletin A330–57–3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017; and Service Bulletin A340–57–4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017. This service information describes procedures for a detailed inspection of the front stop lateral and aft surfaces for marks (dents or scratches), repetitive special detailed inspections of the front stop attachment areas, of slat track numbers 5 to 16 inclusive, both LH and RH wings for cracks, and corrective actions. These documents are distinct since they apply to different airplane models.

Airbus has also issued Service Bulletin A330–57–3126, including Appendixes 02 and 03, dated December 21, 2017; and Service Bulletin A340–57–4133, including Appendixes 02 and 03, dated December 21, 2017. This service information describes procedures for modification of all affected slat tracks on an airplane. These documents are distinct since they apply to different airplane models.

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Differences Between This Proposed AD and the MCAI or Service Information

Although the MCAI specifies to continue repetitive inspections if certain cracks that do not exceed specified damage limits are found, this proposed AD would require repairing before further flight in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–57–3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017; Airbus Service Bulletin A340–57–4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017; or obtaining corrective action instructions approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus’s EASA Design Organization Approval (DOA), and accomplishing them within the compliance time specified therein.

Although the MCAI specifies accomplishing the proposed actions in accordance with Airbus Service Bulletin A330–57–3123, dated June 14, 2016, or Airbus Service Bulletin A340–57–4130, dated June 14, 2016, this proposed AD would require using Airbus Service Bulletin A330–57–3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, or Airbus Service Bulletin A340–57–4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017. For airplanes on which the actions specified in Airbus Service Bulletin A330–57–3123, dated June 14, 2016, or Airbus Service Bulletin A340–57–4130, dated June 14, 2016, have been done, this proposed AD provides credit for those actions provided that the additional work identified in Airbus Service Bulletin A330–57–3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, or Airbus Service Bulletin A340–57–4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, is done. The additional work

includes inspecting for certain part numbers and for those affected parts, doing a detailed inspection, and corrective actions if necessary. We have coordinated this difference with EASA.

Costs of Compliance

We estimate that this proposed AD affects 101 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed Inspection	25 work-hours × \$85 per hour = \$2,125 per inspection cycle.	\$0	\$2,125 per inspection cycle	\$214,625 per inspection cycle.
Special Detailed Inspection	25 work-hours × \$85 per hour = \$2,125 per inspection cycle.	0	\$2,125 per inspection cycle	\$214,625 per inspection cycle.
Reporting	1 work-hour × \$85 per hour = \$85 per inspection cycle.	0	\$85 per inspection cycle	\$8,585 per inspection cycle.
Modification	49 work-hour × \$85 per hour = \$4,165	8,150	\$12,315	\$1,243,815.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this NPRM is 2120-0056. The paperwork cost associated with this NPRM has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this NPRM is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW, Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2018-0454; Product Identifier 2017-NM-056-AD.

(a) Comments Due Date

We must receive comments by July 13, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1), (c)(2), (c)(3), (c)(4), and (c)(5) of this AD, certificated in any category, all certificated models, all manufacturer serial numbers.

(1) Airbus Model A330-223F and -243F airplanes.

(2) Airbus Model A330-201, -202, -203, -223, and -243 airplanes.

(3) Airbus Model A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.

(4) Airbus Model A340-211, -212, -213 airplanes.

(5) Airbus Model A340-311, -312, and -313 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by reports of cracked slat tracks at the location of the front stop attachment to the track. We are issuing this AD to detect and correct cracked slat tracks which could affect the structural

integrity of the slat surface, possibly leading to detachment of an outer or inner slat surface, and resulting in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

(1) For the purpose of this AD, “affected slat track” is defined as a pre-modification 45967 slat track, located at the wing positions as indicated in figure 1 to paragraph (g) of this AD, and having a part number specified in figure 2 to paragraph (g) of this AD. In case the part number identification (ID) plate is missing or cannot be read, the slat track can be identified by the ink marking. If the

operator cannot determine the part number, then that airplane is in Group 1.

(2) For the purpose of this AD: Group 1 airplanes are those that, on the effective date of this AD, have an affected slat track installed. Group 2 airplanes are those that, on the effective date of this AD, do not have any affected slat track installed.

BILLING CODE 4910-13-P

Figure 1 to paragraph (g) of this AD – Positions of Affected Slat Tracks




Figure 2 to paragraph (g) of this AD – Affected Slats, Slat Track Positions, an Part Numbers (P/Ns)

Slat	Slat Track Position	Track Assembly P/N (according to ID plate)	Track Assembly and Linkage P/N (according to ink marking)
No. 2	Track 5	F57464105-000 F57464105-002 F57464105-004	F57464005-000/001 F57464005-002/003 F57464005-004/005
	Track 6	F57464106-000 F57464106-002 F57464106-004	F57464006-000/001 F57464006-002/003 F57464006-004/005
No. 3	Track 7	F57464107-000 F57464107-002	F57464007-000/001 F57464007-002/003
	Track 8	F57464108-000 F57464108-002 F57464108-004	F57464008-000/001 F57464008-002/003 F57464008-004/005
No. 4	Track 9	F57464109-000 F57464109-002	F57464009-000/001 F57464009-002/003
	Track 10	F57464110-000 F57464110-002 F57464127-000	F57464010-000/001 F57464010-002/003 F57464082-000/001
No. 5	Track 11	F57464111-000 F57464111-002 F57464111-004	F57464011-000/001 F57464011-002/003 F57464011-004/005
	Track 12	F57464112-000 F57464112-002	F57464012-000/001 F57464012-002/003
No. 6	Track 13	F57464113-000 F57464113-002 F57464113-004	F57464013-000/001 F57464013-002/003 F57464013-004/005
	Track 14	F57464114-000 F57464114-002 F57464114-004	F57464014-000/001 F57464014-002/003 F57464014-004/005
No. 7	Track 15	F57464115-000 F57464115-002 F57464115-004	F57464015-000/001 F57464015-002/003 F57464015-004/005
	Track 16	F57464116-000 F57464116-002	F57464016-000/001 F57464016-002/003

(h) One-Time Detailed Inspection and Repetitive Special Detailed Inspections

For Group 1 airplanes: At the applicable times specified in figure 3 to paragraph (h) of this AD, do a detailed inspection of the front stop lateral and aft surfaces, and do a

special detailed inspection of the front stop attachment areas of each affected slat track, both right hand (RH) and left hand (LH) wings, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-57-3123, Revision 01,

including Appendixes 02 and 03, dated September 27, 2017; or Airbus Service Bulletin A340-57-4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017; as applicable. Thereafter, repeat the special detailed

inspection for the front stop attachment areas of each affected slat track, both RH and LH wings, at intervals not to exceed the

applicable compliance times specified in figure 4 to paragraph (h) of this AD.

Figure 3 to Paragraph (h) of this AD – Initial Inspection Compliance Times

Compliance Time: (whichever occurs later, A or B)	
A	A330: Before exceeding 15,000 flight cycles (FC) or 50,000 flight hours (FH), whichever occurs first since airplane first flight
	A340: Before exceeding 15,000 FC or 78,000 FH, whichever occurs first since airplane first flight
B	Within 24 months after the effective date of this AD

Figure 4 to Paragraph (h) of this AD – Repetitive Inspection Interval

Airplane	Compliance Times (FC or FH, whichever occurs first)
A330:	7,000 FC or 24,000 FH
A340:	4,400 FC or 23,000 FH

BILLING CODE 4910-13-C

(i) Corrective Actions

(1) If, during any special detailed inspection required by paragraph (h) of this AD, any crack is detected at the front stop attachment area of an affected slat track: Before further flight, obtain corrective action instructions approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA), and accomplish them within the compliance time specified therein. If approved by the DOA, the approval must include the DOA-authorized signature.

(2) If, during any inspection required by paragraph (h) of this AD, marks (dents or scratches) are found on the front stop lateral or aft surfaces of an affected slat track; provided that no crack is detected; before further flight, rework the affected lateral front stop surface of that slat track, and accomplish slat rigging, as applicable, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-57-3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017; or Airbus Service Bulletin A340-57-4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017. Accomplishment of rework or slat rigging on an airplane, as required by this paragraph, does not constitute terminating action for the

repetitive special detailed inspection required by paragraph (h) of this AD.

(3) If, during any inspection required by paragraph (h) of this AD, marks (dents or scratches) are found on the front stop lateral or aft surfaces of an affected slat track, and any crack is detected at the front stop attachment area of that slat track: Before further flight, obtain corrective action instructions approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA, and accomplish them within the compliance time specified therein. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Reporting

At the applicable time specified in paragraph (j)(1) or (j)(2) of this AD: Report the results of the inspections required by paragraph (h) of this AD to Airbus Service Bulletin Reporting Online Application on Airbus World (<https://w3.airbus.com/>), or submit the results to Airbus in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-57-3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, or Airbus Service Bulletin A340-57-4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017. The report must include the inspection results (including no findings), a description of any discrepancies found, the airplane serial number, and the

number of landings and flight hours on the airplane.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 60 days after each inspection required by paragraph (h) of this AD.

(2) If the inspection was done before the effective date of this AD: Submit the report within 60 days after the effective date of this AD.

(k) Optional Terminating Actions

(1) Replacement of an affected slat track at any position with a post-modification 45967 slat track, if accomplished as part of the corrective actions specified in paragraph (i)(1) or (i)(3) of this AD, terminates the repetitive inspections required by paragraph (h) of this AD, for that slat track position.

(2) Modification of all affected slat tracks on an airplane in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-57-3126, including Appendixes 02 and 03, dated December 21, 2017; or Airbus Service Bulletin A340-57-4133, including Appendixes 02 and 03, dated December 21, 2017; as applicable, terminates the repetitive inspections required by paragraph (h) of this AD for that airplane, provided that, prior to modification, the affected slat tracks pass an inspection (crack free) in accordance with the instructions of Airbus Service Bulletin A330-57-3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017; or Airbus Service Bulletin A340-57-4130, Revision 01,

including Appendixes 02 and 03, dated September 27, 2017; as applicable.

(l) Parts Installation Limitations

(1) Except as specified in paragraph (l)(2) of this AD: For Group 1 airplanes, after the effective date of this AD, an affected slat track may be installed, provided the installation is accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(2) After modification of a Group 1 airplane as specified in paragraph (k)(2) of this AD, no person may install an affected slat track on that airplane.

(3) For Group 2 airplanes: As of the effective date of this AD, no person may install an affected slat track on any Group 2 airplane.

(m) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (h), (i), and (j) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A330-57-3123, dated June 14, 2016, or Airbus Service Bulletin A340-57-4130, dated June 14, 2016, provided that within 12 months after the effective date of this AD, the additional work identified in Airbus Service Bulletin A330-57-3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, or Airbus Service Bulletin A340-57-4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, as applicable, has been completed in accordance with Airbus Service Bulletin A330-57-3123, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, or Airbus Service Bulletin A340-57-4130, Revision 01, including Appendixes 02 and 03, dated September 27, 2017, as applicable.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA. If approved by the

DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(4) *Required for Compliance (RC)*: Except as required by paragraph (i) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2017-0060, dated April 7, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0454.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206 231 3229.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on May 21, 2018.

James Cashdollar,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-11415 Filed 5-25-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0452; Product Identifier 2017-NM-150-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes. This proposed AD was prompted by the results of a fleet survey, which revealed cracking in bulkhead frame webs at a certain body station. This proposed AD would require repetitive inspections of the bulkhead frame web at a certain body station and applicable on-condition actions. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 13, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0452.