

B672M1002202 or L672M2802205; or lateral control lever assembly, P/N B670M1008101, installed.

**(b) Unsafe Condition**

This AD defines the unsafe condition as incorrectly installed flight control bearings. This condition could cause the affected control lever to shift and contact the helicopter structure, resulting in reduced control of the helicopter.

**(c) Comments Due Date**

We must receive comments by July 31, 2018.

**(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

(1) For Model EC135 P1, P2, P2+, T1, T2, and T2+ helicopters: Within the next 100 hours time-in-service (TIS) or at the next annual inspection, whichever occurs first, modify the left-hand (LH) and right-hand (RH) guidance units and the cyclic shaft by installing bushings and washers to prevent shifting of the bearings in the axial direction as follows:

(i) Remove and disassemble the LH guidance unit and install a bushing, P/N L672M1012260, between the bearing block and the lever of the LH guidance unit as depicted in Detail A of Figure 5 of Eurocopter Alert Service Bulletin EC135-67A-019, Revision 3, dated December 16, 2009 (EC135 ASB).

(ii) For helicopters without a yaw brake, remove and disassemble the RH guidance unit and install a bushing, P/N L672M1012260, between the bearing block and the lever as depicted in Detail B of Figure 5 of EC135 ASB.

(iii) Remove and disassemble the cyclic shaft and install a washer, P/N L671M10055260, between the bearing block and the lever as depicted in Detail C of Figure 6 of EC135 ASB.

(iv) Remove the collective control rod from the bellcrank and install a washer, P/N L221M1042208, on each side of the collective control rod and bellcrank as depicted in Detail D of Figure 6 of EC135 ASB.

(2) For Model MBB-BK 117C-2 helicopters: Within the next 100 hours TIS or at the next annual inspection, whichever occurs first, modify the LH and RH guidance units and the lateral control lever by installing bushings and washers to prevent shifting of the bearings in the axial direction as follows:

(i) Remove and disassemble the RH guidance unit and install a bushing, P/N L672M1012260, between the lever and the bracket as depicted in Detail B of Figure 4 of Eurocopter Alert Service Bulletin MBB BK117C-2-67A-010, Revision 3, dated February 8, 2010 (BK117 ASB). Remove and disassemble the LH guidance unit and install a bushing, P/N L672M1012260, between the lever and the bracket as depicted in Detail C of Figure 4 of BK117 ASB.

(ii) Remove the lateral control lever and install new bushings in accordance with the

Accomplishment Instructions, paragraphs 3.C(9)(a) through 3.C(9)(g) of BK117 ASB.

(iii) Identify the modified lever assembly by writing "MBB BK117C-2-67A-010" on the lever with permanent marking pen and protect with a single layer of lacquer (CM 421 or equivalent).

(iv) Apply corrosion preventive paste (CM518 or equivalent) on the shank of the screws and install airworthy parts as depicted in Figure 5 of BK117 ASB.

**(f) Affected ADs**

This AD replaces AD 2014-05-06, Amendment 39-17779 (79 FR 13196, March 10, 2014).

**(g) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

**(h) Additional Information**

(1) Airbus Helicopters Alert Service Bulletin EC135-67A-019, Revision 4, dated April 3, 2017, and Alert Service Bulletin MBB-BK117C-2-67A-010, Revision 4, dated April 3, 2017, which are not incorporated by reference, contain additional information about this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at [http://www.helicopters.airbus.com/website/en/ref/Technical-Support\\_73.html](http://www.helicopters.airbus.com/website/en/ref/Technical-Support_73.html). You may review service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2010-0058R1, dated April 7, 2017. You may view the EASA AD on the internet at <http://www.regulations.gov> in the AD Docket.

**(i) Subject**

Joint Aircraft Service Component (JASC) Code: 6710, Main Rotor Control.

Issued in Fort Worth, Texas, on May 11, 2018.

**Scott A. Horn,**

*Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2018-11447 Filed 5-31-18; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2018-0496; Product Identifier 2018-NM-031-AD]

**RIN 2120-AA64**

**Airworthiness Directives; Dassault Aviation Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 2000 and FALCON 2000EX airplanes. This proposed AD was prompted by reports of metallic debris found in the wing slat piccolo tubes; investigation revealed that the debris originated from the flow guide of the ball joint of the wing anti-ice valve. This proposed AD would require repetitive inspections for metallic debris and damage of the flow guide of the ball joint of the wing anti-ice valve, and related investigative and corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by July 16, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://>

[www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA–2018–0496; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206–231–3226.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–0496; Product Identifier 2018–NM–031–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

**Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European

Union, has issued EASA Airworthiness Directive 2018–0022, dated January 29, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Dassault Aviation Model FALCON 2000 and FALCON 2000EX airplanes. The MCAI states:

Occurrences were reported on Falcon 2000 and Falcon 2000EX aeroplanes, where metallic debris was found in slat piccolo tubes. The technical investigation revealed that debris originated from the flow guide of the ball joint located downstream of the wing anti-ice valve. It was also determined that small debris gathers at the end of the piccolo tube, but larger pieces of debris may stop before, in the distribution piping, restricting the airflow and potentially leading to undetected insufficient wing anti-ice capability.

This condition, if not detected and corrected, could lead to undetected significant ice accretion on the wing, possibly resulting in loss of control of the aeroplane.

To address this potential unsafe condition, Dassault Aviation issued Service Bulletin (SB) F2000EX–413 for Falcon 2000EX and SB F2000–441 for Falcon 2000, providing applicable instructions.

For the reasons described above, this [EASA] AD requires repetitive [detailed] inspections [for discrepancies including cracks and loss of material] of the affected ball joint and, depending on findings, accomplishment of applicable related investigative and corrective actions \* \* \*.

Related investigative actions include, for any loss of material, borescope inspections of anti-ice pipes for debris, nicks, and damage. Corrective actions include replacing any cracked or damaged ball joint, and removing debris from the flow guide. You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0496.

**Related Service Information Under 1 CFR Part 51**

Dassault Aviation has issued Service Bulletins F2000–441, dated June 20, 2017; and F2000EX–413, dated July 10, 2017. This service information describes procedures for repetitive inspections for metallic debris and damage of the flow guide of the anti-ice ball joint of the wing. The service information also describes procedures for replacing the ball joint and pipe, and performing borescope inspections of damaged wing anti-ice pipes and removal of any debris from the flow guide. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

**Costs of Compliance**

We estimate that this proposed AD affects 348 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510 .....	\$0	\$510	\$177,480

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance

and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

*Authority:* 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Dassault Aviation:** Docket No. FAA-2018-0496; Product Identifier 2018-NM-031-AD.

#### (a) Comments Due Date

We must receive comments by July 16, 2018.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Dassault Aviation Model FALCON 2000 and FALCON 2000EX airplanes, certificated in any category, all serial numbers equipped with any anti-ice

pipe having part number (P/N) F2MA724561A1 or P/N F2MA724561A2, except airplanes on which Dassault Modification (mod) M5000 or Dassault mod M5001 has been embodied in production.

#### (d) Subject

Air Transport Association (ATA) of America Code 30, Ice and Rain Protection.

#### (e) Reason

This AD was prompted by reports of metallic debris found in the wing slat piccolo tubes; investigation revealed that the debris originated from the flow guide of the ball joint of the wing anti-ice valve. We are issuing this AD to address restricted airflow of the piccolo tubes, leading to insufficient wing anti-ice capability and significant undetected ice accretion on the wing, which could result in loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Repetitive Inspections and Corrective Actions

Within 25 months after the effective date of this AD: Perform a detailed inspection for discrepancies of the flow guide of the ball joint located downstream of the wing anti-ice valve, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-441, dated June 20, 2017; or Dassault Aviation Service Bulletin F2000EX-413, dated July 10, 2017; as applicable. Repeat the detailed inspection thereafter at intervals not to exceed 25 months. Do all applicable corrective actions before further flight.

#### (h) No Reporting Requirement

Although the service information identified in paragraph (g) of this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must

be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0022, dated January 29, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0496.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206-231-3226.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on May 22, 2018.

**James Cashdollar,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-11679 Filed 5-31-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0494; Product Identifier 2017-NM-182-AD]

RIN 2120-AA64

#### Airworthiness Directives; ATR-GIE Avions de Transport Régional Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2006-07-26, which applies to all ATR-GIE Avions de Transport Régional Model ATR42 airplanes. AD 2006-07-26 requires a one-time inspection to detect discrepancies (e.g., cracking, loose/sheared fasteners, distortion) of the upper skin and rib feet of the outer wing boxes, and repair if necessary. Since we issued AD 2006-07-26, we have