

in paragraph 1.E., “Compliance,” of Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017, except as required by paragraph (j)(2) of this AD, do a post-repair HFEC inspection for cracking, in accordance with Part 3 of the Accomplishment Instructions of Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017, and repeat the inspection thereafter at the applicable times specified in paragraph 1.E., “Compliance,” of Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017.

(iii) If any crack is found during any inspection required by paragraph (h)(3)(ii) of this AD, repair before further flight using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(i) Repair Approval

Repairs of the lower outboard wing skin that were approved after June 15, 2017, and before the effective date of this AD, by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, are approved for the applicable repairs required by paragraphs (g) and (h) of this AD. The ODA repairs will have post-installation inspection requirements in lieu of the post-inspection instructions specified in Aviation Partners Boeing Service Bulletin AP767–57–010, Revision 11, dated April 3, 2017; and Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017.

(j) Exceptions to Service Information Specifications

(1) Where paragraph 1.E., “Compliance,” of Aviation Partners Boeing Service Bulletin AP767–57–010, Revision 11, dated April 3, 2017, specifies a compliance time “after the issue date of Revision 11 of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where paragraph 1.E., “Compliance,” of Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017, specifies a compliance time “after the initial issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(3) For Condition 1 and Condition 2 airplanes: Where paragraph 1.E., “Compliance,” of Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017, specifies a compliance time for accomplishing the Part 3 HFEC inspection of 18 months “after the initial issue date of this service bulletin,” the required compliance time is 6,000 flight cycles or 18,000 flight hours, whichever occurs first, after doing the Part 2 repair.

(4) For airplanes on which a stringer L–9.5 replacement was accomplished per Part 11 of Aviation Partners Boeing Service Bulletin AP767–57–010, Revision 11, dated April 3, 2017; Where Aviation Partners Boeing Service Bulletin AP767–57–010, Revision 11, dated April 3, 2017, specifies repeating the post-repair HFEC inspection “in Part 9,” this

AD requires repeating the post-repair HFEC inspection in Part 13.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes ODA that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraphs (g)(1)(i)(B)(3), (g)(1)(i)(C)(3), (g)(1)(i)(D)(3), (g)(1)(ii)(A)(3), (g)(1)(ii)(B)(3), (g)(1)(iii)(A)(3), (g)(1)(iii)(B)(3), (g)(1)(iv), (g)(2), (h)(2)(iii), and (h)(3)(iii) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

For more information about this AD, contact Allen Rauschendorfer, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA; phone and fax: 206–231–3528; email: allen.rauschendorfer@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Aviation Partners Boeing Service Bulletin AP767–57–010, Revision 11, dated April 3, 2017.

(ii) Aviation Partners Boeing Service Bulletin AP767–57–014, Revision 1, dated April 12, 2017.

(3) For service information identified in this AD, contact Aviation Partners Boeing, 2811 S. 102nd Street, Suite 200, Seattle, WA 98168; telephone 206–762–1171; internet <https://www.aviationpartnersboeing.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 21, 2018.

James Cashdollar,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–11825 Filed 6–4–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–1099; Product Identifier 2017–NM–093–AD; Amendment 39–19296; AD 2018–11–08]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 767–200 and –300 series airplanes. This AD was prompted by a report of two cracks at a certain frame inner chord. This AD requires a detailed inspection for any material review board (MRB) filler installed in the area from the frame web to the stub-beam fitting at certain stations to determine if the filler extends above the frame-to-stub-beam joint, and applicable on-condition actions. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 10, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 10, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1099.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1099; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Wayne Lockett, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 S. 216th St., Des Moines, WA 98198; phone and fax: 206-231-3524; email: wayne.lockett@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 767-200 and -300 series airplanes. The NPRM was published in the **Federal Register** on December 6, 2017 (82 FR 57552). The NPRM was prompted by a report of a crack on the transition radius of the station (STA) 883.5 frame inner chord and an additional crack indication at a fastener hole in the frame inner chord common to a material review board (MRB) filler that extended above the frame-to-stub-beam joint. The NPRM proposed to

require a detailed inspection for any MRB filler installed in the area from the frame web to the stub-beam fitting at certain stations to determine if the filler extends above the frame-to-stub-beam joint, and applicable on-condition actions.

We are issuing this AD to detect and correct cracking of the frame inner chord, which could result in the inability of one or more overwing stub frames between STA 808 and STA 933, each a principal structural element, to sustain limit loads; this condition could adversely affect the structural integrity of the airplane.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment. Boeing concurred with the NPRM.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that accomplishing the Supplemental Type Certificate (STC) ST01920SE does not affect the actions specified in the NPRM.

We concur with the commenter. We have redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01920SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01920SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

Request To Confirm Intent of Compliance Time

Paragraph (h)(1) of the proposed AD allowed operators to substitute "the effective date of this AD" for "the original issue date of Requirements Bulletin 767-53A0278 RB." United Airlines noted that this wording is different from that of recent NPRMs, where the AD effective date is the sole compliance date. United added that the proposed wording suggested that the operator can choose to use either the AD effective date or the original issue date of the RB when determining the

compliance timeline. United requested that we clarify the intent of the provision of paragraph (h)(1) of the proposed AD.

We agree with the commenter. We have revised paragraph (h)(1) of this AD to specify use of the effective date of this AD in determining the compliance time.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017. This service information describes procedures for a detailed inspection for any MRB filler installed in the area from the frame web to the stub-beam fitting on the left and right side at STA 859.5, 883.5, and 903.5 to determine if the filler extends above the frame-to-stub-beam joint, and applicable on-condition actions. The applicable on-condition actions include repetitive surface high frequency eddy current inspections and repair for cracking in the frame inner chord around the end fastener common to each affected MRB filler. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 51 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed Inspection	20 work-hours × \$85 per hour = \$1,700	\$0	\$1,700	\$86,700

We estimate the following costs to do any necessary on-condition actions that would be required. We have no way of determining the number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION INSPECTIONS

Labor cost	Parts cost	Cost per product
3 work-hours × \$85 per hour = \$255 per inspection cycle	\$0	\$255 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition repairs specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a

substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018–11–08 The Boeing Company:
Amendment 39–19296; Docket No. FAA–2017–1099; Product Identifier 2017–NM–093–AD.

(a) Effective Date

This AD is effective July 10, 2018.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 767–200 and –300 series airplanes, as identified in Boeing Alert Requirements Bulletin 767–53A0278 RB, dated June 30, 2017, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01920SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/59027F43B9A7486E8625B1D006591EE?OpenDocument&Highlight=st01920se](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rkstc.nsf/0/59027F43B9A7486E8625B1D006591EE?OpenDocument&Highlight=st01920se)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01920SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of a crack on the transition radius of the station (STA) 883.5 frame inner chord and an additional crack indication at a fastener hole in the frame inner chord common to a material review board (MRB) filler that extended above the frame-to-stub-beam joint. We are issuing this AD to detect and correct cracking of the frame inner chord, which could result in the inability of one or more overwing stub frames between STA 808 and STA 933, each a principal structural element, to sustain limit loads; this condition could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as required by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017.

Note 1 to paragraph (g) of this AD: Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 767-53A0278, dated June 30, 2017, which is referred to in Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, uses the phrase "the original issue date of Requirements Bulletin 767-53A0278 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, specifies contacting Boeing, this AD requires repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(3) For airplanes identified as Group 1, Configuration 1, in Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, that have been modified to a freighter configuration: The actions specified in Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, for Group 1, Configuration 2, must be done instead of the actions for Group 1, Configuration 1, except as required by paragraph (h)(2) of this AD.

(4) For airplanes identified as Group 2, Configuration 1, in Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, that have been modified to a freighter configuration: The actions specified in Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017, for Group 2, Configuration 2, must be done instead of the actions for Group 2, Configuration 1, except as required by paragraph (h)(2) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 S. 216th St., Des Moines, WA 98198; phone and fax: 206-231-3524; email: wayne.lockett@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 767-53A0278 RB, dated June 30, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 18, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-11427 Filed 6-4-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2017-0779; Product Identifier 2017-NM-040-AD; Amendment 39-19301; AD 2018-11-13]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 airplanes. This AD was prompted by a report of possible degraded bond-line performance of co-bonded upper wing stringer-to-skin joints. This AD requires repetitive inspections of certain upper wing stringers for any disbond and corrective actions, if necessary; and a terminating preventive modification of installing disbond arrestment (DBA) fasteners. This AD also requires revising the inspection or maintenance program to incorporate an airworthiness limitation. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 10, 2018.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 10, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone: 562-797-1717; internet: <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0779.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0779; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule,