

number (RIN) 2590-AA95, by any one of the following methods:

- *Agency website:* www.fhfa.gov/open-for-comment-or-input.
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments. If you submit your comment to the Federal eRulemaking Portal, please also send it by email to FHFA at RegComments@fhfa.gov to ensure timely receipt by FHFA. Include the following information in the subject line of your submission: Comments/RIN 2590-AA95.

- *Hand Delivered/Courier:* The hand delivery address is: Alfred M. Pollard, General Counsel, Attention: Comments/RIN 2590-AA95, Federal Housing Finance Agency, Eighth Floor, 400 Seventh Street SW, Washington, DC 20219. Deliver the package at the Seventh Street entrance Guard Desk, First Floor, on business days between 9 a.m. and 5 p.m.

- *U.S. Mail, United Parcel Service, Federal Express, or Other Mail Service:* The mailing address for comments is: Alfred M. Pollard, General Counsel, Attention: Comments/RIN 2590-AA95, Federal Housing Finance Agency, Eighth Floor, 400 Seventh Street SW, Washington, DC 20219. Please note that all mail sent to FHFA via U.S. Mail is routed through a national irradiation facility, a process that may delay delivery by approximately two weeks. For any time-sensitive correspondence, please plan accordingly.

FOR FURTHER INFORMATION CONTACT: Naa Awaa Tagoe, Senior Associate Director, Office of Financial Analysis, Modeling & Simulations, (202) 649-3140, NaaAwaa.Tagoe@fhfa.gov; Andrew Varrieur, Associate Director, Office of Financial Analysis, Modeling & Simulations, (202) 649-3141, Andrew.Varrieur@fhfa.gov; or Miriam Smolen, Associate General Counsel, Office of General Counsel, (202) 649-3182, Miriam.Smolen@fhfa.gov. These are not toll-free numbers. The mailing address is: Federal Housing Finance Agency, 400 Seventh Street SW, Washington, DC 20219. The telephone number for the Telecommunications Device for the Hearing Impaired is (800) 877-8339.

SUPPLEMENTARY INFORMATION:

Comments

FHFA invites comments on all aspects of the proposed rule and will take all comments into consideration before issuing a final rule. Copies of all comments will be posted without change, and will include any personal information you provide such as your

name, address, email address, and telephone number, on the FHFA website at <http://www.fhfa.gov>. In addition, copies of all comments received will be available for examination by the public through the electronic rulemaking docket for this proposed rule also located on the FHFA website.

Background

On July 17, 2018, FHFA published in the **Federal Register** a proposed rule proposing a new regulatory capital framework for Fannie Mae and Freddie Mac which includes a new framework for risk-based capital requirements and two alternatives for an updated minimum leverage capital requirement. See 83 FR 33312. The comment period for the proposed rule was originally set to expire on September 17, 2018. FHFA is extending the comment period an additional 60 days, changing the deadline for submitting comments to November 16, 2018.

Dated: July 30, 2018.

Melvin L. Watt,

Director, Federal Housing Finance Agency.

[FR Doc. 2018-16654 Filed 8-2-18; 8:45 am]

BILLING CODE 8070-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0633; Product Identifier 2018-NE-22-AD]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) GENx-2B67, -2B67B, and -2B67/P turbofan engines. This proposed AD was prompted by low-cycle fatigue (LCF) cracking of the fuel manifold leading to an engine fire. This proposed AD would require removal from service of certain fuel manifolds at the next engine shop visit and their replacement with parts eligible for installation. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 17, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: geae.aoc@ge.com. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0633; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Herman Mak, Aerospace Engineer, ECO Branch, FAA, 1200 District Ave., Burlington, MA 01803; phone: 781-238-7147; fax: 781-238-7199; email: herman.mak@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2018-0633; Product Identifier 2018-NE-22-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://>

www.regulations.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

We received information concerning a fire in the under-cowl compartment of a GE GEnx-2B turbofan engine. Insufficient bushing clearance in the fuel manifold bracket resulted in additional fuel manifold loads, premature manifold cracking, fuel leakage, and fuel ignition. Twelve fuel manifolds were found to have LCF cracks. Three of these twelve cracked

fuel manifolds resulted in a fire. This condition, if not addressed, could result in failure of the fuel manifold, engine fire, and damage to the airplane.

Related Service Information

We reviewed GE GEnx-2B Service Bulletin (SB) 73-0038 R02, dated November 19, 2015. The SB describes procedures for removing and replacing the fuel manifold system with parts eligible for installation.

FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition

described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require removal from service of certain fuel manifolds at the next engine shop visit and their replacement with parts eligible for installation.

Costs of Compliance

We estimate that this proposed AD affects two engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace fuel manifolds	220 work-hours × \$85 per hour = \$18,700	\$119,485	\$138,185	\$276,370

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator.

Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This

proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

General Electric Company: Docket No. FAA-2018-0633; Product Identifier 2018-NE-22-AD.

(a) Comments Due Date

We must receive comments by September 17, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) GEnx-2B67, -2B67B, and -2B67/P turbofan engines with top main fuel manifolds, part numbers (P/Ns) 2419M11G01, 2561M11G01, or 2546M11G01, or lower fuel manifolds, P/Ns 2419M12G01, 2561M12G01, or 2546M12G01, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7310, Engine Fuel Distribution.

(e) Unsafe Condition

This AD was prompted by low-cycle fatigue cracking of the fuel manifold leading to an engine fire. We are issuing this AD to prevent the failure of the fuel manifold. The unsafe condition, if not addressed, could result in failure of the fuel manifold, engine fire, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

At the next engine shop visit, remove the applicable fuel manifolds from service and replace with parts eligible for installation.

(h) Installation Prohibition

After the effective date of this AD, do not install top main fuel manifolds, P/Ns 2419M11G01, 2561M11G01, or 2546M11G01, or lower fuel manifolds, P/Ns 2419M12G01, 2561M12G01, or 2546M12G01.

(i) Definition

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine case flanges, except for the following situations, which do not constitute an engine shop visit:

- (1) Separation of engine flanges solely for the purposes of transportation of the engine without subsequent maintenance.
- (2) Separation of engine flanges solely for the purposes of replacing the fan or propulsor without subsequent maintenance.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Herman Mak, Aerospace Engineer, ECO Branch, FAA, 1200 District Ave., Burlington, MA 01803; phone: 781-238-7147; fax: 781-238-7199; email: herman.mak@faa.gov.

(2) For service information identified in this AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: gae.aoc@ge.com. You may view this referenced service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Issued in Burlington, Massachusetts, on July 27, 2018.

Karen M. Grant,

Acting Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2018-16515 Filed 8-2-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0704; Product Identifier 2018-NM-066-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus SAS Model A330-200 Freighter, -200 and -300 series airplanes; and Airbus SAS Model A340-200, -300, -500, and -600 series airplanes. This proposed AD was prompted by reports of depressurization of hydraulic reservoirs caused by air leakage from the pressure relief valve (PRV) of the hydraulic reservoir (HR) due to the extrusion of the O-ring seal from certain HR PRVs. This proposed AD would require identifying the part number of the HR, and replacing and re-identifying affected HR PRVs. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 17, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAL, Rond Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0704; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206-231-3229.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0704; Product Identifier 2018-NM-066-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2018-0064, dated March 23, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A330-200 Freighter, -200 and -300 series airplanes; and Airbus SAS Model A340-200, -300, -500, and -600 series airplanes. The MCAI states:

Some events of depressurisation of hydraulic reservoirs have been reported, due to air leakage from the HR PRV [hydraulic reservoir pressure relief valve]. The results of the investigations revealed that the air leakage was due to the extrusion of the O-ring seal from the HR PRV. This may have