

(g) Revision of Maintenance or Inspection Program

Within 90 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate the information specified in Airbus A318/A319/A320/A321 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 06, dated June 13, 2018 ("ALS Part 3, CMR, R6"). The initial compliance time for accomplishing the tasks specified in ALS Part 3, CMR, R6, is at the applicable time specified in ALS Part 3, CMR, R6, or within 90 days after the effective date of this AD, whichever occurs later.

(h) Terminating Actions for AD 2017–25–04

Accomplishing the actions required by paragraph (g) of this AD terminates all of the requirements of AD 2017–25–04.

(i) No Alternative Actions or Intervals

After the maintenance or inspection program, as applicable, has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j)(1) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2017–25–04, or AD 2014–22–08, Amendment 39–18013 (79 FR 67042, November 12, 2014), that allow incorporation of ALS Part 3, CMR, R6, are considered approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply

with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0180, dated August 27, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0554.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on October 30, 2018.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–24393 Filed 11–7–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2018–0957; Product Identifier 2018–NM–102–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus SAS Model A318–111, –112, –121, and –122 airplanes; Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes; and Model A320–211, –212, –214, –216, –231, –232, and

–233 airplanes. This proposed AD was prompted by reports of cracks that were found after improperly performed magnetic particle inspections of the main landing gear (MLG) sliding tubes were done. This proposed AD would require instructions for repetitive general visual inspections of the affected parts for cracks and replacement if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by December 24, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0957; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–0957; Product Identifier 2018–NM–102–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018–0136, dated June 26, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A318–111, –112, –121, and –122 airplanes; Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes; and

Model A320–211, –212, –214, –216, –231, –232, and –233 airplanes. The MCAI states:

During a walk-around inspection, prior to aeroplane dispatch, an A320 MLG was found collapsed. Investigation revealed that, following a magnetic particle inspection of the MLG sliding tube, performed improperly during overhaul, cracks were initiated, eventually leading to fatigue fracture. A limited number of MLG sliding tubes have been identified that may have been subject to the same improper inspection during the last overhaul.

This condition, if not detected and corrected, could lead to MLG sliding tube fracture, possibly resulting in MLG collapse, damage to the aeroplane, and injury to occupants.

To address this potential unsafe condition, Airbus issued the SB [Service Bulletin A320–32–1461], providing instructions for repetitive general visual inspections (GVI) of the affected parts until next overhaul.

For the reasons described above, this [EASA] AD requires repetitive GVI of the affected parts [for cracks] and, depending on findings, replacement.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0957.

Related Service Information Under 1 CFR Part 51

Airbus has issued Service Bulletin A320–32–1461, dated April 11, 2018. This service information describes procedures for repetitive general visual

inspections of MLG sliding tubes for cracks and replacement of affected sliding tubes. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 817 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS [“]

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 2 work-hours × \$85 per hour = \$170	\$0	Up to \$170	Up to \$138,890.

* Table does not include estimated costs for reporting.

We estimate that it would take about 1 work-hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based on these

figures, we estimate the cost of reporting the inspection results on U.S. operators to be \$9,945, or \$85 per product.

We estimate the following costs to do any necessary on-condition actions that

would be required based on the results of any required actions. We have no way of determining the number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
19 work-hours × \$85 per hour = \$1,615	\$185	\$1,800

We estimate that it would take about 1 work-hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based on these figures, we estimate the cost of reporting

the inspection results on U.S. operators to be \$85 per product.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a

collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this NPRM is 2120–0056.

The paperwork cost associated with this NPRM has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this NPRM is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW, Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to

issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus SAS: Docket No. FAA-2018-0957; Product Identifier 2018-NM-102-AD.

(a) Comments Due Date

We must receive comments by December 24, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Reason

This AD was prompted by reports of cracks that were found after improperly performed magnetic particle inspections of the main landing gear (MLG) sliding tubes were done. We are issuing this AD to address this condition, which could result in fracture of the MLG sliding tube, possibly resulting in MLG collapse, damage to the airplane, and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purposes of this AD, the definitions specified in paragraphs (g)(1) and (g)(2) of this AD apply.

(1) An affected part is any MLG sliding tube, having a part number (P/N) and serial number (S/N) listed in Figure 1 to paragraph (g)(1) of this AD, that has been last overhauled between October 27, 2003, and September 21, 2009, inclusive.

BILLING CODE 4910-13-P

Figure 1 to paragraph (g)(1) of this AD – *Affected parts: P/N and S/N*

Part number	Serial number	Part number	Serial number	Part number	Serial number
201160302	1071	201371302	B198-4649	201371304	B0544888
201160302	1116B	201371302	B274-4849	201371304	B0751922
201160302	73B	201371302	B225-4715	201371304	B1392028
201160302	1309B	201371302	B228-4755	201371304	B1655066
201160302	1024B	201371302	1801B	201371304	B1025007
201160302	64B	201371302	4441B	201371304	B994937
201160324	B2414670	201371302	B197-4656	201371304	B019-05
201160324	B013-4846	201371302	B210-4687	201371304	B1261991
201160324	B235-4749	201371302	B227-4697	201371304	B123-4994
201160324	1321B	201371302	SS4353B	201371304	B0334860
201160324	MAL1161	201371302	SS4375	201371304	B0234843
201160324	1057	201371304	B168-1948	201371304	B0364875
201160324	MAL-1315	201371304	B951935	201371304	B042-1899
201160324	12088	201371304	B003-4830	201371304	B554896
201160324	1693B	201371304	B005-4815	201371304	B0474885
201371302	B2584800	201371304	B006-4819	201371304	B0494851
201371302	B210-4684	201371304	B0181916	201371304	B0924936
201371302	B196-1879	201371304	B0211889	201371304	B1064967
201371302	B241-4668	201371304	B0311902	201371304	B1054968
201371302	B264-4787	201371304	B026-1895	201371304	B1081962
201371302	B265-4808	201371304	B029-1904	201371304	B013-4845
201371302	B2564777	201371304	B006-4829	201371304	B0374865
201371302	B2704816	201371304	B0281900	201371304	B1194983
201371302	B196-1880	201371304	B0254853	201371304	B4675255
201371302	B2714811	201371304	B0271893	201371304	B1111974
201371302	B229-4729	201371304	B0321906		
201371302	B261-4810	201371304	B003-4821		
201371302	B2724797	201371304	B009-4818		

BILLING CODE 4910-13-C

(2) Group 1 airplanes are those that have an affected part installed. Group 2 airplanes are those that do not have an affected part installed.

(h) Repetitive Inspections

For Group 1 airplanes: Within 500 flight cycles after the effective date of this AD, and, thereafter, at intervals not to exceed 500 flight cycles, accomplish a general visual inspection for cracks of each affected part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-32-1461, dated April 11, 2018.

(i) Corrective Action

If any crack is found during any inspection required by paragraph (h) of this AD: Before further flight, replace the affected part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-32-1461, dated April 11, 2018.

(j) Terminating Action for Certain Actions Required by Paragraph (h) of This AD

Accomplishment of an overhaul of an affected part after September 21, 2009, constitutes terminating action for the repetitive general visual inspections required by paragraph (h) of this AD for that affected part.

(k) Reporting

Submit a report of findings (both positive and negative) of the inspections specified in paragraph (h) of this AD to Airbus, in accordance with Airbus Service Bulletin A320-32-1461, dated April 11, 2018, at the applicable time specified in paragraph (k)(1) or (k)(2) of this AD. If operators have reported findings as part of obtaining any corrective actions approved by Airbus SAS's European Aviation Safety Agency (EASA) Design Organization Approval (DOA), operators are

not required to report those findings as specified in this paragraph.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(l) Exception to Paragraphs (h) and (i) of This AD

An airplane embodying Airbus Modification 161202 (Evolution (EV) MLG) is not affected by the requirements of paragraphs (h) and (i) of this AD, provided it is determined that no affected parts are installed on that airplane. A review of airplane delivery and/or maintenance records is acceptable to make this determination, provided those records can be relied upon for that purpose and the part number and serial

number of the MLG sliding tube can be positively identified from that review.

(m) Parts Installation

(1) For Group 1 airplanes: From the effective date of this AD, it is allowed to install on any airplane an affected part, or an MLG equipped with an affected part, provided that, within the last 500 flight cycles before installation, the part passed an inspection specified in paragraph (h) of this AD, and that, following installation, the part is inspected as required by this AD.

(2) For Group 2 airplanes: From the effective date of this AD, do not install on any airplane an affected part.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by The Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to

be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES 200.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0136, dated June 26, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0957.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on October 26, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-24390 Filed 11-7-18; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 86

[EPA-HQ-OAR-2017-0755; FRL-9986-20-OAR]

RIN 2060-AT75

Light-Duty Vehicle GHG Program Technical Amendments; Reopening of Comment Period

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule; reopening of comment period.

SUMMARY: EPA is announcing a reopening of the comment period for the proposed rule “Light-duty Vehicle GHG Program Technical Amendments,” to provide an additional 30 days for public comment. This document reopens the comment period and establishes a new comment period end date. This

additional opportunity to submit comments is provided in response to a request for such an extension and to allow the public additional time to comment on the proposed rule.

DATES: The comment period for the proposed rule, published on October 1, 2018 (83 FR 49344), is reopened. Written comments must be received on or before November 30, 2018, in order to be considered timely.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-HQ-OAR-2017-0755, at <http://www.regulations.gov>. Follow the online instructions for submitting comments. Once submitted, comments cannot be edited or removed from *Regulations.gov*. The EPA may publish any comment received to its public docket. Do not submit electronically any information you consider to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Multimedia submissions (audio, video, etc.) must be accompanied by a written comment. The written comment is considered the official comment and should include discussion of all points you wish to make. The EPA will generally not consider comments or comment contents located outside of the primary submission (*i.e.* on the web, cloud, or other file sharing system). For additional submission methods, the full EPA public comment policy, information about CBI or multimedia submissions, and general guidance on making effective comments, please visit <http://www2.epa.gov/dockets/commenting-epa-dockets>.

FOR FURTHER INFORMATION CONTACT: Christopher Lieske, Office of Transportation and Air Quality (OTAQ), Assessment and Standards Division (ASD), Environmental Protection Agency, 2000 Traverwood Drive, Ann Arbor, MI 48105; telephone number: (734) 214-4584; email address: lieske.christopher@epa.gov fax number: 734-214-4816.

SUPPLEMENTARY INFORMATION: In the EPA proposal “Light-duty Vehicle GHG Program Technical Amendments,” published in the **Federal Register** on October 1, 2018 (83 FR 49344), EPA requested comment on all aspects of the proposal. The initial comment period ended on October 31, 2018 (30 days after publication of the proposal in the **Federal Register**). EPA received a request from the Chesapeake Bay Foundation for a 30-day extension of the comment period based on its concern regarding the complexity of calculations involved in the proposal. The request can be found in the docket for the