

PART 330—DEPOSIT INSURANCE COVERAGE

■ 1. The authority citation for Part 330 continues to read as follows:

Authority: 12 U.S.C. 1813(l), 1813(m), 1817(i), 1818(q), 1819(a)(Tenth), 1820(f), 1820(g), 1821(a), 1821(d), 1822(c).

■ 2. Revise § 330.9(c) to read as follows:

§ 330.9 Joint ownership accounts.

* * * * *

(c) *Qualifying joint accounts.* (1) *Qualification requirements.* A joint deposit account shall be deemed to be a qualifying joint account, for purposes of this section, only if:

(i) All co-owners of the funds in the account are “natural persons” (as defined in § 330.1(l));

(ii) Each co-owner has personally signed, which may include signing electronically, a deposit account signature card; and

(iii) Each co-owner possesses withdrawal rights on the same basis.

(2) *Limited exceptions.* The signature-card requirement of paragraph (c)(1)(ii) of this section shall not apply to certificates of deposit, to any deposit obligation evidenced by a negotiable instrument, or to any account maintained by an agent, nominee, guardian, custodian, or conservator on behalf of two or more persons.

(3) *Evidence of deposit ownership.* All deposit accounts that satisfy the criteria in paragraph (c)(1) of this section, and those accounts that come within the exception provided for in paragraph (c)(2) of this section, shall be deemed to be jointly owned provided that, in accordance with the provisions of § 330.5(a), the FDIC determines that the deposit account records of the insured depository institution are clear and unambiguous as to the ownership of the accounts. If the deposit account records are ambiguous or unclear as to the manner in which the deposit accounts are owned, then the FDIC may, in its sole discretion, consider evidence other than the deposit account records of the insured depository institution for the purpose of establishing the manner in which the funds are owned. The signatures of two or more persons on the deposit account signature card or the names of two or more persons on a certificate of deposit or other deposit instrument shall be conclusive evidence that the account is a joint account (although not necessarily a qualifying joint account) unless the deposit records as a whole are ambiguous and some other evidence indicates, to the satisfaction of the FDIC, that there is a contrary ownership capacity.

(4) *Alternative method to satisfy signature-card requirement.* The signature-card requirement of paragraph (c)(1)(ii) of this section also may be satisfied by information contained in the deposit account records of the insured depository institution establishing co-ownership of the deposit account, such as evidence that the institution has issued a mechanism for accessing the account to each co-owner or evidence of usage of the deposit account by each co-owner.

* * * * *

By order of the Board of Directors of the Federal Deposit Insurance Corporation.

Dated at Washington, DC, on March 29, 2019.

Valerie Best,

Assistant Executive Secretary.

[FR Doc. 2019-06534 Filed 4-3-19; 8:45 am]

BILLING CODE 6714-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0189; Product Identifier 2019-NM-001-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model DHC-8-102, -103, and -106 airplanes; DHC-8-200 series airplanes; and DHC-8-300 series airplanes. This proposed AD was prompted by the reported loss of an elevator spring tab balance weight prior to takeoff. This proposed AD would require inspecting the two balance weights and the two hinge arms on each elevator spring tab, and corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by May 20, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations,

M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0189; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Andrea Jimenez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0189; Product Identifier 2019-NM-001-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2018-30, dated November 7, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model DHC-8-102, -103, and -106 airplanes; DHC-8-200 series airplanes; and DHC-8-300 series airplanes. The MCAI states:

One operator has reported the loss of an elevator spring tab balance weight prior to takeoff. An investigation found that clearances, due to tolerance stack-up between balance weight and hinge arm, allow the attachment bolts to fret with the hinge arm causing wear and potentially progressing to fracture and loss of the spring tab balance weight. The loss of a spring tab balance weight could result in unacceptable flutter margins and loss of the aeroplane.

This [Canadian] AD mandates a one-time [detailed] inspection to verify the spring tab balance weights are securely attached on both the left hand and right hand spring tab assemblies. If any of the balance weights are

found loose, instructions are given to repair any damage to the hinge arm, and to add a solid shim between balance weight and hinge arm to eliminate any potential gap, and to specify balance weight attachment hardware that has low susceptibility to hydrogen embrittlement.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0189.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin 8-55-27, Revision A, dated August 15, 2018. This service information describes procedures for inspecting the two balance weights and the two hinge arms on each elevator spring tab, and corrective actions including inspecting the holes in the hinge arm, inspecting the hinge arm for corrosion and chafing, installing bushings and a solid shim, replacing the hinge arm, repairing damage to the hinge arm, and permanently securing the mass balance.

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 47 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170	\$0	\$170	\$7,990

We estimate the following costs to do any necessary on-condition actions that would be required based on the results

of any required actions. We have no way of determining the number of aircraft

that might need these on-condition actions:

ESTIMATED COSTS FOR ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 18 work-hours × \$85 per hour = \$1,530	\$0	Up to \$1,530.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures

the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to

issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA–2019–0189; Product Identifier 2019–NM–001–AD.

(a) Comments Due Date

We must receive comments by May 20, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model DHC–8–102, –103, –106, –201, –202, –301, –311, and –315 airplanes, certificated in any category, serial numbers 003 through 672 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 55, Stabilizers.

(e) Reason

This AD was prompted by the reported loss of an elevator spring tab balance weight prior to takeoff. We are issuing this AD to address tolerance stack-up between the balance weight and the hinge arm that can allow the attachment bolts to fret with the hinge arm and result in wear, fracture, and loss of the spring tab balance weight. Loss of the spring tab balance weight can lead to unacceptable flutter margins and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Actions

Within 600 flight hours after the effective date of this AD, perform a detailed inspection of the two balance weights and a detailed inspection of the two hinge arms on each elevator spring tab (left hand and right hand), in accordance with Section 3.B, Part A, of the Accomplishment Instructions of Bombardier Service Bulletin 8–55–27, Revision A, dated August 15, 2018.

(1) If any of the balance weight attachment locknuts, part number (P/N) MS21042–4, is found fractured, loose, or missing: Before further flight conduct the rectification in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 8–55–27, Revision A, dated August 15, 2018.

(2) If the balance weight is found not secure: Within 60 flight hours after the inspection required by paragraph (g) of this AD, repair any damage to the hinge arm and permanently secure the mass balance, in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 8–55–27, Revision A, dated August 15, 2018.

(3) If the balance weight is found secure: Within 5,000 flight hours after the inspection required by paragraph (g) of this AD, repair any damage to the hinge arm and permanently secure the mass balance, in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 8–55–27, Revision A, dated August 15, 2018.

(4) Where Bombardier Service Bulletin 8–55–27, Revision A, dated August 15, 2018, specifies to contact Bombardier for appropriate action: Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (i)(2) of this AD.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g), (g)(2), (g)(3), and (g)(4) of this AD, if those actions were performed before the effective date of this AD using Section 3.B of the Accomplishment Instructions of Bombardier Service Bulletin 8–55–27, dated April 17, 2018, provided that within 600 flight hours after the effective date of this AD, a detailed visual inspection of the balance weight locknuts, P/N MS21042–4, is performed in accordance with Section 3.B, Part C, of the Accomplishment Instructions of Bombardier Service Bulletin 8–55–27, Revision A, dated August 15, 2018, and the rectification is performed before further flight for any fractured, loose, or missing balance weight attachment locknuts, P/N MS21042–4, in accordance with Section 3.B, Part B, of Bombardier Service Bulletin 8–55–27, Revision A dated August 15, 2018.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO

Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF–2018–30, dated November 7, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0189.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7330; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email thd.qseries@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on March 28, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–06458 Filed 4–3–19; 8:45 am]

BILLING CODE 4910–13–P

FEDERAL TRADE COMMISSION

16 CFR Part 313

RIN 3084–AB42

Privacy of Consumer Financial Information Rule Under the Gramm-Leach-Bliley Act

AGENCY: Federal Trade Commission.