

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2013-07-09 are approved as AMOCs for the corresponding provisions of this AD.

(l) Related Information

(1) For more information about this AD, contact Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3570; email: susan.l.monroe@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on June 12, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-13336 Filed 6-24-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-0482; Product Identifier 2019-NM-066-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A300 series airplanes; Airbus SAS Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Airbus SAS Model A310 series airplanes. This proposed AD was prompted by a report indicating that the trimmable horizontal stabilizer (THS) actuator ball nut trunnion lower attachment was missing parts. This proposed AD would require a one-time detailed inspection of the THS actuator right-hand spherical bearing and retaining parts (bolt, tab washer, and end cap) for correct installation of the retaining parts and correct bolt position, and applicable corrective actions, as specified in an European Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 9, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 1000; email: ADs@

easa.europa.eu; internet: www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <http://www.regulations.gov>.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0482; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3225.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0482; Product Identifier 2019-NM-066-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments, without change, to <http://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this NPRM.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0078, dated March 29, 2019 ("EASA AD 2019-0078") (also referred to as the Mandatory Continuing Airworthiness Information, or "the

MCAI’), to correct an unsafe condition for all Airbus SAS Model A300 series airplanes; Airbus SAS Model A300–600 series airplanes; and Airbus SAS Model A310 series airplanes. The MCAI states:

During maintenance on an A300–600 aeroplane, affected parts were found missing from THS actuator ball nut trunnion lower attachment. The THS actuator lower attachment has a fail-safe design through a primary and secondary load path, which ensures the load path continuity between the horizontal tail plane and the actuator. The primary load path is engaged thanks in particular to these affected parts.

Investigation results highlighted that human error is the most likely scenario to have caused the affected parts to have been missing. In flight, absence of affected parts would cause THS actuator secondary load path engagement, which is designed to withstand the full loads only for a limited period of time.

This condition, if not detected and corrected, could lead to THS actuator failure, possibly resulting in loss of control of the aeroplane.

To address this potential unsafe condition, Airbus issued the applicable SB [Airbus Service Bulletin A300–27–0206; Airbus Service Bulletin A300–27–6073; and Airbus Service Bulletin A310–27–2108] to provide inspection instructions.

For the reason described above, this [EASA] AD requires a one-time detailed inspection (DET) of the affected parts [for correct installation of the retaining parts and correct bolt position] to establish fleet-wide status and, depending on findings, accomplishment of applicable corrective action(s).

Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0078 describes procedures for a one-time detailed inspection of the THS actuator right-hand spherical bearing and retaining parts for correct installation of the retaining parts and correct bolt position, and applicable corrective actions. Corrective actions include torquing and securing the bolt with new lockwire, or installing new dowel, end cap, washer, bolt, and securing with new lockwire. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require accomplishing the actions specified in

EASA AD 2019–0078 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. As a result, EASA AD 2019–0078 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with the provisions specified in EASA AD 2019–0078, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information specified in EASA AD 2019–0078 that is required for compliance with EASA AD 2019–0078 will be available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0482 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this proposed AD affects 128 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170	\$0	\$170	\$21,760

The FAA estimates the following costs to do any necessary on-condition repairs that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition repairs:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
2 work-hours × \$85 per hour = \$170	*	\$170*

* The FAA has received no definitive data that would enable the agency to provide parts cost estimates for the on-condition repairs specified in this proposed AD.

The FAA has received no definitive data that would enable us to provide cost estimates for the other on-condition action specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section

44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus SAS: Docket No. FAA-2019-0482; Product Identifier 2019-NM-066-AD.

(a) Comments Due Date

The FAA must receive comments by August 9, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all the Airbus SAS airplanes identified in paragraphs (c)(1) through (c)(6) of this AD, certificated in any category.

- (1) Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.
- (2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.
- (3) Model A300 B4-605R and B4-622R airplanes.
- (4) Model A300 F4-605R and F4-622R airplanes.
- (5) Model A300 C4-605R Variant F airplanes.
- (6) Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by a report indicating that the trimmable horizontal stabilizer (THS) actuator ball nut trunnion lower attachment was missing the THS actuator right-hand spherical bearings and retaining parts (bolt, tab washer, and end cap). The FAA is issuing this AD to address missing THS actuator right-hand spherical bearings and retaining parts from the THS actuator ball nut trunnion lower attachment, which could lead to THS actuator failure, possibly resulting in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Aviation Safety Agency (EASA) AD 2019-0078, dated March 29, 2019 ("EASA AD 2019-0078").

(h) Exceptions to EASA AD 2019-0078

- (1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019-0078 refers to its effective date, this AD requires using the effective date of this AD.
- (2) The "Remarks" section of EASA AD 2019-0078 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019-0078 that contains RC procedures and tests: Except as required by paragraph (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) For information about EASA AD 2019-0078, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 6017; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0078 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0482.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3225.

Issued in Des Moines, Washington, on June 18, 2019.

Michael Kaszycki,

*Acting Manager, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2019-13332 Filed 6-24-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF VETERANS AFFAIRS

38 CFR Part 17

RIN 2900-AQ62

Health Professional Scholarship Program

AGENCY: Department of Veterans Affairs.

ACTION: Proposed rule.

SUMMARY: The Department of Veterans Affairs (VA) proposes to amend its regulations that govern the Health Professional Scholarship Program (HPSP). This rule would ensure that VA award not less than 50 HPSP scholarships each year to students who are accepted for enrollment or are enrolled in a program of education or training that leads to employment as a physician or dentist until such a date as VA determines the current staffing shortage is reduced. This rule would also expand the number of years of obligated service that a HPSP participant would have to serve in VA in the discipline for which the HPSP was awarded. This rulemaking would implement the mandates of the VA MISSION Act of 2018.

DATES: Comments must be received on or before August 26, 2019.

ADDRESSES: Written comments may be submitted through <http://www.Regulations.gov>; by mail or hand-delivery to: Director, Office of Regulation Policy and Management (00REG), Department of Veterans Affairs, 810 Vermont Ave. NW, Room 1064, Washington, DC 20420; or by fax to (202) 273-9026. (This is not a toll-free telephone number.) Comments should indicate that they are submitted in response to "RIN 2900-AQ62-Health Professional Scholarship Program." Copies of comments received will be available for public inspection in the Office of Regulation Policy and Management, Room 1064, between the hours of 8 a.m. and 4:30 p.m., Monday through Friday (except holidays). Please call (202) 461-4902 for an appointment. (This is not a toll-free telephone number.) In addition, during the comment period, comments may be viewed online through the Federal Docket Management System (FDMS) at <http://www.Regulations.gov>.

FOR FURTHER INFORMATION CONTACT:

Nicole Nedd, Director, Scholarships and Clinical Education, 1250 Poydras Street, Suite 1000 New Orleans, LA 70113. Nicole.Nedd@va.gov. (504) 507-4895 (This is not a toll-free number.)

SUPPLEMENTARY INFORMATION: On June 6, 2018, section 301 of Public Law 115-182, the John S. McCain III, Daniel K. Akaka, and Samuel R. Johnson VA Maintaining Internal Systems and Strengthening Integrated Outside Networks Act of 2018, or the VA MISSION Act of 2018, amended title 38 of the United States Code (U.S.C.) 7612(b) and 7617, which govern the Health Professional Scholarship Program (HPSP). This program is regulated under title 38 of the Code of Federal Regulations (CFR) 17.600 through 17.612. Section 7612(b) of 38 U.S.C. was amended to state that VA will ensure that not less than 50 HPSP scholarships are awarded each year to students who are accepted for enrollment or are enrolled in a program of education or training that leads to employment as a physician or dentist until such a date as VA determines that there is a staffing shortage of less than 500 individuals in these health care professions in VA. The VA MISSION Act of 2018 further amended section 7612(b) to state that once the staffing shortage is less than 500 health care professionals, VA will award HPSP scholarships each year to not less than 10 percent of the total staffing shortage of physicians and dentists. Section 7612 was also amended by expanding the number of years of obligated service that a participant who pursues a course of study leading to employment as a physician or dentist would have to serve in VA in a discipline for which the HPSP was awarded. Instead of one year of obligated service for each school year or part thereof for which the participant was awarded a scholarship, the VA MISSION Act of 2018 amended this requirement to 18 months of obligated service for each school or part thereof for which the participant was awarded a scholarship. The VA MISSION Act of 2018 also amended 38 U.S.C. 7617 by adding that a participant has breached the service agreement if the participant fails to successfully complete post-graduate training leading to eligibility for board certification for employment as a physician. This proposed rulemaking would implement the mandates of section 301 of the VA MISSION Act of 2018 by proposing to amend 38 CFR 17.603, 17.607, and 17.610 as further described below.

17.603 Availability of HPSP Scholarships

We would amend § 17.603(b) to comply with the requirements of section 301 of the VA MISSION Act of 2018 by establishing proposed paragraph (b)(1), which would state the new priorities for awarding the HPSP scholarship to physicians and dentists. Proposed paragraph (b)(1)(i) would state that VA would "award not less than 50 HPSP to individuals who are accepted for enrollment or are enrolled in a program of education or training leading to employment as a physician or dentist until such date as VA determines that the staffing shortage of physicians and dentists in VA is less than 500." In proposed paragraph (b)(1)(ii), we would state that once the staffing shortage of physicians and dentists is less than 500, "VA will award HPSP scholarships to individuals in an amount equal to not less than ten percent of the staffing shortage of physicians and dentists in VA."

Current paragraph (b) describes the qualifying fields of education for which VA will grant HPSP scholarships. We would add new paragraph (b)(2) which would restate current paragraph (b) with one edit to state that the requirements of this paragraph would apply to health care professions other than physicians or dentists.

17.607 Obligated Service

We propose to amend § 17.607(c)(1) by adding a new proposed paragraph (c)(1)(i) and renumbering current paragraph (c)(1) as proposed paragraph (c)(1)(ii). Proposed paragraph (c)(1)(i) would state the duration of the obligated service for physicians and dentists. This proposed paragraph would state that "a participant who attended school as a full-time student will agree to serve as a full-time physician or dentist in the Veterans Health Administration for 18 months for each school year or part thereof for which a scholarship was awarded. This proposed paragraph would be in accordance with section 301 of the VA MISSION Act of 2018.

Current paragraph (c)(1) describes the duration of service for full-time and part-time students. We would add new paragraph (c)(1)(ii) which would restate current paragraph (c)(1) with one edit to distinguish that this paragraph would apply to health care professions other than physicians or dentists.

17.610 Failure To Comply With Terms and Conditions of Participation

We would amend § 17.610 by adding a new proposed paragraph (b)(4), redesignating current paragraph (b)(4) as