

valve (OBV). The FAA is issuing this AD to prevent failure of the OBV. The unsafe condition, if not addressed, could result in engine fire and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For CF34-8C1, CF34-8C5, CF34-8C5A1, and CF34-8C5B1 model turbofan engines with serial numbers (S/Ns): 965101 through 965670 inclusive; 194101 through 194999 inclusive; and 195101 through 195653 inclusive:

(i) Perform an inspection of the OBV bleed air manifold link rod assemblies and the OBV fuel fittings within 500 flight hours after November 30, 2017 (effective date of AD 2017-23-06), or before next flight after the effective date of this AD, whichever occurs later.

(ii) Within 880 flight hours since the previous inspection, 500 flight hours from the effective date of this AD, or 6,880 flight hours since new, whichever occurs later, inspect the OBV bleed air manifold link rod assemblies, the OBV fuel fittings, and the OBV fuel tubes.

(iii) Thereafter, perform additional repeat inspections of the OBV bleed air manifold link rod assemblies, the OBV fuel fittings, and the OBV fuel tubes within every 880 flight hours since the previous inspection.

(iv) Use the Accomplishment Instructions, Paragraph 3.B., of GE CF34-8C-AL S/B 75-0020, R04, dated May 10, 2019 ("the SB"), to perform the inspections in paragraphs (g)(1)(i) through (iii) of this AD and, per the criteria for the results of inspections in Paragraph 3.B. of the SB, do the following:

(A) Replace any OBV or fuel tube that is leaking and tighten or replace any loose OBV fuel tube clamps with a part eligible for installation before further flight.

(B) Replace any worn OBV link rod assembly hardware within 50 flight cycles after the inspection required by paragraphs (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD. The engine can be returned to service each day for up to the 50 flight cycles if the OBV fittings are inspected each day for fuel leaks and looseness and, if they do not require removal based on the criteria in Table 1, "OBV Inspection," of GE SB CF34-8C-AL S/B 75-0020, R04, dated May 10, 2019.

(2) For CF34-8C5B1 model turbofan engines with S/Ns not listed in paragraph (g)(1) of this AD and for all CF34-8C5A2 and CF34-8C5A3 model turbofan engines, perform the following:

(i) For engines with 6,000 flight hours or more since new on the effective date of this AD, perform an initial inspection of the OBV bleed air manifold link rod assemblies, OBV fuel fittings, and OBV fuel tubes within 880 flight hours after the effective date of this AD.

(ii) For engines with less than 6,000 flight hours since new on the effective date of this AD, perform an initial inspection of the OBV bleed air manifold link rod assemblies, OBV fuel fittings, and OBV fuel tubes within 880 flight hours time in service or 6,880 flight hours since new, whichever occurs later.

(iii) Thereafter, repeat the inspection of the OBV bleed air manifold link rod assemblies, OBV fuel fittings, and OBV fuel tubes within 880 flight hours since the last inspection.

(iv) Use the Accomplishment Instructions, Paragraph 3.B., of GE CF34-8C-AL S/B 75-0020, R04, dated May 10, 2019, to perform the inspections in paragraphs (g)(2)(i) through (iii) of this AD.

(v) Replace any parts according to the criteria in paragraph (g)(1)(iv) of this AD after the inspection required by paragraphs (g)(2)(i), (g)(2)(ii), or (g)(2)(iii) of this AD.

(3) For all affected engines, the reporting instructions in GE SB CF34-8C-AL S/B 75-0020, R04, dated May 10, 2019, are not required by this AD.

(h) Credit for Previous Actions

(1) For engines identified in paragraph (g)(1) of this AD, you may take credit for the inspection of the OBV bleed air manifold link rod assemblies and the OBV fuel fittings required by paragraph (g)(1)(i) of this AD if you performed this inspection before November 30, 2017 (the effective date of AD 2017-23-06) using GE SB CF34-8C SB 75-0019, Revision 01, dated October 24, 2017, or R00, dated August 4, 2017;

(2) For all affected engines, you may take credit for the inspection of the OBV bleed air manifold link rod assemblies and the OBV fuel fittings required by paragraph (g)(1)(i) or (g)(2)(i) of this AD if you performed this inspection before the effective date of this AD using GE SB CF34-8C SB 75-0020, Revision 03, dated December 14, 2018.

(3) You are still required to perform the repeat inspections and any replacements, as needed, required by paragraphs (g)(1)(ii) through (g)(1)(iv) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Michael Richardson-Bach, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7747; fax: 781-238-7199; email: michael.richardson-bach@faa.gov.

(2) For service information identified in this AD, contact General Electric Company, GE-Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215, phone: 513-552-3272; fax: 513-552-3329; email: geae.aoc@ge.com. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington,

MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on June 24, 2019.

Robert J. Ganley,

Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2019-13761 Filed 6-27-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0438; Product Identifier 2019-NM-033-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 757 airplanes. This proposed AD was prompted by a report that during a maintenance check an operator discovered cracking in the station 1460 frame web and inner chord between certain stringers. This proposed AD would require an inspection of the fuselage frames for any existing repair, repetitive surface high frequency eddy current (HFEC) inspections of the fuselage frames with a cargo liner support channel for any cracking, and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 12, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial

Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0438.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0438; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5234; fax: 562-627-5210; email: peter.jarzomb@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0438; Product Identifier 2019-NM-033-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments, without change, to <http://www.regulations.gov>, including any personal information you provide. The

FAA will also post a report summarizing each substantive verbal contact the agency receives about this proposed AD.

Discussion

The FAA has received a report indicating that an operator found cracking of the aft cargo compartment frames in the station 1460 frame web and inner chord between stringers S-26 and S-27 near an existing repair. The crack initiated at the fastener hole common to the cargo liner support channel, and was found near an existing structural repair manual (SRM) repair. Primer was discovered in the crack, indicating that the crack already existed at the time the SRM repair was installed. The crack was discovered at 82,227 total flight hours and 37,450 total flight cycles, and was the result of fatigue caused by cyclic pressurization of the fuselage and flight loads. This condition, if not addressed, could allow cracks to propagate until they cause a severed frame, which could result in additional undetected cracking in adjacent fuselage frames, and could ultimately result in reduced structural integrity of the aft cargo frames and consequent rapid decompression of the airplane.

Related Service Information Under 1 CFR Part 15

The FAA reviewed Boeing Alert Requirements Bulletin 757-53A0113 RB, dated February 22, 2019. The service information describes procedures for a general visual inspection of the fuselage frames with a cargo liner support channel for any existing repair, repetitive surface HFEC inspections of the fuselage frames with a cargo liner support channel for any cracking, and applicable on-condition actions. On-condition actions include a general visual inspection of the fuselage frames adjacent to the frame with a severed inner chord for any existing repair, a detailed inspection and a surface HFEC inspection of the fuselage frames adjacent to a frame with a severed inner chord for any cracking, and repair.

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified in Boeing Alert Requirements Bulletin 757-53A0113 RB, dated February 22, 2019, described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0438.

Explanation of Requirements Bulletin

The FAA worked in conjunction with industry, under the Airworthiness Directive Implementation Aviation Rulemaking Committee (AD ARC), to enhance the AD system. One enhancement is a process for annotating which steps in the service information are "required for compliance" (RC) with an AD. Boeing has implemented this RC concept into Boeing service bulletins.

In an effort to further improve the quality of ADs and AD-related Boeing service information, a joint process improvement initiative was worked between the FAA and Boeing. The initiative resulted in the development of a new process in which the service information more clearly identifies the actions needed to address the unsafe condition in the "Accomplishment Instructions." The new process results in a Boeing Requirements Bulletin, which contains only the actions needed to address the unsafe condition (*i.e.*, only the RC actions).

Costs of Compliance

The FAA estimates that this proposed AD affects 544 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
General visual inspection.	37 work-hours × \$85 per hour = \$3,145	\$0	\$3,145	\$1,710,880.

ESTIMATED COSTS FOR REQUIRED ACTIONS—Continued

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Repetitive surface HFEC inspections.	Up to 37 work-hours × \$85 per hour = Up to \$3,145 per inspection cycle.	0	Up to \$3,145 per inspection cycle.	Up to \$1,710,880 per inspection cycle.

The FAA estimates the following costs to do any necessary on-condition inspections that would be required. The FAA has no way of determining the number of aircraft that might need these on-condition inspections:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 20 work-hour × \$85 per hour = Up to \$1,700 per inspection cycle	\$0	Up to \$1,700 per inspection cycle.

The FAA has received no definitive data that would enable us to provide cost estimates for the on-condition repair specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the

national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2019–0438; Product Identifier 2019–NM–033–AD.

(a) Comments Due Date

The FAA must receive comments by August 12, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 757–200, –200PF, –200CB,

and –300 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a report that during a maintenance check an operator discovered cracking of the aft cargo compartment frames in the station 1460 frame web and inner chord between certain stringers. The FAA is issuing this AD to address cracking at the frame web and inner chord; such cracks could propagate until they cause a severed frame, which could result in additional undetected cracking in adjacent fuselage frames, and could ultimately result in reduced structural integrity of the aft cargo frames and consequent rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757–53A0113 RB, dated February 22, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757–53A0113 RB, dated February 22, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757–53A0113, dated February 22, 2019, which is referred to in Boeing Alert Requirements Bulletin 757–53A0113 RB, dated February 22, 2019.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 757–53A0113 RB, dated February 22, 2019, uses the phrase “the original issue date of Requirements Bulletin 757–53A0113 RB,” this AD requires using “the effective date of this AD,” except where Boeing Alert Requirements Bulletin 757–53A0113 RB,

dated February 22, 2019, uses the phrase “the original issue date of Requirements Bulletin 757–53A0113 RB” in a note or flag note.

(2) Where Boeing Alert Requirements Bulletin 757–53A0113 RB, dated February 22, 2019, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5234; fax: 562–627–5210; email: peter.jarzomb@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on June 12, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–13672 Filed 6–27–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 91

[Docket No.: FAA–2019–0451; Notice No. 19–08]

RIN 2120–AL30

Special Flight Authorizations for Supersonic Aircraft

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: Current regulations prohibit overland supersonic civil flights in the United States, but include a procedure to request authorization for these flights for the purposes of test and development of new aircraft. The criteria for such authorizations were developed in the 1970s and placed in an appendix to the operating regulations. With renewed interest in supersonic aircraft development, the FAA is proposing to modernize the procedure for requesting these special flight authorizations.

DATES: Send comments on or before August 27, 2019.

ADDRESSES: Send comments identified by docket number FAA–2019–0451 using any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the online instructions for sending your comments electronically.
- *Mail:* Send comments to Docket Operations, M–30; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* Fax comments to Docket Operations at 202–493–2251.

Privacy: In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to <http://www.regulations.gov>, as described in the system of records notice (DOT/ALL–14 FDMS), which can be reviewed at <http://www.dot.gov/privacy>.

Docket: Background documents or comments received may be read at

<http://www.regulations.gov> at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

Mehmet Marsan, Office of Environment and Energy, AEE–100, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone (202) 267–7703; email mehmet.marsan@faa.gov.

SUPPLEMENTARY INFORMATION:

I. Executive Summary

Civil aircraft may not operate in the United States in excess of Mach 1 except in accordance with an authorization issued by the FAA. Currently, the application requirements for an authorization are found in appendix B to 14 CFR part 91, Authorizations to exceed Mach 1 (§ 91.817). The FAA is proposing to streamline the application procedure for these special flight authorizations by clarifying the information that needs to be submitted and specifying the contact office within the FAA. This proposed rule sets forth those application criteria in a more user-friendly format.

In this proposed rule, the FAA has identified three areas to improve provisions that are currently appendix B. The first designates to which office in the agency applicants should send applications and direct questions. The second gathers the scattered application requirements into a list, and presents them in current regulatory format. As part of this effort, the FAA is correcting the language to be consistent throughout the new section. Third, the agency is proposing the addition of a new reason for flight testing to accommodate future noise certification actions.

This proposal removes the application criteria and procedure from an appendix and places it in regulatory text¹ in accordance with current regulatory format. This modernization of the authorization process for certain civil supersonic flights is intended to simplify and clarify the process for applicants interested in the authorization process.

Finally, while not proposed as a change, the FAA is requesting comment on whether a regulatory provision that has yet to be used should be removed.

¹ The material in appendix B was originally proposed as part of § 91.55 (now § 91.817) but was moved to an appendix at the suggestion of a commenter.