

(b) Affected ADs

This AD replaces AD 2017–12–07, Amendment 39–18922 (82 FR 27416, June 15, 2017).

(c) Applicability

This AD applies to all The Boeing Company Model 737–800, –900, and –900ER series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 21, Air conditioning.

(e) Unsafe Condition

This AD was prompted by reports of in-flight failure of the left temperature control valve and control cabin trim air modulating valve. The FAA is issuing this AD to address the possible occurrence of temperatures in excess of 100 degrees Fahrenheit in the flight deck or the passenger cabin during cruise, which could lead to the impairment of the flightcrew and prevent continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Valve Replacement, With Revised Compliance Language

This paragraph restates the requirements of paragraph (g) of AD 2017–12–07 with revised compliance language. For airplanes identified in Boeing Alert Service Bulletin 737–21A1203, dated June 8, 2016: Within 60 months after July 20, 2017 (the effective date of AD 2017–12–07), replace the left temperature control valve and control cabin trim air modulating valve, as applicable, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–21A1203, dated June 8, 2016.

(h) New Valve Identification and Replacement

For airplanes not identified in paragraph (g) of this AD with an original certificate of airworthiness or an original export certificate of airworthiness dated on or before the effective date of this AD, do the actions specified in paragraphs (h)(1) and (h)(2) of this AD.

(1) Within 60 months after the effective date of this AD, perform a general visual inspection of the left temperature control valve and control cabin trim air modulating valve to determine the valve part numbers. A review of airplane maintenance records is acceptable in lieu of this inspection if the part numbers of the valves can be conclusively determined from that review.

(2) If the left temperature control valve or control cabin trim air modulating valve has part number 398908–4: Within 60 months after the effective date of this AD, replace the left temperature control valve or control cabin trim air modulating valve in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–21A1203, dated June 8, 2016.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install a valve having part

number 398908–4, in either the left temperature control valve location or the control cabin trim air modulating valve location on any airplane.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Julie Moon, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3571; email: julie.moon@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South

216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on June 24, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–14284 Filed 7–5–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2019–0487; Product Identifier 2019–NM–044–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes. This proposed AD was prompted by a report of a fuel leak resulting from a crack on the left in-spar upper wing skin. This proposed AD would require repetitive surface high frequency eddy current (HFEC) inspections of the left and right upper wing skin, and repetitive general visual inspections of the upper wing skin in the adjacent rib bay areas for any crack, and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 22, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0487.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0487; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Payman Soltani, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5313; fax: 562-627-5210; email: payman.soltani@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0487; Product Identifier 2019-NM-044-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of

this NPRM. The agency will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments, without change, to <http://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this proposed AD.

Discussion

The FAA has received an operator report of a fuel leak resulting from a crack on the left in-spar upper wing skin. The crack was found at wing buttock line 157, between stringer 4 and stringer 5 and measured approximately 2.5 inches in length. The crack was caused by higher local stress than predicted, possibly attributable to fit-up issues from the rib installation. This condition, if not addressed, could result in a crack in the upper wing skin growing undetected, which could result in the inability of the structure to carry limit load and adversely affect the structural integrity of the airplane.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 737-57A1344 RB, dated February 18, 2019. The service information describes procedures for repetitive surface HFEC inspections of the left and right upper wing skin at wing buttock line 157, between stringer 4 and stringer 5, and repetitive general visual inspections of the upper wing skin in the adjacent rib bay areas for any crack, and applicable on-condition actions. On-condition actions include repair.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

The FAA is proposing this AD because the agency evaluated all the

relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified in Boeing Alert Requirements Bulletin 737-57A1344 RB, dated February 18, 2019, described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0487.

Explanation of Requirements Bulletin

The FAA worked in conjunction with industry, under the Airworthiness Directive Implementation Aviation Rulemaking Committee (AD ARC), to enhance the AD system. One enhancement is a process for annotating which steps in the service information are "required for compliance" (RC) with an AD. Boeing has implemented this RC concept into Boeing service bulletins.

In an effort to further improve the quality of ADs and AD-related Boeing service information, a joint process improvement initiative was worked between the FAA and Boeing. The initiative resulted in the development of a new process in which the service information more clearly identifies the actions needed to address the unsafe condition in the "Accomplishment Instructions." The new process results in a Boeing Requirements Bulletin, which contains only the actions needed to address the unsafe condition (*i.e.*, only the RC actions).

Costs of Compliance

The FAA estimates that this proposed AD affects 160 airplanes of U.S. registry. The agency estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
HFEC Inspection and General Visual Inspection.	1 work-hour × \$85 per hour = \$85 per inspection cycle.	\$0	\$85 per inspection cycle.	\$13,600 per inspection cycle.

The FAA has received no definitive data that would enable the agency to provide cost estimates for the on-

condition repair specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2019–0487; Product Identifier 2019–NM–044–AD.

(a) Comments Due Date

The FAA must receive comments by August 22, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of a fuel leak resulting from a crack on the left in-spar upper wing skin. The FAA is issuing this AD to address cracks in the upper wing skin, which could grow undetected. This condition, if not addressed, could result in the inability of the structure to carry limit load and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions for Group 1 Airplanes

For airplanes identified as Group 1 in Boeing Alert Requirements Bulletin 737–57A1344 RB, dated February 18, 2019: Within 120 days after the effective date of this AD, do a surface high frequency eddy current (HFEC) inspection of the left and right upper wing skin and a general visual inspection of the upper wing skin in the adjacent rib bay areas for any crack, and do applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Required Actions for Groups 2 and 3 Airplanes

Except as specified by paragraph (i) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–57A1344 RB, dated February 18, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–57A1344 RB, dated February 18, 2019.

Note 1 to paragraph (h): Guidance for accomplishing the actions required by this

AD can be found in Boeing Alert Service Bulletin 737–57A1344, dated February 18, 2019, which is referred to in Boeing Alert Requirements Bulletin 737–57A1344 RB, dated February 18, 2019.

(i) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 737–57A1344 RB, dated February 18, 2019, uses the phrase "the original issue date of Requirements Bulletin 737–57A1344 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 737–57A1344 RB, dated February 18, 2019, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any inspection, repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the inspection, repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Payman Soltani, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5313; fax: 562–627–5210; email: payman.soltani@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on June 24, 2019.

Dionne Palermo,

*Acting Director, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2019-14285 Filed 7-5-19; 8:45 am]

BILLING CODE 4910-13-P

CONSUMER PRODUCT SAFETY COMMISSION

16 CFR Parts 1112 and 1239

[Docket No. CPSC-2019-0014]

Safety Standard for Gates and Enclosures

AGENCY: Consumer Product Safety Commission.

ACTION: Proposed rule.

SUMMARY: The Consumer Product Safety Improvement Act of 2008 (CPSIA) requires the United States Consumer Product Safety Commission (Commission or CPSC) to promulgate consumer product safety standards for durable infant or toddler products. Accordingly, the Commission is proposing a safety standard for gates and enclosures in response to the direction under Section 104(b) of the CPSIA. The Commission is also amending its regulations regarding third party conformity assessment bodies to include the safety standard for gates and enclosures in the list of notice of requirements (NORs) issued by the Commission.

DATES: Submit comments by September 23, 2019.

ADDRESSES: Comments related to the Paperwork Reduction Act aspects of the marking, labeling, and instructional literature of the proposed rule should be directed to the Office of Information and Regulatory Affairs, OMB, Attn: CPSC Desk Officer, FAX: 202-395-6974, or emailed to oir_submission@omb.eop.gov.

Other comments, identified by Docket No. CPSC-2019-0014, may be submitted electronically or in writing:

Electronic Submissions: Submit electronic comments to the Federal eRulemaking Portal at: <http://www.regulations.gov>. Follow the instructions for submitting comments. The CPSC does not accept comments submitted by electronic mail (email), except through www.regulations.gov. The CPSC encourages you to submit electronic comments by using the Federal eRulemaking Portal, as described above.

Written Submissions: Submit written submissions in the following way: Mail/

Hand delivery/Courier (for paper, disk, or CD-ROM submissions), preferably in five copies, to: Division of the Secretariat, Consumer Product Safety Commission, Room 820, 4330 East West Highway, Bethesda, MD 20814; telephone (301) 504-7923.

Instructions: All submissions received must include the agency name and docket number for this proposed rulemaking. All comments received may be posted without change, including any personal identifiers, contact information, or other personal information provided, to: <http://www.regulations.gov>. Do not submit confidential business information, trade secret information, or other sensitive or protected information that you do not want to be available to the public. If furnished at all, such information should be submitted in writing.

Docket: For access to the docket to read background documents or comments received, go to: <http://www.regulations.gov>, and insert the docket number, CPSC-2019-0014, into the "Search" box, and follow the prompts.

FOR FURTHER INFORMATION CONTACT:

Hope Nesteruk, Project Manager, Directorate for Engineering Sciences, Consumer Product Safety Commission, 5 Research Place, Rockville, MD 20850; telephone: 301-987-2579; email: hnesteruk@cpsc.gov.

SUPPLEMENTARY INFORMATION:

I. Background and Statutory Authority

Section 104(b) of the CPSIA, part of the Danny Keysar Child Product Safety Notification Act, requires the Commission to: (1) examine and assess the effectiveness of voluntary consumer product safety standards for durable infant or toddler products, in consultation with representatives of consumer groups, juvenile product manufacturers, and independent child product engineers and experts; and (2) promulgate consumer product safety standards for durable infant and toddler products. These standards are to be "substantially the same as" the applicable voluntary standards or more stringent than the voluntary standard if the Commission concludes that more stringent requirements would further reduce the risk of injury associated with the product. The term "durable infant or toddler product" is defined in section 104(f)(1) of the CPSIA as "a durable product intended for use, or that may be reasonably expected to be used, by children under the age of 5 years." "Gates and other enclosures for confining a child" are specifically identified in section 104(f)(2)(G) of the

CPSIA as a durable infant or toddler product.

Pursuant to Section 104(b)(1)(A), the Commission consulted with manufacturers, retailers, trade organizations, laboratories, consumer advocacy groups, consultants, and members of the public in the development of this proposed standard, largely through the ASTM process. The proposed rule is based on the voluntary standard developed by ASTM International, ASTM F1004-19, *Standard Consumer Safety Specification for Expansion Gates and Expandable Enclosures* (ASTM F1004-19). The ASTM standard is copyrighted, but it can be viewed as a read-only document during the comment period at: <https://www.astm.org/CPSC.htm>, by permission of ASTM.

II. Product Description

A. Definition of "Gates and Other Enclosures"

ASTM F1004-19 defines an "expansion gate" as a "barrier intended to be erected in an opening, such as a doorway, to prevent the passage of young children, but which can be removed by older persons who are able to operate the locking mechanism" (section 3.1.7). ASTM F1004-19 defines an "expandable enclosure" as a "self-supporting barrier intended to completely surround an area or play-space within which a young child may be confined" (section 3.1.6). These products are intended for young children aged 6 months through 24 months (section 1.2).

Although the title of the ASTM F1004-19 standard and its definitions include the word "expansion" and "expandable" before the words "gate" and "enclosure," respectively, the scope of the ASTM F1004-19 standard includes all children's gates and enclosures, whether they expand or not. ASTM F1004-19 covers: "[p]roducts known as expansion gates and expandable enclosures, or by any other name," (section 1.2, emphasis added).¹ Both expandable gates and non-expandable gates may serve as barriers that are intended to be erected in an opening, such as a doorway, to prevent the passage of young children. Both expandable enclosures and non-expandable enclosures may serve as barriers intended to completely surround an area or play-space to confine young children. Similarly, all children's gates and enclosures, whether

¹ Gates or enclosures for non-domestic use (such as commercial or industrial), and those intended for pets only, are not covered under the scope of ASTM F1004-19.