

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–15–02 Airbus SAS: Amendment 39–19695; Docket No. FAA–2019–0577; Product Identifier 2019–NM–119–AD.

(a) Effective Date

This AD becomes effective September 6, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A321–251N, A321–252N, A321–253N, A321–271N, A321–272N, A321–251NX, A321–252NX, A321–253NX, A321–271NX, and A321–272NX airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by analysis of the behavior of the elevator aileron computer (ELAC) L102 that revealed that excessive pitch attitude can occur in certain conditions and during specific maneuvers. The FAA is issuing this AD to address this excessive pitch attitude, which could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0171, dated July 17, 2019 (“EASA AD 2019–0171”).

(h) Exceptions to EASA AD 2019–0171

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019–0171 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019–0171 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA,

has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019–0171 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019–0171, dated July 17, 2019.

(ii) [Reserved]

(3) For EASA AD 2019–0171, contact the EASA, at Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

EASA AD 2019–0171 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0577.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 26, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–17978 Filed 8–21–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0018; Product Identifier 2018–NM–116–AD; Amendment 39–19681; AD 2019–14–03]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2016–07–12, which applied to certain Airbus SAS Model A318, A319, A320, and A321 series airplanes. AD 2016–07–12 required repetitive inspections for damage and cracking of the aft fixed fairing (AFF) of the pylons, and repair if necessary. This AD retains the requirements of AD 2016–07–12 and requires additional repetitive inspections at the upper spar at a certain rib area and corrective actions if necessary, as specified in an European Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD was prompted by reports of cracking of the AFF of the pylons due to fatigue damage of the structure and reports of cracks on a certain rib of a modified AFF of the pylons. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective September 26, 2019.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 26, 2019.

ADDRESSES: For the material incorporated by reference (IBR) in this

AD, contact the EASA, at Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0018.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0018; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2016-07-12, Amendment 39-18457 (81 FR 19482, April 5, 2016) (“AD 2016-07-12”). AD 2016-07-12 applied to certain Airbus SAS Model A318, A319, A320, and A321 series airplanes. The NPRM published in the **Federal Register** on February 22, 2019 (84 FR 5617). The NPRM was prompted by reports of cracking of the AFF of the pylons due to fatigue damage of the structure and reports of cracks on a certain rib of a modified AFF of the pylons. The NPRM proposed to continue to require repetitive inspections for damage and cracking of the AFF of the pylons. The NPRM also proposed to require additional repetitive inspections at the upper spar at a certain rib area and corrective actions if necessary. The FAA is issuing this AD to address damage and cracking of the AFF of the pylons,

which could result in detachment of a pylon and consequent reduced structural integrity of the airplane.

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0137R1, dated January 9, 2019 (“EASA AD 2018-0137R1”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A318-111, and -112; Model A319-111, -112, -113, -114, and -115; Model A320-211, -212, -214, and -216; and Model A321-111, -112, -211, -212, and -213 airplanes. The MCAI states:

On aeroplanes equipped with post-mod 33844 CFM pylons, several operators reported finding cracks on the Aft Fixed Fairing (AFF). After material analysis, it appeared that the pylon AFF structure, especially on this configuration, was subject to fatigue-induced damage which could lead to pylon AFF cracks.

This condition, if not detected and corrected, could lead to detachment of a pylon AFF from the aeroplane, possibly resulting in injury to persons on the ground.

To address this unsafe condition, Airbus published Alert Operators Transmission (AOT) A54N002-12, providing inspection instructions. Thereafter, Airbus issued Service Bulletin (SB) A320-54-1027, later revised, superseding AOT A54N002-12. EASA issued AD 2014-0154 [which corresponds to FAA AD 2016-07-12] to require repetitive inspections of the pylon AFF and, depending on findings, replacement.

After that [EASA] AD was issued, Airbus developed mod 156593 to increase the fatigue life of the pylon AFF structure by using a different material and introducing thermal treatment of the aluminium sheets parts. Prompted by new findings of cracks on rib 15, it was determined that this area also needs to be inspected to ensure the structural integrity of the new pylon AFF. Airbus revised SB A320-54-1027, including instructions for repetitive inspection of that area. Repetitive inspections are also required on post-mod 156593 aeroplanes.

Airbus also developed mod 159806 and 156765, redesigning the corner fittings at the junction upper spar and rib 15, which constitutes terminating action for the repetitive inspections. For retrofit purposes, Airbus issued SB A320-54-1035 and SB A320-54-1036, later revised, providing instructions to modify and re-identify the pylon AFF, which constitutes terminating action for the repetitive inspections.

For the reasons described above, EASA issued AD 2018-0137 [which was referred to as the appropriate source of service information for accomplishing the actions specified in the FAA NPRM], retaining the requirements of EASA AD 2014-0154, which was superseded, and requiring repetitive inspections of the upper spar at rib 15 area and, depending on findings, accomplishment of applicable corrective action(s). This [EASA] AD also included references to

optional terminating actions, and provided installation requirements for the new pylon AFF.

Since that [EASA] AD was issued, comments and requests for clarification have been received from operators. This [EASA] AD is revised, merging the restatement of requirements of AD 2014-0154 with the new requirements.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0018.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Support for the NPRM

Commenters Delta Air Lines (DAL), Jeff Hymen, and Megan Neeley indicated their support for the NPRM.

Request To Reference the Latest EASA AD

Alaska Airlines (Alaska) and DAL requested that the FAA refer to EASA AD 2018-0137R1 in lieu of EASA AD 2018-0137, dated July 12, 2018 (“EASA AD 2018-0137”). Alaska requested revision of paragraphs (c) and (g) of the proposed AD to cite EASA AD 2018-0137R1.

The FAA agrees with the commenters’ requests. No additional work is required for airplanes on which the requirements of EASA AD 2018-0137, dated June 28, 2018 (“EASA AD 2018-0137”), have been accomplished. The FAA has revised paragraphs (c) and (g) of this AD to cite EASA AD 2018-0137R1 in addition to EASA AD 2018-0137. The FAA has also revised paragraph (h)(1)(i) of this AD to require the use of the effective date of this AD rather than the effective date of EASA 2018-0137 (July 12, 2018), as referenced in EASA ADs 2018-0137 and 2018-0137R1, to determine compliance.

Request To Remove Paragraph (h)(4) of the Proposed AD

DAL requested that paragraph (h)(4) of the proposed AD be removed, which did not allow for the provisions of paragraph (5) of EASA AD 2018-0137 (credit for actions done using certain service information). DAL argued that if the provisions of paragraph (5) of EASA AD 2018-0137R1 are disallowed, the result would be a requirement that is more restrictive to U.S. operators. DAL further noted that disallowing paragraph (5) of EASA AD 2018-0137R1, which allows credit for initial inspections

using additional revisions of certain service information, would mean the initial inspections would have to be accomplished faster and may require special scheduled inspections, which often results in utilizing less experienced mechanics. DAL requested that the AD specify which revision of the EASA AD will be allowed. Accordingly, DAL requests that, if this AD is updated to reflect EASA AD 2018-0137R1, that paragraph (h)(4) of this AD be removed.

The FAA agrees with the request for the reasons provided. Also note that paragraph (5) of EASA AD 2018-0137R1 adds credit for initial inspections performed in accordance with Airbus Service Bulletin A320-54-1027, dated April 10, 2014; and Airbus Service Bulletin A320-54-1027, Revision 1, dated January 14, 2015; which were not included in paragraph (5) of EASA AD 2018-0137. Paragraph (h)(4) of the proposed AD is removed and paragraphs (h)(5) and (h)(6) of the proposed AD are redesignated as paragraphs (h)(4) and (h)(5) of this AD to reflect this request.

Request To Allow Re-Installation of an Affected Part Under Certain Circumstances

DAL requested that the AD allow for the re-installation of an affected AFF if it was removed for reasons other than meeting the requirement of the AD, such as routine maintenance. DAL pointed out that an affected AFF may need to be removed for access to perform either unrelated maintenance or for compliance with certain service information referenced in EASA ADs 2018-0137 and 2018-0137R1. DAL's interpretation of the "do not install" language in paragraph (11) of EASA AD 2018-0137 led it to believe that operators would struggle to comply with the instructions as written, and recommended that the FAA add a statement that would allow the re-installation of an AFF that was removed from the airplane for the purpose of maintenance or inspections.

The FAA agrees to clarify. Group 1 airplanes, as specified in EASA ADs 2018-0137 and 2018-0137R1, are those that, as of the effective date of this AD, have an affected AFF installed. The intent of paragraph (11.1) of EASA ADs 2018-0137 and 2018-0137R1 is to prevent an affected AFF from being re-installed on a Group 1 airplane only if the modification specified in paragraph (9) or (10) of EASA AD 2018-0137 or EASA AD 2018-0137R1 has already been accomplished on that airplane. An operator has the full compliance time to accomplish the modification, and, up

until the modification is accomplished, an affected AFF may be re-installed for reasons such as routine maintenance.

Group 2 airplanes, as specified in EASA ADs 2018-0137 and 2018-0137R1, are those airplanes that, as of the effective date of this AD, do not have an affected AFF installed. For Group 2 airplanes, the intent of paragraph (11.2) of EASA ADs 2018-0137 and 2018-0137R1 is to prevent an affected AFF from being installed on an airplane on which an affected AFF was not already installed as of the effective date of this AD. The AD has not been changed in this regard.

Request To Use Later Approved Revisions of Service Information

DAL pointed out that the reference publications section of EASA ADs 2018-0137 and 2018-0137R1 allows the use of later-approved revisions to the specified service information for compliance. DAL requested clarification to determine if this statement is applicable to this AD.

The AD does not exclude the "Ref. Publications" section of EASA ADs 2018-0137 and 2018-0137R1, so that section is applicable to this AD. The AD has not been changed in this regard.

Request To Add Exceptions for Alternative Methods of Compliance

DAL requested that the proposed AD be revised to add an exception that allows the use of consumable material list (CML) 10ABE1, "touch up alodine," in addition to CML 10ABC1, "tank alodine." DAL noted that while Airbus commonly specifies tank alodine, DAL prefers to use touch up alodine. DAL explained that they contacted Airbus on this issue and Airbus confirmed that touch up alodine can be used instead of tank alodine for the embodiment of Airbus Service Bulletin A320-54-1027; Airbus Service Bulletin A320-54-1035; and Airbus Service Bulletin A320-54-1036.

DAL claimed that Airbus Service Bulletin A320-54-1027 and Airbus Service Bulletin A320-54-1035 state that all steps in the Procedure and Test sections are required for compliance (RC). DAL also maintained that some of those steps are corrosion prevention control program (CPCP) controlled tasks. Because corrosion inhibition compound (CIC) is part of CPCP, DAL argued that application of CIC should be managed by each individual operator regardless of the AD requirement. As a result, DAL requested language added to the proposed AD that allows for operators to control the reapplication of CICs as an alternative to the service information specifications.

DAL also noted that the "Preparation" section of the service information referenced in EASA ADs 2018-0137 and 2018-0137R1 contains references to a certain aircraft maintenance manual (AMM) section for basic aircraft configuration. The basic aircraft configuration of the AMM states that the aircraft is in the "weight on wheels" configuration. DAL noted that sometimes their airplanes are on jacks and that having the airplane in a weight on wheels configuration may limit the ability of their maintenance technicians to perform the required actions. DAL requested an exception to the proposed AD that allows for the required actions to be performed with either weight on wheels or while the aircraft is in a jacked configuration.

The FAA agrees with the request to add an exception that allows the use of CML 10ABE1, touch up alodine for the reasons provided. This AD has been revised to change the content of paragraph (h)(6) of this AD to state that where any service information referenced in EASA ADs 2018-0137 and 2018-0137R1 specifies to use CML material number 10ABC1, this AD allows the use of CML material number 10ABE1 as an additional method of compliance.

The FAA disagrees with the request to add language to the proposed AD that allows for operators to control the reapplication of CICs via CPCP because not all U.S. operators have a standardized CPCP. If DAL cannot follow the CIC specified by Airbus in the service information, then they can reference the Airbus CML for an alternative CIC. Airbus's CML document contains a list of the latest consumables and alternatives that can be used. Operators may apply for an alternative method of compliance (AMOC) using the procedures in paragraph (j)(1) of this AD for using alternate consumables allowed in the CML with appropriate substantiations. The AD has not been changed in this regard.

The FAA agrees to clarify regarding the request for airplanes in a jacked configuration. The step the commenter referred to says to "refer to" the AMM. As noted in the service information, when the words "refer to" are used and the operator has a FAA accepted alternative procedure, the accepted alternative procedure can be used. Operators therefore have latitude in how to accomplish any work steps that use the term "refer to." This AD has not been changed in this regard.

Request for Clarification of Repetitive Inspection Intervals

DAL requested clarification regarding the interval of the repetitive inspection specified in paragraph (3) of EASA ADs 2018-0137 and 2018-0137R1. DAL noted that, based on its understanding, the first repetitive inspection interval threshold is not to exceed 10,000 flight cycles or 15,000 flight hours, whichever occurs first. DAL remarked that it appears this threshold is based on the assumption that the initial inspections were done close to the initial threshold of 5,000 flight cycles or 7,500 flight hours, whichever occurred first. DAL requested clarification for a scenario in which an operator performed the specified inspection at 1,000 flight cycles or 1,000 flight hours, and asked if the first repetitive inspection interval would still be required before exceeding 10,000 flight cycles or 15,000 flight hours, whichever occurs first. DAL inquired if, in that same scenario, a grace period from the previous inspection would be more appropriate.

The FAA agrees to clarify. For the DAL scenario, the repetitive inspection will be due before exceeding 5,000 flight cycles or 7,500 flight hours, whichever occurs first since the last inspection. As stated previously, this AD now refers to EASA AD 2018-0137R1, as well as EASA AD 2018-0137. Paragraph (3) of EASA AD 2018-0137R1 has been revised to include multiple compliance

times, including a grace period for airplanes on which an inspection has already been accomplished using earlier revisions of the service information or accomplishment of a certain maintenance planning document (MPD) task or a certain AOT. The AD has not been changed in this regard.

Request To Clarify Revision Level for Optional Terminating Modification

DAL noted that paragraph (9) of EASA ADs 2018-0137 and 2018-0137R1 reference service information without a revision level. DAL inquired if the intent of the reference is to use only the original issue of the service information, or if any revision level is acceptable for compliance.

The FAA agrees to clarify. Operators may use any approved revision of the service information to perform the optional terminating modification, so long as the modification meets the provisions of paragraph (9) of EASA ADs 2018-0137 and 2018-0137R1.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. The FAA determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related IBR Material Under 1 CFR Part 51

EASA AD 2018-0137 and EASA AD 2018-0137R1 describe procedures for repetitive inspections for pre- and post-Airbus SAS modification 156593 airplanes, corrective actions, and optional terminating actions for the repetitive inspections. Corrective actions include modifications and repair. These documents are distinct since EASA AD 2018-0137R1 omits certain language, provides credit for additional service information, and clarifies certain compliance times. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 205 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2016-07-12.	4 work-hours × \$85 per hour = \$340.	\$0	\$340	\$69,700.
New proposed actions	Up to 21 work-hours × \$85 per hour = Up to \$1,785.	0	Up to \$1,785	Up to \$365,925.

ESTIMATED COSTS FOR OPTIONAL ACTIONS

Labor cost	Parts cost	Cost per product
Up to 70 work-hours × \$85 per hour = Up to \$5,950	Up to \$32,800	Up to \$38,750.

The FAA has received no definitive data that would enable the agency to provide cost estimates for the on-condition actions specified in this AD.

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under

that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service,

as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2016–07–12, Amendment 39–18457 (81 FR 19482, April 5, 2016), and adding the following new AD:

2019–14–03 Airbus SAS: Amendment 39–19681; Docket No. FAA–2019–0018; Product Identifier 2018–NM–116–AD.

(a) Effective Date

This AD is effective September 26, 2019.

(b) Affected ADs

This AD replaces AD 2016–07–12, Amendment 39–18457 (81 FR 19482, April 5, 2016) (“AD 2016–07–12”).

(c) Applicability

This AD applies to Airbus SAS Model A318–111, –112; Model A319–111, –112, –113, –114, –115; Model A320–211, –212, –214, –216; and Model A321–111, –112, –211, –212, –213 airplanes, certificated in any category, as identified in European Aviation Safety Agency (EASA) AD 2018–0137R1, dated January 9, 2019 (“EASA AD 2018–0137R1”).

(d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

(e) Reason

This AD was prompted by reports of cracking of the aft fixed fairing (AFF) of the pylons due to fatigue damage of the structure and reports of cracks on a certain rib of a modified AFF of the pylons. The FAA is issuing this AD to address damage and cracking of the AFF of the pylons, which could result in detachment of a pylon and consequent reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2018–0137, dated June 28, 2018 (“EASA AD 2018–0137”); or EASA AD 2018–0137R1.

(h) Exceptions to EASA ADs 2018–0137 and 2018–0137R1

(1) For purposes of determining compliance with the requirements of this AD, use the following paragraphs.

(i) Where EASA ADs 2018–0137 and 2018–0137R1 refer to the effective date of EASA AD 2018–0137 (July 12, 2018), this AD requires using the effective date of this AD.

(ii) Where EASA AD 2018–0137 refers to a compliance time of after July 16, 2014, this AD requires using May 10, 2016 (the effective date of AD 2016–07–12).

(2) The “Remarks” section of EASA ADs 2018–0137 and 2018–0137R1 do not apply.

(3) Where paragraph (3) of EASA ADs 2018–0137 and 2018–0137R1 requires that airplanes that have embodied Airbus modification 156593 accomplish the initial inspection of the AFF of the pylons before exceeding 10,000 flight cycles or 15,000 flight hours, whichever occurs first since airplane first flight, this AD requires inspection of those airplanes before exceeding 10,000 flight cycles or 15,000 flight hours since embodiment of Airbus modification 156593, whichever occurs first.

(4) Where paragraph (6) of EASA AD 2018–0137 gives credit for “the initial requirements of paragraph (4)” of EASA AD 2018–0137, this AD gives credit for “the requirements of paragraph (4)” of EASA AD 2018–0137.

(5) Where EASA ADs 2018–0137 and 2018–0137R1 require any approval from EASA or Airbus SAS’s Design Organization Approval (DOA), this AD requires approval

by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(6) Where any service information referenced in EASA ADs 2018–0137 and 2018–0137R1 specifies to use consumable material list (CML) material number 10ABC1, this AD allows the use of CML material number 10ABE1 as an additional method of compliance.

(i) No Reporting Requirement

Although the service information referenced in EASA ADs 2018–0137 and 2018–0137R1 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2018–0137 or EASA AD 2018–0137R1 that contains RC procedures and tests: Except as required by paragraphs (h)(6) and (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018–0137, dated June 28, 2018.

(ii) EASA AD 2018–0137R1, dated January 9, 2019.

(3) For EASA AD 2018–0137 and EASA AD 2018–0137R1, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find these EASA ADs on the EASA website at <https://ad.easa.europa.eu>.

Note 1 to paragraph (I)(3): EASA AD 2018–0137 can be accessed in the zipped file at the bottom of the web page for EASA AD 2018–0137R1. When EASA posts a revised AD on their website, they watermark the previous AD as “Revised,” alter the file name by adding “_revised” to the end, and move it into a zipped file attached at the bottom of the AD web page.

(4) You may view these EASA ADs at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. EASA AD 2018–0137 and EASA AD 2018–0137R1 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0018.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 16, 2019.

Michael Millage,

*Acting Director, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2019–18045 Filed 8–21–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Highway Administration****23 CFR Part 658**

[Docket No. FHWA–2018–0042]

RIN 2125–AF86

FAST Act Section 5516 “Additional State Authority” Implementation

AGENCY: Federal Highway Administration (FHWA), U.S. Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: This final rule implements Section 5516, “Additional State Authority,” of the Fixing America’s Surface Transportation (FAST) Act, which provides the State of South Dakota with the opportunity to update and revise the routes for Longer Combination Vehicles (LCV) and commercial motor vehicles (CMV) with two or more cargo-carrying units.

DATES: This rule is effective September 23, 2019.

FOR FURTHER INFORMATION CONTACT:

Vince Mantero, FHWA Office of Freight Management and Operations, (202) 366–2997, or by email at Vince.Mantero@dot.gov, or William Winne, FHWA Office of the Chief Counsel, (202) 366–1397, or by email at William.Winne@dot.gov. Business hours for FHWA are from 8:00 a.m. to 4:30 p.m., e.t., Monday through Friday, except Federal holidays.

SUPPLEMENTARY INFORMATION:**Electronic Access**

The Notice of Proposed Rulemaking (NPRM), the comments received, and this document may be viewed online through the Federal eRulemaking portal at: <http://www.regulations.gov> under docket ID FHWA–2018–0042. Copies of this document also may be downloaded by accessing the Office of the Federal Register’s home page at: <http://www.archives.gov> or the Government Publishing Office’s web page at: <http://www.gpoaccess.gov/nara>.

Background

The Intermodal Surface Transportation Efficiency Act (ISTEA) of 1991 (Pub. L. 102–240, 105 Stat. 1914, Dec. 18, 1991) restricts the operation of LCVs on the Interstate Highway System (Sec. 1023(b), 105 Stat. 1952) and CMV combinations with two or more cargo-carrying units on the National Network (NN) (Sec. 4006, 105 Stat. 2148) to the types of vehicles in use on or before June 1, 1991, subject to whatever State rules, regulations, or restrictions were in effect on that date. A listing of these vehicles and restrictions is found in 23 CFR part 658, Appendix C.

The FHWA is modifying its regulations, as found in 23 CFR part 658, Appendix C, governing vehicles covered by 23 U.S.C. 127(d) (LCVs) and 49 U.S.C. 31112 (CMVs with two or more cargo-carrying units) in the State of South Dakota, as proposed in a NPRM published on February 6, 2019, at 84 FR 2071.

This action is necessary to implement the provisions of Section 5516 of the FAST Act, which provides South Dakota the opportunity to update and

revise the routes designated as qualifying Federal-aid Primary System highways as long as the update shifts routes to divided highways or does not increase centerline miles by more than 5 percent and is expected to increase safety performance. The FAST Act Conference Report to Accompany H.R. 22 (House of Representatives 114th Congress 1st Session Report 114–357, December 1, 2015) states, “Conferees expect that the implementation of section 5516 will provide the maximum flexibility possible to re-route longer combination vehicles in the affected State to divided highways, highway facilities designed for freight transportation, or along routes that will enhance overall highway safety.”

In an August 30, 2016, letter to FHWA, the South Dakota Department of Transportation (SDDOT) requested that FHWA add the additional routes for South Dakota’s LCV network and provided a map and listing of those routes.

All of the proposed routes are on the NN, which is comprised of the Interstate Highway System and routes designated as qualifying Federal-aid Primary System highways. Combinations with a cargo-carrying length of 81.5 feet or less may use all NN routes. Combinations with a cargo-carrying length over 81.5 feet are restricted to the Interstate System and the routes listed in 23 CFR part 658, Appendix C. This listing of routes is applicable to both double trailers and triple trailers.

There were errors in the tables published in the “Background” section of the NPRM, on page 2075, regarding existing and proposed routes of operation for LCVs and trucks in excess of the lengths designated by the Surface Transportation Assistance Act (STAA) of 1982 for use on the NN. The route segments that were incorrect include a portion of US 14 and US 14B in Pierre, South Dakota. In addition, incorrect mileage is shown on several existing and proposed routes. The correct routes were provided to FHWA in a letter from the SDDOT dated June 6, 2018, which was added to the docket for this rulemaking. Nevertheless, all routes identified in the regulatory text of the NPRM were correct and included both existing and proposed routes of operation for LCVs and trucks over STAA lengths on the NN.

The FHWA finds that this update shifts routes to divided highways or does not increase centerline miles by more than 5 percent and is expected to increase safety performance. Based on this information and the comments received, FHWA is revising the Federal Regulations at 23 CFR part 658,