

procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) For information about EASA AD 2019-0126, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0126 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0611.

(2) For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

Issued in Des Moines, Washington, on August 22, 2019.

Suzanne Masterson,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-18764 Filed 8-29-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0666; Product Identifier 2019-NM-086-AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Services B.V. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. This proposed AD was prompted by reports of lavatory waste bin fire extinguishers found depleted. This proposed AD would require a one-time inspection of the installation of the waste bins for interference (the inspection also includes a weight check of the waste bin fire extinguisher and an inspection of the discharge tubes for damage), modification of affected waste bins, and replacement of affected fire extinguishers, as specified in a

European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. This proposed AD would also require replacement of the fire extinguisher if any damaged discharge tube is found or the weight of the waste bin fire extinguisher is too low. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by October 15, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA, at Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0666.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0666; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South

216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-0666; Product Identifier 2019-NM-086-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments received, without change, to <http://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0095, dated April 30, 2019 (“EASA AD 2019-0095”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. The MCAI states:

Occurrences have been reported of lavatory waste bin fire extinguishers found depleted. The subsequent investigation results revealed that this was due to damage to the discharge tubes, which may have occurred during installation or removal of the waste bin, having collided with the fire extinguisher discharge tubes. Except for the affected fire extinguishers, having too long discharge tubes, this interference is fully due to the geometry of the affected waste bins.

This condition, if not detected and corrected, could lead to failure of discharging the extinguishing agent in case of lavatory bin fire, possibly resulting in damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, Fokker Services published the SB [Fokker Service Bulletin SBF100-25-134, dated February 28, 2019], providing inspection instructions to verify correct clearance between the waste bin and the fire extinguisher discharge tubes and to replace affected fire extinguishers.

For the reasons described above, this [EASA] AD requires a one-time inspection of the installation of each affected waste bin, modification of the affected waste bin(s) and replacement of the affected fire extinguisher(s). This [EASA] AD also prohibits (re) installation of affected waste bins or affected fire extinguishers.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0095 describes procedures for a one-time inspection of the installation of each affected waste bin for interference between the waste bins and the fire extinguisher discharge tubes (the inspection for interference also includes a weight check of the waste bin fire extinguisher and a detailed inspection of the discharge tubes for damage), modification of affected waste bins, and replacement of affected fire extinguishers. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section, and it is publicly available through the EASA website.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to a bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in EASA AD 2019–0095 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD, and except as discussed under “Differences Between this Proposed AD and the MCAI.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers to use this process. As a result, EASA AD 2019–0095 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with the provisions specified in EASA AD 2019–0095, in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled

“Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2019–0095 that is required for compliance with EASA AD 2019–0095 will be available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0666 after the FAA final rule is published.

Differences Between This Proposed AD and the MCAI

EASA AD 2019–0095 specifies doing an inspection for interference, which includes a weight check of the waste bin fire extinguisher and an inspection of the discharge tubes for damage. EASA AD 2019–0095 includes a corrective action for the inspection for interference but does not identify a corrective action for the weight check and inspection of the discharge tubes. However, the service information referenced in EASA AD 2019–0095 does specify a corrective action for the weight check and inspection of the discharge tubes (*i.e.*, replacement of the fire extinguisher). Therefore, this proposed AD would require replacement of the fire extinguisher if any damaged discharge tube is found or the weight of the waste bin fire extinguisher is too low.

Costs of Compliance

The FAA estimates that this proposed AD affects 4 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$340

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
3 work-hours × \$85 per hour = \$255	\$1,100	\$1,355

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Fokker Services B.V.: Docket No. FAA–2019–0666; Product Identifier 2019–NM–086–AD.

(a) Comments Due Date

The FAA must receive comments by October 15, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Reason

This AD was prompted by reports of lavatory waste bin fire extinguishers found depleted. An investigation revealed that damage to the discharge tubes may have occurred during installation or removal of the waste bin. Insufficient clearance between the waste bin and the discharge tubes may have caused the fire extinguisher discharge tubes to collide with the waste bin and discharge. The FAA is issuing this AD to address this condition, which could lead to failure of discharging the extinguishing agent during a lavatory bin fire, and consequent damage to the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements as Specified in EASA AD 2019–0095

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0095, dated April 30, 2019 ("EASA AD 2019–0095").

(h) Exceptions to EASA AD 2019–0095

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019–0095 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2019–0095 does not apply to this AD.

(i) Additional Requirement: Corrective Action

If, during any inspection required by paragraph (1) of EASA AD 2019–0095 (which includes a weight check of the waste bin fire extinguisher and an inspection of the discharge tubes for damage), any damaged discharge tube is found or the weight of the waste bin fire extinguisher is too low, before further flight, replace the fire extinguisher with a serviceable fire extinguisher.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it

to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Fokker Services B.V.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) For information about EASA AD 2019–0095, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. EASA AD 2019–0095 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0666.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226.

Issued in Des Moines, Washington, on August 22, 2019.

Suzanne Masterson,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–18762 Filed 8–29–19; 8:45 am]

BILLING CODE 4910–13–P

POSTAL REGULATORY COMMISSION

39 CFR Part 3050

[Docket No. RM2019–12; Order No. 5211]

Periodic Reporting

AGENCY: Postal Regulatory Commission.
ACTION: Notice of proposed rulemaking.

SUMMARY: The Commission is acknowledging a recent filing requesting the Commission initiate a rulemaking proceeding to consider changes to analytical principles relating to periodic reports (Proposal Seven). This document informs the public of the filing, invites public comment, and takes other administrative steps.

DATES: *Comments are due:* September 26, 2019.