

List of Subjects in 7 CFR Part 932

Olives, Marketing agreements, Reporting and recordkeeping requirements.

For the reasons set forth in the preamble, 7 CFR part 932 is proposed to be amended as follows:

PART 932—OLIVES GROWN IN CALIFORNIA

- 1. The authority citation for 7 CFR part 932 continues to read as follows:

Authority: 7 U.S.C. 601–674.

§ 932.36 [Amended]

- 2. Amend § 932.36 to read as follows:

§ 932.36 Procedure.

Decisions of the committee shall be by majority vote of the members, including alternates acting as members, present and voting, and a quorum must be present: *Provided*, That decisions requiring a recommendation to the Secretary on matters pertaining to grade and size regulations shall require at least 10 affirmative votes, at least 5 of which must be from producer members and at least 5 of which must be from handler members and, if the committee is increased by the addition of a public member, at least 11 affirmative votes shall be required, at least 5 of which must be from producer members and at least 5 of which must be from handler members. A quorum shall consist of at least 10 members, including alternates acting as members, and, if the committee is increased by the addition of a public member, a quorum shall consist of at least 11 members, including alternates acting as members. Except in case of an emergency, a minimum of 5 days advance notice shall be given with respect to any meeting of the committee. In case of an emergency, to be determined within the discretion of the chairman of the committee, as much advance notice of a meeting as is practicable in the circumstances shall be given. The committee may vote by mail or telegram upon due notice to all members, but any proposition to be so voted upon first shall be explained accurately, fully, and identically by mail or telegram to all members. When voted on by such method, at least 14 affirmative votes, of which seven shall be producer member votes and seven shall be handler member votes, shall be required for adoption and, if the committee is increased by the addition of a public member, votes by mail or telegram shall require at least 15 affirmative votes, of which at least 7 shall be producer member votes and at least 7 shall be handler member votes. The committee may recommend for the

Secretary's approval changes in the number of affirmative votes required for adoption of any proposition voted upon by means of a mail or telegram ballot: *Provided*, That the number of affirmative votes required for adoption shall not be less than ten, and in any case an equal number of producer member and handler member votes shall be required for adoption and, if the committee is increased by the addition of a public member, the number of affirmative votes required for adoption shall be increased by one.

Dated: November 1, 2019.

Bruce Summers,

Administrator, Agricultural Marketing Service.

[FR Doc. 2019–24224 Filed 11–5–19; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2019–0728; Product Identifier 2019–NM–071–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD–100–1A10 airplanes. This proposed AD was prompted by a report that during ALTS CAP or (V) ALTS CAP mode, the flight guidance/autopilot does not account for engine failure while capturing an altitude. This proposed AD would require revising the existing airplane flight manual (AFM) to provide the flightcrew with new warnings for “Autoflight” and “Engine Failure in Climb During ALTS CAP.” The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by December 23, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–

30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free phone: 1–866–538–1247 or direct-dial phone: 1–514–855–2999; *email:* ac.yul@aero.bombardier.com; *internet:* <https://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0728; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516–228–7367; fax: 516–794–5531; *email:* 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2019–0728; Product Identifier 2019–NM–071–AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <http://www.regulations.gov>, including any personal information you provide. The

FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2019-12, dated April 3, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model BD-100-1A10 airplanes.

This proposed AD was prompted by a report that during ALTS CAP or (V) ALTS CAP mode, the flight guidance/autopilot does not account for engine failure while capturing an altitude. The FAA is proposing this AD to address the occurrence of an engine failure during or before a climb while in ALTS CAP or (V) ALTS CAP mode, as it could cause the airspeed to drop significantly below the safe operating speed and may require prompt flightcrew intervention to maintain a safe operating speed. See the MCAI for more information.

Related Service Information Under 1 CFR Part 51

Bombardier has issued the following service information, which provides new warnings for “Autoflight” and “Engine Failure in Climb During ALTS CAP,” in the LIMITATIONS—System Limitations and the EMERGENCY PROCEDURES—Powerplant sections of the applicable AFM.

- Bombardier Challenger 300, Airplane Flight Manual, Publication No. CSP 100-1, Revision 55, dated April 8, 2019.
- Bombardier Challenger 350, Airplane Flight Manual, Publication No. CH 350 AFM, Revision 21, dated April 8, 2019.

These documents are distinct since they apply to different airplane models in different configurations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

This product has been approved by the aviation authority of another

country, and is approved for operation in the United States. Pursuant to a bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require revising the existing AFM with new warnings for “Autoflight” and “Engine Failure in Climb During ALTS CAP,” in the LIMITATIONS—System Limitations and the EMERGENCY PROCEDURES—Powerplant sections, as described previously.

Costs of Compliance

The FAA estimates that this proposed AD affects 252 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$21,420

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is

normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2019-0728; Product Identifier 2019-NM-071-AD.

(a) Comments Due Date

The FAA must receive comments by December 23, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD-100-1A10 airplanes, certificated in any category, serial numbers 20003 through 20500 inclusive and 20501 through 20752 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

(e) Reason

This AD was prompted by a report that during ALTS CAP or (V) ALTS CAP mode, the flight guidance/autopilot does not account for engine failure while capturing an altitude. The FAA is issuing this AD to address the occurrence of an engine failure during or before a climb while in ALTS CAP or (V) ALTS CAP mode, as it could cause the airspeed to drop significantly below the safe operating speed and may require prompt flightcrew intervention to maintain a safe operating speed.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Airplane Flight Manual (AFM)

Within 30 days after the effective date of this AD: Revise the LIMITATIONS—System Limitations and the EMERGENCY PROCEDURES—Powerplant sections of the existing AFM to include the information in “Autoflight” and “Engine Failure in Climb During ALTS CAP” of Bombardier Challenger 300, Airplane Flight Manual, Publication No. CSP 100-1, Revision 55, dated April 8, 2019 (for airplanes having serial numbers 20003 through 20500 inclusive); or Bombardier Challenger 350, Airplane Flight Manual, Publication No. CH 350 AFM, Revision 21, dated April 8, 2019 (for airplanes having serial numbers 20501 through 20752 inclusive).

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight

standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-12, dated April 3, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0728.

(2) For more information about this AD, contact Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7367; fax: 516-794-5531; email: 9-avs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free phone: 1-866-538-1247 or direct-dial phone: 1-514-855-2999; email: ac.yul@aero.bombardier.com; internet: <https://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on October 28, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-24192 Filed 11-5-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 117**

[Docket No. USCG-2018-0953]

RIN 1625-AA09

Drawbridge Operation Regulations; Lacombe Bayou, LA

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to change the operating schedule that governs the Tammany Trace swing bridge across Lacombe Bayou, mile 5.2, at Lacombe, St. Tammany Parish, Louisiana. This action is necessary to

effectively coordinate Tammany Trace trail operations and maintenance with drawbridge operations.

DATES: Comments and related material must be received by the Coast Guard on or before December 6, 2019.

ADDRESSES: You may submit comments identified by docket number USCG-2018-0953 using Federal eRulemaking Portal at <http://www.regulations.gov>.

See the “Public Participation and Request for Comments” portion of the **SUPPLEMENTARY INFORMATION** section for further instructions on submitting comments.

FOR FURTHER INFORMATION CONTACT: If you have questions about this proposed rulemaking, call or email Mr. Doug Blakemore, Eighth Coast Guard District Bridge Administrator; telephone (504) 671-2128, email Douglas.A.Blakemore@uscg.mil.

SUPPLEMENTARY INFORMATION:**I. Table of Abbreviations**

CFR Code of Federal Regulations
DHS Department of Homeland Security
FR Federal Register
NPRM Notice of proposed rulemaking
STP St. Tammany Parish
Trace Tammany Trace
§ Section

II. Background, Purpose and Legal Basis

Saint Tammany Parish (STP) has requested to change the operating requirements for the Tammany Trace swing bridge across Lacombe Bayou, mile 5.2, at Lacombe, St. Tammany Parish, Louisiana. This bridge currently opens on signal according to 33 CFR 117.5. STP has requested to open the bridge if vessels provide 2 hours advance notification.

This bridge spans the Tammany Trace which is a park area that is used by pedestrians and bicyclists. The Trace is open from 7 a.m. to 7:30 p.m. daily. The bridge operates during Trace hours and is secured in the open to navigation position when the Trace is closed. This bridge has a vertical clearance of 9.7 feet above mean high water in the closed to vessel position and unlimited vertical clearance in the open to vessel traffic position. There are few vessel movements through this bridge. From 2015 through 2017 the bridge opened 197 times for vessel passage. This waterway is primarily used by recreational boaters in the Lacombe area and does not support commercial activity.

In addition to bridge operations, STP bridge tenders assist with Trace bike, pedestrian and equestrian operations and maintenance. This change would