

application for a license) or by the loan originator organization employing the individual loan originator (to comply with § 1026.36(f)(3)). Under that scheme, both the State and the loan originator organization did not have to complete screening and training. If § 1026.36(f)(3) were interpreted to apply to a loan originator organization that employs a loan originator with temporary authority, both the State (as part of reviewing the loan originator's application for a license) and the loan originator organization (to comply with § 1026.36(f)(3)) would have to obtain the required criminal background and credit history reports and make the required criminal, financial responsibility, and character and fitness findings at the same time on the same individual. Similarly, both the State and the loan originator organization would have responsibilities related to the loan originator's training. This duplication of efforts would be inconsistent with the Bureau's purpose in issuing § 1026.36(f)(3), because such duplication would not result in additional consumer protections that could justify these new burdens on loan originator organizations.

For these reasons, the Bureau concludes that the individual loan originators described in § 1026.36(f)(3) do not include the loan originators with temporary authority described in section 1518 of the SAFE Act, 12 U.S.C. 5117. Thus, if an individual loan originator employee has temporary authority to act as a loan originator in a State, the loan originator organization is not required to comply with the screening and training requirements in § 1026.36(f)(3) to permit that employee to act as a loan originator in that State.

Finally, the Bureau underscores that loan originator organizations continue to be subject to the obligation in § 1026.36(f)(2) to ensure that any individual loan originator who works for them is licensed or registered to the extent required by the SAFE Act, its implementing regulations, or State SAFE Act implementing laws before permitting the individual to act as a loan originator on a consumer credit transaction secured by a dwelling. Thus, when satisfying the loan originator organization's obligations under § 1026.36(f)(2), the loan originator organization must ensure that any individual loan originator that works for it is either registered or licensed as required by the SAFE Act or excluded from those requirements because the

individual may act as a loan originator with temporary authority.³⁰

II. Effective Date

Because this rule is solely interpretive, it is not subject to the 30-day delayed effective date for substantive rules under section 553(d) of the Administrative Procedure Act.³¹ Therefore, this rule is effective on November 24, 2019, the same date that the EGRCPA amendments to the SAFE Act take effect.

III. Regulatory Requirements

This rule articulates the Bureau's interpretation of Regulation Z. As an interpretive rule, it is exempt from the notice-and-comment rulemaking requirements of the Administrative Procedure Act.³² Because no notice of proposed rulemaking is required, the Regulatory Flexibility Act does not require an initial or final regulatory flexibility analysis.³³

The Bureau has determined that this interpretive rule does not impose any new or revise any existing recordkeeping, reporting, or disclosure requirements on covered entities or members of the public that would be collections of information requiring approval by the Office of Management and Budget under the Paperwork Reduction Act.³⁴

IV. Congressional Review Act

Pursuant to the Congressional Review Act,³⁵ the Bureau will submit a report containing this interpretive rule and other required information to the U.S. Senate, the U.S. House of Representatives, and the Comptroller General of the United States prior to the rule's published effective date. The Office of Information and Regulatory Affairs has designated this interpretive rule as not a "major rule" as defined by 5 U.S.C. 804(2).

Dated: November 12, 2019.

Kathleen L. Kraninger,

Director, Bureau of Consumer Financial Protection.

[FR Doc. 2019-24944 Filed 11-18-19; 8:45 am]

BILLING CODE 4810-AM-P

³⁰ The Bureau also reminds loan originator organizations that they continue to be subject to § 1026.36(f)(1)'s obligation to comply with all applicable State law requirements for legal existence and foreign qualification.

³¹ 5 U.S.C. 553(d).

³² 5 U.S.C. 553(b).

³³ 5 U.S.C. 603(a), 604(a).

³⁴ 44 U.S.C. 3501-3521.

³⁵ 59 U.S.C. 801-808.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0400; Product Identifier 2019-NM-022-AD; Amendment 39-19776; AD 2019-21-10]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes. This AD was prompted by a quality control review, which determined that the wrong aluminum alloy was used to manufacture several structural parts. This AD requires a one-time eddy current conductivity measurement of certain structural parts of the outer flaps to determine if the incorrect alloy was used, and replacement if necessary, as specified in a European Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 24, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 24, 2019.

ADDRESSES: For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0400.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-

0400; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0012, dated January 24, 2019 (“EASA AD 2019-0012”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes. The NPRM published in the **Federal Register** on June 7, 2019 (84 FR 26598). The NPRM was prompted by a quality control review, which determined that the wrong aluminum alloy was used to manufacture several structural parts. The NPRM proposed to require a one-time eddy current conductivity measurement of certain structural parts of the outer flaps to determine if the incorrect alloy was used, and replacement if necessary.

The FAA is issuing this AD to address structural parts made of incorrect aluminum alloy, which could result in reduced structural integrity of the outer flaps and reduced controllability of the airplane. See the MCAI for additional background information.

Explanation of Change to Format of Paragraph Designation References

The FAA has revised the format used for referring to paragraph designations throughout this AD. This change is necessary to meet Office of the Federal Register’s drafting requirements. For example, where the FAA used to say paragraphs (g)(1) and (g)(2) of this AD, the FAA now says paragraphs (g)(1) and (2) of this AD. This change does not affect the requirements of this AD.

Comment

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the NPRM and the FAA’s response.

Request To Revise Reporting Requirement

American Airlines requested that paragraph (h) of the proposed AD be changed so operators would be required to report only positive findings. The commenter stated that negative findings are not value added and only serve to add unnecessary work for operators. In addition, the commenter requested that the compliance time for reporting findings be extended from 30 days after the inspection to 90 days after the inspection. The commenter remarked that it creates an undue burden for operators to report inspection results within 30 days after an inspection.

The FAA partially agrees with the commenter’s request. The FAA agrees to extend the compliance time in paragraph (h)(4)(ii) of this AD, which applies to inspections done before the effective date of this AD. This extension will provide flexibility to operators who have done the inspections required by this AD, but have not completed an inspection report. However, the FAA does not agree to change the compliance time in paragraph (h)(4)(i) of this AD, which applies to inspections done on or after the effective date of this AD, because the service information referenced in EASA AD 2019-0012 requires reporting within 30 days after the inspection is done. If the inspection was done on or after the effective date of this AD an operator must submit the

report within 30 days after the inspection. If the inspection was done before the effective date of this AD, an operator must submit the report within 90 days after the effective date of this AD.

The FAA does not agree with the commenter’s request to require that only positive findings be reported. Airbus uses the information from all findings, both positive and negative, to plan and provide corrective actions for the unsafe condition identified in this AD. The FAA has not revised this AD in regard to this issue.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. The FAA determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019-0012 describes procedures for a one-time eddy current conductivity measurement of certain structural parts on the outer flaps to determine if an incorrect aluminum alloy was used, and replacement of any affected part with a serviceable part.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 29 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS *

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510	\$0	\$510	\$14,790

* Table does not include estimated costs for reporting.

The FAA estimates that it will take about one work-hour per product to comply with the reporting requirement in this AD. The average labor rate is \$85 per hour. Based on these figures, the FAA estimates the cost of reporting the inspection results on U.S. operators to be \$2,465, or \$85 per product.

The FAA has received no definitive data that will enable the agency to provide cost estimates for the on-condition actions specified in this AD.

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the agency has included all known costs in the cost estimate.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120-0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce.

This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019-21-10 Airbus SAS: Amendment 39-19776; Docket No. FAA-2019-0400; Product Identifier 2019-NM-022-AD.

(a) Effective Date

This AD is effective December 24, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, and A321-232 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by a quality control review, which determined that the wrong aluminum alloy was used to manufacture several structural parts. The FAA is issuing this AD to address structural parts made of incorrect aluminum alloy, which could result in reduced structural integrity of the outer flaps and reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Aviation Safety Agency (EASA) AD 2019-0012, dated January 24, 2019 ("EASA AD 2019-0012").

(h) Exceptions to EASA AD 2019-0012

(1) Where EASA AD 2019-0012 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2019-0012 does not apply to this AD.

(3) Where paragraph (5) of EASA AD 2019-0012 mandates a parts installation limitation, this AD requires the following parts installation limitation: From the effective date of this AD, only serviceable parts as defined in EASA AD 2019-0012 are allowed to be installed on any airplane.

(4) Where any service information referenced in EASA AD 2019-0012 specifies reporting, this AD requires reporting all inspection results at the applicable time specified in paragraph (h)(4)(i) or (ii) of this AD. If operators have reported findings as part of obtaining any corrective actions approved by Airbus SAS's EASA Design Organization Approval (DOA), operators are not required to report those findings as specified in this paragraph.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 90 days after the effective date of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found

in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019-0012 that contains RC procedures and tests: Except as required by paragraphs (h)(4) and (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) *Paperwork Reduction Act Burden Statement:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD; the nature and extent of confidentiality to be provided, if any. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2019-0012, dated January 24, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0012, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0400.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 1, 2019.

Jeffrey E. Duven,

Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-24994 Filed 11-18-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0739; Product Identifier 2015-NE-07-AD; Amendment 39-19782; AD 2019-22-03]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney Canada Corp. Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2015-20-04 for certain Pratt & Whitney Canada Corp. (P&WC) PT6B-37A turboshaft engines. AD 2015-20-04 required initial and repetitive inspections until replacement of the No. 10 bearing, and eventual replacement of the No. 9 bearing, both located in the engine

reduction gearbox (RGB) assembly. This AD requires removal from service and replacement of the No. 9 and No. 10 position bearings. This AD was prompted by reports of incorrect engine torque for PT6B-37A turboshaft engines. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 24, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 24, 2019.

ADDRESSES: For service information identified in this final rule, contact Pratt & Whitney Canada Corp., 1000 Marie-Victorin, Longueuil, Quebec, Canada, J4G 1A1; phone: 800-268-8000; fax: 450-647-2888; website: <https://www.pwc.ca/en/>. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0739.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0739; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Barbara Caufield, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7146; fax: 781-238-7199; email: barbara.caufield@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2015-20-04, Amendment 39-18282 (80 FR 61717, October 14, 2015), ("AD 2015-20-04"). AD 2015-20-04 applied to certain P&WC PT6B-37A turboshaft engines. The NPRM published in the **Federal Register** on September 17, 2018 (83 FR