

(e) Actions and Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(1) For MGB input flexible coupling flange assemblies with less than 50 hours time-in-service (TIS) since new or since a complete overhaul of the MGB, re-adjust the tightening torque load of the 6 nuts on the flexible coupling-to-flange attachment bolts.

Accomplish this re-adjustment between 50 hours TIS and 75 hours TIS since new or since a complete overhaul of the MGB in accordance with paragraph 2.B.2.a. of Eurocopter Emergency Alert Service Bulletin No. 05.95, Revision 0, dated March 3, 2008 (EASB 05.95) or Airbus Helicopters Emergency Alert Service Bulletin No. 05.95, Revision 1, dated October 22, 2015 (EASB 05.95 Rev 1).

(2) For MGB input flexible coupling flange assemblies with 50 hours TIS and 75 or less hours TIS since new or since a complete overhaul of the MGB, either:

(i) Upon or before reaching 75 hours TIS since new or since a complete overhaul of the MGB, re-adjust the tightening torque load of the 6 nuts on the flexible coupling-to-flange attachment bolts in accordance with paragraph 2.B.2.a. of EASB 05.95 or EASB 05.95 Rev 1; or

(ii) Upon or before reaching 125 hours TIS since new or since a complete overhaul of the MGB, inspect the tightening torque load of the 6 nuts on the flexible coupling-to-flange attachment bolts in accordance with paragraph 2.B.2.b. of EASB 05.95 or EASB 05.95 Rev 1, except you are not required to contact the manufacturer.

(3) For MGB input flexible coupling flange assemblies that have more than 75 hours TIS since new or since a complete overhaul of the MGB, within the next 50 hours TIS, inspect the tightening torque load of the 6 nuts on the flexible coupling-to-flange attachment bolts, in accordance with paragraph 2.B.2.b. of EASB 05.95 or EASB 05.95 Rev 1, except you are not required to contact the manufacturer.

(4) Prior to installing an MGB that contains an input flexible coupling flange assembly that has been modified per MOD 0752416 and MOD 0752419, you must comply with the provisions of this AD.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, FAA, may approve AMOCs for this AD. Send your proposal to: Jignesh Patel, Aerospace Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2008-0049R1, dated December 18, 2015. You may view the EASA AD on the internet at <https://www.regulations.gov> in the AD Docket.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6310, Engine/Transmission Coupling.

Issued in Fort Worth, Texas, on December 11, 2019.

Gaetano A. Sciortino,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2019-27430 Filed 12-19-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-0988; Product Identifier 2019-NM-175-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD-500-1A11 airplanes. This proposed AD was prompted by reports that, under certain combinations of airplane configuration and flight conditions, higher than anticipated temperatures could lead to an engine fire warning nuisance message. This proposed AD would require installation of Integrated Air Systems Controller (IASC) software version 5.0. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by February 3, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0988; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Thomas Niczky, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7347; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0988; Product Identifier 2019-NM-175-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2019-31, dated September 6, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus Canada Limited Partnership Model BD-500-1A11 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0988.

This proposed AD was prompted by reports that, under certain combinations of airplane configuration and flight conditions, higher than anticipated temperatures could lead to an engine fire warning nuisance message. The FAA is proposing this AD to address this potential nuisance message, which

could lead to an unnecessary shutdown of the engine by the flightcrew, and consequent reduced controllability of the airplane. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin BD500-219001, Issue 002, dated September 11, 2018. This service information describes procedures for installation of IASC software version 5.0. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation

in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

The FAA estimates that this proposed AD affects 8 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170	\$0	\$170	\$1,360

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated

appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Docket No. FAA-2019-0988; Product Identifier 2019-NM-175-AD.

(a) Comments Due Date

The FAA must receive comments by February 3, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD-500-1A11 airplanes, certificated in any category, serial numbers 55018, 55019, 55022, 55024, 55026, 55028, 55031, and 55035.

(d) Subject

Air Transport Association (ATA) of America Code 30, Ice and rain protection.

(e) Reason

This AD was prompted by reports that, under certain combinations of airplane configuration and flight conditions, higher than anticipated temperatures could lead to an engine fire warning nuisance message. The FAA is issuing this AD to address this condition, which could lead to an unnecessary shutdown of the engine by the flightcrew, which could lead to reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Software Update

Within 850 flight hours or 6 months, whichever occurs first after the effective date of this AD: Install Integrated Air Systems Controller (IASC) software version 5.0, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin BD500–219001, Issue 002, dated September 11, 2018.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin BD500–219001, Issue 001, dated August 3, 2018.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Airbus Canada Limited Partnership's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF–2019–31, dated September 6, 2019, for related information. This MCAI may be found in the AD docket on the internet at

<https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0988.

(2) For more information about this AD, contact Thomas Niczky, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7347; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on December 12, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–27466 Filed 12–19–19; 8:45 am]

BILLING CODE 4910–13–P

SOCIAL SECURITY ADMINISTRATION**20 CFR Parts 402, 404, 408, 411, 416, and 422**

[Docket No. SSA–2017–0073]

RIN 0960–AI25

Hearings Held by Administrative Appeals Judges of the Appeals Council

AGENCY: Social Security Administration.

ACTION: Notice of proposed rule making.

SUMMARY: We propose to revise our rules to clarify when and how administrative appeals judges (AAJ) on our Appeals Council may hold hearings and issue decisions. The Appeals Council already has the authority to hold hearings and issue decisions under our existing statute and regulations, but we have not exercised this authority or explained the circumstances under which it would be appropriate for the Appeals Council to assume responsibility for holding a hearing and issuing a decision. The proposed clarifications will ensure the Appeals Council is not limited in the type of claims for which it may hold hearings. We expect that these proposed rules will increase our adjudicative capacity when needed, allowing us to adjust more quickly to fluctuating short-term workloads, such as when an influx of cases reaches the hearings level. Our ability to utilize our limited resources more effectively will help us quickly optimize our hearings capacity, which

in turn will allow us to continue to issue accurate, timely, high-quality decisions.

DATES: To ensure that your comments are considered, we must receive them no later than February 18, 2020.

You may submit comments by any one of three methods—internet, fax, or mail. Do not submit the same comments multiple times or by more than one method. Regardless of which method you choose, please state that your comments refer to Docket No. SSA–2017–0073 so that we may associate your comments with the correct rule.

Caution: You should be careful to include in your comments only information that you wish to make publicly available. We strongly urge you not to include in your comments any personal information, such as Social Security numbers or medical information.

1. *Internet:* We strongly recommend that you submit your comments via the internet. Please visit the Federal eRulemaking portal at <http://www.regulations.gov>. Use the *Search* function to find docket number SSA–2017–0073. The system will issue a tracking number to confirm your submission. You will not be able to view your comment immediately because we must post each comment manually. It may take up to a week for your comments to be viewable.

2. *Fax:* Fax comments to (410) 966–2830.

3. *Mail:* Mail your comments to the Office of Regulations and Reports Clearance, Social Security Administration, 3100 West High Rise Building, 6401 Security Boulevard, Baltimore, Maryland 21235–6401.

Comments are available for public viewing on the Federal eRulemaking portal at <http://www.regulations.gov> or in person, during regular business hours, by arranging with the contact person identified in **FOR FURTHER INFORMATION CONTACT**.

FOR FURTHER INFORMATION CONTACT: Nancy Chung, Office of Appellate Operations, Social Security Administration, 5107 Leesburg Pike, Falls Church, VA 22041, (703) 605–7100. For information on eligibility or filing for benefits, call our national toll-free number, 1–800–772–1213 or TTY 1–800–325–0778, or visit our internet site, Social Security Online, at <http://www.socialsecurity.gov>.

SUPPLEMENTARY INFORMATION:**Background**

As of November 2019, pending applicants have waited from a low of about 8.5 months to a high of about 20