

The Statement of Policy explains that the FDIC as conservator or receiver has the right to call, redeem or prepay any CPOs by repudiation or disaffirmance of the applicable written contract entered into by the IDI, either directly by cash payment in exchange for release of collateral or by liquidation of the collateral by a trustee or other secured party.

Based on market research, the FDIC has concluded, to the best of its knowledge, that it is unlikely that any public or privately issued transactions of this type remain outstanding at this time. Therefore, the FDIC is rescinding the Statement of Policy effective December 31, 2019.

(d) Statement of Policy on Contracting With Firms That Have Unresolved Audit Issues With FDIC

The *Statement of Policy on Contracting with Firms That Have Unresolved Audit Issues With FDIC* (1997 Statement of Policy) was not approved by the FDIC Board but it is being consolidated in this notice for convenience and completeness.

The 1997 Statement of Policy was adopted to address situations in which the FDIC seeks to contract with firms with which there are unresolved audit issues.⁷ The 1997 Statement of Policy established certain rights and procedures for the handling of contracting parties that have unresolved audit issues, as determined by various FDIC auditing agents. After review of the relevant Statement of Policy, the FDIC concluded that the document may give rise to *de facto* exclusions from future FDIC contracting opportunities in a manner that is inconsistent with procedural protections specified in 12 CFR 367.

In determining whether to revise or rescind the Statement of Policy, the FDIC considered a variety of factors, including whether or not the Policy provided the FDIC and its various audit agents with essential or additional protections regarding the repayment of challenged amounts. The FDIC determined that existing remedies are sufficient to allow the FDIC and its agents to pursue such challenged amounts without the need for those measures specified in the Statement of Policy. Therefore, the FDIC is rescinding this Statement of Policy effective December 31, 2019.

(Authority: 12 U.S.C. 1811 *et seq.*)

Dated at Washington, DC, on December 12, 2019.

Federal Deposit Insurance Corporation.

⁷ 62 FR 13382. (<https://www.govinfo.gov/content/pkg/FR-1997-03-20/pdf/97-6995.pdf>).

By order of the Board of Directors.

Annamarie H. Boyd,

Assistant Executive Secretary.

[FR Doc. 2019–27225 Filed 12–20–19; 8:45 am]

BILLING CODE 6714–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0813; Product Identifier 2019–SW–006–AD; Amendment 39–19787; AD 2019–22–08]

RIN 2120–AA64

Airworthiness Directives; Leonardo S.p.A. Helicopters

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Leonardo S.p.A. Model AW169 and AW189 helicopters. This AD requires inspecting certain part-numbered and serial-numbered tail rotor (T/R) actuators, reporting information, and depending on the inspection outcome, marking a part, performing an additional inspection, and removing the T/R actuator from service. This AD also prohibits the installation of affected T/R actuators. This AD is prompted by reports of incorrect installations of the T/R actuator back-end input lever. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD becomes effective January 7, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of January 7, 2020.

The FAA must receive comments on this AD by February 21, 2020.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <https://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202–493–2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590–0001.

- *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0813; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) AD, any service information that is incorporated by reference, the economic evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

For Leonardo Helicopters service information identified in this final rule, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://www.leonardocompany.com/en/home>.

For UTC Aerospace Systems service information identified in this final rule, contact Collins Aerospace (previously UTC Aerospace Systems); telephone 1–877–808–7575; fax 1–860–660–0372; email tech.solutions@hs.utc.com; or at <https://utcaerospacesystems.com/aftermarket-services/technical-support/>.

You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0813.

FOR FURTHER INFORMATION CONTACT:

David Hatfield, Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5110; email david.hatfield@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and the FAA did not provide you with notice and an opportunity to provide your comments prior to it becoming effective. However, the FAA invites you to participate in this rulemaking by submitting written comments, data, or views. The FAA also invites comments relating to the economic, environmental, energy, or federalism impacts that

resulted from adopting this AD. The most helpful comments reference a specific portion of the AD, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit them only one time. The FAA will file in the docket all comments received, as well as a report summarizing each substantive public contact with FAA personnel concerning this rulemaking during the comment period. The FAA will consider all the comments received and may conduct additional rulemaking based on those comments.

Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2019-0019, dated January 30, 2019 (EASA AD 2019-0019) to correct an unsafe condition for Leonardo S.p.A. (formerly Finmeccanica S.p.A., AgustaWestland S.p.A.) Model AW169 and AW189 helicopters with T/R actuator part number (P/N) 6F6730V00331 and a serial number (S/N) up to 489 inclusive, except those marked with "SB 67-0007," installed. EASA advises of reports of non-conformities of the T/R actuator back-end input lever, indicating incorrect orientation of the lever with its trunnion locking pin.

EASA states this condition could lead to de-bonding and slippage of one of the two redundant lever bearings and possibly affect the functionality of the T/R actuator. A batch of T/R actuators was identified that may be also affected. Accordingly, EASA AD 2019-0019 requires one-time conformity checks of certain T/R actuator input levers, sending information and photos to Leonardo S.p.A., and depending on inspection findings, marking a part, inspecting the bonding of each bearing, and replacing the T/R actuator. EASA AD 2019-0019 also prohibits installation of the affected parts.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA of the unsafe condition described in its AD. The FAA is issuing this AD after evaluating all information provided by EASA and determining the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs.

Related Service Information Under 1 CFR Part 51

UTC Aerospace Systems (Collins Aerospace) has issued Service Bulletin 67-0007, Basic Issue, dated January 17, 2019 (SB 67-0007). SB 67-0007 specifies verifying that the width of the bearing circular collar of the input lever is within the allowable limits of 4 ± 0.3 mm, and checking the input lever pin head, and the nut and cotter pin of the intermediate bolt for proper installation. Depending on the inspection results, SB 67-0007 specifies replacing the T/R actuator, or marking the input lever and sending its completed registration form and photos of each side of the input lever to Leonardo Helicopters. SB 67-0007 is incorporated by reference in this AD.

SB 67-0007 is attached as Annex A to Leonardo Helicopters Alert Service Bulletin (ASB) No. 169-129, dated January 30, 2019 (ASB 169-129), for Model AW169 helicopters, and Leonardo Helicopters ASB No. 189-220, dated January 30, 2019 (ASB 189-220), for Model AW189 helicopters. ASB 169-129 and ASB 189-220 are not incorporated by reference in this AD.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Other Related Service Information

Leonardo Helicopters has issued ASB 169-129 and ASB 189-220. This service information refers to SB 67-0007 for instructions to inspect certain part-numbered and serial-numbered T/R actuator input lever assemblies. Depending on findings, this service information specifies marking the input lever, inspecting the bonding of each bearing, and replacing the T/R actuator on a specified compliance time schedule based on findings. This service information also specifies sending information, photos, and certain T/R actuators to Leonardo Helicopters.

AD Requirements

For Model AW169 and AW189 helicopters with a T/R actuator P/N 6F6730V00331 and an S/N up to 489 inclusive, except those marked with "SB 67-0007," installed, this AD requires inspecting the T/R actuator input lever assembly by determining if the width of the bearing circular collar of the input lever is within allowable limits, and inspecting for proper installation of the pin and of the intermediate bolt's nut and cotter pin. This AD requires reporting certain information and photos to Leonardo

S.p.A. Based on the inspection outcome, this AD requires marking "SB 67-0007" on the input lever, inspecting each bearing for correct bonding, and removing the T/R actuator from service at different compliance times. This AD also prohibits installation of affected T/R actuators.

Differences Between This AD and the EASA AD

The EASA AD requires returning a removed T/R actuator to Leonardo Helicopters, whereas this AD does not. Depending on the inspection results of the T/R actuator input lever assembly, one of the compliance times to replace the T/R actuator in the EASA AD is 200 hours TIS or 2 months, whichever occurs first. This AD requires removing the T/R actuator from service within 60 hours TIS for the same inspection results instead.

Costs of Compliance

The FAA estimates that this AD affects 10 helicopters of U.S. Registry. Labor costs are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs in order to comply with this AD.

Inspecting the T/R actuator input lever assembly takes about 1 work-hour, and reporting information and photos to Leonardo S.p.A. takes about 1 work-hour, for an estimated cost of \$170 per helicopter and \$1,700 for the U.S. fleet. Marking a part takes a minimal amount of time for a nominal cost. Replacing a T/R actuator takes about 6 work-hours and parts cost about \$20,000, for an estimated cost of \$20,510 per helicopter.

According to Leonardo Helicopter's service information, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage by Leonardo Helicopters. Accordingly, the FAA has included all costs in the cost estimate.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the

data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C.) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without seeking comment prior to the rulemaking.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies foregoing notice and comment prior to adoption of this rule because the initial inspection requirements must be completed within 30 hours time-in-service. Therefore notice and opportunity for prior public comment are impracticable and contrary to public interest pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the reason stated above, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866, and
2. Will not affect intrastate aviation in Alaska.

The FAA prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019-22-08 Leonardo S.p.A.: Amendment 39-19787; Docket No. FAA-2019-0813; Product Identifier 2019-SW-006-AD.

(a) Applicability

This AD applies to Leonardo S.p.A. Model AW169 and AW189 helicopters, certificated

in any category, with a tail rotor (T/R) actuator part number (P/N) 6F6730V00331 with a serial number (S/N) up to 489 inclusive, except those marked with “SB 67-0007.”

(b) Unsafe Condition

This AD defines the unsafe condition as incorrect installation of the T/R actuator back-end input lever. This condition could result in de-bonding and slippage of one or both of the two redundant lever bearings, a reduction or loss of T/R control, and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective January 7, 2020.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 30 hours time-in-service (TIS), for Model AW169 helicopters, with access panels 470AT and 470BT removed; and for Model AW189 helicopters, with access panels 496A and 495A removed, inspect the T/R actuator input lever assembly by following the Accomplishment Instructions, paragraph 3.B. through 3.C.4., of UTC Aerospace Systems Service Bulletin 67-0007, Basic Issue, dated January 17, 2019 (SB 67-0007).

(i) Report the information requested in the form at the end of SB 67-0007, along with a photo of each side of the installed T/R actuator back-end input lever, by email to: pse_aw189.mbx.aw@leonardocompany.com. Refer to Figure 4 and Figure 5 of SB 67-0007 for an example of each photo.

(ii) If the width of the bearing circular collar of the input lever is within the allowable limits of 4 ± 0.3 mm, the input lever pin head is not on side “A” of the T/R actuator as shown in Figure 2b of SB 67-0007 (the input lever pin head is on side “B”), and the nut and cotter pin of the intermediate bolt are installed on side “A” of the T/R actuator side as shown in Figure 3 of SB 67-0007, before further flight, mark “SB 67-0007” on the input lever with permanent ink as shown in Figure 4 of SB 67-0007.

(iii) If the width of the bearing circular collar of the input lever is outside the allowable limits of 4 ± 0.3 mm, the input lever pin head is on side “A” of the T/R actuator, or the nut and cotter pin of the intermediate bolt are not installed on side “A” of the T/R actuator side, before further flight, use Table 1 to paragraph (e)(1)(iii) of this AD for next instruction.

Circular collar width of the input lever is within the allowable limits of 4 +/- 0.3 mm.	The input lever pin head is not on side “A” of the T/R actuator (the input lever pin head is on side “B”).	The nut and cotter pin of the intermediate bolt are installed on side “A” of the T/R actuator.	Instruction:
Yes	Yes	No	Proceed to paragraph (e)(1)(v) of this AD
No	No	Yes	Proceed to paragraph (e)(1)(v) of this AD
No	No	No	Proceed to paragraph (e)(1)(v) of this AD
Yes	No	No	Proceed to paragraph (e)(1)(iv) of this AD
Yes	No	Yes	Proceed to paragraph (e)(1)(iv) of this AD
No	Yes	Yes	Proceed to paragraph (e)(1)(iv) of this AD
No	Yes	No	Proceed to paragraph (e)(1)(iv) of this AD

Table 1 to Paragraph (e)(1)(iii)

(iv) Before further flight, inspect for correct bonding (no axial or rotational relative movement compared to the lever) of each bearing by moving the input lever along the pin axial direction.

(A) If there is no axial or rotational relative movement compared to the lever in both bearings, within 10 hours TIS after completing the inspections required by paragraph (e)(1) of this AD, remove from service the T/R actuator.

(B) If there is axial or rotational relative movement compared to the lever in one or both bearings, before further flight, remove from service the T/R actuator.

(v) Within 60 hours TIS after completing the inspections required by paragraph (e)(1) of this AD, remove from service the T/R actuator.

(2) After the effective date of this AD, do not install a T/R actuator P/N 6F6730V00331 with an S/N up to 489 inclusive, except those marked with “SB 67-0007,” on any helicopter.

(f) Special Flight Permits

Special flight permits are prohibited.

(g) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this

information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to David Hatfield, Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(i) Additional Information

(1) Leonardo Helicopters Alert Service Bulletin (ASB) No. 169-129 and Leonardo Helicopters ASB No. 189-220, both dated January 30, 2019, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2019-0019, dated January 30, 2019. You may view the EASA AD on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No.FAA-2019-0813.

(j) Subject

Joint Aircraft Service Component (JASC) Code: 6400, Tail Rotor System.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) UTC Aerospace Systems (Collins Aerospace) Service Bulletin No. 67-0007, Basic Issue, dated January 17, 2019.

Note 1 to paragraph (k)(2)(i): UTC Aerospace Systems (Collins Aerospace) Service Bulletin No. 67-0007, Basic Issue, dated January 17, 2019, is attached as Annex A to Leonardo Helicopters ASB No. 169-129 and Leonardo Helicopters ASB No. 189-220, both dated January 30, 2019, which are not incorporated by reference in this AD.

(ii) [Reserved]

(3) For UTC Aerospace Systems service information identified in this AD, contact Collins Aerospace (previously UTC Aerospace Systems); telephone 1-877-808-7575; fax 1-860-660-0372; email tech.solutions@hs.utc.com; or at <https://utcaerospacesystems.com/aftermarket-services/technical-support/>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on November 20, 2019.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2019-27633 Filed 12-20-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 31288; Amdt. No. 3884]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the

commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective December 23, 2019. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 23, 2019.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001;

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Navigation Products, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center online at nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg. 29, Room 104, Oklahoma City, OK 73169. Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) by amending the referenced SIAPs. The

complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (NFDC)/Permanent Notice to Airmen (P-NOTAM), and is incorporated by reference under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR 97.20. The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained on FAA form documents is unnecessary.

This amendment provides the affected CFR sections, and specifies the SIAPs and Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure and the amendment number.

Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and ODPs as identified in the amendatory language for part 97 of this final rule.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP and Takeoff Minimums and ODP as amended in the transmittal. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained for each SIAP and Takeoff Minimums and ODP as modified by FDC permanent NOTAMs.

The SIAPs and Takeoff Minimums and ODPs, as modified by FDC permanent NOTAM, and contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these changes to SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied only to specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a FDC NOTAM as an emergency action of immediate flight safety relating directly to published aeronautical charts.

The circumstances that created the need for these SIAP and Takeoff