

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-1070; Product Identifier 2019-NM-178-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 and 787-9 airplanes. This proposed AD was prompted by reports that the cabin air compressor (CAC) outlet check valve failed due to fatigue of the aluminum flappers, and exposed the Y-duct to temperatures above its design limit. This proposed AD would require installing new inboard and outboard CAC outlet check valves on the left-side and right-side cabin air conditioning and temperature control system (CACTCS) packs. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by February 24, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this

material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1070.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1070; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Allie Buss, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3564; email: Allison.Buss@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2019-1070; Product Identifier 2019-NM-178-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

Discussion

The FAA has received reports that the CAC outlet check valve failed due to fatigue of the aluminum flappers, and exposed the Y-duct to temperatures above its design limit. Operators have reported failures of the CAC outlet check valve caused by fatigue of the aluminum flappers due to increasing open/close cycles, induced by CAC surge. This can cause reverse flow through the broken check valve from the

operational CAC. The reverse flow is recirculated through the operational CAC inlet ducting and reheating CAC air, leading to exposure of the Y-duct to temperatures above its design limit. This condition, if not addressed, could expose the flight deck and passenger cabin to smoke and fumes, and lead to reduced crew performance or produce passenger discomfort. Off gassed compounds could cause respiratory distress and could cause serious injury for an individual with a compromised respiratory system. The new check valve has an improved design with a stronger Corrosion Resistant Steel (CRES) housing and flappers, and an increased stopper contact area for better distribution of the flapper load.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Boeing Service Bulletin B787-81205-SB210108-00, Issue 002, dated October 15, 2019. The service information describes procedures for installing new inboard and outboard CAC outlet check valves on the left-side and right-side CACTCS packs. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified as “RC” (required for compliance) in the Accomplishment Instructions of Boeing Service Bulletin B787-81205-SB210108-00, Issue 002, dated October 15, 2019, described previously.

For information on the procedures and compliance times, see this service information at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1070.

Costs of Compliance

The FAA estimates that this proposed AD affects 90 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace CAC outlet check valves.	3 work-hours × \$85 per hour = \$255 per check valve.	\$0	\$255 per check valve ...	\$22,950 per check valve.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty by UTC Aerospace Systems, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA has determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2019–1070; Product Identifier 2019–NM–178–AD.

(a) Comments Due Date

The FAA must receive comments on this AD action by February 24, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787–8 and 787–9 airplanes, certificated in any category, as identified in Boeing Service Bulletin B787–81205–SB210108–00, Issue 002, dated October 15, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 21, Air conditioning.

(e) Unsafe Condition

This AD was prompted by reports that the cabin air compressor (CAC) outlet check valve failed due to fatigue of the aluminum flappers, and exposed the Y-duct to temperatures above its design limit. The FAA is issuing this AD to address this condition,

which could expose the flight deck and passenger cabin to smoke and fumes, and lead to reduced crew performance or produce passenger discomfort. Off gassed compounds could cause respiratory distress and could cause serious injury for an individual with a compromised respiratory system.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 5., "Compliance," of Boeing Service Bulletin B787–81205–SB210108–00, Issue 002, dated October 15, 2019, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Service Bulletin B787–81205–SB210108–00, Issue 002, dated October 15, 2019.

(h) Exceptions to Service Information Specifications

Where Boeing Service Bulletin B787–81205–SB210108–00, Issue 002, dated October 15, 2019, uses the phrase "the Issue 002 date of this service bulletin," this AD requires using "the effective date of this AD."

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install a CAC outlet check valve, with a part number listed in paragraph 1.B, "Spares Affected" of Boeing Service Bulletin B787–81205–SB210108–00, Issue 002, dated October 15, 2019, on any airplane.

(j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin B787–81205–SB210108–00, Issue 001, dated May 25, 2018.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Allie Buss, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3564; email: Allison.Buss@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740 5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on December 31, 2019.

John P. Piccola,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2020-00059 Filed 1-9-20; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 282

[EPA-R10-UST-2019-0363; FRL-10003-27-Region 10]

Idaho: Final Approval of State Underground Storage Tank Program Revisions, Codification, and Incorporation by Reference

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: Pursuant to the Resource Conservation and Recovery Act (RCRA or Act), the Environmental Protection Agency (EPA) is proposing to approve revisions to the State of Idaho's Underground Storage Tank (UST) program submitted by the State. This action is based on EPA's determination that the State's revisions satisfy all requirements for UST program approval. This action also proposes to codify Idaho's State program as revised by Idaho and approved by the EPA and to incorporate by reference the State regulations that we have determined meet the requirements for approval. The State's federally-authorized and codified UST program, as revised pursuant to this action, will remain subject to the EPA's inspection and enforcement authorities under sections 9005 and 9006 of RCRA Subtitle I and other applicable statutory and regulatory provisions.

DATES: Send written comments by February 10, 2020.

ADDRESSES: Submit your comments by one of the following methods:

1. *Federal eRulemaking Portal:* <https://www.regulations.gov>. Follow the online instructions for submitting comments.

2. *Email:* wilder.scott@epa.gov.

3. *Mail:* Scott Wilder, Enforcement and Compliance Assurance Division (ECAD 20-C04) EPA Region 10, 1200 Sixth Avenue, Suite 155, Seattle, Washington 98101.

4. *Hand Delivery or Courier:* Deliver your comments to Scott Wilder, Enforcement and Compliance Assurance Division (ECAD 20-C04), EPA Region 10, 1200 Sixth Avenue, Suite 155, Seattle, Washington 98101.

Instructions: Direct your comments to Docket ID No. EPA-R10-UST-2019-0363. The EPA's policy is that all comments received will be included in the public docket without change and may be available online at <https://www.regulations.gov>, including any personal information provided, unless

the comment includes information claimed to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Do not submit information that you consider to be CBI or otherwise protected through <https://www.regulations.gov>, or email. The federal <https://www.regulations.gov> website is an "anonymous access" system, which means the EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send an email comment directly to the EPA without going through <https://www.regulations.gov>, then your email address will be automatically captured and included as part of the comment that is placed in the public docket and made available on the internet. If you submit an electronic comment, then the EPA recommends that you include your name and other contact information in the body of your comment and with any disk or CD-ROM you submit. If the EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, then the EPA may not be able to consider your comment. Electronic files should avoid the use of special characters, any form of encryption, and be free of any defects or viruses.

You can view and copy the documents that form the basis for this action and associated publicly available materials from 8:30 a.m. to 4:00 p.m. Monday through Friday at the following location: EPA Region 10, 1200 Sixth Avenue, Seattle, Washington 98101, phone number (206) 553-6693. Interested persons wanting to examine these documents should make an appointment with the office at least 2 days in advance.

FOR FURTHER INFORMATION CONTACT: Scott Wilder, (206) 553-6693, Region 10, Enforcement and Compliance Assurance Agreement, EPA Region 10, 1200 Sixth Avenue, Seattle, Washington, 98101, email address: wilder.scott@epa.gov.

SUPPLEMENTARY INFORMATION: For additional information, see the direct final rule published in the "Rules and Regulations" section of this **Federal Register**.

Authority: This rule is issued under the authority of Sections 2002(a), 9004, and 7004(b) of the Solid Waste Disposal Act, as amended, 42 U.S.C. 6912, 6991c, 6991d, and 6991e.

Dated: November 27, 2019.

Chris Hladick,

Regional Administrator, EPA Region 10.

[FR Doc. 2019-28391 Filed 1-9-20; 8:45 am]

BILLING CODE 6560-50-P