

List of Subjects**5 CFR Part 1600**

Government employees, Pensions, Retirement.

5 CFR Part 1650

Alimony, Claims, Government employees, Pensions, Retirement.

Ravindra Deo,

Executive Director, Federal Retirement Thrift Investment Board.

For the reasons stated in the preamble, the FRTIB proposes to amend 5 CFR Chapter VI as follows:

PART 1600—EMPLOYEE CONTRIBUTION ELECTIONS, CONTRIBUTION ALLOCATIONS, AND AUTOMATIC ENROLLMENT PROGRAM

■ 1. The authority citation will continue to read as follows:

Authority: 5 U.S.C. 8351, 8432(a), 8432(b), 8432(c), 8432(j), 8432d, 8474(b)(5) and (c)(1), and 8440e.

§ 1600.34 [Amended]

■ 2. In § 1600.34, amend paragraphs (a), (b), and (c) by removing the term “3%” and adding the term “5%” in its place.

§ 1600.37 [Amended]

■ 3. In § 1600.37, amend paragraph (a) by removing the term “3 percent” and adding the term “5 percent” in its place.

PART 1650—METHODS OF WITHDRAWING FUNDS FROM THE THRIFT SAVINGS PLAN

■ 4. The authority citation continues to read as follows:

Authority: 5 U.S.C. 8351, 8432d, 8433, 8434, 8435, 8474(b)(5) and 8474(c)(1).

■ 5. Amend § 1650.13 by revising paragraph (a)(2) to read as follows:

§ 1650.13 Installment payments.

(a) * * *

(2) *An installment payment amount calculated based on life expectancy.* Payments based on life expectancy are determined using the factors set forth in the Internal Revenue Service life expectancy tables codified at 26 CFR 1.401(a)(9)–9, Q&A 1 and 2. The installment payment amount is calculated by dividing the account balance by the factor from the IRS life expectancy tables based upon the participant’s age as of his or her birthday in the year payments are to begin. This amount is then divided by the number of installment payments to be made per calendar year to yield the installment payment amount. In subsequent years, the installment

payment amount is recalculated on the first installment payment date of the year by dividing the prior December 31 account balance by the factor in the IRS life expectancy tables based upon the participant’s age as of his or her birthday in the year payments will be made. There is no minimum amount for an installment payment calculated based on this method.

* * * * *

[FR Doc. 2020–03102 Filed 2–14–20; 8:45 am]

BILLING CODE 6760–01–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2020–0092; Product Identifier 2020–NM–001–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes, Model CL–600–2C10 (Regional Jet Series 700, 701 & 702) airplanes, Model CL–600–2D15 (Regional Jet Series 705) airplanes, and Model CL–600–2D24 (Regional Jet Series 900) airplanes; and all Model CL–600–2C11 (Regional Jet Series 550) airplanes. This proposed AD was prompted by reports of fractured rudder primary feel unit shafts; a subsequent investigation determined that the fractures in the shafts are consistent with fatigue damage. This proposed AD would require replacement of the rudder primary feel unit shaft. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by April 3, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1–866–538–1247 or direct-dial telephone 1–514–855–2999; fax 514–855–7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0092; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Andrea Jimenez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7330; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2020–0092; Product Identifier 2020–NM–001–AD” at the beginning of your comments. The FAA specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2019-42, dated November 8, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, Model CL-600-2C10 (Regional Jet Series 700, 701 & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, and Model CL-600-2D24 (Regional Jet Series 900) airplanes; and all Model CL-600-2C11 (Regional Jet Series 550) airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0092.

This proposed AD was prompted by reports of fractured rudder primary feel unit shafts; a subsequent investigation determined that the fractures in the shafts are consistent with fatigue damage. The FAA is proposing this AD

to address fractures of the rudder primary feel unit shaft, which could result in a loss of feel in the yaw axis and thereby impact the controllability of the airplane. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin 601R-27-166, dated April 5, 2019, and Service Bulletin 670BA-27-075, dated April 5, 2019. This service information describes procedures for replacing the rudder primary feel unit shaft that has part number 600-90251-1 with a new shaft. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

This product has been approved by the aviation authority of another

country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

The FAA estimates that this proposed AD affects 1,002 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
18 work-hours × \$85 per hour = \$1,530	\$158	\$1,688	\$1,691,376

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

The FAA has determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2020-0092; Product Identifier 2020-NM-001-AD.

(a) Comments Due Date

We must receive comments by April 3, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. airplanes, certificated in any category, as specified in paragraphs (c)(1) through (4) of this AD.

(1) Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, serial number (S/N) 7003 through 7990 inclusive, and S/N 8000 and subsequent.

(2) Model CL-600-2C10 (Regional Jet Series 700, 701 & 702) airplanes, S/N 10002 through 10347 inclusive.

(3) Model CL-600-2D15 (Regional Jet Series 705) airplanes and Model CL-600-2D24 (Regional Jet Series 900) airplanes, S/N 15001 through 15469 inclusive.

(4) Model CL-600-2C11 (Regional Jet Series 550) airplanes, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports of fractured rudder primary feel unit shafts; a subsequent investigation determined that the fractures in the shafts are consistent with fatigue damage. The FAA is issuing this AD to address fractures of the rudder primary feel unit shaft, which could result in a loss of feel in the yaw axis and thereby impact the controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within the compliance times specified in figure (1) to paragraph (g) of this AD: Replace all rudder primary feel unit shafts that have part number (P/N) 600-90251-1 with a new shaft, in accordance with the Accomplishment Instructions of the Bombardier Service Bulletin 601R-27-166, dated April 5, 2019; or Bombardier Service Bulletin 670BA-27-075, dated April 5, 2019; as applicable. For Model CL-600-2C11 (Regional Jet Series 550) airplanes, do the replacement in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-075, dated April 5, 2019.

Figure 1 to paragraph (g) – Compliance Times

Accumulated Airplane Flight Cycles	Compliance Time for the Replacement
For airplanes that have accumulated 22,000 total flight cycles or less as of the effective date of this AD.	Before the airplane reaches 30,000 total flight cycles.
For airplanes that have accumulated more than 22,000 total flight cycles, but less than 37, 000 total flight cycles as of the effective date of this AD.	Within 8,000 flight cycles from the effective date of this AD.
For airplanes that have accumulated 37,000 total flight cycles or more, but less than 40,000 total flight cycles as of the effective date of this AD.	Before the airplane reaches 45,000 total flight cycles.
For airplanes that have accumulated 40,000 total flight cycles or more, but less than 46,500 total flight cycles as of the effective date of this AD.	Within 5,000 flight cycles from the effective date of this AD.
For airplanes that have accumulated 46,500 total flight cycles or more as of the effective date of this AD.	Before the airplane reaches 51,500 total flight cycles.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install a rudder primary feel unit shaft, P/N 600-90251-1, on any airplane.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office,

send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by

the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-42, dated November 8, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0092.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on February 11, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-03042 Filed 2-14-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-1115; Product Identifier 2018-SW-065-AD]

RIN 2120-AA64

Airworthiness Directives; Sikorsky Aircraft Corporation Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Sikorsky Aircraft Corporation (Sikorsky) Model S-92A helicopters. This proposed AD was prompted by two incidents of erroneous low oil pressure caution cockpit indications and unintended actuation of the main gearbox (MGB) auto bypass valve. This proposed AD would require installing auxiliary circuit breaker modification (MOD) kits and inserting a Rotorcraft Flight Manual (RFM) Supplement into the RFM for your helicopter. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by April 3, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact your local Sikorsky Field Representative or Sikorsky's Service Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S; email wcs_cust_service_eng.gr-sik@lmco.com. Operators may also log on to the Sikorsky 360 website at <https://www.sikorsky360.com>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-1115; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Michael Schwetz, Aviation Safety Engineer, Boston ACO Branch, Compliance & Airworthiness Division, FAA, 1200 District Avenue, Burlington, MA 01803; telephone 781-238-7761; email michael.schwetz@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-1115; Product Identifier 2018-SW-065-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The

FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

Discussion

The FAA proposes to adopt a new AD for Sikorsky Model S-92A helicopters. This proposed AD is prompted by two incidents of erroneous low oil pressure caution cockpit indications and unintended actuation of the MGB auto bypass valve caused by unintended popping of the M XMSN OIL WARN circuit breaker during flight. The root cause of this circuit breaker popping is unknown. When this circuit breaker trips, the following cautions will display "MGB PUMP 1 FAIL, MGB PUMP 2 FAIL, MGB OIL HOT, MGB MAN COOL, MGB OIL PRES." With the MGB auto bypass valve actuated, the MGB BYPASS caution will not annunciate. For the given conditions, the appropriate action for the crew is "land as soon as possible" in accordance with the RFM Emergency Procedures. The erroneous indications conflicting with correct gauge readings may overwhelm the flight crew, resulting in a forced landing of the helicopter.

To address this unsafe condition, Sikorsky developed MOD kits based on helicopter serial number (S/N) to introduce a separate circuit breaker for the MGB last jet pressure switch. These MOD kits specify reworking the overhead panel to install new clips and brackets, circuit breaker wiring harnesses, wiring MODs, the auxiliary circuit breaker panel, and the M XMSN PRESS SWITCH circuit breaker.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Sikorsky Special Service Instructions No. 92-121, dated October 26, 2017 (SSI 92-121). This service information describes procedures for installing an auxiliary circuit breaker panel MOD kit and M XMSN PRESS SWITCH circuit breaker MOD kit based on helicopter S/N.

The FAA also reviewed RFM Supplement No. 45, Revision No. 2, Sikorsky Model S-92A, Part 1, dated April 27, 2017 (S-92A RFMS 45, Part 1, Revision 2). This service information specifies operating limitations, preflight checks, normal and emergency procedures, and malfunction information for helicopters with Avionics Management System version 7.1 or 8.0 with the MGB OIL OUT warning activated, pump failure indicating system, MGB auto bypass, and M XMSN PRESS SWITCH circuit breaker installed.