

power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2019–11–08, Amendment 39–19654 (84 FR 27511, June 13, 2019), and adding the following new AD:

2020–05–28 International Aero Engines

LLC: Amendment 39–19878; Docket No. FAA–2019–0614; Product Identifier 2019–NE–14–AD.

(a) Effective Date

This AD is effective April 21, 2020.

(b) Affected ADs

This AD replaces AD 2019–11–08, Amendment 39–19654 (84 FR 27511, June 13, 2019).

(c) Applicability

This AD applies to all International Aero Engines, LLC (IAE) PW1133G–JM, PW1133GA–JM, PW1130G–JM, PW1129G–JM, PW1127G–JM, PW1127GA–JM, PW1127G1–JM, PW1124G–JM, PW1124G1–JM, and PW1122G–JM model turbofan engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7260, Turbine Engine Accessory Drive.

(e) Unsafe Condition

This AD was prompted by multiple reports of in-flight engine shutdowns as the result of high-cycle fatigue causing fracture of certain parts of the main gearbox (MGB) assembly. The FAA is issuing this AD to prevent failure of the MGB assembly. The unsafe condition, if not addressed, could result in failure of one

or more engines, loss of thrust control, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

- (1) Remove the MGB assembly, part number (P/N) 5322505, and install a part eligible for installation as follows:
 - (i) For engines that operate on 180-minute extended operations (ETOPS) flights, before further flight after the effective date of this AD.
 - (ii) For engines that operate on 120-minute ETOPS flights, within 120 days from June 28, 2019 (the effective date of AD 2019–11–08), or before further flight after the effective date of this AD, whichever occurs later.
 - (iii) For engines that do not operate on ETOPS flights, at the next engine shop visit after the effective date of this AD.
- (2) For engines with MGB assembly P/N 5322505, within 120 days from June 28, 2019 (the effective date of AD 2019–11–08), or before further flight after the effective date of this AD, whichever occurs later, remove electronic engine control (EEC) software earlier than FCS5.0 from the engine and install EEC software that is eligible for installation.

(h) Installation Prohibition

- (1) After the effective date of this AD, do not install integrated drive generator (IDG) oil pump drive gearshaft assembly, P/N 5322630–01, into an MGB assembly.
- (2) After the effective date of this AD, do not load EEC software earlier than FCS5.0 on any engine identified in paragraph (c) of this AD with an MGB assembly, P/N 5322505.

(i) Definitions

- (1) For the purpose of this AD, a “part eligible for installation” is an MGB assembly with an IDG oil pump drive gearshaft assembly other than P/N 5322630–01.
- (2) For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation of the engine without subsequent engine maintenance does not constitute an engine shop visit.
- (3) For the purpose of this AD, “EEC software that is eligible for installation” is EEC software FCS5.0 and later.

(j) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Kevin M. Clark, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781–238–7088; fax: 781–238–7199; email: kevin.m.clark@faa.gov.

(l) Material Incorporated by Reference

None.

Issued on March 11, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–05330 Filed 3–16–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0974; Product Identifier 2019–NM–155–AD; Amendment 39–19856; AD 2020–04–19]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2017–15–01, which applied to certain The Boeing Company Model 777 airplanes. AD 2017–15–01 required replacing the existing mode control panel (MCP) with a new MCP having a different part number. This AD retains the requirements of AD 2017–15–01, expands the applicability to include certain other airplanes, and adds a new requirement for certain airplanes to identify and replace the affected parts. This AD was prompted by a determination that the affected parts may be installed on airplanes outside of the original applicability of AD 2017–15–01. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 21, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 25, 2017 (82 FR 33782, July 21, 2017).

ADDRESSES: For service information identified in this final rule, contact

Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0974.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0974; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and

fax: 206-231-3539; email: frank.carreras@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2017-15-01, Amendment 39-18961 (82 FR 33782, July 21, 2017) (“AD 2017-15-01”). AD 2017-15-01 applied to certain The Boeing Company Model 777 airplanes. The NPRM published in the **Federal Register** on December 13, 2019 (84 FR 68060). The NPRM was prompted by a determination that the affected parts may be installed on airplanes outside of the original applicability of AD 2017-15-01. The NPRM proposed to retain the requirements of AD 2017-15-01, expand the applicability to include those other airplanes, and add a new requirement for certain airplanes to identify and replace the affected parts. The FAA is issuing this AD to address uncommanded changes to the MCP selected altitude; such uncommanded changes could result in incorrect spatial separation between airplanes, midair collision, or controlled flight into terrain.

Comments

The FAA gave the public the opportunity to participate in developing this AD. The FAA has considered the comments received. The Air Line Pilots Association, International (ALPA) and Boeing indicated their support for the

NPRM. United Airlines and FedEx had no objection to the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

This AD requires Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016, which the Director of the Federal Register approved for incorporation by reference as of August 25, 2017 (82 FR 33782, July 21, 2017). This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 231 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement	2 work-hours × \$85 per hour = \$170	Up to \$5,800 * ..	Up to \$5,970 * ..	Up to \$1,379,070 *.
(retained actions from AD 2017-15-01) ..				
Inspection/records check (new proposed action) (up to 28 airplanes).	1 work-hour × \$85 per hour = \$85	\$0	\$85	Up to \$2,380.

* Since the FAA has received no definitive data regarding the cost of a new MCP, the FAA has provided costs for the upgrade (modified part) only.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing

regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA has determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of

power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2017-15-01, Amendment 39-18961 (82 FR 33782, July 21, 2017), and adding the following new AD:

2020-04-19 The Boeing Company:

Amendment 39-19856 ; Docket No. FAA-2019-0974; Product Identifier 2019-NM-155-AD.

(a) Effective Date

This AD is effective April 21, 2020.

(b) Affected ADs

This AD replaces AD 2017-15-01, Amendment 39-18961 (82 FR 33782, July 21, 2017) (“AD 2017-15-01”).

(c) Applicability

This AD applies to all The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

(e) Unsafe Condition

This AD was prompted by reports of uncommanded altitude display changes in the mode control panel (MCP) altitude window. The FAA is issuing this AD to address uncommanded changes to the MCP selected altitude; such uncommanded changes could result in incorrect spatial separation between airplanes, midair collision, or controlled flight into terrain.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) New Definitions

(1) For the purposes of this AD, an affected part is an MCP having part number S241W001-201, S241W001-202, S241W001-251, S241W001-252, or S241W001-261.

(2) For the purposes of this AD, later-approved parts are only those parts that are approved as a replacement for the applicable part identified in Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016; and are approved as part of the type

design by the FAA or The Boeing Company Organization Designation Authorization (ODA) after March 3, 2016 (the publication date of Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016).

(h) Retained Replacement of MCP With Revised Compliance Language

This paragraph restates the requirements of AD 2017-15-01, with revised compliance language. For airplanes identified in Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016, within 60 months after August 25, 2017, (the effective date of AD 2017-15-01): Do the actions specified in paragraph (h)(1) or (2) of this AD.

(1) Replace the existing MCP part with an MCP having part number S241W001-262, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016.

(2) Install a later-approved part as defined in paragraph (g)(2) of this AD.

(i) New MCP Identification and Replacement

For airplanes not identified in paragraph (h) of this AD with an original airworthiness certificate or original export certificate of airworthiness issued on or before the effective date of this AD, do the actions specified in paragraphs (i)(1) and (2) of this AD.

(1) Within 60 months after the effective date of this AD, perform a general visual inspection of the MCP to determine the MCP part number. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the MCP can be conclusively determined from that review.

(2) If the MCP is an affected part, within 60 months after the effective date of this AD: Do the actions specified in paragraph (i)(2)(i) or (ii) of this AD.

(i) Replace the existing MCP with an MCP having part number S241W001-262, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016.

(ii) Install a later-approved part as defined in paragraph (g)(2) of this AD.

(j) Parts Installation Prohibition

As of the effective date of this AD, no person may install an MCP having part number S241W001-201, S241W001-202, S241W001-251, S241W001-252, or S241W001-261, on any airplane.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company ODA that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2017-15-01 are approved as AMOCs for the corresponding provisions of this AD.

(5) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(5)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

For more information about this AD, contact Frank Carreras, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3539; email: frank.carreras@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on August 25, 2017 (82 FR 33782, July 21, 2017).

(i) Boeing Special Attention Service Bulletin 777-22-0034, dated March 3, 2016.

(ii) [Reserved]

(4) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(5) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this service information that is incorporated by reference at the

National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 25, 2020.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2020-05362 Filed 3-16-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

U.S. Customs and Border Protection

19 CFR Chapter I

Transportation Security Administration

49 CFR Chapter XII

Notification of Arrival Restrictions Applicable to Flights Carrying Persons Who Have Recently Traveled From or Were Otherwise Present Within the Countries of the Schengen Area

AGENCY: U.S. Customs and Border Protection and U.S. Transportation Security Administration, Department of Homeland Security.

ACTION: Notification of arrival restrictions.

SUMMARY: This document announces the decision of the Secretary of Homeland Security (DHS) to direct all flights to the United States carrying persons who have recently traveled from, or were otherwise present within, the countries of the Schengen Area to arrive at one of the United States airports where the United States Government is focusing public health resources. There are twenty-six countries in the Schengen Area: Austria, Belgium, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Italy, Latvia, Liechtenstein, Lithuania, Luxembourg, Malta, the Netherlands, Norway, Poland, Portugal, Slovakia, Slovenia, Spain, Sweden, and Switzerland. This document also modifies two notifications regarding decisions of the Secretary of DHS: To direct all flights to the United States carrying persons who have recently traveled from, or were otherwise present within, the People's Republic of China (excluding the Special Regions of Hong Kong and Macau) to arrive at one of the United States airports where the United States Government is focusing public health resources (effective February 2, 2020); and to direct all flights to the

United States carrying persons who have recently traveled from, or were otherwise present within, the Islamic Republic of Iran to arrive at one of the United States airports where the United States Government is focusing public health resources (effective March 2, 2020). This document also adds two additional airports to the list of airports where flights subject to the arrival restrictions are permitted to land—Boston Logan International Airport (BOS) and Miami International Airport (MIA).

DATES: Flights departing after 11:59 p.m. Eastern Daylight Time on Friday, March 13, 2020, and covered by the arrival restrictions regarding the countries of the Schengen Area are required to land at one of the airports identified in this document. These arrival restrictions will continue until cancelled or modified by the Secretary of DHS and notification is published in the **Federal Register** of such cancellation or modification.

FOR FURTHER INFORMATION CONTACT: Matthew S. Davies, Office of Field Operations, U.S. Customs and Border Protection (CBP) at 202-325-2073.

SUPPLEMENTARY INFORMATION:

Background

Coronaviruses are a large family of viruses that are common in many different species of animals, including camels, cattle, cats, and bats. While it is rare, animal coronaviruses can infect people, and then spread between people (human-to-human) such as with Middle East Respiratory Syndrome and Severe Acute Respiratory Syndrome. The United States Government is closely monitoring an outbreak of respiratory illness caused by human-to-human transmission of a novel (new) coronavirus (which has since been renamed “SARS-CoV-2” and causes the disease COVID-19), first identified in Wuhan City, Hubei Province, People's Republic of China.

The potential for widespread transmission of this virus by infected individuals seeking to enter the United States threatens the security of our transportation system and infrastructure, and the national security. Noting recent pronouncements by the World Health Organization (WHO) and the Centers for Disease Control and Prevention (CDC) for the novel coronavirus outbreak to assist in preventing the introduction, transmission, and spread of this communicable disease globally and in the United States, including the categorization by WHO of COVID-19 as a pandemic on March 11, 2020, DHS, in

coordination with CDC and other Federal, state and local agencies charged with protecting the American public, is implementing enhanced protocols to ensure that all travelers seeking to enter the United States with recent travel from, or who were otherwise recently present within, any of the countries of the Schengen Area are provided appropriate public health services.

The enhanced arrival protocols concerning travelers with recent travel from, or who were otherwise recently present within, the People's Republic of China, excluding the Special Administrative Regions of Hong Kong and Macau, identified in the documents published at 85 FR 6044 on February 4, 2020 and 85 FR 7214 on February 7, 2020, also remain in place in this notice, except that flights are permitted to land at two additional airports. The enhanced arrival protocols concerning travelers with recent travel from, or who were otherwise present within, the Islamic Republic of Iran, identified in the document published at 85 FR 12731 on March 4, 2020, also remain in place in this notice except that flights are permitted to land at two additional airports.

Enhanced traveler arrival protocols are part of a layered approach used with other public health measures already in place to detect arriving travelers who are exhibiting overt signs of illness. Related measures include reporting ill travelers identified by carriers during travel to appropriate public health officials for evaluation, and referring ill travelers arriving at a U.S. port of entry by CBP to appropriate public health officials in order to slow and prevent the introduction into, and transmission and spread of, communicable disease in the United States.

To ensure that travelers with recent presence in the countries of the Schengen Area are screened appropriately, DHS directs that all flights to the United States carrying persons who have recently traveled from, or were otherwise present within, the countries of the Schengen Area arrive at airports where enhanced public health services and protocols have been implemented. Although DHS will continue to work with carriers to ensure that they identify potential persons who traveled from, or who have otherwise recently been present within, the affected areas prior to boarding, carriers shall comply with the requirements of this document in all cases, including when such persons are identified after boarding but prior to takeoff.

On Friday, January 31, 2020, DHS posted a document on the **Federal Register** public inspection page, in