

featured significant levels of volatility. In approving changes to parts 225 and 238 of the Board's regulations, the Board noted that companies may need to consult with Board staff about prior investments and relationships that have not been previously reviewed by the Board. Delaying the changes to parts 225 and 238 of the Board's regulations will allow companies additional time to consult with Board staff about existing investments and relationships, allowing companies greater flexibility to focus on COVID-19-related issues. For these reasons, the Board finds that there is good cause consistent with the public interest to issue the rule without advance notice and comment.³

The APA also requires a 30-day delayed effective date, except for (1) substantive rules which grant or recognize an exemption or relieve a restriction; (2) interpretative rules and statements of policy; or (3) as otherwise provided by the agency for good cause.⁴ As noted above, the Board finds that there is good cause to delay the effective date of the previously approved changes to parts 225 and 238 of the Board's regulations, for the reasons noted above.⁵

B. Congressional Review Act

For purposes of Congressional Review Act, the OMB makes a determination as to whether a final rule constitutes a "major" rule.⁶ If a rule is deemed a "major rule" by the Office of Management and Budget (OMB), the Congressional Review Act generally provides that the rule may not take effect until at least 60 days following its publication.⁷

The Congressional Review Act defines a "major rule" as any rule that the Administrator of the Office of Information and Regulatory Affairs of the OMB finds has resulted in or is likely to result in (A) an annual effect on the economy of \$100,000,000 or more; (B) a major increase in costs or prices for consumers, individual industries, Federal, State, or local government agencies or geographic regions, or (C) significant adverse effects on competition, employment, investment, productivity, innovation, or on the ability of United States-based enterprises to compete with foreign-based enterprises in domestic and export markets.⁸

For the same reasons set forth above, the Board is adopting the final rule without the delayed effective date generally prescribed under the Congressional Review Act. The delayed effective date required by the Congressional Review Act does not apply to any rule for which an agency for good cause finds (and incorporates the finding and a brief statement of reasons therefor in the rule issued) that notice and public procedure thereon are impracticable, unnecessary, or contrary to the public interest.⁹ In light of current market uncertainty, the Board believes that delaying the effective date of the rule would be contrary to the public interest.

As required by the Congressional Review Act, the Board will submit the final rule and other appropriate reports to Congress and the Government Accountability Office for review.

C. Paperwork Reduction Act

In accordance with the requirements of the Paperwork Reduction Act (PRA), an agency may not conduct or sponsor, and a respondent is not required to respond to, an information collection unless it displays a currently valid Office of Management and Budget (OMB) control number. The Board has reviewed this final rule pursuant to authority delegated by the OMB and has determined that it does not contain any collections of information pursuant to the PRA.

D. Regulatory Flexibility Act

The Regulatory Flexibility Act (RFA)¹⁰ requires an agency to consider whether the rules it proposes will have a significant economic impact on a substantial number of small entities.¹¹ The RFA applies only to rules for which an agency publishes a general notice of proposed rulemaking pursuant to 5 U.S.C. 553(b). As discussed previously, consistent with section 553(b)(B) of the APA, the Board has determined for good cause that general notice and opportunity for public comment is unnecessary, and therefore the Board is not issuing a notice of proposed rulemaking. Accordingly, the Board has concluded that the RFA's requirements relating to initial and final regulatory flexibility analysis do not apply.

⁹ 5 U.S.C. 808.

¹⁰ 5 U.S.C. 601 *et seq.*

¹¹ Under regulations issued by the Small Business Administration, a small entity includes a depository institution, bank holding company, or savings and loan holding company with total assets of \$600 million or less and trust companies with total assets of \$41.5 million or less. See 13 CFR 121.201.

E. Use of Plain Language

Section 722 of the Gramm-Leach-Bliley Act¹² requires the Federal banking agencies to use plain language in all proposed and final rules published after January 1, 2000. The Board has sought to present the final rule in a simple and straightforward manner. The Board invites comments on whether there are additional steps it could take to make the rule easier to understand.

By order of the Board of Governors of the Federal Reserve System, March 31, 2020.

Ann Misback,

Secretary of the Board.

[FR Doc. 2020-06993 Filed 3-31-20; 11:15 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0210; Product Identifier 2020-NM-045-AD; Amendment 39-19887; AD 2020-06-18]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A318, A319, A320, and A321 series airplanes. This AD was prompted by a recent maintenance repair organization's report to Airbus of deviations from the component maintenance manual acceptance test procedure for certain trimmable horizontal stabilizer actuators (THSAs). This AD requires replacement of affected THSAs with serviceable THSAs, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD becomes effective April 2, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publications listed in this AD as of April 2, 2020.

The FAA must receive comments on this AD by May 18, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

³ 5 U.S.C. 553(b)(3)(B); 553(d)(3).

⁴ 5 U.S.C. 553(d).

⁵ *Id.*

⁶ 5 U.S.C. 801 *et seq.*

⁷ 5 U.S.C. 801(a)(3).

⁸ 5 U.S.C. 804(2).

¹² 12 U.S.C. 4809.

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0210.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0210; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0073, dated March 26, 2020 (“EASA AD 2020-0073”) (also referred to as the Mandatory Continuing

Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, -133, -151N, -153N, and -171N airplanes; Model A320-211, -212, -214, -215, -216, -231, -232, -233, -251N, -252N, -253N, -271N, -272N, and -273N airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes. (Model A320-215 airplanes are not certified by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.)

This AD was prompted by a recent maintenance repair organization’s report to Airbus of deviations from the acceptance test procedure for certain THSAs as specified in the Airbus component maintenance manual (CMM) after disassembly and reassembly of the THSA ball screw sub-assembly. A deviation from the accepted test procedure affects, in particular, the verification of proper installation of the THSA ball screw in shop. Improper installation of the THSA ball screw jack compromises the fail safe design of the THSA that prevents the axial separation of the screw shaft. Subsequent missed inspections or testing regimes further compromise the fail safe design of the THSA. A compromised fail safe design of the THSA can result in a single failure of the THSA. The FAA is issuing this AD to address this unsafe condition, which can compromise fail safe design of the THSA, which may result in uncontrolled movement of the horizontal stabilizer as a result of a single failure, and consequent loss of control of the airplane. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2020-0073 describes procedures for replacing affected THSAs with serviceable THSAs. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition

described in the MCAI referenced above. The FAA is issuing this AD because the agency evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2020-0073 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020-0073 is incorporated by reference in this final rule. This AD, therefore, requires compliance with EASA AD 2020-0073 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2020-0073 that is required for compliance with EASA AD 2020-0073 is available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0210.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C.) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without seeking comment prior to the rulemaking. Similarly, Section 553(d) of the APA authorizes agencies to make

rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies foregoing notice and comment prior to adoption of this rule because, as described in the Discussion section of this AD, improper installation of THSA ball screw jack compromises fail safe design of the THSA, which can result in uncontrolled movement of the horizontal stabilizer as a result of a single failure of the THSA, and consequent loss of control of the airplane. Given the significance of the risk presented by this unsafe condition, it must be immediately addressed.

Accordingly, notice and opportunity for prior public comment are impracticable pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the reasons

stated above, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and the FAA did not precede it by notice and opportunity for public comment. The FAA invites you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the

ADDRESSES section. Include “Docket No. FAA–2020–0210; Product Identifier 2020–NM–045–AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this AD. The FAA will consider all comments received by the closing date and may amend this AD based on those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this AD.

Costs of Compliance

The FAA estimates that this AD affects 89 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 13 work-hours × \$85 per hour = Up to \$1,105	\$0	Up to \$1,105	Up to \$98,345.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2020–06–18 Airbus SAS: Amendment 39–19887; Docket No. FAA–2020–0210; Product Identifier 2020–NM–045–AD.

(a) Effective Date

This AD becomes effective April 2, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus SAS airplanes identified in paragraphs (c)(1) through (4) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Model A318–111, –112, –121, and –122 airplanes.

(2) Model A319–111, –112, –113, –114, –115, –131, –132, –133, –151N, –153N, and –171N airplanes.

(3) Model A320–211, –212, –214, –216, –231, –232, –233, –251N, –252N, –253N, –271N, –272N, and –273N airplanes.

(4) Model A321–111, –112, –131, –211, –212, –213, –231, –232, –251N, –251NX, –252N, –252NX, –253N, –253NX, –271N, –271NX, –272N, and –272NX airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by a maintenance repair organization’s report of deviations from the component maintenance manual acceptance test procedure for certain trimmable horizontal stabilizer actuators (THSAs). The FAA is issuing this AD to address improper installation of the THSA ball screw jack, which can compromise fail safe design of the THSA, that may result in uncontrolled movement of the horizontal stabilizer as a result of a single failure of the THSA, and consequent loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020-0073, dated March 26, 2020 (“EASA AD 2020-0073”).

(h) Exceptions to EASA AD 2020-0073

(1) Where EASA AD 2020-0073 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2020-0073 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA AD 2020-0073 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference

(IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020-0073, dated March 26, 2020.

(ii) [Reserved]

(3) For information about EASA AD 2020-0073, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0210.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 30, 2020.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-07009 Filed 3-31-20; 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-0876; Product Identifier 2019-NM-070-AD; Amendment 39-19877; AD 2020-05-27]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. This AD was prompted by a report that cracking was discovered in a channel within a structural support member for the rudder quadrant, rudder feel unit assembly, and environmental control system due to fatigue. This AD requires repetitive inspections of the rudder quadrant box assembly for any cracking,

and modification of the rudder quadrant box assembly. The FAA issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 7, 2020.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of May 7, 2020.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; internet <https://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0876.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0876; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Andrea Jimenez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2019-11, dated March 22, 2019 (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for