

# Rules and Regulations

Federal Register

Vol. 85, No. 66

Monday, April 6, 2020

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## FEDERAL RESERVE SYSTEM

### 12 CFR Chapter II

[Docket No. OP-1589]

#### Federal Reserve Policy on Payment System Risk; U.S. Branches and Agencies of Foreign Banking Organizations

**AGENCY:** Board of Governors of the Federal Reserve System.

**ACTION:** Notification of delay.

**SUMMARY:** The Board of Governors of the Federal Reserve System (“Board”) is delaying the implementation date of changes to part II of the Federal Reserve Policy on Payment System Risk (“PSR policy”) related to procedures for determining the net debit cap and maximum daylight overdraft capacity of a U.S. branch or agency of a foreign banking organization (“FBO”).

**DATES:** The implementation date of the amendments to the PSR policy published on April 1, 2019 (84 FR 12049), has been delayed from April 1, 2020 to October 1, 2020.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Walker, Deputy Associate Director (202-721-4559), Jason Hinkle, Assistant Director (202-912-7805); or Brajan Kola, Senior Financial Institution and Policy Analyst (202-736-5683), Division of Reserve Bank Operations and Payment Systems; or Evan Winerman, Senior Counsel (202-872-7578), Legal Division, Board of Governors of the Federal Reserve System. For users of Telecommunications Device for the Deaf (TDD) only, please call 202-263-4869.

**SUPPLEMENTARY INFORMATION:** On April 1, 2019, the Board approved amendments to part II of the PSR policy, which establishes the maximum levels of daylight overdrafts that depository institutions may incur in their Federal Reserve accounts.<sup>10</sup> These amendments

will remove references to the Strength of Support Assessment (“SOSA”) ranking; remove references to FBOs’ financial holding company (“FHC”) status; and adopt alternative methods for determining an FBO’s eligibility for a positive net debit cap, the size of its net debit cap, and its eligibility to request a streamlined procedure to obtain maximum daylight overdraft capacity. The Board selected April 1, 2020, as the implementation date for these amendments in response to a comment requesting that the Board delay implementation for at least 12 months. The Board stated “that a transition period would help FBOs adjust to these changes.”<sup>11</sup>

The availability of intraday credit from the Federal Reserve Banks supports the smooth functioning of payment systems and the settlement and clearing of transactions across a range of credit markets. The coronavirus outbreak has disrupted economic activity and financial markets in the United States. In light of these ongoing disruptions, the Board believes that, out of an abundance of caution, it should extend the transition period to October 1, 2020. This additional time will allow FBOs and the Reserve Banks to focus on other heightened priorities rather than establishing new arrangements for accessing intraday credit.

Accordingly, the Board is delaying the implementation date of the amendments to the PSR policy from April 1, 2020, to October 1, 2020.

By order of the Board of Governors of the Federal Reserve System, March 24, 2020.

**Michele Taylor Fennell,**

*Assistant Secretary of the Board.*

[FR Doc. 2020-06482 Filed 4-3-20; 8:45 am]

**BILLING CODE 6210-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0019; Product Identifier 2017-SW-074-AD; Amendment 39-19881; AD 2020-06-12]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS332L2 and EC225LP helicopters. This AD requires determining the accumulated hours time-in-service (TIS) of certain part-numbered main gearbox (MGB) suspension bar attachment bolts and fittings, applying a life limit add-on factor, and inspecting the torque of certain MGB suspension bar attachment nuts. This AD was prompted by a report of torque loss on an MGB suspension bar bolt. The actions of this AD are intended to address an unsafe condition on these products.

**DATES:** This AD is effective May 11, 2020.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of May 11, 2020.

**ADDRESSES:** For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0019.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> in Docket No. FAA-2018-0019; or in person at Docket Operations between 9 a.m. and 5 p.m.,

<sup>10</sup> 84 FR 12049 (April 1, 2019).

<sup>11</sup> *Id.* at 12056.

Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Union Aviation Safety Agency (previously European Aviation Safety Agency) (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email [matthew.fuller@faa.gov](mailto:matthew.fuller@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Discussion**

On December 9, 2019, at 84 FR 67248, the **Federal Register** published the FAA's notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model AS332L2 and EC225LP helicopters, with an MGB suspension bar front attachment bolt (bolt) part number (P/N) 332A22-1613-21 or 332A22-1613-20, MGB suspension bar rear bolt P/N 332A22-1614-20, MGB suspension bar front attachment fitting (fitting) P/N 332A22-1623-01, MGB suspension bar rear left hand fitting P/N 332A22-1624-02 or 332A22-1624-04, or MGB suspension bar rear right hand fitting P/N 332A22-1624-03 or 332A22-1624-05 installed.

For Airbus Helicopters Model AS332L2 and EC225LP helicopters, the NPRM proposed to require, within 30 hours time-in-service (TIS), re-calculating the life limit accumulated by each front and rear bolt by applying an add-on factor listed in the applicable service information. For each bolt that meets or exceeds its life limit, also known as service life limit (SLL), the NPRM proposed to require removing each bolt from service before further flight. For each bolt that has not exceeded its life limit, the NPRM proposed to require continuing to calculate and record the life limit of each bolt on its component history card or equivalent record and removing the bolt from service before reaching its life limit.

For Model AS332L2 helicopters, the NPRM proposed to require, within 30 hours TIS, re-calculating the life limit accumulated by the front, rear left hand, and rear right hand fittings by applying

an add-on factor listed in the applicable service information. For each fitting that meets or exceeds its life limit, the NPRM proposed to require removing the fitting from service before further flight. For each fitting that has not exceeded its life limit, the NPRM proposed to require continuing to calculate and record the life limit of each fitting on its component history card or equivalent record and removing the fitting from service before reaching its life limit.

For Model AS332L2 helicopters, the NPRM proposed to require, within 150 hours TIS (without applying an add-on factor), inspecting the torque of each MGB suspension bar fitting front and rear nut. If the torque on any nut is higher than the maximum allowable limit, the NPRM proposed to require removing the nut and its bolt from service before further flight. If the torque on any nut is lower than the minimum allowable limit, the NPRM proposed to require tightening the nut before further flight and removing the nut and its bolt from service within 150 hours TIS.

The proposed requirements were intended prevent the MGB suspension bar bolts and fittings remaining in service beyond their fatigue life, which could result in structural failure of the MGB suspension bar and loss of helicopter control.

The NPRM was prompted by EASA AD No. 2017-0189, dated September 22, 2017, issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale) Model AS 332 L2 and EC 225 LP helicopters. EASA advises that the installation of the MGB upper deck fittings of the three MGB suspension bars could lead to tightening torque loss on the fittings' attachment pins (bolts). Due to design similarities, Model AS 332 L2 helicopters could also be affected by the same installation condition. An investigation determined that the life limits in the Airworthiness Limitations Sections for the pins and fittings are valid if an "add-on penalty factor" is applied.

EASA states that this condition, if not corrected, could lead to structural failure of the MGB suspension bar attachment pins or fittings. Accordingly, the EASA AD requires applying the add-on penalty factor to the flight hours to re-calculate the life limits and replacing an affected part before exceeding its life limit. EASA further advises that Airbus Helicopters' initial service information contained an error that may have resulted in the installation of pins or fittings using an incorrect torque value. As a result, the EASA AD also requires

replacing pins if an incorrect torque value was applied and reporting the information to Airbus Helicopters.

**Comments**

The FAA gave the public the opportunity to participate in developing this AD, but the FAA did not receive any comments on the NPRM.

**FAA's Determination**

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA of the unsafe condition described in its AD. The FAA is issuing this AD after evaluating all information provided by EASA and determining the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed.

**Differences Between This AD and the EASA AD**

The EASA AD allows an optional 150 hours TIS extension to the life limit of an affected fitting for Model AS 332 L2 helicopters by performing dye-penetrant inspections. This AD does not allow this option. For Model AS 332 L2 helicopters, the EASA AD requires replacing pins (bolts) that are replacement pins installed before the AD's effective date with an incorrect torque value applied. This AD requires inspecting the torque for each nut for Model AS 332 L2 helicopters instead and depending on the outcome, removing the nut and its bolt from service. The EASA AD requires reporting certain information to Airbus Helicopters, while this AD does not.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 01.00.86 for Model AS332 helicopters and Airbus Helicopters EASB No. 04A013 for Model EC225LP helicopters, both Revision 1 and dated August 25, 2017. This service information specifies applying an add-on factor to the flying hours logged by the pins and fittings and replacing them if the SLL is exceeded. If an incorrect tightening torque value was applied to the pins, the service information specifies replacing the pins and contacting Airbus Helicopters.

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in the **ADDRESSES** section.

### Costs of Compliance

The FAA estimates that this AD affects 23 helicopters of U.S. Registry. The FAA estimates that operators may incur the following costs in order to comply with this AD. Labor costs are estimated at \$85 per work-hour.

Determining the adjusted life limit for the bolts and fittings takes about 0.5 work-hour for an estimated cost of \$43 per helicopter and \$989 for the U.S. fleet.

Replacing a bolt takes about 4 work-hours and parts cost about \$89 for an estimated cost of \$429 per bolt.

There are no costs of compliance for replacing a fitting and inspecting, and if necessary tightening, the torque for Model AS332L2 helicopters by this AD because there are no Model AS332L2 helicopters on the U.S. Registry.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Will not affect intrastate aviation in Alaska, and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2020-06-12 Airbus Helicopters:

Amendment 39-19881; Docket No. FAA-2018-0019; Product Identifier 2017-SW-074-AD.

#### (a) Applicability

This AD applies to Airbus Helicopters Model AS332L2 and EC225LP helicopters, certificated in any category, with a main gearbox (MGB) suspension bar front attachment bolt (bolt) part number (P/N) 332A22-1613-21 or 332A22-1613-20, MGB suspension bar rear bolt P/N 332A22-1614-20, MGB suspension bar front attachment fitting (fitting) P/N 332A22-1623-01, MGB suspension bar rear left hand fitting P/N 332A22-1624-02 or 332A22-1624-04, or MGB suspension bar rear right hand fitting P/N 332A22-1624-03 or 332A22-1624-05 installed.

#### (b) Unsafe Condition

This AD defines the unsafe condition as MGB suspension bar bolts and fittings remaining in service beyond their fatigue life and loose MGB suspension bar bolts or fittings, which could result in structural failure of the MGB suspension bar and loss of helicopter control.

#### (c) Effective Date

This AD becomes effective May 11, 2020.

#### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (e) Required Actions

(1) Within 30 hours time-in-service (TIS), review records to determine the total hours TIS of each MGB suspension bar bolt.

(i) Determine the life limit of each bolt by applying the hours TIS by the add-on factor listed in Table No. 1 of Airbus Helicopters Emergency Alert Service Bulletin No. 01.00.86, Revision 1, dated August 25, 2017 (EASB 01.00.86), or Airbus Helicopters

Emergency Alert Service Bulletin No. 04A013, Revision 1, dated August 25, 2017, as applicable to your model helicopter.

Note 1 to paragraph (e)(1)(i) of this AD: Airbus Helicopters refers to bolts as "pins."

(A) Before further flight, remove from service any bolt that has reached or exceeded its life limit.

(B) For each bolt that has not exceeded its life limit, continue to calculate and record the life limit on its component history card or equivalent record by applying the add-on factor each time the helicopter accumulates hours TIS, and remove from service any bolt before reaching its life limit.

(ii) Thereafter following paragraph (e)(1)(i) of this AD, continue to calculate and record the life limit of each bolt on its component history card or equivalent record by applying the add-on factor each time the helicopter accumulates hours TIS and remove from service any bolt before reaching its life limit.

(2) For Model AS332L2 helicopters, within 30 hours TIS, review records to determine the total hours TIS of each MGB suspension bar fitting.

(i) Determine the life limit of each fitting by applying the hours TIS by the add-on factor listed in Table No. 1 of EASB 01.00.86.

(A) Before further flight, remove from service any fitting that has reached or exceeded its life limit.

(B) For each fitting that has not exceeded its life limit, continue to calculate and record the life limit on its component history card or equivalent record by applying the add-on factor each time the helicopter accumulates hours TIS, and remove from service any fitting before reaching its life limit.

(ii) Thereafter following paragraph (e)(2)(i) of this AD, continue to calculate and record the life limit of each fitting on its component history card or equivalent record by applying the add-on factor each time the helicopter accumulates hours TIS and remove from service any fitting before reaching its life limit.

(3) For Model AS332L2 helicopters, within 150 hours TIS (without the add-on factor), inspect the torque of each MGB suspension bar attachment front and rear nut. The allowable torque for each front nut is 602–663 lbf. in (6.8–7.5 daN.m) and the allowable torque for each rear nut is 337–398 lbf. in (3.8–4.5 daN.m).

(i) If the torque on any nut is higher than the maximum allowable torque stated in paragraph (e)(3) of this AD, before further flight, remove from service the bolt and nut.

(ii) If the torque on any nut is lower than the minimum allowable torque value stated in paragraph (e)(3) of this AD, before further flight, tighten the nut to the allowable torque stated in paragraph (e)(3) of this AD. Within 150 hours TIS (without the add-on factor), remove from service any bolt and nut that were tightened as required by this paragraph.

#### (f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101

Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email [9-ASW-FTW-AMOC-Requests@faa.gov](mailto:9-ASW-FTW-AMOC-Requests@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

The subject of this AD is addressed in European Union Aviation Safety Agency (previously European Aviation Safety Agency) (EASA) AD No. 2017-0189, dated September 22, 2017. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2018-0019.

#### (h) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

#### (i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 01.00.86, Revision 1, dated August 25, 2017.

(ii) Airbus Helicopters EASB No. 04A013, Revision 1, dated August 25, 2017.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 25, 2020.

#### Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-07140 Filed 4-3-20; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-1015; Product Identifier 2018-SW-104-AD; Amendment 39-19882; AD 2020-06-13]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS332C, AS332C1, AS332L, and AS332L1 helicopters. This AD requires determining the accumulated hours time-in-service (TIS) of certain part-numbered main gearbox (MGB) suspension bar attachment fittings (fittings) and bolts, and establishes new life limits. This AD was prompted by the outcome of tests and analyses performed by Airbus Helicopters. The actions of this AD are intended to address an unsafe condition on these products.

**DATES:** This AD is effective May 11, 2020.

**ADDRESSES:** For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> in Docket No. FAA-2019-1015; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Union Aviation Safety Agency (previously European Aviation Safety Agency) (EASA) AD, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Matt Fuller, Senior Aviation Safety Engineer,

Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email [matthew.fuller@faa.gov](mailto:matthew.fuller@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

On December 9, 2019, at 84 FR 67246, the **Federal Register** published the FAA's notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model AS332C, AS332C1, AS332L, and AS332L1 helicopters, with an MGB suspension bar right-hand side (RH) rear fitting part number (P/N) 330A22-2702-07 and bolt P/N 330A22-0135-20, MGB suspension bar left-hand side (LH) rear fitting P/N 330A22-2702-06 and bolt P/N 330A22-0135-20, or MGB suspension bar front bolt P/N 330A22-0134-20 installed. The NPRM proposed to require within 50 hours TIS, reviewing the helicopter records to determine the total hours TIS of the MGB suspension bar RH and LH rear fittings. The NPRM also proposed to require removing from service the RH rear fitting and its bolts and the LH rear fitting and its bolts based on the accumulated total hours TIS of the fittings and other conditions. Thereafter, the NPRM proposed to require removing from service the RH rear fitting and its bolts at intervals not to exceed 1,470 hours TIS, removing from service the LH rear fitting at intervals not to exceed 13,600 hours TIS, and removing from service the LH rear bolts during each Major Inspection "G." Finally, the NPRM proposed to require removing from service the front bolts during each Major Inspection "G."

The proposed requirements were intended to prevent structural failure of the MGB suspension bar fittings and bolts, possibly resulting in detachment of the MGB suspension bars.

The NPRM was prompted by EASA AD No. 2018-0260, dated December 3, 2018, issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for Airbus Helicopters (formerly Eurocopter, Eurocopter France, Aerospatiale) Model AS 332 C, AS 332 C1, AS 332 L, and AS 332 L1 helicopters. From review of reported Model EC 225 LP data, EASA advises that the installation of the MGB upper deck fittings of the three MGB suspension bars could lead to tightening torque loss on the fittings' attachment screws (bolts). Due to design similarities, Model AS 332 C, AS 332 C1, AS 332 L, and AS 332 L1 helicopters could also be affected by the same installation condition.