

appropriate. If sending information directly to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. You may email your request to: *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Related Information

(1) For more information about this AD, contact Scott Stevenson, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7132; fax: 781-238-7199; email: *scott.m.stevenson@faa.gov*.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2018-0202R1, dated September 25, 2018, for more information. You may examine the EASA AD in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1034.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce (RR) Alert Non-Modification Service Bulletin No. RB.211-72-AC879, Revision 9, dated April 23, 2018.

(ii) RR Service Bulletin RB.211-72-C946, Revision 4, dated June 22, 2010.

(3) For RR service information identified in this AD, contact Rolls-Royce plc, PO Box 31, Derby, England, DE248BJ; telephone: 011-44-1332-242424; fax: 011-44-1332-249936.

(4) You may view this service information at FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: *fedreg.legal@nara.gov*, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 7, 2020.

**Lance T. Gant,**

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-07675 Filed 4-10-20; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-0314; Project Identifier AD-2020-00369-E; Amendment 39-21110; AD 2020-07-51]

RIN 2120-AA64

#### Airworthiness Directives; International Aero Engines AG (IAE) Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain International Aero Engines AG (IAE) V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines. This emergency AD was sent previously to all known U.S. owners and operators of these engines. This AD requires removal of affected high-pressure turbine (HPT) 1st-stage disks from service. This AD was prompted by investigative findings from an event involving an uncontained failure of a HPT 1st-stage disk that resulted in high-energy debris penetrating the engine cowling. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective April 28, 2020 to all persons except those persons to whom it was made immediately effective by Emergency AD 2020-07-51, issued on March 21, 2020, which contained the requirements of this amendment.

The FAA must receive comments on this AD by May 28, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0314; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Nicholas J. Paine, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7116; fax: 781-238-7199; Email: *nicholas.j.paine@faa.gov*.

**SUPPLEMENTARY INFORMATION:**

#### Discussion

On March 21, 2020, the FAA issued Emergency AD 2020-07-51, which requires removal from service of affected HPT 1st-stage disks installed on IAE V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines. This emergency AD was sent previously to all known U.S. owners and operators of these engines. This action was prompted by investigative findings from an event that occurred on March 18, 2020, in which an Airbus Model A321-231 airplane, powered by IAE V2533-A5 model turbofan engines, experienced an uncontained HPT 1st-stage disk failure that resulted in an aborted takeoff. This condition, if not addressed, could result in uncontained HPT failure, release of high-energy debris, damage to the engine, damage to the airplane, and loss of the airplane.

#### FAA's Determination

The FAA is issuing this AD because the Agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

#### AD Requirements

This AD requires removal from service of affected HPT 1st-stage disks installed on IAE V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines.

#### Interim Action

The FAA considers this AD interim action. The root cause of this event is still under investigation.

#### FAA's Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5

U.S.C.) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without seeking comment prior to the rulemaking. Similarly, Section 553(d) of the APA authorizes agencies to make rules effective in less than 30 days, upon a finding of good cause.

An unsafe condition exists that required the immediate adoption of Emergency AD 2020–07–51, issued on March 21, 2020, to all known U.S. owners and operators of these engines. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule. On March 18, 2020, an Airbus Model A321–231 airplane, powered by IAE V2533–A5 model turbofan engines, experienced an uncontained HPT 1st-stage disk failure that resulted in an aborted takeoff. The uncontained failure of the HPT 1st-stage disk resulted in high-energy debris penetrating the engine cowling. This unsafe condition, caused by an uncontained HPT 1st-stage disk failure, may result in loss of the airplane.

The FAA considers removal of the affected HPT 1st-stage disks to be an urgent safety issue. Removal of the affected HPT 1st-stage disks must be accomplished within 5 cycles after the effective date of this AD. These conditions still exist and the AD is hereby published in the **Federal Register** as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13) to make it

effective to all persons. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to public interest pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the reasons stated above, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

**Comments Invited**

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA–2020–0314 and Product Identifier AD–2020–00369–E at the beginning of your comments. The FAA specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this AD.

**Confidential Business Information**

Confidential Business Information (CBI) is commercial or financial

information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Nicholas J. Paine, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Regulatory Flexibility Act**

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

**Costs of Compliance**

The FAA estimates that this AD affects 2 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor Cost	Parts Cost	Cost per product	Cost on U.S. operators
Remove 1st-stage HPT disk .....	226 work-hours × \$85 per hour = \$19,210 ....	\$335,690	\$354,900	\$709,800

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on

the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2020-07-51 International Aero Engines AG (IAE):** Amendment 39-21110; Docket No. FAA-2020-0314; Project Identifier AD-2020-00369-E.

**(a) Effective Date**

This AD is effective April 28, 2020 to all persons except those persons to whom it was made immediately effective by Emergency AD 2020-07-51, issued on March 21, 2020, which contained the requirements of this amendment.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all International Aero Engines AG (IAE) V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 model turbofan engines with a high-pressure turbine (HPT) 1st-stage disk, part number (P/N) 2A5001 and serial number PKLBR37442, PKLBR38359, PKLBR73862, PKLBR73289, PKLBR73270, PKLBR38981, PKLBR38661, PKLBR40207, PKLBR37445, PKLBR73861, PKLBR73268, PKLBR38629, PKLBSC8047, or PKLBR38979, installed.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

**(e) Unsafe Condition**

This AD was prompted by investigative findings from an event involving an uncontained failure of a HPT 1st-stage disk that resulted in high-energy debris penetrating the engine cowling. The FAA is issuing this AD to prevent failure of the HPT. The unsafe condition, if not addressed, could result in uncontained HPT failure, release of high-energy debris, damage to the engine, damage to the airplane, and loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) For affected IAE model turbofan engines with an engine serial number and HPT 1st-stage disk serial number listed in Table 1 to paragraph (g)(1) of this AD, within 5 flight cycles after the effective date of this AD, remove the HPT 1st-stage disk from service.

**Table 1 to Paragraph (g)(1) of this AD – HPT 1st-Stage Disk with Known Engine Installations**

Engine Serial Number	HPT 1st-Stage Disk Serial Number
V10443	PKLBR73268
V10976	PKLBR73270
V11303	PKLBR38359
V11490	PKLBR38979
V12265	PKLBR73289
V15638	PKLBR37445
V15686	PKLBSC8047
V16372	PKLBR73861
V16570	PKLBR38629
V16468	PKLBR38981
V16622	PKLBR73862

(2) For all other affected IAE model turbofan engines, review the engine records within 3 calendar days after the effective date of this AD to determine if an HPT 1st-stage disk with serial number PKLBR37442, PKLBR38661, or PKLBR40207 is installed in the engine. If an affected HPT 1st-stage disk is installed, within 5 flight cycles after this determination, remove the affected HPT 1st-stage disk from service.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19,

send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. You may email your request to *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

For further information about this AD, contact Nicholas J. Paine, Aerospace

Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7116; fax: 781-238-7199; Email: *nicholas.j.paine@faa.gov*.

**(j) Material Incorporated by Reference**

None.

Issued on April 7, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020-07627 Filed 4-10-20; 8:45 am]

**BILLING CODE 4910-13-P**