

within 72 months after the most recent inspection was performed as specified in AWL No. 28-AWL-24, whichever is later.

(7) For AWL No. 28-AWL-29, "Full Cushion Clamps and Teflon Sleeving (If Installed) Installed on Out-of-Tank Wire Bundles Installed on Brackets that are Mounted Directly on the Fuel Tanks:" For airplanes having line numbers (L/N) 1 through 1754 inclusive, within 120 months after accomplishment of the actions specified in Boeing Service Bulletin 737-57A1279. For airplanes having L/N 1755 and subsequent, within 120 months after the date of issuance of the original airworthiness certificate or the original export certificate of airworthiness, or within 48 months after the effective date of this AD, whichever is later.

(8) For AWL No. 28-AWL-35, "Fuel Quantity Indicating System (FQIS)—Center Fuel Tank In-Tank Component and Wire Harness Protection Features—Separation from Center Tank Internal Structure:" For airplanes that have incorporated Boeing Service Bulletin 737-28-1356, within 120 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28-1356, or within 120 months after the most recent inspection was performed as specified in AWL No. 28-AWL-35, whichever is later.

(9) For AWL No. 28-AWL-37, "Fuel Quantity Indicating System (FQIS)—Built in Test Equipment (BITE) Test:" For airplane L/Ns 6987 and 7000 and subsequent, within 750 flight hours since the date the most recent BITE test was accomplished as specified in AWL No. 28-AWL-37, or within 750 flight hours after the effective date of this AD, whichever is later.

(10) For AWL No. 47-AWL-04, "Nitrogen Generation System-Thermal Switch:" Within 22,500 flight hours after the date of issuance of the original airworthiness certificate or the original export certificate of airworthiness, within 22,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1003, or within 22,500 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-04, whichever is latest.

(11) For AWL No. 47-AWL-06, "Nitrogen Generation System (NGS)-Cross Vent Check Valve:" Within 13,000 flight hours after the date of issuance of the original airworthiness certificate or the original export certificate of airworthiness, within 13,000 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1003, or within 13,000 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-06, whichever is latest.

(12) For AWL No. 47-AWL-07, "Nitrogen Generation System (NGS)-Nitrogen Enriched Air (NEA) Distribution Ducting Integrity:" Within 6,500 flight hours after the date of issuance of the original airworthiness certificate or the original export certificate of airworthiness, within 6,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1003, or within 6,500 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-07, whichever is latest.

(13) For AWL No. 47-AWL-09, "Nitrogen Generation System—Oxygen Sensor:" Within 18,000 flight hours after the date of issuance

of the original airworthiness certificate or the original export certificate of airworthiness, or within 18,000 flight hours after the most recent replacement was performed as specified in AWL No. 47-AWL-09, or within 12 months after the effective date of this AD, whichever is latest.

(14) For AWL No. 28-AWL-101, "Engine Fuel Suction Feed Operational Test:" Within 7,500 flight hours or 36 months, whichever occurs first, after the date of issuance of the original airworthiness certificate or the original export certificate of airworthiness; or within 7,500 flight hours or 36 months, whichever occurs first, after the most recent inspection was performed as specified in AWL No. 28-AWL-101; whichever is later.

(h) Additional Acceptable Wire Types and Sleeving

As an option, when accomplishing the actions required by paragraph (g) of this AD, the changes specified in paragraphs (h)(1) and (2) of this AD are acceptable.

(1) Where AWL No. 28-AWL-05 identifies wire types BMS 13-48, BMS 13-58, and BMS 13-60, the following wire types are acceptable: MIL-W-22759/16, SAE AS22759/16 (M22759/16), MIL-W-22759/32, SAE AS22759/32 (M22759/32), MIL-W-22759/34, SAE AS22759/34 (M22759/34), MIL-W-22759/41, SAE AS22759/41 (M22759/41), MIL-W-22759/86, SAE AS22759/86 (M22759/86), MIL-W-22759/87, SAE AS22759/87 (M22759/87), MIL-W-22759/92, and SAE AS22759/92 (M22759/92); and MIL-C-27500 and NEMA WC 27500 cables constructed from these military or SAE specification wire types, as applicable.

(2) Where AWL No. 28-AWL-05 identifies TFE-2X Standard wall for wire sleeving, the following sleeving materials are acceptable: Roundit 2000NX and Varglas Type HO, HP, or HM.

(i) No Alternative Actions, Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

Except as provided in paragraph (h) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k) of this AD.

(j) Terminating Action for Certain AD Requirements

Accomplishment of the revision required by paragraph (g) of this AD terminates the requirements specified in paragraphs (j)(1) through (6) of this AD for that airplane.

(1) The revision required by paragraphs (h) and (h)(1) of AD 2008-06-03.

(2) All requirements of AD 2008-10-10 R1.

(3) The revision required by paragraph (g) of AD 2008-17-15.

(4) The revision required by paragraph (k) of AD 2011-18-03.

(5) All requirements of AD 2013-15-17.

(6) All requirements of AD 2018-20-24.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact Christopher Baker, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3556; email: Christopher.R.Baker@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on April 23, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-09395 Filed 5-5-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0443; Project Identifier AD-2020-00178-E]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all General Electric Company (GE) GENx-1B64, 1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, -1B70/75/P1, -1B70/75/P2, -1B70/P1, -1B70/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76/P2, and -1B76A/P2 model turbofan engines. This proposed AD was prompted by reports of combustor case burn-through. This proposed AD would require installation of electronic engine control (EEC) software, version B205 or later. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by June 22, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, 1 Neumann Way, Cincinnati, OH, 45215, United States; phone: (513) 552-3272; email: aviation.fleetsupport@ae.ge.com; website: www.ge.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0443; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is

listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7743; fax: (781) 238-7199; email: Mehdi.Lamnyi@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2020-0443; Project Identifier AD-2020-00178-E” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

Confidential Business Information

Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Mehdi Lamnyi,

Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

The FAA received two reports of engine overheat messages on airplanes operating GE GENx-1B model turbofan engines during revenue flights. One message led to a commanded in-flight shutdown and both flights diverted and made safe landings. Investigation of these incidents revealed combustor case burn-through as the result of damage to the fuel nozzle caused by high amplitude load on the combustor components during fuel mixing. The breach in the fuel nozzle produced sideways jets and fanned spray directed towards the combustor case which led to burn-through of the cases. The software upgrade required by this AD would introduce changes to the fuel scheduling to reduce the high load during the fuel mixing that led to damage to the fuel nozzle. This condition, if not addressed, could result in failure of the fuel nozzle, damage to the combustor case, engine fire and damage to the airplane.

Related Service Information

The FAA reviewed GE GENx-1B Service Bulletin (SB) 73-0085 R00, dated December 23, 2019. The SB describes procedures for installing the EEC software version B205.

FAA's Determination

The FAA is proposing this AD because the Agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require installation of EEC software, version B205 or later.

Costs of Compliance

The FAA estimates that this proposed AD affects 176 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

| Action | Labor cost | Parts cost | Cost per product | Cost on U.S. operators |
|---|--|------------|------------------|------------------------|
| Install EEC software version B205 or later | 1 work-hour × \$85 per hour = \$85 | \$0 | \$85 | \$14,960 |

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

General Electric Company: Docket No. FAA–2020–0443; Project Identifier AD–2020–00178–E.

(a) Comments Due Date

The FAA must receive comments by June 22, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) GENx–1B64, 1B64/P1, –1B64/P2, –1B67, –1B67/P1, –1B67/P2, –1B70, –1B70/75/P1, –1B70/75/P2, –1B70/P1, –1B70/P2, –1B70C/P1, –1B70C/P2, –1B74/75/P1, –1B74/75/P2, –1B76/P2, and –1B76A/P2 model turbofan engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7240, Turbine Engine Combustion Section.

(e) Unsafe Condition

This AD was prompted by two reports of combustor case burn-through. The FAA is issuing this AD to prevent failure of the fuel nozzle. The unsafe condition, if not addressed, could result in damage to the combustor case, engine fire, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 120 days after the effective date of this AD, install electronic engine control (EEC) software that is eligible for installation.

(h) Definition

For the purpose of this AD, EEC software that is eligible for installation is EEC software that is version B205 or later.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector

or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: ANE–AD–AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: (781) 238–7743; fax: (781) 238–7199; email: Mehdi.Lamnyi@faa.gov.

(2) For service information identified in this AD, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215, United States; phone: (513) 552–3272; email: aviation.fleetsupport@ae.ge.com; website: www.ge.com. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781–238–7759.

Issued on April 29, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–09437 Filed 5–5–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2020–0331; Product Identifier 2020–NM–019–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes. This proposed AD was prompted by a report that the