

# Proposed Rules

Federal Register

Vol. 85, No. 114

Friday, June 12, 2020

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF AGRICULTURE

### Office of the Secretary

#### 7 CFR Part 9

[Docket ID: FSA–2020–0004]

#### Notice of Funding Availability; Coronavirus Food Assistance Program (CFAP) Additional Commodities Request for Information; Correction

**AGENCY:** Office of the Secretary, USDA.

**ACTION:** Notice of funding availability; request for comments; correction.

**SUMMARY:** This document corrects the supplementary information section to the notice of funding availability and additional commodities request for information published in the **Federal Register** on May 22, 2020, concerning CFAP. This document adds questions to request specific information related to certain specialty crops. This is intended to add clarity. USDA is still requesting comments on additional commodities that are not already identified and on the paperwork reduction act for CFAP activities. The questions added in this correction cover additional commodities and the development of their payment rates as envisioned in the cost analysis for the CFAP rule and are not expected to impact the costs of CFAP.

**DATES:** We will consider comments that we receive on additional commodities by June 22, 2020.

We will consider comments that we receive on the Paperwork Reduction Act by July 21, 2020.

**ADDRESSES:** We invite you to submit comments to provide information about additional commodities and comment on the information collection specified in this document. In your comment, specify [Docket ID: FSA–2020–0004], and include the volume, date, and page number of this issue of the **Federal Register**. You may submit comments by either of the following methods:

- *Federal Rulemaking Portal:* Go to <http://www.regulations.gov> and search for Docket ID FSA–2020–0004. Follow

the instructions for submitting comments.

- *Mail:* Director, SND, FSA, US Department of Agriculture, 1400 Independence Avenue SW, Stop 0522, Washington, DC 20250–0522.

Comments will be available for viewing online at <http://www.regulations.gov>. In addition, comments will be available for public inspection at the above address during business hours from 8 a.m. to 5 p.m., Monday through Friday, except holidays.

#### FOR FURTHER INFORMATION CONTACT:

William L. Beam, telephone (202) 720–3175; email [Bill.Beam@usda.gov](mailto:Bill.Beam@usda.gov).

Persons with disabilities or who require alternative means for communication should contact the USDA Target Center at (202) 720–2600.

#### SUPPLEMENTARY INFORMATION:

##### Correction

In the **Federal Register** of May 22, 2020, at 85 FR 31062–31065, the Secretary is making the following correction, in the **SUPPLEMENTARY** section. On page 31063, in the third column, add “Specialty Crops” before the heading “Nursery Products” to read as follows:

##### *Specialty Crops*

In addition to the questions above applicable to specialty crops, for producers of specialty crops that have been shipped from the farm by April 15, 2020, but subsequently spoiled or are unpaid due to loss of marketing channels, payments will be based on the volume of shipped, spoiled crops or that are unpaid multiplied by a pre-specified payment rate expected to represent 30 percent of the crop’s sales value. For producers with specialty crop shipments that have not left the farm or mature crops that were unharvested between January 15, 2020 and April 15, 2020, and which have not been and will not be sold, payments will be based on the volume of unharvested or unshipped crops multiplied by a pre-specified payment rate expected to represent 5.875 percent of the crop’s value.

If you are providing information for a specialty crop meeting the above conditions, please specify your response to the questions below:

(1) The quantity and price of the crop(s) you produced that left your farm

by April 15, 2020, and subsequently spoiled or are unpaid due to no market, and for which you did not have Federal crop insurance or Noninsured Crop Disaster Assistance Program (NAP) coverage for the loss.

(2) The quantity and price of crop(s) ready for sale that did not leave the farm by April 15, 2020, and that will not be sold due to lack of markets.

The questions in this correction, in addition to the questions in the initial NOFA, cover additional commodities and the development of their payment rates as envisioned in the cost analysis for the CFAP rule and are not expected to impact the costs of CFAP.

**Stephen L. Censky,**

*Vice Chairman, Commodity Credit Corporation, and Deputy Secretary, U.S. Department of Agriculture.*

[FR Doc. 2020–12529 Filed 6–10–20; 4:15 pm]

**BILLING CODE P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2020–0542; Project Identifier AD–2020–00582–E]

RIN 2120–AA64

#### Airworthiness Directives; Pratt & Whitney Division Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Pratt & Whitney Division (PW) PW4164, PW4164–1D, PW4168, PW4168–1D, PW4168A, PW4168A–1D, and PW4170 model turbofan engines with a certain outer combustion chamber assembly and 3rd stage low-pressure turbine (LPT) duct segments installed. This proposed AD was prompted by reports of damaged or failed 3rd stage LPT duct segments on PW engines with the Talon IIB outer combustion chamber assembly configuration installed. This proposed AD would require removing and replacing certain 3rd stage LPT duct segments. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by July 27, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**Examining the AD Docket**

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0542; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Carol Nguyen, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7655; fax: 781-238-7199; email: [carol.nguyen@faa.gov](mailto:carol.nguyen@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2020-0542; Project Identifier AD-2020-00582-E” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic,

environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Carol Nguyen, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Discussion**

The FAA received multiple reports of damaged or failed 3rd stage LPT duct segments that resulted in engine surges, in-flight shutdowns, diversions, and air turnbacks. The reports were attributed to elevated gas path temperature at the

outer diameter of the turbine flowpath and high-pressure turbine 2nd stage blade outer air seal spallation, which led to the distortion and liberation of 3rd stage LPT duct segments. This condition, if not addressed, could result in uncontained release of LPT blades and vanes, damage to the engine, and damage to the airplane.

**Related Service Information**

The FAA reviewed PW Service Bulletin (SB) No. PW4G-100-72-214, dated December 15, 2011; PW SB No. PW4G-100-72-219, Revision 1, dated October 5, 2011; and PW SB No. PW4G-100-72-253, dated November 24, 2014. PW SB No. PW4G-100-72-214 introduces the Talon IIB outer combustion chamber assembly that reduces the combustor exit temperature levels at the outer diameter of the combustor. PW SB No. PW4G-100-72-219, Revision 1, describes procedures for installing the Advantage70 engine upgrade kit to improve engine reliability and fuel consumption, and to reduce maintenance costs. PW SB No. PW4G-100-72-253 describes procedures for replacing the outer combustion chamber assembly waspaloy nuts.

**FAA’s Determination**

The FAA is proposing this AD because the Agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require removing and replacing certain 3rd stage LPT duct segments.

**Costs of Compliance**

The FAA estimates that this proposed AD affects 99 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace 3rd stage LPT duct segments.	56 work-hours × \$85 per hour = \$4,760 .....	\$85,000	\$89,760	\$8,886,240

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section

44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Pratt & Whitney Division:** Docket No. FAA–2020–0542; Project Identifier AD–2020–00582–E.

#### (a) Comments Due Date

The FAA must receive comments by July 27, 2020.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Pratt & Whitney Division (PW) PW4164, PW4164–1D, PW4168, PW4168–1D, PW4168A, PW4168A–1D, and PW4170 model turbofan engines that have 3rd stage low-pressure turbine (LPT) duct segments, part number (P/N) 50N434–01 or P/N 50N450–01 installed, and have the

Talon IIB outer combustion chamber assembly, P/N 51J500 or P/N 51J381, installed.

#### (d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

#### (e) Unsafe Condition

This AD was prompted by reports of damaged or failed 3rd stage LPT duct segments on PW engines with the Talon IIB outer combustion chamber assembly configuration installed. The FAA is issuing this AD to prevent failure of the 3rd stage LPT duct segments. The unsafe condition, if not addressed, could result in uncontained release of LPT blades and vanes, damage to the engine, and damage to the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Action

At every engine shop visit after the effective date of this AD, remove from service the 3rd stage LPT duct segments, P/N 50N434–01 and P/N 50N450–01, and replace them with parts with zero flight cycles.

#### (h) Terminating Action

Removal of the 3rd stage LPT duct segments, P/N 50N434–01 and P/N 50N450–01, and their replacement with parts having P/Ns other than P/N 50N434–01 and P/N 50N450–01, constitutes terminating action for the repetitive replacement required by paragraph (g) of this AD.

#### (i) Definition

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges (lettered flanges). The separation of engine flanges solely for the purpose of transportation without subsequent engine maintenance does not constitute an engine shop visit.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: [ANE-AD-AMOC@faa.gov](mailto:ANE-AD-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Related Information

For more information about this AD, contact Carol Nguyen, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–

7655; fax: 781–238–7199; email: [carol.nguyen@faa.gov](mailto:carol.nguyen@faa.gov).

Issued on June 5, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020–12626 Filed 6–11–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2020–0463; Product Identifier 2013–SW–041–AD]

RIN 2120–AA64

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to remove Airworthiness Directive (AD) 2015–17–01, which applies to certain Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters. AD 2015–17–01 requires certain inspections of each tail rotor pitch horn assembly (pitch horn) for a crack, replacement of a cracked pitch horn, and a repetitive visual inspection of certain pitch horns. AD 2015–17–01 is no longer necessary because the cause of the unsafe condition has been removed from all affected helicopter models. Accordingly, the FAA proposes to remove AD 2015–17–01.

**DATES:** The FAA must receive comments on this proposed AD by July 27, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region,