

**(a) Applicability**

This AD applies to Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category, with an engine mounting rod part number (P/N) 3G7120V00132 with a serial number (S/N) listed in Figures 2 or 3 of Leonardo Helicopters Alert Service Bulletin No. 139–593, Revision A, dated June 14, 2019 (ASB 139–593), installed.

**(b) Unsafe Condition**

This AD defines the unsafe condition as a non-conforming engine mounting rod. This condition could result in structural failure of the engine mounting rod and subsequent loss of control of the helicopter.

**(c) Comments Due Date**

The FAA must receive comments by September 8, 2020.

**(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

(1) Before further flight, determine the total hours time-in-service (TIS) of each engine mounting rod.

(2) Before reaching 225 total hours TIS or within 25 hours TIS, whichever occurs later, with the battery and any other electrical power supply disconnected, remove from service the engine mounting rod as follows:

(i) For the Number 1 engine outboard mounting rod, remove from service the Number 1 engine outboard mounting rod and install an airworthy Number 1 engine outboard mounting rod as shown in Detail “B” of Figure 1 of ASB 139–593 and by following the Accomplishment Instructions, paragraphs 3.1 and 3.2 of ASB 139–593, except you are not required to discard the Number 1 engine outboard mounting rod or comply with the “Scrap Report” instruction in paragraph 3.1 of ASB 139–593.

**Note 1 to paragraph (e)(2)(i) through (iv) of this AD:** Figure 1 of ASB 139–593 shows the engine outboard and inboard mounting rod assemblies for the left-hand side only, the right-hand side is symmetrical.

(ii) For the Number 1 engine inboard mounting rod, remove from service the Number 1 engine inboard mounting rod and install an airworthy Number 1 engine inboard mounting rod as shown in Detail “C” of Figure 1 of ASB 139–593 and by following the Accomplishment Instructions, paragraphs 3.3 and 3.4 of ASB 139–593, except you are not required to discard the Number 1 engine inboard mounting rod or comply with the “Scrap Report” instruction in paragraph 3.3 of ASB 139–593.

(iii) For the Number 2 engine outboard mounting rod, remove from service the Number 2 engine outboard mounting rod and install an airworthy Number 2 engine outboard mounting rod as shown in Detail “B” of Figure 1 of ASB 139–593 and by following the Accomplishment Instructions, paragraphs 4.1 and 4.2 of ASB 139–593, except you are not required to discard the Number 2 engine outboard mounting rod or comply with the “Scrap Report” instruction in paragraph 4.1 of ASB 139–593.

(iv) For the Number 2 engine inboard mounting rod, remove from service the Number 2 engine inboard mounting rod and install an airworthy Number 2 engine inboard mounting rod as shown in Detail “C” of Figure 1 of ASB 139–593 and by following the Accomplishment Instructions, paragraphs 4.3 and 4.4 of ASB 139–593, except you are not required to discard the Number 2 engine inboard mounting rod or comply with the “Scrap Report” instruction in paragraph 4.3 of ASB 139–593.

(3) As of the effective date of this AD, do not install on any helicopter an engine mounting rod with a P/N and S/N listed in paragraph (a) of this AD.

**(f) Credit for Previous Actions**

Actions accomplished before the effective date of this AD in accordance with the procedures specified in Leonardo Helicopters Alert Service Bulletin No. 139–593, dated June 11, 2019, are considered acceptable for compliance with the corresponding actions specified in paragraphs (e)(1) and (2) of this AD.

**(g) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Kristi Bradley, Aerospace Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

**(h) Additional Information**

(1) Leonardo Helicopters Alert Service Bulletin No. 139–593, dated June 11, 2019, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Leonardo S.p.a. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://www.leonardocompany.com/en/home>. You may view a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD No. 2019–0149, dated June 24, 2019. You may view the EASA AD on the internet at <https://www.regulations.gov> in the AD Docket.

**(i) Subject**

Joint Aircraft Service Component (JASC) Code: 7120, Engine Mount Section.

Issued on July 1, 2020.

**Gaetano A. Scirtino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020–14607 Filed 7–8–20; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2020–0625; Product Identifier 2016–SW–007–AD]**

**RIN 2120–AA64**

**Airworthiness Directives; Various Restricted Category Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for various restricted category helicopters, originally manufactured by Sikorsky Aircraft Corporation (Sikorsky), Model EH–60A, HH–60L, S–70, S–70A, S–70C, S–70C(M), S–70C(M1), and UH–60A. This proposed AD would require initial and recurring inspections of the main rotor (M/R) blade spindle cuff for a crack. This proposed AD is prompted by multiple reports of a cracked M/R blade spindle cuff. The proposed actions are intended to prevent an unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 24, 2020.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <https://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202–493–2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590–0001.

- *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**Examining the AD Docket**

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0625; or in person at Docket Operations

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact your local Sikorsky Field Representative or Sikorsky's Service Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S; email [wcs\\_cust\\_service\\_eng\\_gr\\_sik@lmco.com](mailto:wcs_cust_service_eng_gr_sik@lmco.com). Operators may also log on to the Sikorsky 360 website at <https://www.sikorsky360.com>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

**FOR FURTHER INFORMATION CONTACT:** Christopher Greer, Aerospace Engineer, Boston ACO Branch, Compliance and Airworthiness Division, FAA, 1200 District Avenue, Burlington, Massachusetts 01803; telephone 781-238-7799; email [kristopher.greer@faa.gov](mailto:kristopher.greer@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to participate in this rulemaking by submitting written comments, data, or views. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will file in the docket all comments received, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments received on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this proposal in light of the comments received.

#### Confidential Business Information

Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Kristopher Greer, Aerospace Engineer, Boston ACO Branch, Compliance and Airworthiness Division, FAA, 1200 District Avenue, Burlington, Massachusetts 01803; telephone 781-238-7799; email [kristopher.greer@faa.gov](mailto:kristopher.greer@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Discussion

The FAA proposes to adopt a new AD for various restricted category helicopters, originally manufactured by Sikorsky, Model EH-60A, HH-60L, S-70, S-70A, S-70C, S-70C(M), S-70C(M1), and UH-60A, with an M/R blade spindle cuff part number 70150-09109-041 installed. This proposed AD would require initial and recurring inspections of the M/R blade spindle cuff for a crack.

This proposed AD is prompted by multiple reports of a cracked M/R blade spindle cuff. In 2008, Sikorsky reported an M/R blade spindle cuff on a Model UH-60A helicopter that cracked across the lower inboard bolt holes. Investigation determined the crack was caused by a non-conforming hole edge break, specifically a burr, introduced during an overhaul at a non-Sikorsky overhaul facility. Sikorsky issued Sikorsky Safety Advisory No. SSA-S70-08-002, dated December 11, 2008 (SSA-S70-08-002), for Black Hawk Model H-60- and S-70-series helicopters to inform operators of the incident and recommend compliance with Sikorsky's preventative maintenance inspections. The safety advisory also recommended that operators with M/R blades overhauled by a non-Sikorsky repair facility contact that facility to verify

whether the hole edge radius requirement was met during the overhaul.

In 2015, the FAA received an additional report of an M/R blade spindle cuff on a military model helicopter that cracked. Investigation from this reporting has revealed no anomalies at the crack initiation site. In each instance, a crack initiated at a bolt hole and spread to either an adjacent bolt hole or to the free edge. Due to design similarity, Model EH-60A, HH-60L, S-70, S-70A, S-70C, S-70C(M), S-70C(M1), and UH-60A helicopters are all affected by this unsafe condition. The proposed actions are intended to detect a crack, prevent failure of an M/R blade spindle cuff, loss of an M/R blade, and loss of control of the helicopter.

#### FAA's Determination

The FAA is proposing this AD after evaluating all known relevant information and determining that an unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs.

#### Related Service Information

The FAA reviewed SSA-S70-08-002. This service information recommends, for helicopters with M/R blades overhauled by non-Sikorsky M/R blade repair facilities, contacting the facilities to verify whether the hole edge radius requirement was met during cuff replacement. The safety advisory also recommends operators conduct 10 hour/14 day visual inspections and follow the inspection procedures regarding sudden onset of low frequency vibration or an out of track condition.

The FAA also reviewed Sikorsky Technical Manual Preventative Maintenance Services 10 Hour/14 Day (30 Hour/42 Day) Inspection Checklist TM 1-70-PMS-1, dated December 1, 2014, for Sikorsky Model S-70 helicopters. This service information contains procedures for the 10 hour/14 day and 30 hour/42 day inspections.

#### Proposed AD Requirements

This proposed AD would require, using 10X or higher power magnification, visually inspecting each M/R blade spindle cuff for a crack, and replacing the M/R blade spindle cuff if there is a crack.

#### Costs of Compliance

The FAA estimates that this proposed AD affects 204 helicopters of U.S. Registry. The FAA estimates that operators may incur the following costs in order to comply with this AD. Labor

costs are estimated at \$85 per work-hour.

Inspecting the M/R blade spindle cuffs would take about 1 work-hour for an estimated cost of \$85 per helicopter and \$17,340 for the U.S. fleet. Replacing an M/R blade spindle cuff would take about 175 work-hours and required parts would cost about \$10,000 for a total estimated replacement cost of \$24,875 per M/R blade spindle cuff.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Will not affect intrastate aviation in Alaska, and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Various Restricted Category Helicopters:**  
Docket No. FAA-2020-0625; Product Identifier 2016-SW-007-AD.

#### (a) Applicability

This AD applies to various restricted category helicopters originally manufactured by Sikorsky Aircraft Corporation, Model EH-60A, HH-60L, S-70, S-70A, S-70C, S-70C(M), S-70C(M1), and UH-60A helicopters with a main rotor (M/R) blade spindle cuff part number 70150-09109-041 installed; type certificate holders include but are not limited to ACE Aeronautics, LLC; BHI H60 Helicopters, LLC; Billings Flying Service Inc.; Carson Helicopters; Delta Enterprise; High Performance Helicopters Corp.; Northwest Rotorcraft LLC; Pickering Aviation, Inc.; PJ Helicopters Inc.; Sikorsky Aircraft Corporation; SixtyHawk TC, LLC; Skydance Blackhawk Operations, LLC; Timberline Helicopters, Inc.; and Unical Aviation, Inc.

#### (b) Unsafe Condition

This AD defines the unsafe condition as a crack in an M/R blade spindle cuff. This condition could result in failure of an M/R blade spindle cuff, loss of an M/R blade, and loss of control of the helicopter.

#### (c) Comments Due Date

The FAA must receive comments by August 24, 2020.

#### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (e) Required Actions

Before further flight, unless already done within the last 10 hours time-in-service (TIS), and thereafter at intervals not to exceed 10 hours TIS from the last inspection:

(1) Using 10X or higher power magnification, visually inspect each M/R blade spindle cuff for a crack. Pay particular attention to the area around each bolt hole and the upper and lower surfaces of the leading and trailing edges of each M/R blade spindle cuff.

(2) If there is a crack, replace the M/R blade spindle cuff before further flight.

#### (f) Alternative Methods of Compliance (AMOC)

(1) The Manager, Boston ACO Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Kristopher Greer, Aerospace Engineer, Boston ACO Branch,

Compliance and Airworthiness Division, FAA, 1200 District Avenue, Burlington, Massachusetts 01803; telephone 781-238-7799; email [kristopher.greer@faa.gov](mailto:kristopher.greer@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

Sikorsky Safety Advisory No. SSA-S70-08-002, dated December 11, 2008, and Sikorsky Technical Manual Preventative Maintenance Services 10 Hour/14 Day (30 Hour/42 Day) Inspection Checklist 1-70-PMS-1, dated December 1, 2014, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact your local Sikorsky Field Representative or Sikorsky's Service Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S; email [wcs\\_cust\\_service\\_eng-gr-sik@lmco.com](mailto:wcs_cust_service_eng-gr-sik@lmco.com). Operators may also log on to the Sikorsky 360 website at <https://www.sikorsky360.com>. You may view a copy of information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

#### (h) Subject

Joint Aircraft Service Component (JASC) Code: 6220, Main Rotor Head—Main Rotor Spindle Cuff.

Issued on July 2, 2020.

#### Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-14787 Filed 7-8-20; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF COMMERCE

### National Oceanic and Atmospheric Administration

#### 50 CFR Part 665

[Docket No. 200702-0175]

RTID 0648-XP010

### Pacific Island Pelagic Fisheries; 2020 U.S. Territorial Longline Bigeye Tuna Catch Limits

**AGENCY:** National Marine Fisheries Service (NMFS), National Oceanic and Atmospheric Administration (NOAA), Commerce.

**ACTION:** Proposed specifications; request for comments.

**SUMMARY:** NMFS proposes a 2020 limit of 2,000 metric tons (t) of longline-