

(l) WSK PZL Mielec and OBR SK Mielec Model PZL M20 03 airplanes;

(li) W.Z.D. Enterprises Inc. (type certificate previously held by JGS Properties, LLC) Model 11A and 11E airplanes;

(lii) Zenair Ltd. Model CH2000 airplanes; and

(liii) Zlin Aircraft a.s. (type certificate previously held by Moravan a.s.) Model Z-143L and Z-242L airplanes.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 3410, FLIGHT ENVIRONMENT DATA; 3420, ATTITUDE AND DIRECTION DATA SYSTEM.

(e) Unsafe Condition

This AD was prompted by an automatic reset occurring when the display internal monitor detects a potential fault causing intermittent loss of airspeed, attitude, and altitude information during flight. The FAA is issuing this AD to address the software interacting with a graphics processing chip defect. The unsafe condition, if not addressed, could result in intermittent loss of airspeed, attitude, and altitude information during flight with consequent loss of airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Before further flight, revise the limitations section of the airplane flight manual (AFM) for your airplane by inserting a copy of this AD or by making a pen and ink change to add: "Operation under Instrument Flight Rules (IFR) or night Visual Flight Rules (VFR) is prohibited."

(2) The action required by paragraph (g)(1) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1) through (4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417. This authority is not applicable to aircraft being operated under 14 CFR part 119.

(h) Special Flight Permit

Special flight permits are prohibited.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Fort Worth ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Mahmood Shah, Aerospace Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: 817-222-5133; fax: 817-222-5960; email: mahmood.shah@faa.gov.

Issued on August 11, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-17902 Filed 8-14-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0717; Product Identifier 2019-CE-038-AD; Amendment 39-21196; AD 2020-16-12]

RIN 2120-AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Pacific Aerospace Limited Model 750XL airplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as inadvertent fuel shut-off to the engine during the operation of the flaps due to the fuel and flap control levers being located too closely together. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective September 8, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of September 8, 2020.

The FAA must receive comments on this AD by October 1, 2020.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Pacific Aerospace Limited, Airport Road, Hamilton, Private Bag 3027, Hamilton 3240, New Zealand; telephone: +64 7 843 6144; facsimile: +64 7 843 6134; email: pacific@aerospace.co.nz; internet: <https://www.aerospace.co.nz>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <https://www.regulations.gov> by searching for Docket No. FAA-2020-0717.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0717; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Mike Kiesov, Aerospace Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The Civil Aviation Authority (CAA), which is the aviation authority for New Zealand, has issued AD DCA/750XL/39, dated September 5, 2019 (referred to after this as "the MCAI"), to correct an unsafe condition for Pacific Aerospace Limited Model 750XL airplanes. The MCAI states:

DCA/750XL/39 with effective date 5 September 2019 is prompted by the findings of an accident investigation. The report recommended that an effective lock mechanism should be introduced for the fuel condition lever in order to prevent inadvertent fuel shut-off to the engine during the operation of the flaps, as the fuel and flap control levers are closely located.

Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/111 issue 1, dated 18 June 2019 introduces a fuel condition lever inspection and instructions to adjust the position of the fuel condition lever to ensure it rests against the left hand side of the control guide slot when selected to the ground idle position.

You may examine the MCAI on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0717.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Pacific Aerospace Mandatory Service Bulletin PACSB/XL/111, Issue 1, dated June 18, 2019. The service information contains procedures for inspecting and adjusting the position of the fuel condition lever relative to the control guide, which assists in prevention of inadvertent movement of the power lever into the cutoff position if ground idle is selected. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of the AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this AD because it evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because of several reported engine failures on these airplanes due to inadvertent movement of the power lever into the cutoff position if ground idle is selected. Engine failure could result in loss of airplane control. The risk assessment received by the FAA, and reconfirmed in July of 2020, indicates that urgent action is required. Therefore, the FAA finds good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reason stated above, the

FAA finds that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the Docket Number FAA-2020-0717 and Product Identifier 2019-CE-038-AD at the beginning of your comments. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact we receive about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Costs of Compliance

The FAA estimates that this AD will affect 22 products of U.S. registry. The FAA also estimates that it will take 1 work-hour per product to comply with the inspection requirement of this AD. The average labor rate is \$85 per work-hour.

Based on these figures, the FAA estimates the cost of this AD on U.S. operators to be \$1,870, or \$85 per product.

In addition, the FAA estimates that any necessary follow-on actions will take 4 work-hours and require parts costing \$20, for a cost of \$360 per product. The FAA has no way of determining the number of products that may need these actions.

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2020–16–12 Pacific Aerospace Limited: Amendment 39–21196; Docket No. FAA–2020–0717; Product Identifier 2019–CE–038–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective September 8, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pacific Aerospace Limited Model 750XL airplanes, serial numbers 101 through 216, 220, 8001, and 8002, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 76: Engine Controls.

(e) Reason

This AD was prompted by inadvertent fuel shut-off to the engine during the operation of the flaps, due to the fuel and flap control levers being located too closely together. The FAA is issuing this AD to adjust the position of the fuel condition lever relative to the control guide, which will prevent inadvertent movement of the power lever into the cutoff position if ground idle is selected and result in engine failure and loss of airplane control.

(f) Actions and Compliance

Unless already done, within the next 30 days after September 8, 2020 (the effective date of this AD), inspect the position of the fuel condition lever by following the Accomplishment Instructions, paragraph 2(1), of Pacific Aerospace Mandatory Service Bulletin PACSB/XL/111, Issue 1, dated June 18, 2019 (MSB PACSB/XL/111). If the fuel condition lever is not positioned against the left side of the control guide slot in the ground idle position, before further flight,

adjust the fuel condition level position by following the Accomplishment Instructions, paragraph 2(3), of MSB PACSB/XL/111.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Small Airplane General Aviation & Rotorcraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4144; fax: (816) 329–4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(h) Related Information

Refer to mandatory continuing airworthiness information (MCAI) CAA AD No. DCA/750XL/39, dated September 5, 2019, for related information. You may examine the MCAI on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0717.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pacific Aerospace Mandatory Service Bulletin PACSB/XL/111, Issue 1, dated June 18, 2019.

(ii) [Reserved]

(3) For Pacific Aerospace Limited service information identified in this AD, contact Pacific Aerospace Limited, Airport Road, Hamilton, Private Bag 3027, Hamilton 3240, New Zealand; phone: +64 7843 6144; fax: +64 7843 6134; email: pacific@aerospace.co.nz; internet: <https://www.aerospace.co.nz>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148. It is also available on the internet at <https://www.regulations.gov> by searching for locating Docket No. FAA–2020–0717.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on August 5, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–17865 Filed 8–14–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0716; Product Identifier 2019–CE–009–AD; Amendment 39–21191; AD 2020–16–07]

RIN 2120–AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Pacific Aerospace Limited Model 750XL airplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as nose landing gear (NLG) and main landing gear (MLG) attachment bolts without dual retaining devices. The FAA is issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective September 8, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of September 8, 2020.

The FAA must receive comments on this AD by October 1, 2020.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.