

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2020-0909; Project Identifier 2019-SW-118-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Helicopters Model AS332C, AS332C1, AS332L, and AS332L1 helicopters. This proposed AD was prompted by a report that the cabin lateral sliding plug door failed its emergency jettisoning test; subsequent investigation revealed that the jettison handle cable interfered with the cable clamps. This proposed AD would require modifying the release system of each cabin lateral sliding plug door, or modifying the design of the jettison system of each cabin lateral sliding plug door, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 23, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Office of the Regional Counsel,

Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0909.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0909; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Kathleen Arrigotti, Aviation Safety Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218; email kathleen.arrigotti@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to participate in this rulemaking by submitting written comments, data, or views about this proposal. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one copy of the comments. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2020-0909; Project Identifier 2019-SW-118-AD" at the beginning of your comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments received by the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this NPRM because of those comments.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Kathleen Arrigotti, Aviation Safety Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218; email kathleen.arrigotti@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0064R1, dated December 19, 2019 ("EASA AD 2019-0064R1") (also referred to as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Airbus Helicopters Model AS332C, AS332C1, AS332L, and AS332L1 helicopters.

This proposed AD was prompted by a report that the cabin lateral sliding plug door failed its emergency jettisoning test; subsequent investigation revealed that the jettison handle cable interfered with the cable clamps. The FAA is proposing this AD to address this condition, which could lead to jamming of the door jettisoning mechanism, preventing the jettisoning of the affected door in an emergency situation, and possibly obstructing occupant evacuation. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019-0064R1 describes, among other things, procedures for modifying the release system of each cabin lateral sliding plug door, or modifying the design of the jettison

system of each cabin lateral sliding plug door.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in EASA AD 2019–0064R1, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD and except as

discussed under “Differences Between this Proposed AD and the MCAI.”

Differences Between This Proposed AD and the MCAI

EASA AD 2019–0064R1 specifies inspections of the jettisoning mechanism of the cabin lateral sliding plug doors and corrective actions. This proposed AD does not include those actions. AD 2019–09–03, Amendment 39–19637 (84 FR 22693, May 20, 2019) (“AD 2019–09–03”) already requires those actions. The FAA has determined that this proposed AD would only require the modification specified in EASA AD 2019–0064R1, which would then terminate the requirements of AD 2019–09–03.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2019–0064R1 will be incorporated by

reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2019–0064R1 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2019–0064R1 that is required for compliance with EASA AD 2019–0064R1 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0909 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this proposed AD affects 19 helicopters of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 214 work-hours × \$85 per hour = Up to \$18,190.	\$*	Up to \$18,190	Up to \$345,610.

*The FAA has received no definitive data that would enable the agency to provide parts cost estimates for the actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus Helicopters: Docket No. FAA-2020-0909; Project Identifier 2019-SW-118-AD.

(a) Comments Due Date

The FAA must receive comments by November 23, 2020.

(b) Affected ADs

This AD affects AD 2019-09-03, Amendment 39-19637 (84 FR 22693, May 20, 2019) (“AD 2019-09-03”).

(c) Applicability

This AD applies to Airbus Helicopters Model AS332C, AS332C1, AS332L, and AS332L1 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019-0064R1, dated December 19, 2019 (“EASA AD 2019-0064R1”).

(d) Subject

Joint Aircraft System Component (JASC) Code 5200, Doors.

(e) Reason

This AD was prompted by a report that the cabin lateral sliding plug door failed its emergency jettisoning test; subsequent investigation revealed that the jettison handle cable interfered with the cable clamps. The FAA is issuing this AD to address this condition, which could lead to jamming of the door jettisoning mechanism, preventing the jettisoning of the affected door in an emergency situation, and possibly obstructing occupant evacuation.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, paragraph (3) or (4) of EASA AD 2019-0064R1.

(h) Exceptions to EASA AD 2019-0064R1

(1) Where EASA AD 2019-0064R1 refers to April 10, 2019 (the effective date of EASA AD 2019-0064, dated March 27, 2019), this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0064R1 does not apply to this AD.

(3) If the modification specified in paragraph (4) of EASA AD 2019-0064R1 is done, it must be done at the compliance time specified in paragraph (3) of EASA AD 2019-0064R1.

(4) Although the service information referenced in EASA AD 2019-0064R1 specifies to discard or scrap certain parts, this AD does not include that requirement.

(5) Where paragraph (3) of EASA AD 2019-0064R1 specifies to do a modification “in accordance with the instructions of section 3 of the modification ASB” this AD excludes paragraph 3.B.5. of “the modification ASB.”

(6) Where paragraph (4) of EASA AD 2019-0064R1 refers to “Eurocopter AS 322 SB No. 52.00.28,” for this AD use “Eurocopter AS 332 SB No. 52.00.28.”

(i) Terminating Action for AD 2019-09-03

Accomplishing the actions required by this AD terminates all requirements of AD 2019-09-03.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, notify your principal inspector or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(k) Related Information

(1) For information about EASA AD 2019-0064R1, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0909.

(2) For more information about this AD, contact Kathleen Arrigotti, Aviation Safety Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218; email kathleen.arrigotti@faa.gov.

Issued on October 1, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-22124 Filed 10-6-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0905; Product Identifier 2019-SW-102-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2015-26-01, which applies to certain Airbus Helicopters Model AS332C1, AS332L1, AS332L2, EC225LP, AS-365N2, AS 365 N3, EC 155B, and EC155B1 helicopters with an energy-absorbing seat. AD 2015-26-01 requires inspecting for the presence of labels (placards) that prohibit stowing anything under the seat, and if a label (placard) is missing or not clearly visible to each occupant, installing a label (placard). Since the FAA issued AD 2015-26-01, the FAA has determined that additional helicopters are affected by the unsafe condition, and that new labels (placards) are required for all affected helicopters. This proposed AD would retain all of the requirements of AD 2015-26-01. This proposed AD would also add helicopters to the applicability and require a modification (installing new labels (placards)). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 23, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; phone: 972-641-0000 or 800-