

based enterprises in domestic and export markets.²⁹

The OMB has determined that the final rule is not a major rule for purposes of the CRA and the FDIC will submit the final rule and other appropriate reports to Congress and the Government Accountability Office for review.

E. Plain Language

Section 722 of the Gramm-Leach-Bliley Act³⁰ requires each Federal banking agency to use plain language in all of its proposed and final rules published after January 1, 2000. The FDIC has sought to present the final rule in a simple and straightforward manner and did not receive any comments on the use of plain language in connection with the proposed rule.

List of Subjects

12 CFR Part 303

Administrative practice and procedure, Bank deposit insurance, Banks, banking, Reporting and recordkeeping requirements, Savings associations.

12 CFR Part 347

Authority delegations (Government agencies), Bank deposit insurance, Banks, banking, Credit, Foreign banking, Investments, Reporting and recordkeeping requirements, U.S. Investments abroad.

FEDERAL DEPOSIT INSURANCE CORPORATION

12 CFR Chapter III

Authority and Issuance

For the reasons set forth in the preamble, the FDIC amends 12 CFR parts 303 and 347 as follows:

PART 303—FILING PROCEDURES

■ 1. The authority citation for part 303 continues to read as follows:

Authority: 12 U.S.C. 378, 478, 1463, 1467a, 1813, 1815, 1817, 1818, 1819 (Seventh and Tenth), 1820, 1823, 1828, 1831i, 1831e, 1831o, 1831p–1, 1831w, 1831z, 1835a, 1843(l), 3104, 3105, 3108, 3207, 5412; 15 U.S.C. 1601–1607.

§ 303.2 [Amended]

■ 2. In § 303.2, remove paragraphs (w) and (x) and redesignate paragraphs (y) through (gg) as paragraphs (w) through (ee), respectively.

§ 303.42 [Amended]

■ 3. In § 303.42, remove paragraphs (b)(4) and (5) and redesignate paragraphs (b)(6) through (8) as paragraphs (b)(4) through (6), respectively.

■ 4. Amend § 303.182 by revising paragraphs (a) and (b)(2)(i) to read as follows:

§ 303.182 Establishing, moving or closing a foreign branch of an insured state nonmember bank.

(a) *Notice procedures for general consent.* Notice in the form of a letter from an eligible depository institution establishing or relocating a foreign branch pursuant to § 347.117(a) of this chapter must be provided to the appropriate FDIC office no later than 30 days after taking such action. The notice must include the location of the foreign branch, including a street address. The FDIC will provide written acknowledgment of receipt of the notice.

(b) * * *

(2) * * *

(i) The exact location of the proposed foreign branch, including the street address.

* * * * *

■ 5. Amend § 303.184 by:

■ a. Removing paragraphs (a)(2)(iii) and (iv);

■ b. Redesignating paragraphs (a)(2)(v) and (vi) as paragraphs (a)(iii) and (iv), respectively; and

■ c. Revising paragraph (d)(1)(iv).

The revision reads as follows:

§ 303.184 Moving an insured branch of a foreign bank.

* * * * *

(d) * * *

(1) * * *

(iv) Compliance with the CRA and any applicable related regulations, including 12 CFR part 345, has been considered and favorably resolved;

* * * * *

PART 347—INTERNATIONAL BANKING

■ 6. The authority citation for part 347 continues to read as follows:

Authority: 12 U.S.C. 1813, 1815, 1817, 1819, 1820, 1828, 3103, 3104, 3105, 3108, 3109; Pub. L. 111–203, section 939A, 124 Stat. 1376, 1887 (July 21, 2010) (codified in 15 U.S.C. 780–7 note).

§ 347.119 [Amended]

■ 7. Amend § 347.119 by removing paragraph (b) and redesignating paragraphs (c) and (d) as paragraphs (b) and (c), respectively.

Federal Deposit Insurance Corporation.

By order of the Board of Directors.

Dated at Washington, DC, on October 20, 2020.

James P. Sheesley,

Assistant Executive Secretary.

[FR Doc. 2020–23529 Filed 11–12–20; 8:45 am]

BILLING CODE 6714–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0779; Product Identifier 2020–NM–092–AD; Amendment 39–21311; AD 2020–22–15]

RIN 2120–AA64

Airworthiness Directives; the Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all The Boeing Company Model DC–10–10 and DC–10–10F airplanes, Model DC–10–15 airplanes, Model DC–10–30 and DC–10–30F (KC–10A and KDC–10) airplanes, Model DC–10–40 and DC–10–40F airplanes, Model MD–10–10F and MD–10–30F airplanes, and Model MD–11 and MD–11F airplanes. This AD was prompted by reports of cracked floor beams and floor beam supports in the area of the overwing exit doors located at certain stations (STA). This AD requires an inspection of the overwing floor beams for any repair, repetitive inspections of the overwing floor beams and floor beam supports at certain STA on the left and right sides for any crack, and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective December 18, 2020.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of December 18, 2020.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

²⁹ 5 U.S.C. 804(2).

³⁰ Public Law 106–102, section 722, 113 Stat. 1338, 1471 (1999).

It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0779.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0779; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Manuel Hernandez, Aerospace Engineer, Systems and Equipment Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5256; fax: 562-627-5210; email: Manuel.F.Hernandez@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model DC-10-10 and DC-10-10F airplanes, Model DC-10-15 airplanes, Model DC-10-30 and DC-10-30F (KC-10A and KDC-10) airplanes, Model DC-10-40 and DC-10-40F airplanes, Model MD-

10-10F and MD-10-30F airplanes, and Model MD-11 and MD-11F airplanes. The NPRM published in the **Federal Register** on August 25, 2020 (85 FR 52287). The NPRM was prompted by reports of cracked floor beams and floor beam supports in the area of the overwing exit doors located at certain STA. The NPRM proposed to require an inspection of the overwing floor beams for any repair, repetitive inspections of the overwing floor beams and floor beam supports at certain STA on the left and right sides for any crack, and applicable on-condition actions.

The FAA is issuing this AD to address potential undetected overwing floor beam cracks that could grow in length until the floor beam severs, and, if limit load is applied with two adjacent severed floor beams, could adversely affect the structural integrity of the airplane, which could result in the loss of primary control systems and lead to reduced controllability of the airplane.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comments received. Boeing and Shawn Darr indicated support for the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin DC10-53A184 RB, dated February 6, 2020; and Boeing Alert Requirements Bulletin MD11-53A088 RB, dated March 6, 2020. The service information describes procedures for a general visual inspection of the overwing floor beams for any repair; repetitive eddy current high frequency (ETHF) inspections of the overwing floor beams and floor beam supports for cracks, or repetitive ETHF inspections of the overwing floor beams and detailed inspections of the overwing floor beam supports at certain stations on the left and right sides for any crack, depending on configuration; and applicable on-condition actions. On-condition actions include repair. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 224 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
General visual inspection	1 work-hour × \$85 per hour = \$85.	\$0	\$85	\$19,040.
ETHF and detailed inspections.	Up to 70 work-hours × \$85 per hour = Up to \$5,950 per inspection cycle.	0	Up to \$5,950 per inspection cycle.	Up to \$1,332,800 per inspection cycle.

The FAA estimates the following costs to do any necessary on-condition actions that would be required. The FAA has no way of determining the number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 375 work-hours × \$85 per hour = Up to \$31,875	Up to \$190,576	Up to \$222,451.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing

regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2020–22–15 The Boeing Company:

Amendment 39–21311; Docket No. FAA–2020–0779; Product Identifier 2020–NM–092–AD.

(a) Effective Date

This AD is effective December 18, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company airplanes specified in paragraphs (c)(1) through (6) of this AD, certificated in any category.

(1) Model DC–10–10 and DC–10–10F airplanes.

(2) Model DC–10–15 airplanes.

(3) Model DC–10–30 and DC–10–30F (KC–10A and KDC–10) airplanes.

(4) Model DC–10–40 and DC–10–40F airplanes.

(5) Model MD–10–10F and MD–10–30F airplanes.

(6) Model MD–11 and MD–11F airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracked floor beams and floor beam supports in the area of the overwing exit doors located at certain stations. The FAA is issuing this AD to address potential undetected overwing floor beam cracks that could grow in length until the floor beam severs, and, if limit load is applied with two adjacent severed floor beams, could adversely affect the structural integrity of the airplane, which could result in the loss of primary control systems and lead to reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin DC10–53A184 RB, dated February 6, 2020; or Boeing Alert Requirements Bulletin MD11–53A088 RB, dated March 6, 2020; as applicable, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin DC10–53A184 RB, dated February 6, 2020; or Boeing Alert Requirements Bulletin MD11–53A088 RB, dated March 6, 2020; as applicable.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin DC10–53A184, dated February 6, 2020; or Boeing Alert Service Bulletin MD11–53A088, dated March 6, 2020; as applicable, which are referred to in Boeing Alert Requirements Bulletin DC10–53A184 RB, dated February 6, 2020; and Boeing Alert Requirements Bulletin MD11–53A088 RB, dated March 6, 2020; respectively.

(h) Exceptions to Service Information Specifications

(1) Where Boeing Alert Requirements Bulletin DC10–53A184 RB, dated February 6, 2020, uses the phrase “the original issue date of Requirements Bulletin DC10–53A184 RB,” this AD requires using “the effective date of this AD,” except where Boeing Alert Requirements Bulletin DC10–53A184 RB, dated February 6, 2020, uses the phrase “the original issue date of Requirements Bulletin DC10–53A184 RB” in a note or flag note.

(2) Where Boeing Alert Requirements Bulletin MD11–53A088 RB, dated March 6, 2020, uses the phrase “the original issue date of Requirements Bulletin MD11–53A088

RB,” this AD requires using “the effective date of this AD,” except where Boeing Alert Requirements Bulletin MD11–53A088 RB, dated March 6, 2020, uses the phrase “the original issue date of Requirements Bulletin MD11–53A088 RB” in a note or flag note.

(3) Where Boeing Alert Requirements Bulletin DC10–53A184 RB, dated February 6, 2020, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(4) Where Boeing Alert Requirements Bulletin MD11–53A088 RB, dated March 6, 2020, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Manuel Hernandez, Aerospace Engineer, Systems and Equipment Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5256; fax: 562–627–5210; email: Manuel.F.Hernandez@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this

paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin DC10-53A184 RB, dated February 6, 2020.

(ii) Boeing Alert Requirements Bulletin MD11-53A088 RB, dated March 6, 2020.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 21, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-25013 Filed 11-12-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0213; Project Identifier 2019-NE-03-AD; Amendment 39-21324; AD 2020-23-08]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (Type Certificate Previously Held by Rolls-Royce plc) Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Rolls-Royce Deutschland Ltd & Co KG (RRD) Tay 611-8C model turbofan engines. This AD was prompted by reports of low-pressure compressor (LPC) rotor blade retention lug failure. This AD requires limiting the service life of the LPC rotor blades based on the number of dry-film lubricant (DFL) re-applications. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 18, 2020.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of December 18, 2020.

ADDRESSES: For service information identified in this final rule, contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, Dahlewitz, Blankenfelde-Mahlow, Germany; phone: +49 0 33-7086-4040; fax: +49 0 33-7086-51-4040; email: rrd.techhelp@rolls.royce.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0213.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0213; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7146; fax: (781) 238-7199; email: barbara.caufield@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain RRD Tay 611-8C model turbofan engines. The NPRM published in the **Federal Register** on May 6, 2019 (84 FR 19745). The NPRM was prompted by reports of LPC rotor blade retention lug failures. In the NPRM, the FAA proposed to require a determination of the number of DFL re-applications that have been applied to the LPC rotor blades and, depending on the number of DFL re-applications, replacement of LPC rotor blades. The FAA is issuing this AD to address the unsafe condition on these products.

The European Aviation Safety Agency (EASA), which is the Technical Agent

for the Member States of the European Community, has issued EASA AD 2018-0055, dated March 12, 2018 (referred to after this as "the MCAI"), to address the unsafe condition on these products. The MCAI states:

The airworthiness limitations for the Tay 611-8C engines, which are approved by EASA, are currently defined and published in the ALS. Among others, the ALS contains limitation(s) applicable to the maximum number of Dry Film Lubrication (DFL) treatments applied on fan blade retention lugs. These instructions have been identified as mandatory for continued airworthiness. Failure to accomplish these instructions could result in an unsafe condition.

In addition to the ALS, RRD issued the NMSB to provide alternative methods to establish, in case this cannot be determined from the engine maintenance records, the number of DFL treatments that have been applied to an engine.

You may obtain further information by examining the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0213.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Modify Applicability

NetJets Aviation (NJA) requested that engines which have incorporated the 12,000 cycle life limit on LPC rotor blade, part number JR58319, per the Airworthiness Limitations section 05-10-01-870-002, chapter 05-10-01, Rolls-Royce (RR) Tay Propulsion System Time Limits Manual, be excluded from the applicability of this AD.

The FAA disagrees because the low cycle fatigue life limit of 12,000 cycles for the LPC rotor blade is a separate requirement from the requirement of this AD to also limit the number of dry film lubricant re-applications.

Comment Regarding DFL Re-application Limit

NJA noted that dry film re-application is only accomplished in an engine overhaul shop, and the 12 DFL-application limit every 1,300 cycles will not be exceeded if the life limit is being tracked. The FAA disagrees. The FAA notes that there are tasks in the Aircraft Maintenance Manual (AMM) for DFL re-applications that are not limited to shop visits. Therefore, this AD is necessary to address those cases in which the AMM DFL re-application tasks are necessary and the engine is not in the shop. This AD requires that when a complete