(A) If a washer on the external fitting makes contact with a weld, perform a spotfacing to the diameter of 17mm (+ 0.1/-0.1) with a cutter root radius of 0.5mm.

(B) If a washer on the internal fitting falls in the radius of the bracket, perform a spotfacing to the diameter of 17 mm (+ 0.1/ - 0.1) with a cutter root radius of 0.5 mm.

(iv) Torque each nut to 169–203 lbf.in (1.9– 2.3 daN.m), and apply sealing compound to outer edge of the LH rear upper fitting.

(4) Completion of the requirements in paragraph in (f)(3) of this AD constitutes terminating action for the repetitive checks required in paragraph (f)(1) of this AD.

(g) Special Flight Permits

Special flight permits are prohibited for flights over water.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Matthew Fuller, AD Program Manager, Operational Safety Branch, Airworthiness Products Section, General Aviation & Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(i) Additional Information

(1) Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 05.01.06, and EASB No. 05A047, each Revision 0 and dated December 18, 2015, and each Revision 1 and dated April 4, 2018, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at https://www.airbus.com/ helicopters/services/technical-support.html. You may view a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD No. 2018–0090, dated April 20, 2018. You may view the EASA AD on the internet at *https://www.regulations.gov* in Docket No. FAA–2018–0893.

(j) Subject

Joint Aircraft Service Component (JASC) Code: 3212, Emergency Flotation Section.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin (ASB) No. AS332–25.03.43, Revision 0, dated April 4, 2018.

(ii) Airbus Helicopters ASB No. AS332– 25.03.43, Revision 2, dated March 21, 2019.

(iii) Airbus Helicopters ASB No. EC225– 25A207, Revision 0, dated April 4, 2018.

(iv) Airbus Helicopters ASB No. EC225– 25A207, Revision 2, dated March 21, 2019.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 800–232–0323 or Fax: 972–641– 3775; or at https://www.airbus.com/ helicopters/services/technical-support.html.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fedreg.legal@nara.gov*, or go to: *https:// www.archives.gov/federal-register/cfr/ibrlocations.html*.

Issued on October 27, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service. [FR Doc. 2020–25493 Filed 11–25–20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0788; Product Identifier 2020–NM–091–AD; Amendment 39–21327; AD 2020–23–11]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT). **ACTION:** Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A300 series airplanes; and Airbus SAS Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Airbus SAS Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes). This AD was prompted by reports of cracking at a certain hole location on the left-hand (LH) side of a certain frame (FR). This AD requires

repetitive inspections for discrepancies of certain areas in and around the fuselage, as specified in two European Union Aviation Safety Agency (EASA) ADs, which are incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 4, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of January 4, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@ *easa.europa.eu*; internet *www.easa.europa.eu*. You may find this IBR material on the EASA website at https://ad.easa.europa.eu. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at *https://* www.regulations.gov by searching for and locating Docket No. FAA-2020-0788.

Examining the AD Docket

You may examine the AD docket on the internet at *https:// www.regulations.gov* by searching for and locating Docket No. FAA–2020– 0788; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email Dan.Rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020–0110R1, dated May 27, 2020; and EASA AD 2020–0111R2, dated June 16, 2020 ("EASA AD 2020–0110R1" and "EASA AD 2020–0111R2") (also referred to as "the Mandatory Continuing Airworthiness Information," or "the MCAI"); to correct an unsafe condition for all Airbus SAS Model A300 series airplanes and Airbus SAS Model A300–600 series airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A300 series airplanes and Airbus SAS Model A300–600 series airplanes. The NPRM published in the **Federal Register** on September 1, 2020 (85 FR 54286). The NPRM was prompted by reports of cracking at hole location #10 on the LH side of FR4. The NPRM proposed to require repetitive inspections for discrepancies of certain areas in and around the fuselage, as specified in two EASA ADs.

The FAA is issuing this AD to address fatigue cracking, which could result in reduced structural integrity of the fuselage. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. FedEx indicated its support for the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

• Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and

• Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2020–0110R1 describes procedures for repetitive special detailed inspections for discrepancies

ESTIMATED COSTS FOR REQUIRED ACTIONS

(*i.e.*, cracking) of the fuselage internal structure at certain frames, windshield frame lower section and closing panel, fuselage skin lap joint, and center wing bottom skin internal angle; and applicable corrective actions (repairing discrepancies).

EASA AD 2020–0111R2 describes procedures for repetitive special detailed inspections for discrepancies of the outer wing bottom skin internal joint plate, outer wing bottom skin, fuselage internal structure at certain frames, and windshield frame lower section and closing panel; and applicable corrective actions (repairing discrepancies).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 118 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
90 work-hours × \$85 per hour = \$7,650	\$0	\$7,650	\$902,700

The FAA has received no definitive data that would enable the agency to provide cost estimates for the oncondition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order

13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2020–23–11 Airbus SAS: Amendment 39– 21327; Docket No. FAA–2020–0788; Product Identifier 2020–NM–091–AD.

(a) Effective Date

This airworthiness directive (AD) is effective January 4, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS airplanes identified in paragraphs (c)(1) and (2) of this AD, certificated in any category.

(1) Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes.

(2) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes; Model A300 B4–605R and B4–622R airplanes; Model A300 F4– 605R and F4–622R airplanes; and Model A300 C4–605R Variant F airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage; 57, Wings.

(e) Reason

This AD was prompted by reports of cracking at hole location #10 on the left-hand side of frame 4. The FAA is issuing this AD to address fatigue cracking, which could result in reduced structural integrity of the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

(1) For airplanes identified in paragraph (c)(1) of this AD: Except as specified in paragraphs (h)(1) and (3) of this AD, comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0110R1, dated May 27, 2020 ("EASA AD 2020–0110R1").

(2) For airplanes identified in paragraph (c)(2) of this AD: Except as specified in paragraphs (h)(2) and (3) of this AD, comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020–0111R2, dated June 16, 2020 ("EASA AD 2020–0111R2").

(h) Exceptions to EASA AD 2020–0110R1 and EASA AD 2020–0111R2

(1) Where EASA AD 2020–0110R1 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (4) of EASA AD 2020– 0111R2 refers to June 3, 2020 ("the effective date of this [EASA] AD at original issue"), this AD requires using the effective date of this AD.

(3) The "Remarks" section of EASA AD 2020–0110R1 and EASA AD 2020–0111R2 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email Dan.Rodina@ faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0110R1, dated May 27, 2020.

(ii) European Union Aviation Safety Agency (EASA) AD 2020–0111R2, dated June 16, 2020.

(3) For EASA AD 2020–0110R1 and EASA AD 2020–0111R2, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@ easa.europa.eu*; Internet *www.easa.europa.eu*. You may find this

EASA AD on the EASA website at *https://ad.easa.europa.eu*

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at *https:// www.regulations.gov* by searching for and locating Docket No. FAA–2020–0788.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fedreg.legal@ nara.gov*, or go to: *https://www.archives.gov/ federal-register/cfr/ibr-locations.html*.

Issued on November 4, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service. [FR Doc. 2020–26046 Filed 11–25–20; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 91

[Docket No.: FAA-2017-0768; Amdt. No. 91-348C]

RIN 2120-AL55

Extension of the Prohibition Against Certain Flights in the Damascus Flight Information Region (FIR) (OSTT)

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT). **ACTION:** Final rule.

SUMMARY: This action extends the prohibition against certain flight operations in the Damascus Flight Information Region (FIR) (OSTT) by all: U.S. air carriers: U.S. commercial operators; persons exercising the privileges of an airman certificate issued by the FAA, except when such persons are operating U.S.-registered aircraft for a foreign air carrier; and operators of U.S.-registered civil aircraft, except when the operator of such aircraft is a foreign air carrier. The FAA finds this action necessary to address significant, continuing hazards to U.S. civil aviation associated with the ongoing and complex conflict in Syria. The FAA also republishes the approval process and exemption information for this Special Federal Aviation Regulation (SFAR), consistent with other recently published flight prohibition SFARs, and makes minor administrative revisions.

DATES: This final rule is effective on November 27, 2020.

FOR FURTHER INFORMATION CONTACT:

Stephen Moates, Air Transportation Division, Flight Standards Service, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone 202–267–8166; email *Stephen.moates@faa.gov.* **SUPPLEMENTARY INFORMATION:**

I. Executive Summary

This action extends the expiration date of the prohibition against certain U.S. civil flight operations in the Damascus FIR (OSTT) by all: U.S. air carriers; U.S. commercial operators; persons exercising the privileges of an airman certificate issued by the FAA, except when such persons are operating U.S.-registered aircraft for a foreign air carrier; and operators of U.S.-registered civil aircraft, except when the operator of such aircraft is a foreign air carrier. Specifically, this amendment extends the expiration date of SFAR No. 114, § 91.1609 of title 14, Code of Federal