Register, the undersigned DOE Federal Register Liaison Officer has been authorized to sign and submit the document in electronic format for publication, as an official document of the Department of Energy. This administrative process in no way alters the legal effect of this document upon publication in the **Federal Register**.

Signed in Washington, DC, on December 1, 2020.

#### Treena V. Garrett,

Federal Register Liaison Officer, U.S. Department of Energy.

[FR Doc. 2020-26722 Filed 12-7-20; 8:45 am]

BILLING CODE 6450-01-P

## **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2020-1113; Project Identifier MCAI-2020-00893-T]

RIN 2120-AA64

# Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 2019-03-10, which applies to all Airbus SAS Model A300 series airplanes; and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes). AD 2019-03-10 requires repetitive detailed visual inspections of the main landing gear (MLG) leg components and replacement of the MLG leg if cracked components are found. Since the FAA issued AD 2019–03–10, it was determined that additional actions (including inspections, modifications, and checks) are needed to address the unsafe condition. This proposed AD would continue to require the actions required by AD 2019-03-10. For certain airplanes, this proposed AD would also require modification of the MLG hinge arm by installing improved MLG hinge arm/barrel pins; an out-of-roundness check of removed pins; repetitive inspections of any affected pins and the associated connecting rod bushes, and replacement of the MLG leg if cracked components are found; and installation of an improved spacer as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for

incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 22, 2021

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.
  - Fax: 202-493-2251.
- *Mail*: U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@ easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at https://ad.easa.europa.eu. You may view this IBR material at the FAA. Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at https:// www.regulations.gov by searching for and locating Docket No. FAA-2020-1113.

#### **Examining the AD Docket**

You may examine the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA—2020—1113; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

# FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@faa.gov.

## SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA–2020–1113; Project Identifier MCAI–2020–00893–T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to https://www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposed AD.

## **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@ faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Discussion

The FAA issued AD 2019–03–10, Amendment 39–19562 (84 FR 5595, February 22, 2019) (AD 2019–03–10), which applies to all Airbus SAS Model A300 series airplanes; and Model A300– 600 series airplanes. AD 2019–03–10 requires repetitive detailed visual inspections of the MLG leg components and replacement of the MLG leg if cracked components are found. The FAA issued AD 2019–03–10 to address cracking of certain components in the MLG leg, which could result in an MLG collapse, and consequent damage to the airplane and injury to the airplane occupants.

# Actions Since AD 2019–03–10 Was Issued

Since the FAA issued AD 2019–03–10, Airbus issued instructions for installation of a new MLG hinge arm/barrel pin with wet primer integration, to improve corrosion protection. It was also determined that an out-of-roundness check of removed pins is needed to detect potential overload. Airbus also issued instructions for repetitive general visual inspections of affected pins and connecting rod bushes. Airbus also issued instructions for modification of the spacer design to prevent migration of the connecting rod bushes in case of bush fracture.

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0145, dated July 1, 2020 (EASA AD 2020-0145) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus SAS Model A300 series airplanes; Model A300-600 series airplanes; and Model A300F4-608ST airplanes. EASA AD 2020-0145 supersedes EASA AD 2018-0170 (which corresponds to FAA AD 2019-03-10). Model A300F4-608ST airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by reports of cracks in MLG leg components, and a determination that additional actions (including inspections, modifications, and checks) are needed to address the unsafe condition. The FAA is proposing this AD to address cracking of certain components in the MLG leg, which could result in an MLG collapse, and consequent damage to the airplane and

injury to the airplane occupants. See the MCAI for additional background information.

# **Explanation of Retained Requirements**

Although this proposed AD does not explicitly restate the requirements of AD 2019–03–10, this proposed AD would retain all of the requirements of AD 2019–03–10. Those requirements are referenced in EASA AD 2020–0145, which, in turn, is referenced in paragraph (g) of this proposed AD.

# **Related Service Information Under 1** CFR Part 51

EASA AD 2020-0145 describes procedures for repetitive detailed visual inspections of the MLG leg components and replacement of the MLG leg if cracked components are found. EASA AD 2020–0145 also describes procedures, for certain airplanes, for modification of the MLG hinge arm by installing improved pins, which would terminate the repetitive detailed inspections required by AD 2019-03-10; an out-of-roundness check of removed pins; repetitive inspections of affected pins and the associated connecting rod bushes for cracking, and replacement of the MLG leg if cracked components are found; and installation of an improved spacer, which would terminate the repetitive pin and rod bushes inspections. EASA AD 2020-0145 also describes procedures for reporting results of the out-of-roundness check to Safran.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

# FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or

develop on other products of the same type design.

# **Proposed AD Requirements**

This proposed AD would require accomplishing the actions specified in EASA AD 2020–0145 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

# **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020-0145 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2020-0145 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD. Service information specified in EASA AD 2020-0145 that is required for compliance with EASA AD 2020–0145 will be available on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA-2020-1113 after the FAA final rule is published.

# **Costs of Compliance**

The FAA estimates that this proposed AD affects 128 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

# ESTIMATED COSTS FOR REQUIRED ACTIONS \*

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2019-03-10.	1 work-hour × \$85 per hour = \$85, per inspection cycle.	\$0	\$85, per inspection cycle	\$10,880, per inspection cycle.
New proposed modifications	180 work-hours × \$85 per	17,993	33,293	4,261,504.

## ESTIMATED COSTS FOR REQUIRED ACTIONS \*—Continued

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
New proposed inspection	1 work-hour × \$85 per hour = \$85.	0	85	10,880.
New proposed out-of-round-ness check.	4 work-hours × \$85 per hour = \$340.	0	340	43,520.

<sup>\*</sup>Table does not include estimated costs for reporting.

The FAA estimates that it would take about 1 work-hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based on these figures, the FAA estimates the

cost of reporting the inspection results on U.S. operators to be \$85, or \$85 per product.

#### **ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per prod- uct
20 work-hours × \$85 per hour = \$1,700 per MLG	\$3,400,000 per MLG	\$3,401,700 per MLG.

# **Paperwork Reduction Act**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120-0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

# Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

# **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

# List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

# The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### §39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing Airworthiness Directive (AD) 2019–03–10, Amendment 39–19562 (84 FR 5595, February 22, 2019), and
- b. Adding the following new AD:

**Airbus SAS:** Docket No. FAA–2020–1113; Project Identifier MCAI–2020–00893–T.

## (a) Comments Due Date

The FAA must receive comments by January 22, 2021.

### (b) Affected Airworthiness Directives (ADs)

This AD replaces AD 2019–03–10, Amendment 39–19562 (84 FR 5595, February 22, 2019) (AD 2019–03–10).

## (c) Applicability

This AD applies to all Airbus SAS airplanes, certificated in any category, identified in paragraphs (c)(1) through (5) of this AD.

- (1) Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes.
- (2) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.
- (3) Model A300 B4–605R and B4–622R airplanes.
- (4) Model A300 F4–605R and F4–622R airplanes.
- (5) Model A300 C4–605R Variant F airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

#### (e) Reason

This AD was prompted by reports of cracks in main landing gear (MLG) leg components, and a determination that additional actions (including inspections, modifications, and out-of-roundness checks) are needed to address the unsafe condition. The FAA is issuing this AD to address cracking of certain components in the MLG leg, which could result in an MLG collapse, and consequent damage to the airplane and injury to the airplane occupant.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

# (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0145, dated July 1, 2020 (EASA AD 2020–0145).

#### (h) Exceptions to EASA AD 2020-0145

- (1) Where EASA AD 2020–0145 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where EASA AD 2020–0145 refers to the effective date of EASA AD 2018–0170, this AD requires using March 29, 2019 (the effective date of AD 2019–03–10).
- (3) The "Remarks" section of EASA AD 2020–0145 does not apply to this AD.
- (4) Paragraph (3) of EASA AD 2020–0145 specifies to "send all removed pins for an out-of-roundness check." For this AD, do an inspection of each pin for out-of-roundness, in accordance with the service information specified in EASA AD 2020–0145.
- (5) Paragraph (3) of EASA AD 2020–0145 specifies to report inspection results to Safran within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(5)(i) or (ii) of this AD.
- (i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.
- (ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

# (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal

inspector, the manager of the responsible Flight Standards Office.

- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.
- (3) Required for Compliance (RC): For any service information referenced in EASA AD 2020-0145 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.
- (4) Paperwork Reduction Act Burden Statement: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

# (j) Related Information

(1) For information about EASA AD 2020-0145, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@ easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at https:// ad.easa.europa.eu. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA-2020-1113.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@faa.gov.

Issued on December 2, 2020.

### Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service. [FR Doc. 2020–26910 Filed 12–7–20; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

## 14 CFR Part 39

[Docket No. FAA-2020-1112; Project Identifier MCAI-2020-01127-T]

RIN 2120-AA64

# Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all ATR—GIE Avions de Transport Régional Model ATR42 airplanes; and Model ATR72 airplanes. This proposed AD was prompted by in-service data which revealed that the minimum operating airspeeds in severe icing conditions, computed to provide adequate stall margins, do not provide sufficient margins to stall speeds at high bank angle while exiting severe icing conditions. This proposed AD would require revising the existing aircraft flight manual (AFM) and applicable corresponding operational procedures to provide emergency procedures and limitations for operating in severe icing conditions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by January 22, 2021

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.
  - Fax: 202-493-2251.