

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Requirements, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2020–01–17, with no changes. Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0316, dated December 23, 2019 (EASA AD 2019–0316).

(h) Retained Exceptions, With No Changes

This paragraph restates the requirements of paragraph (h) of AD 2020–01–17, with no changes.

(1) Where EASA AD 2019–0316 refers to its effective date, this AD requires using February 14, 2020 (the effective date of FAA AD 2020–01–17).

(2) The “Remarks” section of EASA AD 2019–0316 does not apply to this AD.

(3) Where EASA AD 2019–0316 specifies to comply with “the instructions of the AOT,” this AD requires compliance with the procedures marked as required for compliance (RC) in the Alert Operators Transmission (AOT).

(i) New Actions

Except as specified in paragraph (j) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020–0236, dated October 27, 2020 (EASA AD 2020–0236). Accomplishment of the initial check, as specified in EASA AD 2020–0236 and required by this paragraph, terminates the requirements of paragraph (g) of this AD.

(j) Exceptions to EASA AD 2020–0236

(1) Where EASA AD 2020–0236 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2020–0236 does not apply to this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved previously for AD 2020–01–17 are approved as AMOCs for the corresponding actions in EASA AD 2020–0236 that are required by paragraph (i) of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (k)(2) of this AD, for any service information referenced in EASA AD 2020–0236 that contains RC procedures and tests, those RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on December 28, 2020.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0236, dated October 27, 2020.

(ii) [Reserved]

(4) The following service information was approved for IBR on February 14, 2020 (85 FR 5310, January 30, 2020).

(i) European Union Aviation Safety Agency (EASA) AD 2019–0316, dated December 23, 2019.

(ii) [Reserved]

(5) For EASA ADs, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find these EASA ADs on the EASA website at <https://ad.easa.europa.eu>.

(6) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1105.

(7) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 30, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–27004 Filed 12–9–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2019–0984; Product Identifier 2019–NM–161–AD; Amendment 39–21290; AD 2020–21–17]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2018–16–05, which applied to certain The Boeing Company Model 757 airplanes. AD 2018–16–05 required repetitive inspections for skin cracking and shim migration at the upper link drag fittings, diagonal brace cracking, and fastener looseness; and applicable on-condition actions. This AD retains the actions required by AD 2018–16–05, reduces the compliance times for certain inspections, and adds repetitive inspections at certain fastener hole locations and applicable on-condition actions. This AD was prompted by reports of bolt rotation in the engine drag fitting joint and fastener heads; an inspection of the fastener holes revealed that cracks were found in the skin. This AD was also prompted by a report of multiple cracks in the drag fitting at fastener holes found during an inspection required by AD 2018–16–05. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 14, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 14, 2021.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services

(C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0984.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0984; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Chandra Ramdoss, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5239; fax: 562-627-5210; email: chandraduth.ramdoss@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2018-16-05, Amendment 39-19345 (83 FR 38250, August 6, 2018) (“AD 2018-16-05”). AD 2018-16-05 applied to certain The Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes. The NPRM published in the **Federal Register** on December 17, 2019 (84 FR 68822). The NPRM was prompted by reports of bolt rotation in the engine drag fitting joint and fastener heads; an inspection of the fastener holes revealed that cracks were found in the skin. The NPRM was also prompted by a report of multiple cracks found in the drag fitting at fastener holes during inspections required by AD 2018-16-05. The NPRM proposed to continue to require repetitive inspections for skin cracking and shim migration at the upper link drag fittings, diagonal brace cracking, and fastener looseness; and applicable on-condition actions. The NPRM also proposed to reduce the

compliance times for certain inspections and add repetitive inspections at certain fastener hole locations and applicable on-condition actions. The FAA is issuing this AD to address cracking in the wing upper skin and forward drag fittings, which could lead to a compromised upper link and reduced structural integrity of the engine strut.

Comments

The FAA gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Support for the NPRM

United Airlines (United) and American Airlines (American) stated their concurrence with the NPRM.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing (APB) stated that they have reviewed the NPRM and have determined that the installation of winglets per Supplemental Type Certificate (STC) ST01518SE does not affect the accomplishment of the manufacturer’s service instructions.

The FAA agrees with the commenter that STC ST01518SE does not affect the accomplishment of the manufacturer’s service instructions. The FAA has redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01518SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST00830SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

Requests To Increase the Inspection Intervals

American and United requested that the repetitive interval for the general visual inspection of the diagonal brace and diagonal brace fittings be increased from 2,100 flight cycles (FC) to 3,000 FC. In addition, American requested that the initial interval for the inspection also be increased to 3,000 FC. The commenters maintained that 2,100 FC does not align with their maintenance program intervals, which causes a significant burden on operators. United and American also stated that they have completed the inspection of 13 and 20 airplanes respectively and found no evidence of cracking, which indicates that the existing 3,000 FC interval is conservative.

The FAA disagrees with the requested change to the indicated repetitive inspection interval and initial interval. The FAA acknowledges that incorporating the interval into the existing maintenance program could be challenging for some operators. However, the inspection involves a visual assessment that requires limited disassembly and could be carried out without placing the aircraft in a heavy maintenance configuration. The reduced intervals are based on the re-assessment of the damage tolerance analysis to adjust for eleven additional crack findings since issuance of Boeing Alert Requirements Bulletin 757-57A0073 RB, dated July 14, 2017. The FAA has determined that the reduced inspection interval is necessary to avoid jeopardizing safety. The FAA has not changed the initial and repetitive inspection intervals required in this AD.

Request for Clarification That Compliance Times Cannot Be Extended

Boeing requested that clarification be added to the proposed AD to specify that the grace period provided for the newly proposed requirements cannot be used to extend compliance times for actions required by AD 2018-16-05. Boeing suggested that the FAA add a new paragraph to the proposed AD that would explicitly re-state the requirements of AD 2018-16-05. Boeing asserted that the new paragraph would maintain the requirements of AD 2018-16-05 only until the actions of paragraph (g) of the proposed AD are implemented.

The FAA does not agree to restate the requirements of AD 2018-16-05 or to add a new paragraph regarding the compliance time for the previously required actions. As explained in the NPRM, the requirements of AD 2018-16-05 are referenced in the service information required in this AD. Except for the diagonal brace inspections, the compliance times given in Boeing Alert Requirements Bulletin 757-57A0073 RB, Revision 1, dated August 1, 2019, for all actions required by AD 2018-16-05 are unchanged. The compliance times are defined both in terms of the effective date of AD 2018-16-05 and the effective date of the service information. For the diagonal brace inspections, the compliance time may provide an additional grace period; however, this affects only one inspection cycle, is applicable to a small number of operators, and is an acceptable compliance time to ensure safety. The FAA has determined all other compliance times will ensure an acceptable level of safety. This AD has not been changed in this regard.

Requests To Clarify the Effective Date of AD 2018–16–05

American and Boeing requested that the proposed AD be revised to include clarification of the effective date of AD 2018–16–05. The commenters observed that some compliance times are given as the number of flight cycles after the “effective date of AD 2018–16–05,” and that where Boeing Alert Requirements Bulletin 757–57A0073 RB, dated July 14, 2017, uses that phrase, the proposed AD should require using “September 10, 2018.” American asserted that the compliance times should be in terms of the date, not of the superseded AD, and that determining the effective date of the replaced AD could be difficult otherwise. The commenters asserted that including this clarification in the new AD would avoid confusion for operators.

The FAA agrees to clarify the effective date of AD 2018–16–05. The FAA has added an exception in paragraph (h)(3) to indicate that, where Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, uses the phrase “the effective date of AD 2018–16–05,” this AD requires using “September 10, 2018 (the effective date of AD 2018–16–05).”

Requests To Give Credit for Previously Accomplished Actions

American, Boeing, and FedEx requested that the proposed AD give credit for previously accomplished actions that were similar to or the same as the actions specified in Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019. American noted that Revision 1 of the service bulletin specifies a high frequency eddy current (HFEC) inspection for cracking at fastener locations 11–18 for airplanes already inspected in accordance with the original issue of the service bulletin.

American and Boeing asserted that operators of airplanes with fastener holes 1–10 already inspected per Boeing Alert Requirements Bulletin 757–57A0073 RB, dated July 14, 2017, should get credit for the initial inspection of fastener holes 1–10.

The FAA agrees and has added paragraph (i) to this AD to provide credit for previous actions accomplished using Boeing Alert Requirements Bulletin 757–57A0073 RB, dated July 14, 2017. The FAA has also reidentified subsequent paragraphs accordingly. As specified in Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, the new actions for fastener locations 11–18 must still be accomplished for airplanes on which the original revision of the RB was previously done.

Requests To Allow Certain AMOCs Previously Approved for AD 2018–16–05

American, Delta Air Lines, FedEx, and United requested that the proposed AD be changed to allow AMOCs previously approved for AD 2018–16–05 for the corresponding requirements of this AD. American, FedEx, and United observed that the inspections specified in Boeing Alert Requirements Bulletin 757–57A0073 RB, dated July 14, 2017, relating to fastener locations 1–10, as well as the repetitive inspections for these locations, do not change with Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019. The commenters asserted that the repairs and corresponding AMOCs should continue to be acceptable.

The FAA agrees with the requested change. The FAA has changed paragraph (j)(4) of this AD (referred to as paragraph (i)(4) in the proposed AD) to specify that AMOCs granted to AD

2018–16–05 are acceptable as AMOCs to this AD for the corresponding requirements.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously, and minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Related IBR Material Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019. This service information describes procedures for repetitive inspections, including general visual, detailed, and HFEC inspections, for loose fasteners, skin cracking, and shim migration at the upper link drag fittings and for cracking in the diagonal brace and diagonal brace fittings and applicable on-condition actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 561 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Repetitive inspections (retained actions from AD 2018–16–05).	83 work-hours × \$85 per hour = \$7,055 per inspection cycle.	\$0	\$7,055 per inspection cycle.	\$3,957,855 per inspection cycle.
Repetitive HFEC inspections (new action).	2 work-hours × \$85 per hour = \$170 per inspection cycle.	0	\$170 per inspection cycle	\$95,370 per inspection cycle.

The FAA has received no definitive data that would enable the agency to provide cost estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue

rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce.

This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA has determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2018–16–05, Amendment 39–19345 (83 FR 38250, August 6, 2018), and adding the following new AD:

2020–21–17 The Boeing Company:
Amendment 39–21290; Docket No. FAA–2019–0984; Product Identifier 2019–NM–161–AD.

(a) Effective Date

This AD is effective January 14, 2021.

(b) Affected ADs

This AD replaces AD 2018–16–05, Amendment 39–19345 (83 FR 38250, August 6, 2018) (“AD 2018–16–05”).

(c) Applicability

(1) This AD applies to all The Boeing Company Model 757–200, –200PF, –200CB, and –300 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01518SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01518SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of bolt rotation in the engine drag fitting joint and fastener heads; an inspection of the fastener holes revealed that cracks were found in the skin. This AD was also prompted by a report of multiple cracks found in the drag fitting at fastener holes during inspections required by AD 2018–16–05. The FAA is issuing this AD to address cracking in the wing upper skin and forward drag fittings, which could lead to a compromised upper link and reduced structural integrity of the engine strut.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757–57A0073, Revision 1, dated August 1, 2019, which is referred to in Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019.

(h) Exceptions to Service Information Specifications

(1) Where Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, uses the phrase “the Revision 1 date of Requirements Bulletin 757–57A0073 RB,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, specifies contacting Boeing for repair instructions: This AD requires doing the repair and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(3) Where Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, uses the phrase “the effective date of AD 2018–16–05,” this AD requires using “September 10, 2018 (the effective date of AD 2018–16–05).”

(i) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, except for the open-hole high frequency eddy current inspections at fastener locations 11–18, if those actions were performed before the effective date of this AD using Boeing Alert Requirements Bulletin 757–57A0073 RB, dated July 14, 2017.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2018–16–05 are approved as AMOCs for the corresponding provisions of Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019, that are required by paragraph (g) of this AD.

(k) Related Information

(1) For more information about this AD, contact Chandra Ramdoss, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5239; fax: 562–627–5210; email: chandraduth.ramdoss@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757–57A0073 RB, Revision 1, dated August 1, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial

Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 7, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-27007 Filed 12-9-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2020-0667; Airspace Docket No. 20-AGL-24]

RIN 2120-AA66

Amendment of Multiple Air Traffic Service (ATS) Routes in the Northcentral United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends VHF Omnidirectional Range (VOR) Federal airways V-15, V-26, V-55, V-78, V-100, V-159, V-175, V-219, and V-307, and Area Navigation (RNAV) routes T-285 and T-354 in the Northcentral United States. The modifications are necessary due to the planned decommissioning of the VOR portion of the Park Rapids, MN, VOR/Distance Measuring Equipment (VOR/DME); Sioux City, IA, VOR/Tactical Air Navigation (VORTAC); and Huron, SD, VORTAC navigation aids (NAVAIDs). The NAVAIDs provide navigation guidance for segments of the affected air traffic service (ATS) routes. The VORs are being decommissioned as part of the FAA's VOR Minimum Operational Network (MON) program.

DATES: Effective date 0901 UTC, February 25, 2021. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of

FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email: fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT: Colby Abbott, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the route structure as necessary to preserve the safe and efficient flow of air traffic within the National Airspace System.

History

The FAA published a notice of proposed rulemaking (NPRM) for Docket No. FAA-2020-0667 in the **Federal Register** (85 FR 47317; August 5, 2020), amending VOR Federal airways V-15, V-26, V-55, V-78, V-100, V-159, V-175, V-219, and V-307, and RNAV routes T-285 and T-354 in the Northcentral United States. The proposed amendment actions were due to the planned decommissioning of the VOR portion of the Park Rapids, MN, VOR/DME; Sioux City, IA, VORTAC; and Huron, SD, VORTAC NAVAIDs. Interested parties were invited to participate in this rulemaking effort by

submitting written comments on the proposal. No comments were received.

Subsequent to the NPRM, the FAA published a rule for Docket No. FAA-2020-0189 in the **Federal Register** (85 FR 50777; August 18, 2020), amending VOR Federal airway V-55 by removing the airway segment between the Pullman, MI, VOR/DME and the intersection of the Green Bay, WI, VORTAC 270° and Oshkosh, WI, VORTAC 339° radials (BIPID fix). That airway amendment, effective November 5, 2020, is included in this rule.

Additionally, subsequent to the NPRM, the FAA published a rule for Docket No. FAA-2020-0294 in the **Federal Register** (85 FR 51324; August 20, 2020), amending RNAV route T-354 by replacing the Sirene DME route point with the SSKYY, WI, waypoint and extending the route southeastward from the SSKYY, WI, waypoint to the Cunningham, KY, VOR/DME. Those route amendments, effective November 5, 2020, are also included in this rule.

VOR Federal airways are published in paragraph 6010(a) and RNAV T-routes are published in paragraph 6011 of FAA Order 7400.11E dated July 21, 2020, and effective September 15, 2020, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airways listed in this document will be subsequently published in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020, and effective September 15, 2020. FAA Order 7400.11E is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11E lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

The FAA is amending Title 14 Code of Federal Regulations (14 CFR) part 71 by modifying VOR Federal airways V-15, V-26, V-55, V-78, V-100, V-159, V-175, V-219, and V-307, and RNAV routes T-285 and T-354. The planned decommissioning of the VOR portion of the Park Rapids, MN, VOR/DME; Sioux City, IA, VORTAC; and Huron, SD, VORTAC NAVAIDs has made this action necessary. The VOR Federal airway changes are outlined below.

V-15: V-15 extends between the Navasota, TX, VOR/DME and the Bonham, TX, VORTAC; between the Okmulgee, OK, VOR/DME and the Neosho, MO, VOR/DME; and between the Sioux City, IA, VORTAC and the