

Structural Inspection Document D6-48040-1, Volume II, Temporary Revision 11-1001, dated February 2020.

(2) At the applicable time specified in paragraph (g)(2)(i) or (ii) of this AD, perform initial inspections to detect cracks in the SSIs identified in Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume I, Temporary Revision 08-1001, dated February 2020; and Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume II, Temporary Revision 11-1001, dated February 2020.

(i) For Model 727-100C and 727-200F series airplanes: Inspect prior to the accumulation of 46,000 total flight cycles, or within 12 months after the effective date of this AD, whichever occurs later.

(ii) For all airplanes except for those airplanes identified in paragraph (g)(2)(i) of this AD: Inspect prior to the accumulation of 55,000 total flight cycles, or within 3,000 flight cycles measured from the date 12 months after the effective date of this AD, whichever occurs later.

(3) At the intervals specified in Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume I, Temporary Revision 08-1001, dated February 2020; and Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume II, Temporary Revision 11-1001, dated February 2020, as applicable, repeat the inspections required by paragraph (g)(2) of this AD.

(4) If any cracked structure is found during any inspections required by paragraph (g) of this AD, repair before further flight using an FAA-approved method or using a method approved in accordance with the procedures specified in paragraph (j) of this AD. Within 12 months after repair, incorporate a revision into the maintenance or inspection program, as applicable, to include a damage-tolerance-based alternative inspection program for the repaired structure. Thereafter, inspect the affected structure in accordance with the alternative program. The inspection method and compliance times (*i.e.*, threshold and repetitive intervals) of the alternative program must be approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g)(1) of this AD, no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j) of this AD.

(i) Terminating Action for Certain Inspections Required by AD 98-11-03 R1

Accomplishing the revision required by paragraph (g)(1) of this AD and the initial inspections identified in Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume I, Temporary Revision 08-1001, dated February 2020; and Boeing 727 Supplemental Structural Inspection Document D6-48040-1,

Volume II, Temporary Revision 11-1001, dated February 2020, as required by paragraph (g)(2) of this AD, terminate the corresponding SSI inspections specified in Boeing Document No. D6-48040-1, Volumes 1 and 2, "Supplemental Structural Inspection Document" (SSID), Revision H, dated June 1994, as required by AD 98-11-03 R1.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 98-11-03 R1 are approved as AMOCs for the corresponding provisions of this AD for the SSIs identified in Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume I, Temporary Revision 08-1001, dated February 2020; and Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume II, Temporary Revision 11-1001, dated February 2020.

(k) Related Information

For more information about this AD, contact Mohit Garg, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5264; fax: 562-627-5210; email: mohit.garg@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume I, Temporary Revision 08-1001, dated February 2020.

(ii) Boeing 727 Supplemental Structural Inspection Document D6-48040-1, Volume

II, Temporary Revision 11-1001, dated February 2020.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 28, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-03598 Filed 2-23-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0859; Product Identifier 2020-NM-084-AD; Amendment 39-21413; AD 2021-03-10]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This AD was prompted by reports of failure of a certain fire detection and extinguishing (FIREX) control unit. This AD requires replacing FIREX control units having a certain part number. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 31, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 31, 2021.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., 200 Côte Vertu Road

West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; email ac.yul@aero.bombardier.com; internet <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0859.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0859; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7362; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued TCCA AD CF-2020-12, dated April 17, 2020 (TCCA AD CF-2020-12) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Bombardier, Inc., Model BD-100-1A10 airplanes.

You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0859.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model BD-100-1A10 airplanes. The NPRM published in the **Federal Register** on October 1, 2020 (85 FR 61881). The NPRM was prompted by reports of failure of a certain FIREX control unit. The NPRM proposed to require replacing FIREX control units having a certain part number. The FAA is issuing this AD to address the failure of a FIREX control unit, which could result in the loss of the ability to detect a fire. See the MCAI for additional background information.

Comment

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the NPRM and the FAA’s response to that comment.

Request To Allow Records Review

NetJets requested that paragraph (i) of the proposed AD be revised to allow operators to review airplane maintenance records to determine the part number of the FIREX control unit installed on an airplane. The commenter stated that for the airplane having serial number (S/N) 20662 the logbook delivery document specifies that the -3 FIREX control unit is installed. The commenter explained that there is not a signoff sheet for Bombardier Service Bulletin 350-26-001, but that the serialized parts list clearly indicates that the -3 FIREX control unit is installed.

The FAA disagrees with the commenter’s request because this AD does not mandate the method an operator must use to determine what FIREX control unit part number is installed on an airplane. As specified in paragraph (c) of this AD, this AD is only

applicable to Bombardier, Inc., Model BD-100-1A10 airplanes fitted with FIREX control unit part number (P/N) 474112-2. If an operator is able to confirm that FIREX control unit P/N 474112-3 is installed on an airplane the requirements of this AD are not applicable to that airplane. This AD requires operators to remove FIREX P/N 474112-2 and install P/N 474112-3. The FAA has not changed this AD in regard to this issue.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin 100-26-01, Revision 01, dated December 5, 2019; and Service Bulletin 350-26-001, Revision 01, dated December 5, 2019. This service information describes procedures for replacing FIREX control units having P/N 474112-2 with units having P/N 474112-3. These documents are distinct since they apply to different airplane configurations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 223 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$6,389	\$6,474	\$1,443,702

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators.

As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–03–10 Bombardier, Inc.: Amendment 39–21413; Docket No. FAA–2020–0859; Product Identifier 2020–NM–084–AD.

(a) Effective Date

This airworthiness directive (AD) is effective March 31, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–100–1A10 airplanes, certificated in any category, serial numbers 20003 through 20500 inclusive, and 20501 through 20669 inclusive, fitted with fire detection and extinguishing (FIREX) control unit part number (P/N) 474112–2.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire protection.

(e) Reason

This AD was prompted by reports of failure of a certain FIREX control unit. The FAA is issuing this AD to address failure of a FIREX control unit, which could result in the loss of the ability to detect a fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 24 months after the effective date of this AD: Replace any FIREX control unit having P/N 474112–2 with a unit having P/N 474112–3, in accordance with paragraphs 2.B.(1) and (3) of the Accomplishment Instructions of the applicable Bombardier service bulletin specified in paragraphs (g)(1) and (2) of this AD.

(1) For airplanes having serial numbers 20003 through 20500 inclusive: Bombardier Service Bulletin 100–26–01, Revision 01, dated December 5, 2019.

(2) For airplanes having serial numbers 20501 through 20669 inclusive: Bombardier Service Bulletin 350–26–001, Revision 01, dated December 5, 2019.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install a FIREX control unit having P/N 474112–2 on any airplane.

(i) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 100–26–01, dated December 20, 2016; or Bombardier Service Bulletin 350–26–001, dated December 20, 2016, as applicable.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your

appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF–2020–12, dated May 1, 2020, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0859.

(2) For more information about this AD, contact Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7362; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 100–26–01, Revision 01, dated December 5, 2019.

(ii) Bombardier Service Bulletin 350–26–001, Revision 01, dated December 5, 2019.

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1–866–538–1247 or direct-dial telephone 1–514–855–2999; email ac.yul@aero.bombardier.com; internet <https://www.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

(6) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 28, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-03600 Filed 2-23-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0977; Project Identifier MCAI-2020-01106-T; Amendment 39-21415; AD 2021-03-12]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2019-03-27, which applied to all Dassault Aviation Model Falcon 10 airplanes. AD 2019-03-27 required repetitive detailed inspections of certain wing anti-ice outboard flexible hoses, and replacement of certain wing anti-ice outboard flexible hoses. This AD continues to require the actions in AD 2019-03-27, and also adds a new life limit for the improved wing anti-ice flexible hose; as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD was prompted by a report indicating that certain wing anti-ice outboard flexible hoses were found damaged, likely resulting from the installation process, and the development of an improved wing anti-ice flexible hose. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 31, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 31, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; internet:

www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0977.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0977; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3226; email: tom.rodriguez@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0127, dated June 4, 2020 (EASA AD 2020-0127) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Dassault Aviation Model Falcon 10 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2019-03-27, Amendment 39-19579 (84 FR 7801, March 5, 2019) (AD 2019-03-27). AD 2019-03-27 applied to all Dassault Aviation Model Falcon 10 airplanes. The NPRM published in the **Federal Register** on November 2, 2020 (85 FR 69269). The NPRM was prompted by a report indicating that certain wing anti-ice outboard flexible hoses were found damaged, likely resulting from the installation process, and the development of an improved wing anti-ice flexible hose. The NPRM proposed to continue to require the actions in AD 2019-03-27, as specified in an EASA

AD. The NPRM also proposed to require adding a new life limit for the improved wing anti-ice flexible hose, as specified in EASA AD 2020-0127.

The FAA is issuing this AD to address damaged wing anti-ice outboard flexible hoses, which could lead to a loss of performance of the wing anti-ice protection system that is not annunciated to the pilot, and could result in reduced control of the airplane. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

EASA AD 2020-0127 describes procedures for repetitive detailed inspections of certain wing anti-ice outboard flexible hoses, replacement of certain wing anti-ice outboard flexible hoses, a new life limit for certain wing anti-ice outboard flexible hoses, and optional terminating actions for the repetitive inspections (replacement of all damaged affected wing anti-ice outboard flexible hoses or accomplishing and passing an inspection on an affected wing anti-ice outboard flexible hose after it has accumulated 100 flight cycles since installation on an airplane). This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 54 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD: