

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2020-1074; Project Identifier MCAI-2020-01257-A]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Pilatus Aircraft Ltd. (Pilatus) Model PC-24 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as the engine attachment hardware not conforming to the approved design, which could affect the structural integrity of the airplane. This proposed AD would require inspecting the engine attachment hardware for missing washers and loose nuts and taking corrective actions as necessary. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 10, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Pilatus Aircraft Ltd., CH-6371, Stans, Switzerland; phone: +41 848 24 7 365; email: techsupport.ch@pilatus-aircraft.com; website: <https://www.pilatus-aircraft.com/>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the

availability of this material at the FAA, call (816) 329-4148. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1074.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1074; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2020-1074; Project Identifier MCAI-2020-01257-A" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted

comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Doug Rudolph, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0194, dated September 8, 2020 (referred to after this as "the MCAI"), to address an unsafe condition on certain serial-numbered Pilatus Model PC-24 airplanes. The MCAI states:

During a scheduled maintenance inspection, the engine attachment hardware of a PC-24 airplane was found not to conform to the approved design. A washer was missing beneath each of the four mating bolt heads on the rear engine beam. In addition, some of the keeper fitting attachment bolts on the LH/RH middle inner nacelle were found with loose nuts. It was also determined that other aeroplanes may have the same non-conformities.

This condition, if not detected and corrected, could damage the engine attachment hardware, possibly affecting the structural integrity of the aeroplane.

To address this potential unsafe condition, Pilatus issued the [service bulletin] SB, providing instructions for inspection and corrective action.

For the reason described above, this [EASA] AD requires a one-time inspection for missing washers and loose nuts on the engine attachment hardware and, depending on findings, the accomplishment of applicable corrective action(s).

You may obtain further information by examining the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1074.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Pilatus PC-24 Service Bulletin No. 71-001, dated June 30, 2020. This service information specifies procedures for inspecting the engine attachment hardware for loose nuts and missing washers and taking corrective actions depending on findings. This service information is reasonably available because the interested parties have access to it through their normal course of business

or by the means identified in

ADDRESSES.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 34 airplanes of U.S. registry.

The FAA estimates that it would take 2.5 work-hours to do the one-time inspections. The average labor rate is \$85 per work-hour.

Based on these figures, the FAA estimates the cost of the proposed AD on U.S. operators would be \$7,225 or \$212.50 per airplane.

The FAA also estimates that, as on-condition costs, installing missing washers, replacing bolts, and doing an eddy current inspection of the bolt holes would take 4.5 work-hours and require parts costing \$200 for a cost of \$582.50 per airplane. This estimate assumes replacing all of the rear engine beam attachment bolts and washers and doing an eddy current inspection of all the attachment bolt holes. If the bolt holes are found damaged during the eddy current inspection, the damage will vary considerably from airplane to airplane, and the FAA has no way of estimating a repair cost. In addition, the FAA has no way of determining the number of aircraft that might need these actions.

The FAA has included all known costs in this cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under

that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Pilatus Aircraft Ltd.: Docket No. FAA-2020-1074; Project Identifier MCAI-2020-01257-A.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 10, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Model PC-24 airplanes, serial numbers (S/Ns) 101 through 162, S/N 164, S/N 165, S/N 167, and S/N 168, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 7120, Engine Mount Section.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as engine attachment hardware not conforming to the approved design. The FAA is issuing this AD to detect and address incorrectly installed attachment hardware in the engine and nacelle area. The unsafe condition, if not addressed, could result in damage to the engine attachment hardware, which may affect the structural integrity of the airplane.

(f) Actions and Compliance

Unless already done, do the actions in paragraphs (f)(1) and (2) of this AD at the next annual inspection after the effective date of this AD or within 11 months after the effective date of this AD, whichever occurs later.

(1) Inspect the left hand (LH) and right hand (RH) middle inner nacelles for loose nuts and correctly install any loose nut before further flight by following section 3.B(1) of the Accomplishment Instructions in Pilatus PC-24 Service Bulletin No. 71-001, dated June 30, 2020 (Pilatus SB 71-001).

(2) Inspect the LH and RH front and rear engine beams for missing washers by following section 3.B(2)(a) through (b) of the Accomplishment Instructions in Pilatus SB 71-001. If there are any missing washers, before further flight, do an eddy current inspection of the bolt holes for damage by following section 3.C of the Accomplishment Instructions in Pilatus SB 71-001. Where Pilatus SB 71-001 specifies obtaining repair instructions from Pilatus, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Pilatus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in Related Information.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(h) Related Information

(1) For more information about this AD, contact Doug Rudolph, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

(2) Refer to MCAI EASA AD 2020-0194, dated September 8, 2020, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2020-1074.

(3) For service information identified in this AD, contact Pilatus Aircraft Ltd., CH-6371, Stans, Switzerland; phone: +41 848 24 7 365; email: techsupport.ch@pilatus-aircraft.com; website: <http://www.pilatus-aircraft.com/>. You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued on March 17, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-05944 Filed 3-25-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2021-0189; Project Identifier AD-2020-00645-R]

RIN 2120-AA64

Airworthiness Directives; Various Restricted Category Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for type certificated Model UH-1H restricted category helicopters. This proposed AD was prompted by multiple reports of failure of the main driveshaft. This proposed AD would require establishing a life limit for certain main driveshafts, and a one-time and repetitive inspections of the main driveshafts. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 10, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Army Publishing Directorate, 9301 Chapek Rd., Bldg 1458, Fort Belvoir, VA 22060-5447; telephone (703) 614-3727; email usarmy.pentagon.hqda-apd.mbx.customer-service@mail.mil; or at <https://armypubs.army.mil/>.

You may also contact the following as applicable:

Arrow Falcon Exporters Inc., 2081 S Wildcat Way, Porterville, CA 93257; telephone (559) 781-8604; fax (559) 781-9271; email afe@arrowfalcon.com.

Global Helicopter Technology, Inc., P.O. Box 180681, Arlington, Texas 76096; telephone (817) 557-3391; email ghti@ghti.net.

Hagglund Helicopters, LLC, 5101 NW A Avenue, Pendleton, OR 97801; telephone (800) 882-3554 or (541) 276-3554; fax (541) 276-1597.

JASPP Engineering Services, LLC., 511 Harmon Terrace, Arlington, TX 76010; telephone (817) 465-4495; or at www.jaspp.com.

Northwest Rotorcraft, LLC, 1000 85th Ave. SE, Olympia, WA 98501; telephone (360) 754-7200; or at www.nwhelicopters.com.

Overseas Aircraft Support, Inc., P.O. Box 898, Lakeside, AZ 85929; telephone (928) 368-6965; fax (928) 368-6962.

Richards Heavylift Helo, Inc., 1181 Osprey Nest Point, Orange Park, FL 32073; (904) 472-1481; email Glenn7444@msn.com.

Rotorcraft Development Corporation, P.O. Box 430, Corvallis, MT 59828; telephone (207) 329-2518; email administration@rotorcraftdevelopment.com.

Southwest Florida Aviation International, Inc., 28000-A9 Airport Road, Bldg. 101, Punta Gorda, FL 33982-9587; telephone (941) 637-1161; fax (941) 637-6264; email info@swfateam.org.

Tamarack Helicopters, Inc., 2849 McIntyre Rd., Stevensville, MT 59870; telephone (406) 777-0144; or at www.tamarackhelicopters.com.

You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321,

Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0189; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Matthew L. Thompson, Aerospace Engineer, DSCO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5251; email matthew.l.thompson@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0189; Project Identifier AD-2020-00645-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential