

the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive (AD) 97–26–02, Amendment 39–10245 (62 FR 65749, December 16, 1997); and
 - b. Adding the following new AD:

2021–07–08 Airbus Helicopters Deutschland GmbH (Type Certificate Previously Held by Eurocopter Deutschland GmbH and Eurocopter Canada Ltd.): Amendment 39–21485; Docket No. FAA–2020–0696; Product Identifier 2018–SW–019–AD.

(a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Deutschland GmbH Model BO–105A, BO–105C, BO–105S, BO–105LS A–1, and BO–105LS A–3 helicopters, certificated in any category, with a main rotor (M/R) mast part number (P/N) 4619 305 032 of M/R mast assembly P/N 4638 205 005, or M/R mast P/N 4639 305 002 of M/R mast assembly P/N 4639 205 017.

Note 1 to Paragraph (a): M/R mast assembly P/N 4639 205 017 may also contain reinforced M/R mast P/N 4639 305 095, which is not affected by this AD.

(b) Unsafe Condition

This AD defines the unsafe condition as cracks in the M/R mast flange (flange). This condition could result in failure of the flange and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD replaces AD 97–26–02, Amendment 39–10245 (62 FR 65749, December 16, 1997).

(d) Effective Date

This AD becomes effective April 30, 2021.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) Before further flight and thereafter at intervals not to exceed 100 hours time-in-service, visually inspect the flange in the ribbed area for cracks using a 5-power or higher magnifying glass in accordance with paragraphs 2.A.1. and 2.A.2. of the Accomplishment Instructions in Eurocopter Deutschland GmbH Alert Service Bulletin No. ASB–BO 105–10–110, dated August 27, 1997.

(2) If there is a crack, remove from service the cracked M/R mast and replace it with an airworthy M/R mast.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (h)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Related Information

(1) For more information about this AD, contact Matt Fuller, AD Program Manager, Operational Safety Branch, Airworthiness Products Section, General Aviation & Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email matthew.fuller@faa.gov.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2018–0056, dated March 14, 2018; and Transport Canada AD CF–1997–18R1, dated March 12, 2018. You may view the EASA and Transport Canada ADs on the internet at <https://www.regulations.gov> in Docket No. FAA–2020–0696.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6230, Main Rotor Mast/Swashplate

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on December 31, 1997 (62 FR 65749, December 16, 1997).

(i) Eurocopter Deutschland GmbH Alert Service Bulletin No. ASB–BO 105–10–110, dated August 27, 1997.

(ii) [Reserved]

(4) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(5) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 20, 2021.

Gaetano A. Scirtorno,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–06205 Filed 3–25–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–1136; Project Identifier MCAI–2020–01301–R; Amendment 39–21468; AD 2021–06–02]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model AS332L, AS332L1, AS332C, and AS332C1 helicopters. This AD was prompted by the failure of a second stage planet gear installed in the main gearbox (MGB). This AD requires identifying the part number of each second stage planet gear

assembly installed in the MGB, replacing an MGB having certain second stage planet gear assembly part numbers with a serviceable MGB, modifying the helicopter by installing a full flow magnetic plug (FFMP), repetitively inspecting the FFMP and the MGB bottom housing and conical housing for metal particles, analyzing any metal particles that are found, and applying corrective actions if necessary, as specified in European Union Aviation Safety Agency (EASA) ADs, which are incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 30, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 30, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1136.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1136; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Mahmood Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817 222 5538; email mahmood.g.shah@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0022R2, dated December 23, 2020 (EASA AD 2020-0022R2) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus Helicopters Model AS332L, AS332L1, AS332C, and AS332C1 helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Helicopters Model AS332L, AS332L1, AS332C, and AS332C1 helicopters. The NPRM published in the **Federal Register** on December 21, 2020 (85 FR 82977). The NPRM was prompted by the failure of a second stage planet gear installed in the MGB of an Airbus Helicopters Model EC225LP helicopter. Airbus Helicopters Model AS332L, AS332L1, AS332C, and AS332C1 helicopters have a similar design to the affected Model EC225LP helicopter, therefore, these models may be subject to the unsafe condition revealed on the Model EC225LP helicopter. The NPRM proposed to require identifying the part number of each second stage planet gear assembly installed in the MGB, replacing an MGB having certain second stage planet gear assembly part numbers with a serviceable MGB, modifying the helicopter by installing an FFMP, repetitively inspecting the FFMP and the MGB bottom housing and conical housing for metal particles, analyzing any metal particles that are found, and applying corrective actions if necessary as specified in an EASA AD.

The FAA is issuing this AD to address failure of a second stage planet gear installed in the MGB, which could result in failure of the MGB and subsequent loss of control of the helicopter. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

New EASA AD

In the NPRM, the FAA referred to EASA AD 2020-0022R1, dated September 18, 2020 (EASA AD 2020-

0022R1). Since the NPRM was issued, EASA issued EASA AD 2020-0022R2, which extends the compliance time for installation of the FFMP.

The FAA determined that no additional work is required for helicopters that have accomplished the actions as required by EASA AD 2020-0022R1. Therefore, the FAA has revised all applicable sections in this final rule to also specify EASA AD 2020-0022R2.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

The FAA also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 1 CFR Part 51

EASA ADs 2020-0022R1 and 2020-0022R2 describe procedures for identifying the part number of each second stage planet gear assembly installed in the MGB, replacing an MGB having certain second stage planet gear assembly part numbers with a serviceable MGB, modifying the helicopter by installing an FFMP, repetitively inspecting the FFMP and the MGB bottom housing and conical housing for metal particles, analyzing any metal particles that are found, and applicable corrective actions. The corrective actions include replacing an affected MGB with a serviceable MGB. These documents are distinct since EASA AD 2020-0022R2 extends the compliance time for installation of the FFMP.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 11 helicopters of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
8.50 work-hours × \$85 per hour = \$722.50	\$17,625	\$18,347.50	\$201,822.50

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of helicopters that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
40.50 work-hour × \$85 per hour = \$3,442.50	\$275,000 (overhauled part)	\$278,442.50

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866,

- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-06-02 Airbus Helicopters:

Amendment 39-21468; Docket No. FAA-2020-1136; Project Identifier MCAI-2020-01301-R.

(a) Effective Date

This airworthiness directive (AD) is effective April 30, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model AS332L, AS332L1, AS332C, and AS332C1 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 6320, Main Rotor Gear Box.

(e) Reason

This AD was prompted by the failure of a second stage planet gear installed in the main gearbox (MGB). The FAA is issuing this AD to address failure of an MGB second stage planet gear, which could result in failure of the MGB and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020-0022R1, dated September 18, 2020 (EASA AD 2020-0022R1); or EASA AD 2020-0022R2, dated December 23, 2020 (EASA AD 2020-0022R2).

(h) Exceptions to EASA ADs 2020-0022R1 and 2020-0022R2

(1) Where EASA ADs 2020-0022R1 and 2020-0022R2 refer to March 30, 2018 (the effective date of EASA AD 2018-0066, dated March 23, 2018) or February 21, 2020 (the effective date of EASA AD 2020-0022, dated February 7, 2020), this AD requires using the effective date of this AD.

(2) The “Remarks” sections of EASA ADs 2020-0022R1 and 2020-0022R2 do not apply to this AD.

(3) Where EASA ADs 2020-0022R1 and 2020-0022R2 refer to flight hours (FH), this AD requires using hours time-in-service.

(4) Where the service information referred to in paragraphs (5) and (6) of EASA ADs 2020-0022R1 and 2020-0022R2 specifies to perform a metallurgical analysis and contact the manufacturer if unsure about the characterization of the particles collected, this AD does not require contacting the manufacturer to determine the characterization of the particles collected.

(5) Although the service information referred to in paragraph (6) of EASA ADs 2020-0022R1 and 2020-0022R2 specifies that if any 16NCD13 particles are found send a 1-liter sample of oil to the manufacturer, this AD does not require that action.

(6) Although the service information referenced in EASA ADs 2020–0022R1 and 2020–0022R2 specifies to discard certain parts, this AD does not include that requirement.

(7) Although the service information referenced in EASA ADs 2020–0022R1 and 2020–0022R2 specifies returning certain parts to the manufacturer, this AD does not require that action.

(8) Although the service information referenced in EASA ADs 2020–0022R1 and 2020–0022R2 specifies to contact the manufacturer if certain specified criteria are exceeded, this AD does not include that requirement.

(9) Although the service information referenced in EASA ADs 2020–0022R1 and 2020–0022R2 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(10) Although the service information referenced in EASA ADs 2020–0022R1 and 2020–0022R2 specifies to watch a video for removing the grease from the full flow magnetic plug (FFMP), using a cleaning agent, and collecting particles, this AD does not include that requirement.

(11) Where EASA ADs 2020–0022R1 and 2020–0022R2 require actions after the last flight of the day or “ALF,” this AD requires those actions before the first flight of the day.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be modified (if the operator elects to do so), provided no passengers are onboard.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Mahmood Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817 222 5538; email mahmood.g.shah@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0022R1, dated September 18, 2020.

(ii) European Union Aviation Safety Agency (EASA) AD 2020–0022R2, dated December 23, 2020.

(3) For EASA AD 2020–0022R1 and EASA AD 2020–0022R2, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

Note 1 to paragraph (i)(3): EASA AD 2020–0022R1 can be accessed in the zipped file at the bottom of the web page for EASA AD 2020–0022R2. When EASA posts a revised AD on their website, they watermark the previous AD as “Revised,” alter the file name by adding “_revised” to the end, and move it into a zipped file attached at the bottom of the AD web page.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1136.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 8, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–06239 Filed 3–25–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 95

[Docket No. 31363; Amdt. No. 558]

IFR Altitudes; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts miscellaneous amendments to the required IFR (instrument flight rules) altitudes and changeover points for certain Federal airways, jet routes, or direct routes for which a minimum or maximum en route authorized IFR

altitude is prescribed. This regulatory action is needed because of changes occurring in the National Airspace System. These changes are designed to provide for the safe and efficient use of the navigable airspace under instrument conditions in the affected areas.

DATES: Effective 0901 UTC, April 22, 2021.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg 29 Room 104, Oklahoma City, OK 73125. Telephone: (405) 954–4164.

SUPPLEMENTARY INFORMATION: This amendment to part 95 of the Federal Aviation Regulations (14 CFR part 95) amends, suspends, or revokes IFR altitudes governing the operation of all aircraft in flight over a specified route or any portion of that route, as well as the changeover points (COPs) for Federal airways, jet routes, or direct routes as prescribed in part 95.

The Rule

The specified IFR altitudes, when used in conjunction with the prescribed changeover points for those routes, ensure navigation aid coverage that is adequate for safe flight operations and free of frequency interference. The reasons and circumstances that create the need for this amendment involve matters of flight safety and operational efficiency in the National Airspace System, are related to published aeronautical charts that are essential to the user, and provide for the safe and efficient use of the navigable airspace. In addition, those various reasons or circumstances require making this amendment effective before the next scheduled charting and publication date of the flight information to assure its timely availability to the user. The effective date of this amendment reflects those considerations. In view of the close and immediate relationship between these regulatory changes and safety in air commerce, I find that notice and public procedure before adopting this amendment are impracticable and contrary to the public interest and that good cause exists for making the amendment effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established