

[fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 24, 2021.

**Lance T. Gant,**

Director, Compliance & Airworthiness  
Division, Aircraft Certification Service.

[FR Doc. 2021-06980 Filed 4-5-21; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-1034; Project Identifier MCAI-2020-00951-T; Amendment 39-21483; AD 2021-07-06]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. This AD was prompted by a determination that certain airplanes have outdated magnetic variation (MagVar) tables inside navigation systems. This AD requires revising the existing airplane flight manual (AFM) to update the Flight Management System (FMS) and Inertial Reference System (IRS) limitations. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 11, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of May 11, 2021.

**ADDRESSES:** For service information identified in this final rule, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone: 1-866-538-1247 or direct-dial telephone: 1-514-855-2999; email: [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet: <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1034.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1034; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7367; fax: 516-794-5531; email: [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued TCCA AD CF-2020-24, dated July 10, 2020 (also referred to after this as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1034.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. The NPRM published in the **Federal Register** on November 27, 2020 (85 FR 75966). The NPRM was prompted by a determination that certain airplanes have outdated MagVar tables inside navigation systems. The NPRM proposed to require revising the existing AFM to update the FMS and IRS limitations. The FAA is issuing this AD to address outdated MagVar tables inside navigation systems, which can affect the performance of the navigation systems and result in the presentation of misleading magnetic heading references on the Primary Flight Displays (PFDs) and Multi-Function Displays (MFDs), positioning the airplane outside of the terrain and obstacle protection provided by instrument flight procedures and

flight route designs (e.g., outdated MagVar tables can lead to significantly inaccurate heading, course, and bearing calculations). See the MCAI for additional background information.

#### Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the NPRM and the FAA's response.

#### Request To Update Calibration of the Navigational Aids

Bombardier asked that the FAA update calibration of the required navigational aids at key ground stations, which would then fully address this potential unsafe condition. Bombardier stated that adherence to the proposed AD only addresses the outdated magnetic variation tables of affected airplane navigation systems; however, it does not guarantee a complete mitigation of the unsafe condition due to the larger issue of outdated calibration of the required navigational aids.

We acknowledge the commenter's concern. However, ADs are legally enforceable rules that only address unsafe conditions on products, such as airplanes, and cannot apply to navigational aids at ground stations. This concern may be addressed by contacting the Navigation Program Manager at the FAA Air Traffic Organization, internet: [https://www.faa.gov/about/office\\_org/headquarters\\_offices/ato/service\\_units/techops/navservices/contact/](https://www.faa.gov/about/office_org/headquarters_offices/ato/service_units/techops/navservices/contact/). We have not changed this AD in this regard.

#### Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

#### Related Service Information Under 14 CFR Part 51

Bombardier has issued the following service information, which provides procedures for updating, among other systems, the FMS and IRS of the applicable AFM. These documents are distinct since they apply to different airplane configurations.

- Section 02–09, Navigation Systems Limitations, of Chapter 2—LIMITATIONS, of the Bombardier Challenger CL–604 AFM, PSP 604–1, Revision 116, dated December 18, 2019.
- Section 02–09, Navigation Systems Limitations, of Chapter 2—LIMITATIONS, Bombardier Challenger

CL–605 AFM, PSP 605–1, Revision 54, dated December 18, 2019.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

The FAA estimates that this AD affects 39 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

| Labor cost                               | Parts cost | Cost per product | Cost on U.S. operators |
|--|------------|------------------|------------------------|
| 1 work-hour × \$85 per hour = \$85 ..... | \$0        | \$85             | \$3,315                |

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,

- (2) Will not affect intrastate aviation in Alaska, and

- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2021–07–06 Bombardier, Inc.:** Amendment 39–21483; Docket No. FAA–2020–1034; Project Identifier MCAI–2020–00951–T.

**(a) Effective Date**

This airworthiness directive (AD) is effective May 11, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc., Model CL–600–2B16 (601–3A, 601–3R, and 604 Variants), serial numbers 5301 through 5665 inclusive, and 5701 through 5988 inclusive, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 34, Navigation.

**(e) Reason**

This AD was prompted by a determination that certain airplanes have outdated magnetic variation (MagVar) tables inside navigation systems. The FAA is issuing this AD to address outdated MagVar tables inside navigation systems, which can affect the performance of the navigation systems and result in the presentation of misleading magnetic heading references on the Primary Flight Displays (PFDs) and Multi-Function Displays (MFDs), positioning the airplane outside of the terrain and obstacle protection provided by instrument flight procedures and flight route designs (e.g., outdated MagVar tables can lead to significantly inaccurate heading, course, and bearing calculations).

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Airplane Flight Manual (AFM) Revision**

Within 60 days after the effective date of this AD: Revise the existing AFM to incorporate the information specified in Section 02–09, Navigation Systems Limitations, of Chapter 2—LIMITATIONS, of the applicable Bombardier Challenger AFM specified in figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) – AFM Revisions

| Bombardier Airplane Model/Serial Number                     | AFM Title                                      | AFM Revision                             |
|---|--|--|
| CL-600-2B16<br>(Variant 604) 5301<br>through 5665 inclusive | Bombardier Challenger CL-604<br>AFM, PSP 604-1 | Revision 116, dated<br>December 18, 2019 |
| CL-600-2B16<br>(Variant 604) 5701<br>through 5988 inclusive | Bombardier Challenger CL-605<br>AFM, PSP 605-1 | Revision 54, dated<br>December 18, 2019  |

**(h) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(i) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF-2020-24, dated July 10, 2020, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1034.

(2) For more information about this AD, contact Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7367; fax: 516-794-5531; email: [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 02-09, Navigation Systems Limitations, of Chapter 2—LIMITATIONS, of the Bombardier Challenger CL-604 Airplane Flight Manual, PSP 604-1, Revision 116, dated December 18, 2019.

(ii) Section 02-09, Navigation Systems Limitations, of Chapter 2—LIMITATIONS, Bombardier Challenger CL-605 Airplane Flight Manual, PSP 605-1, Revision 54, dated December 18, 2019.

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone: 1-866-538-1247 or direct-dial telephone: 1-514-855-2999; email: [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet: <https://www.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 19, 2021.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021-06961 Filed 4-5-21; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2020-1138; Project Identifier MCAI-2020-01258-E; Amendment 39-21488; AD 2021-07-11]

RIN 2120-AA64

**Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (Type Certificate Previously Held by Rolls-Royce plc) Turbofan Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Rolls-Royce Deutschland Ltd & Co KG (RRD) Trent 1000-A2, 1000-AE2, 1000-C2, 1000-CE2, 1000-D2, 1000-E2, 1000-G2, 1000-H2, 1000-J2, 1000-K2, and 1000-L2 model turbofan engines. This AD was prompted by the manufacturer's analysis which determined that cracks may initiate in the front seal fins and cause cracks in the low-pressure turbine (LPT) disk. This AD requires repetitive inspection of the seal fins and, depending on the results of the inspection, replacement of the LPT disk before further flight. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 11, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 11, 2021.

**ADDRESSES:** For service information identified in this final rule, contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: +44 (0)1332 242424; website: <https://www.rolls-royce.com/contact-us.aspx>. You may view this service information