

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2021–12–16 Airbus Helicopters**

**Deutschland GmbH (AHD):** Amendment 39–21603; Docket No. FAA–2021–0265; Project Identifier MCAI–2020–01541–R.

**(a) Effective Date**

This airworthiness directive (AD) is effective August 3, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Airbus Helicopters Deutschland GmbH (AHD) Model MBB–BK117 C–2 and MBB–BK117 D–2 helicopters, certificated in any category.

**(d) Subject**

Joint Aircraft System Component (JASC) Code: 6710, Main Rotor Control.

**(e) Reason**

This AD was prompted by a report of increased control force in the collective axis. The FAA is issuing this AD to prevent failure of the main rotor actuator and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0257, dated November 17, 2020 (EASA AD 2020–0257).

**(h) Exceptions to EASA AD 2020–0257**

(1) Where EASA AD 2020–0257 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Note 1 of EASA AD 2020–0257 specifies a tolerance of 3 months may be applied to the initial threshold and to the repetitive inspection interval, this AD does not allow this tolerance.

(3) Where paragraph (2) of EASA AD 2020–0257 specifies contacting Airbus Helicopters, this AD requires performing the corrective action in accordance with FAA-approved procedures.

(4) Where paragraph (3) of EASA AD 2020–0257 specifies an alternative method to comply with the requirements of paragraph (2) of EASA AD 2020–0257 by replacing an affected part, this AD requires removing an affected part from service as an alternative method.

(5) Where paragraph (1) of EASA AD 2020–0257 specifies a compliance time for the initial inspection of “before an affected part exceeds 12 months since new, or since last overhaul, or within 3 months after the effective date of this AD, whichever occurs later” and repetitive inspections at intervals not to exceed 12 months, this AD requires a compliance time for the initial inspection of before an affected part exceeds 319 total hours time-in-service (TIS), or within 319 hours TIS after the date of the last overhaul, or within 80 hours TIS after the effective date of this AD, whichever occurs later, and repetitive inspections at intervals not to exceed 319 hours TIS.

(6) Although the service information referenced in EASA AD 2020–0257 does not specify a compliance time for the reporting requirement, this AD requires the reporting action to be performed within 30 days after accomplishing each inspection and determining that there is a crack, damage, black coloration, or corrosion.

(7) The “Remarks” section of EASA AD 2020–0257 does not apply to this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(j) Related Information**

For more information about this AD, contact Katherine Venegas, Aviation Safety Engineer, Los Angeles ACO Branch, FAA, 3960 Paramount Blvd., Lakewood, California 90712; telephone (562) 627–5353; email [katherine.venegas@faa.gov](mailto:katherine.venegas@faa.gov).

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0257, dated November 17, 2020.

(ii) [Reserved]

(3) For EASA AD 2020–0257, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0265.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 4, 2021.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021–13710 Filed 6–28–21; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2021–0304; Project Identifier 2017–SW–108–AD; Amendment 39–21606; AD 2021–13–01]**

**RIN 2120–AA64**

**Airworthiness Directives; Leonardo S.p.a. (Type Certificates Previously Held by Agusta S.p.A. and AgustaWestland S.p.A.) Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for Leonardo S.p.a. (Type Certificate previously held by Agusta S.p.A.) Model AB139 and AW139 helicopters and Leonardo S.p.a. (Type Certificate previously held by AgustaWestland S.p.A.) Model AW189 helicopters. This AD was prompted by reports of missing lock wire and loose fasteners. This AD requires a one-time inspection of the main rotor (M/R) slip ring and depending on the outcome, removing the M/R slip ring from service, removing screws and washers from service,

applying torque, installing lock wire, and re-identifying the M/R slip ring. This AD also prohibits the installation of certain M/R slip rings. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective August 3, 2021.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of August 3, 2021.

**ADDRESSES:** For Leonardo Helicopters and Moog service information identified in this final rule, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C.Costa di Sarnate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. Service information that is incorporated by reference is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0304.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0304; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) ADs, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Steven Warwick, Aerospace Engineer, Certification Section, Fort Worth ACO Branch, Compliance & Airworthiness Division, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5225; email [steven.r.warwick@faa.gov](mailto:steven.r.warwick@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Leonardo S.p.a. (Type Certificate previously held by Agusta S.p.A.) Model AB139 and AW139 helicopters and Leonardo S.p.a. (Type Certificate previously held by

AgustaWestland S.p.A.) Model AW189 helicopters with an M/R slip ring part number (P/N) 4G6220V00151 with a serial number (S/N) up to and including S/N 0141, except those marked with an "L" following the S/N, installed. The NPRM published in the **Federal Register** on April 19, 2021 (86 FR 20338). In the NPRM, the FAA proposed to require, with the M/R slip ring removed, inspecting each screw and double-twist lock wire of the upper (connector) end and lower (pigtail or standpipe) end fasteners of the M/R slip ring. Depending on the outcome, the NPRM proposed to require marking the M/R slip ring; removing the M/R slip ring from service; or removing screws and washers, lock wire, and ferrule ended safety cable from service, installing new screws and washers, applying torque, installing double-twist lock wire, and marking the M/R slip ring. The NPRM also proposed to prohibit the installation of an affected M/R slip ring unless the proposed requirements have been completed. The NPRM was prompted by EASA AD 2017-0083, dated May 10, 2017 (EASA AD 2017-0083), to correct an unsafe condition for Leonardo S.p.A. (formerly Finmeccanica S.p.A, AgustaWestland S.p.A., Agusta S.p.A), AgustaWestland Philadelphia Corporation (formerly Agusta Aerospace Corporation) Model AB139 and AW139 helicopters, and EASA AD 2017-0087, dated May 12, 2017 (EASA AD 2017-0087), to correct the same unsafe condition for Leonardo S.p.A. Helicopters (formerly Finmeccanica S.p.A, AgustaWestland S.p.A.) Model AW189 helicopters, each issued by EASA, which is the Technical Agent for the Member States of the European Union. EASA advises of reports of missing lock wire and loose fasteners found during inspections of the M/R slip ring of Model AW139 helicopters. EASA also advises that the same part-numbered M/R slip ring may also be installed on Model AW189 helicopters. Model AB139 helicopters may also be affected by this unsafe condition due to having the same type design as Model AW139 helicopters. EASA ADs 2017-0083 and 2017-0087 require a one-time visual inspection of the M/R slip ring fastener installation, and depending on the outcome, replacing the M/R slip ring, replacing fasteners, applying torque, installing lock wire, and re-identifying the M/R slip ring. EASA ADs 2017-0083 and 2017-0087 also prohibit installation of an affected M/R slip ring. EASA states, this condition, if not detected and corrected, could lead to failure of the M/R slip ring bearing inner race, possibly

resulting in damage to drive system components and subsequent reduced control of the helicopter.

#### Discussion of Final Airworthiness Directive

##### Comments

The FAA received no comments on the NPRM or on the determination of the costs.

##### Conclusion

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its ADs. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

#### Related Service Information Under 1 CFR Part 51

The FAA reviewed Leonardo Helicopters Alert Service Bulletin (ASB) No. 139-472, dated May 9, 2017 (ASB 139-472), for Model AB139 and AW139 helicopters, and Leonardo Helicopters ASB No. 189-138, dated May 12, 2017 (ASB 189-138), for Model AW189 helicopters. ASB 139-472 and ASB 189-138 specify inspecting the M/R slip ring by following the procedures in Moog Service Bulletin SB 16-01, Revision 5, undated (SB 16-01), which is attached as Annex A to both ASB 139-472 and ASB 189-138. ASB 139-472 and ASB 189-138 are incorporated by reference in this AD. SB 16-01 is not incorporated by reference in this AD.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### Other Related Service Information

The FAA also reviewed SB 16-01, which specifies procedures to visually inspect the M/R slip ring upper (connector) end and lower (pigtail or standpipe) end fastener screws and double-twist lock wire.

#### Differences Between This AD and the EASA ADs

EASA ADs 2017-0083 and 2017-0087 include the compliance time of at the next M/R slip ring removal, whereas this AD does not because it could be difficult to track. This AD has a shorter compliance time for all affected M/R slip rings that have accumulated 900 or

more total hours time-in-service, whereas EASA AD 2017–0087 allows a longer compliance time for these affected M/R slip rings that are installed on Model AW189 helicopters. EASA ADs 2017–0083 and 2017–0087 specify inspecting for the proper lock wire installed, while this AD specifies inspecting for correct installation of lock wire 0.20 CRES NAS 33540 P/N MS20995C20 (double-twist lock wire) and any missing double-twist lock wire. If a screw is missing from the inner diameter (the connector flange) of the upper end of the M/R slip ring, EASA ADs 2017–0083 and 2017–0087 specify replacing the M/R slip ring with a serviceable part, whereas this AD requires removing the M/R slip ring from service instead. If a screw is missing from the outer diameter of the upper end, from the inner diameter of the lower end (shaft extension attachment area), or from the outer diameter of the lower end, this AD requires installing a new screw and washer, applying torque, and installing lock wire, whereas corrective action for this condition is not specified in EASA AD 2017–0083 or 2017–0087.

#### Costs of Compliance

The FAA estimates that this AD affects 134 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

Inspecting an M/R slip ring takes about 10 work-hours for an estimated cost of \$850 per helicopter and \$113,900 for the U.S. fleet. Marking an M/R slip ring takes a minimal amount of time and parts cost a nominal amount. Replacing an M/R slip ring takes about 3 work-hours and parts cost about \$65,000 for an estimated cost of \$65,255 per helicopter. Removing any ferrule ended safety cable; replacing screws and washers; applying torque; and installing lock wire takes about 1 work-hour and parts cost a nominal amount for an estimated cost of \$85 per helicopter.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2021–13–01 Leonardo S.p.a. (Type Certificates Previously Held by Agusta S.p.A. and AgustaWestland S.p.A.):** Amendment 39–21606; Docket No. FAA–2021–0304; Project Identifier 2017–SW–108–AD.

#### (a) Effective Date

This airworthiness directive (AD) is effective August 3, 2021.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Leonardo S.p.a. (Type Certificate previously held by Agusta S.p.A.)

Model AB139 and AW139 helicopters and Leonardo S.p.a. (Type Certificate previously held by AgustaWestland S.p.A.) Model AW189 helicopters, certificated in any category, with a main rotor (M/R) slip ring part number (P/N) 4G6220V00151 with a serial number (S/N) up to and including S/N 0141, except those marked with an "L" following the S/N, installed.

#### (d) Subject

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

#### (e) Unsafe Condition

This AD was prompted by reports of missing lock wire and loose fasteners. The FAA is issuing this AD to address failure of an M/R slip ring fastener. The unsafe condition, if not addressed, could result in failure of the M/R slip ring bearing inner race, reduced M/R control, and subsequent loss of control of the helicopter.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

(1) For an M/R slip ring that has accumulated 900 or more total hours time-in-service (TIS), within 50 hours TIS after the effective date of this AD; and for an M/R slip ring that has accumulated less than 900 total hours TIS, within 300 hours TIS after the effective date of this AD or before accumulating 950 total hours TIS, whichever occurs first:

(i) With the M/R slip ring removed, visually inspect for the presence of each screw, the presence of any ferrule ended safety cable, the correct installation of lock wire 0.20 CRES NAS 33540 P/N MS20995C20 (double-twist lock wire), and any missing double-twist lock wire for each set of upper (connector) end and lower (pigtail or standpipe) end fasteners of the M/R slip ring as depicted in Figures 1 and 2 of Annex A to Leonardo Helicopters Alert Service Bulletin (ASB) No. 139–472, dated May 9, 2017 (ASB 139–472), or Leonardo Helicopters ASB No. 189–138, dated May 12, 2017 (ASB 189–138), as applicable to your model helicopter. Figures 2 and 3 of Annex A to ASB 139–472 and ASB 189–138 also show examples of a ferrule ended safety cable installed that are not approved.

**Note 1 to paragraph (g)(1)(i):** Annex A to ASB 139–472 and ASB 189–138 is Moog Service Bulletin SB 16–01, Revision 5, undated.

(ii) If all of the screws are present, there is not any ferrule ended safety cable installed, the double-twist lock wire is correctly installed, and none of the double-twist lock wire is missing on each set of upper end and lower end fasteners of the M/R slip ring, before further flight, mark the letter "L" following the S/N on the identification label by following the Compliance Instructions, paragraph 3) of Annex A to ASB 139–472 or ASB 189–138, as applicable to your model helicopter.

(iii) If a screw is missing from the inner diameter (the connector flange) of the upper

end of the M/R slip ring, before further flight, remove the M/R slip ring from service.

(iv) If a screw is missing from the outer diameter of the upper end, from the inner diameter of the lower end (shaft extension attachment area), or from the outer diameter of the lower end, before further flight, install a new screw and washer, apply a torque to 1–1.25 Nm, and install double-twist lock wire by following the Compliance Instructions, paragraphs 9(a) through (g) of Annex A to ASB 139–472 or ASB 189–138, as applicable to your model helicopter.

(v) If any double-twist lock wire is not correctly installed, is missing, or if there is a ferrule ended safety cable installed on any set of upper end or lower end fasteners of the M/R slip ring, before further flight, remove the incorrectly installed lock wire or ferrule ended safety cable from service, as applicable, and inspect the fastener torque by applying 1–1.25 Nm of torque.

(A) If the torque of a screw installed in the inner diameter (the connector flange) of the upper end of the M/R slip ring is below 1 Nm of torque, do not remove or replace the screw, before further flight, apply a torque of 1–1.25 Nm.

(B) If the torque of a screw installed in the outer diameter of the upper end, in the inner diameter of the lower end (shaft extension attachment area), or in the outer diameter of the lower end is below 1 Nm of torque, before further flight, remove the affected screw and washer from service, install a new screw and washer, and apply a torque of 1–1.25 Nm.

(C) Install double-twist lock wire by following the Compliance Instructions, paragraphs 9(a) through (g) of Annex A to ASB 139–472 or ASB 189–138, as applicable to your model helicopter.

(vi) Mark the letter “L” following the S/N on the identification label by following the Compliance Instructions, paragraph 3) of Annex A to ASB 139–472 or ASB 189–138, as applicable to your model helicopter.

(2) As of the effective date of this AD, do not install an M/R slip ring identified in paragraph (c) of this AD unless the requirements of paragraph (g)(1) of this AD have been accomplished.

#### (h) Special Flight Permits

Special flight permits are prohibited.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Related Information

(1) For more information about this AD, contact Steven Warwick, Aerospace Engineer, Certification Section, Fort Worth ACO Branch, Compliance & Airworthiness Division, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5225; email [steven.r.warwick@faa.gov](mailto:steven.r.warwick@faa.gov).

(2) Moog Service Bulletin SB 16–01, Revision 5, undated, is attached as Annex A to both ASB 139–472 and ASB 189–138. As the design approval holder for the products identified in paragraph (c) of this AD, contact Leonardo Helicopters for the Moog service information at the contact information specified in paragraph (k)(3) of this AD. It is also available at the contact information specified in paragraph (k)(4) of this AD.

(3) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2017–0083, dated May 10, 2017, and EASA AD 2017–0087, dated May 12, 2017. You may view the EASA ADs at <https://www.regulations.gov> in Docket No. FAA–2021–0304.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Leonardo Helicopters Alert Service Bulletin (ASB) No. 139–472, dated May 9, 2017.

(ii) Leonardo Helicopters ASB No. 189–138, dated May 12, 2017.

(3) For Leonardo Helicopters service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C.Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://www.leonardocompany.com/en/home>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 8, 2021.

#### Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–13711 Filed 6–28–21; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2021–0225; Airspace Docket No. 20–AAL–13]

RIN 2120–AA66

#### Amendment of Class E Airspace; Anaktuvuk Pass, AK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies the Class E airspace extending upward from 700 feet above the surface at Anaktuvuk Pass Airport, Anaktuvuk Pass, AK. This action updates the airport’s geographic coordinates and removes the Anaktuvuk Pass NDB from the Class E5 text header and airspace description. The airspace supports instrument flight rules (IFR) operations at the airport.

**DATES:** Effective 0901 UTC, October 7, 2021. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

#### FOR FURTHER INFORMATION CONTACT:

Matthew Van Der Wal, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 . 216th Street, Des Moines, WA 98198; telephone (206) 231–3695.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is