

(e) Unsafe Condition

This AD was prompted by a report of cracks on the M/R scissor link. The FAA is issuing this AD to replace the metal bushings installed on the M/R swashplate guide bellcrank with plastic bushings. The unsafe condition, if not addressed, could result in failure of the M/R swashplate guide bellcrank and reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 50 hours time-in-service (TIS) or 2 months, whichever occurs first after the effective date of this AD:

(i) Disconnect the bellcrank from the swashplate guide by removing each bolt and, ensuring that the bellcrank remains attached to the flight control rod, remove each metal bushing from service using a bushing disassembly tool.

(ii) Visually inspect the lug bore area for any corrosion and any cracks. If there is any corrosion or any cracks, before further flight, remove the swashplate guide from service or repair it using an FAA-approved method. If there is no corrosion and no cracks, install plastic bushing part number HG22–1001, coat plastic bushing with isolation compound, re-install the bellcrank, torque each bolt to 7.5 Nm–9 Nm (5.5 ft-lbs–6.6 ft-lbs), and install cotter pins.

(2) As of the effective date of this AD, do not install any metal bushing on any helicopter.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Westbury, NY 11590; telephone (516) 228–7330; email andrea.jimenez@faa.gov.

(2) Guimbal Service Bulletin SB 17–003, Revision C, dated July 12, 2019, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Hélicoptères Guimbal, Basile Ginel, 1070, rue du Lieutenant Parayre,

Aérodrome d'Aix-en-Provence, 13290 Les Milles, France; telephone 33–04–42–39–10–88; email basile.ginel@guimbal.com; web <https://www.guimbal.com>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(3) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2019–0185, dated July 30, 2019. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA–2021–0498.

Issued on June 10, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–14495 Filed 7–8–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2021–0560; Project Identifier MCAI–2021–00192–T]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes. This proposed AD was prompted by reports that the sliding bushings in the forward engine mount system were missing. This proposed AD would require an inspection (gap check) of the front and aft engine mounts to verify the proper installation of the sliding bushings, and repair if necessary. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 23, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor,

Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; internet <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0560; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7362; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2021–0560; Project Identifier MCAI–2021–00192–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7362; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued TCCA AD CF-2021-04, dated February 15, 2021 (also referred to after this as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe

condition for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0560.

This proposed AD was prompted by reports that the sliding bushings in the forward engine mount system were missing. The FAA is proposing this AD to address redistribution of load/stress on the mount components, which may decrease the component fatigue life; failure of the mount structural components could result in the loss of the engine attachment to the airframe. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

Bombardier, Inc., has issued the following service information.

- Bombardier Service Bulletin 700-1A11-71-005, dated December 14, 2020.
- Bombardier Service Bulletin 700-71-005, dated December 14, 2020.
- Bombardier Service Bulletin 700-71-5005, dated December 14, 2020.
- Bombardier Service Bulletin 700-71-5501, dated December 14, 2020.
- Bombardier Service Bulletin 700-71-6005, December 14, 2020.
- Bombardier Service Bulletin 700-71-6501, December 14, 2020.

This service information describes procedures for verifying the proper installation of the sliding bushings by doing an inspection (gap check), including a gap outside acceptable limits, a missing or damaged nut or bolt

at the upper side of front mount beam, and a bolt that turns freely with finger pressure. These documents are distinct since they apply to different airplane serial numbers. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the service information already described.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 376 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
11 work-hours × \$85 per hour = \$935	\$0	\$935	\$351,560

The FAA has received no definitive data on which to base the cost estimates for the repairs specified in this proposed AD.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Bombardier, Inc.: Docket No. FAA–2021–0560; Project Identifier MCAI–2021–00192–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 23, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes, certificated in any category, serial numbers 9002 through 9879 inclusive, 9998, 60001 through 60005 inclusive, 60007, 60009, 60015, 60016, and 60024.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Unsafe Condition

This AD was prompted by reports that the sliding bushings in the forward engine mount system were missing. The FAA is issuing this AD to address redistribution of load/stress on the mount components, which may decrease the component fatigue life; failure of the mount structural components could result in the loss of the engine attachment to the airframe.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Action

Within 15 months or 750 flight hours, whichever occurs first, after the effective date of this AD: Verify the proper installation of the sliding bushings by doing an inspection (gap check) for discrepancies of the front and aft engine mounts, in accordance with paragraphs 2.B. through 2.F. of the Accomplishment Instructions of the applicable service information specified in figure 1 to paragraph (g) of this AD. If any discrepancy is found: Before further flight, repair using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature. Where a serial number is identified in more than one row in figure 1 to paragraph (g) of this AD, the applicable service information is identified based on the marketing designations in paragraph 1.M., "Equivalent Service Bulletins," of each service information.

BILLING CODE 4910–13–P

Figure 1 to paragraph (g) – Service Information

Serial Number–	Model–	Bombardier Service Bulletin–
9002 to 9312 inclusive, 9314 to 9380 inclusive, and 9384 to 9429 inclusive	BD-700-1A10 airplanes	700-71-005, dated December 14, 2020
9313, 9381, 9432 to 9860 inclusive, 9863 to 9871 inclusive, 9873 to 9879 inclusive, 60005 and 60024	BD-700-1A10 airplanes	700-71-6005, December 14, 2020
9861, 9872, 60001 to 60004 inclusive, 60009, and 60016	BD-700-1A10 airplanes	700-71-6501, December 14, 2020
9127 to 9383 inclusive, 9389 to 9400 inclusive, 9404 to 9431 inclusive, and 9998	BD-700-1A11 airplanes	700-1A11-71-005, dated December 14, 2020
9386, 9401, 9445 to 9862 inclusive, and 9868 to 9879 inclusive	BD-700-1A11 airplanes	700-71-5005, dated December 14, 2020
60007 and 60015	BD-700-1A11 airplanes	700-71-5501, dated December 14, 2020

(h) No Reporting Requirement

Although the service information identified in table 1 to paragraph (g) of this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF-2021-04, dated February 15, 2021; for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0560.

(2) For more information about this AD, contact Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7362; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; internet <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on July 2, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-14611 Filed 7-8-21; 8:45 am]

BILLING CODE 4910-13-P

POSTAL REGULATORY COMMISSION**39 CFR Chapter III**

[Docket No. PI2021-2; Order No. 5930]

Public Inquiry

AGENCY: Postal Regulatory Commission.

ACTION: Advanced notice of proposed rulemaking.

SUMMARY: The Commission seeks further input from the public about what regulations promulgated by the Commission may be necessary to carry out the requirements of agency law. This document informs the public of this proceeding, invites public comment, and takes other administrative steps.

DATES: *Comments are due:* August 26, 2021.

ADDRESSES: Submit comments electronically via the Commission's Filing Online system at <http://www.prc.gov>. Those who cannot submit comments electronically should contact the person identified in the **FOR FURTHER INFORMATION CONTACT** section by telephone for advice on filing alternatives.

FOR FURTHER INFORMATION CONTACT: David A. Trissell, General Counsel, at 202-789-6820.

SUPPLEMENTARY INFORMATION:**Table of Contents**

- I. Introduction
- II. Background
- III. Discussion
- IV. Comments
- V. Ordering Paragraphs

I. Introduction

In this docket, the Commission seeks further input from the public about what regulations promulgated by the Commission may be necessary to carry out the requirements of 39 U.S.C. 601. Section 601 describes instances when letters may be carried out of the mail, or when the letter monopoly does not apply to a mailpiece. In particular, the Commission seeks to determine whether regulations promulgated by the Commission are needed to carry out those statutory exemptions.

II. Background

The Postal Service has exclusive rights in the carriage and delivery of letters under certain circumstances. This letter monopoly is codified in the Private Express Statutes (PES), which are a group of civil and criminal statutes that make it unlawful for any entity other than the Postal Service to send or

carry letters. *See* 18 U.S.C. 1693-1699; 39 U.S.C. 601-606.¹

Section 601 provides specific instances (exceptions) where letters may be carried out of the mail (*i.e.*, not subject to the letter monopoly). Section 601(a) sets forth the conditions under which a letter may be carried out of the mail, which include requiring that the letter be enclosed in an envelope, that the proper amount of postage is affixed to the envelope, and that the postage is canceled. 39 U.S.C. 601(a).

Section 601(b) provides additional exceptions such that the letter monopoly does not apply to letters charged more than six times the current rate for the first ounce of a Single-Piece First Class Letter or to letters weighing more than 12.5 ounces. *See* 39 U.S.C. 601(b)(1), (b)(2). The "grandfather clause" in Section 601(b)(3) references exceptions from prior Postal Service regulations that permitted private carriage as in effect on July 1, 2005. 39 U.S.C. 601(b)(3); *see also* 39 CFR 310.1 and 39 CFR 320.2-320.8 (2005).

Section 601(c), which is the subject of this proceeding, directs the Commission (rather than the Postal Service) to promulgate any regulations necessary to carry out this section. 39 U.S.C. 601(c). This Public Inquiry seeks to answer how the Commission shall meet this statutory requirement.

Prior to the Postal Accountability and Enhancement Act (PAEA) of 2006, the Postal Service issued regulations that purported to suspend the PES.² The PAEA included the term "purport" to describe the Postal Service's efforts to suspend the PES, reflecting some disagreement between the Postal Service and policymakers about the Postal Service's authority to promulgate such regulations prior to the PAEA.³ Post-PAEA, the law clearly cedes such authority to the Commission. These regulations defined the term "letter" as "a message directed to a specific person or address and recorded in or on a tangible object," subject to several provisions. 39 CFR 310.1(a) (2005). The regulations also described several statutory exceptions to the letter monopoly, such as when the letter accompanies and relates to cargo or when a special messenger is used. *See* 39 CFR 310.3 (2005). In addition, the

¹ Although these provisions of the U.S. Code are customarily referred to collectively as the "Private Express Statutes," they do not all relate to private expresses or prohibit carriage of letters out of the mails.

² *See* Postal Accountability and Enhancement Act, Public Law 109-435, 120 Stat. 3198 (2006); *see also* 39 CFR 310, 320 (2005).

³ *See* H.R. Rep. No. 109-66, 109th Cong., 1st Sess., pt. 1, at 58 (2005) (H.R. Rep. No. 109-66).