

14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Atlanta ACO Branch, FAA.

(4) *Required for compliance (RC):* Except as specified by paragraph (m)(3) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (n) Related Information

(1) For more information about this AD, contact John Marshall, Aerospace Engineer, Airframe Section, FAA, Atlanta ACO Branch, 1701 Columbia Avenue, College Park, GA 30337; phone: 404-474-5524; fax: 404-474-5606; email: [John.R.Marshall@faa.gov](mailto:John.R.Marshall@faa.gov).

(2) For Airbus service information identified in this AD, contact Airbus SAS, Airworthiness Office—ELIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <https://www.airbus.com>. For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on October 14, 2021.

**Lance T. Gant,**

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-22785 Filed 10-21-21; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2021-0873; Project Identifier MCAI-2021-00336-R]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 2018-11-01, which applies to certain Airbus Helicopters Model AS332L2 and EC225LP helicopters. AD 2018-11-01 requires installing a cut-out for the left-hand (LH) and right-hand (RH) rail support junction profiles and repetitively inspecting splices, frame 5295, and related equipment for a crack. Since the FAA issued AD 2018-11-01, the manufacturer has developed a modification for in-service helicopters for replacing aluminum splices with steel splices on frame 5295. This proposed AD would retain the requirements of AD 2018-11-01 and require a modification for replacing aluminum splices with steel splices on frame 5295 if cracking is found. This proposed AD would also provide terminating action for the repetitive inspections. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 6, 2021.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/>

[services/technical-support.html](https://www.airbus.com/helicopters/services/technical-support.html). You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0873; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the European Union Aviation Safety Agency (EASA) AD, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0873; Project Identifier MCAI-2021-00336-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

##### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial

information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Background

The FAA issued AD 2018-11-01, Amendment 39-19289 (83 FR 23778, May 23, 2018), (AD 2018-11-01), for Airbus Helicopters Model AS332L2 and EC225LP helicopters with an extended aluminum splice installed on frame 5295, except helicopters with steel splice kit part number 332A08-2649-3072 installed. AD 2018-11-01 requires installing a cut-out for the LH and RH rail support junction profiles and repetitively inspecting splices, frame 5295, and related equipment for a crack. AD 2018-11-01 was prompted by reports of cracks on frame 5295 and on splices installed to prevent those cracks. The FAA issued AD 2018-11-01 to address a crack in frame 5295, which if not detected and corrected, could lead to loss of structural integrity of the helicopter frame and subsequent loss of control of the helicopter.

### Actions Since AD 2018-11-01 Was Issued

Since the FAA issued AD 2018-11-01, EASA issued AD 2021-0075, dated March 16, 2021 (EASA AD 2021-0075), which supersedes EASA Emergency AD 2014-0098-E, dated April 25, 2014 (EASA Emergency AD 2014-0098-E). EASA advises that since EASA Emergency AD 2014-0098-E was issued, Airbus Helicopters developed MOD 0728463, available for helicopters in service through the applicable modification service bulletin, providing instructions to replace aluminum splices with steel splices on frame 5295. Airbus Helicopters also issued the applicable inspection alert service

bulletins, as defined in EASA AD 2021-0075. Accordingly, EASA AD 2021-0075 retains the requirements of EASA Emergency AD 2014-0098-E, which is superseded, and requires a modification, replacing aluminum splices with steel splices on helicopters on which any cracked aluminum splice has been detected. EASA AD 2021-0075 also advises that the modification is terminating action for the repetitive inspections.

### FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type designs.

### Related Service Information Under 1 CFR Part 51

The FAA reviewed the following Airbus Helicopters service information.

- Alert Service Bulletins Nos. AS332-05.00.97, Revision 1; and EC225-05A038, Revision 1; both dated February 9, 2021; which specify procedures for, among other actions, installing a cut-out for the LH and RH rail support junction profiles and inspecting splices, frame 5295, and related equipment for a crack. These documents are distinct since they apply to different helicopter models.
- Service Bulletins Nos. AS332-53.01.97, Revision 0; and EC225-53-061, Revision 0; both dated February 9, 2021; which specify procedures for modifying the helicopter by replacing the aluminum LH and RH splices with steel splices under the plates and the brackets of the main gear box (MGB) bars. The modification includes taking reference readings of the brackets of the MGB bars, removing the MGB brackets and plates, removing the aluminum splices and inspecting the joggling areas for scratches or other damage, inspecting frame 5295 for cracking (including a dye penetrant inspection if the inspection results are not conclusive), identifying the current measurements (values) of the rivet and attachment plate holes for installation of the steel splice (including determining the values of the rivet holes and attachment plate holes on frame 5295 with a calibrated pad and determining

the elongations of the holes and the lengths of the straps), modifying the door hinge rail brackets on the LH and RH sides, and installing the steel splices. These documents are distinct since they apply to different helicopter models.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

### Other Related Service Information

The FAA reviewed Eurocopter Helicopters (now Airbus Helicopters) Service Bulletin No. 53-003, Revision 4, for Model EC225LP helicopters and Service Bulletin No. 53.01.52, Revision 5, for Model AS332L2 helicopters, both dated July 23, 2010. The service bulletins specify procedures to reinforce frame 5295 by installing a new titanium plate underneath the fitting and a new widened aluminum splice below the upper corner of the door.

The FAA also reviewed Airbus Helicopters Service Bulletin No. 05-019, Revision 4, dated September 22, 2014, for Model EC225 LP helicopters. This service information specifies procedures for cutting out the junction profiles.

The FAA also reviewed Airbus Helicopters Alert Service Bulletins Nos. AS332-05.00.97, Revision 0; and EC225-05A038, Revision 0; both dated April 15, 2014; which specify procedures for, among other actions, installing a cut-out for the LH and RH rail support junction profiles and inspecting splices, frame 5295, and related equipment for a crack.

### Proposed AD Requirements in This NPRM

This proposed AD would retain all requirements of AD 2018-11-01 and require a modification for replacing aluminum splices with steel splices on frame 5295. This proposed AD would also provide terminating action for the repetitive inspections required by AD 2018-11-01. This proposed AD would also require accomplishing the actions specified in the service information already described, except as discussed under "Differences Between this AD and the EASA AD."

### Redesignation of AD 2018-11-01 Paragraph Identifier

Since AD 2018-11-01 was issued, the AD format has been revised, and certain paragraphs have been rearranged. As a result, the corresponding paragraph

identifiers have been redesignated in this proposed AD, as listed in the following table:

REVISED PARAGRAPH IDENTIFIER	
Requirement in AD 2018–11–01	Corresponding requirement in this proposed AD
paragraph (e) .....	paragraph (g).
paragraph (f) .....	paragraph (j)(1).

**Differences Between This Proposed AD and the EASA AD 2021–0075**

EASA AD 2021–0075 requires contacting Airbus Helicopters for approved repair instructions if any crack is found during an inspection. This proposed AD would not require that action.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 38 helicopters of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained installation of cut-outs on frame 5295 from AD 2018–11–01.	40 work-hours × \$85 per hour = \$3,400	\$5,000	\$8,400 .....	\$319,200.
Retained inspection of frame 5295 from AD 2018–11–01.	2 work-hours × \$85 per hour = \$170, per inspection cycle.	0	\$170, per inspection cycle.	\$6,460, per inspection cycle.

The FAA estimates the following costs to do any necessary repairs that

would be required based on the results of the proposed inspection. The agency

has no way of determining the number of aircraft that might need these repairs:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Action	Labor cost	Parts cost	Cost per product
Repair .....	40 work-hours × \$85 per hour = \$3,400 .....	\$5,000	\$8,400
New proposed modification (replacement of aluminum splices with steel splices).	830 work-hours × \$85 per hour = \$70,550 .....	35,000	105,550

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or

on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by:
  - a. Removing Airworthiness Directive 2018–11–01, Amendment 39–19289 (83 FR 23778, May 23, 2018); and
  - b. Adding the following new airworthiness directive:

**Airbus Helicopters:** Docket No. FAA–2021–0873; Project Identifier MCAI–2021–00336–R.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) action by December 6, 2021.

**(b) Affected ADs**

This AD replaces AD 2018–11–01, Amendment 39–19289 (83 FR 23778, May 23, 2018) (AD 2018–11–01).

**(c) Applicability**

This AD applies to Airbus Helicopters Model AS332L2 and Model EC225LP helicopters, certificated in any category, as specified in paragraphs (c)(1) and (2) of this AD.

- (1) Model AS332L2 helicopters equipped with extended aluminum splices on frame 5295 installed in accordance with Airbus Helicopters (AH) Modification (MOD) 0726517, Eurocopter (EC) AS332 Service Bulletin (SB) 53.01.52, or AH repair design 332–53–507–06, 332–53–21–07, or 332–53–82–06; except helicopters embodying AH MOD 0728463, AH SB AS 332–53.01.97, or

repair design 332-53-409-12, 332-53-1284-13, 332-53-1079-16, or 332-53-1358-16.

**Note 1 to paragraph (c)(1):** As referenced in paragraphs (c)(1) and (2) of this AD, helicopters with AH MOD 0728463 installed have replaced the aluminum splices with steel splices.

(2) Model EC225LP helicopters equipped with extended aluminum splices on frame 5295 installed in accordance with AH MOD 0726517, or EC EC225 SB 53-003 (pre AH MOD 0726493 and post AH MOD 0726517), except helicopters embodying AH MOD 0728463, or SB EC225-53-061.

**Note 2 to paragraph (c)(2):** Helicopters with AH MOD 0726493 have installed steel splice kit part number 332A08-2649-3072.

**(d) Subject**

Joint Aircraft Service Component (JASC) Code: 5300, Fuselage Structure.

**(e) Unsafe Condition**

This AD was prompted by reports of cracks on frame 5295 and on aluminum splices installed to prevent those cracks. The FAA is issuing this AD to address cracking on frame 5295 and on the inner skins. The unsafe condition, if not addressed, could result in loss of structural integrity of the helicopter frame and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Installation and Inspections With New Service Information and Corrective Actions (Modification)**

This paragraph retains the requirements of paragraph (e) of AD 2018-11-01, with new service information and corrective actions (modification).

(1) Before a splice reaches 1,700 hours time-in-service (TIS), within 50 hours TIS, or before the helicopter reaches 11,950 hours TIS, whichever occurs latest, do the following.

(i) Install the rail support cut-out and identify the left-hand (LH) and right-hand (RH) junction profile, in accordance with the Accomplishment Instructions, paragraph 3.B.2., of Airbus Helicopters Alert Service Bulletin (ASB) No. EC225-05A038, Revision 1, dated February 9, 2021 (Airbus Helicopters ASB No. EC225-05A038, Revision 1); or Airbus Helicopters ASB No. AS332-05.00.97, Revision 1, dated February 9, 2021 (Airbus Helicopters ASB No. AS332-05.00.97, Revision 1); whichever is applicable to your helicopter.

(ii) Inspect each splice for a crack in the area depicted as Area Y in Figure 3 of Airbus Helicopters ASB No. EC225-05A038, Revision 1; or Airbus Helicopters ASB No. AS332-05.00.97, Revision 1; whichever is applicable to your helicopter. If a crack exists, do the applicable action required by paragraph (g)(1)(ii)(A) or (B) of this AD.

(A) For any cracking found before the effective date of this AD: Repair or replace the splice before further flight.

(B) For any cracking found on or after the effective date of this AD: Before further flight, modify the helicopter in accordance with

paragraph 3.B.2. of the Accomplishment Instructions of Airbus Helicopters Service Bulletin (SB) No. AS332-53.01.97, Revision 0, dated February 9, 2021 (Airbus Helicopters SB No. AS332-53.01.97, Revision 0); or Service Bulletin No. EC225-53-061, Revision 0, dated February 9, 2021 (Airbus Helicopters SB No. EC225-53-061, Revision 0); as applicable to your helicopter; except as specified in paragraph (h) of this AD.

(2) Thereafter at intervals not to exceed 110 hours TIS, inspect each splice for a crack in the area depicted as Area Y in Figure 3 of Airbus Helicopters ASB No. EC225-05A038, Revision 1; or Airbus Helicopters ASB No. AS332-05.00.97, Revision 1; whichever is applicable to your helicopter. If a crack exists, do the applicable actions required by paragraph (g)(2)(i) or (ii) of this AD. Accomplishing the modification specified in paragraph (g)(1)(ii)(B) and (g)(2)(ii) of this AD terminates the inspections required by this paragraph.

(i) For any cracking found before the effective date of this AD: Repair or replace the splice before further flight.

(ii) For any cracking found on or after the effective date of this AD: Before further flight, modify the helicopter in accordance with paragraph 3.B.2. of the Accomplishment Instructions of Airbus Helicopters SB No. AS332-53.01.97, Revision 0; or Airbus Helicopters SB No. EC 225-53-061, Revision 0; as applicable to your helicopter; except as specified in paragraph (h) of this AD.

**(h) Service Information Exceptions**

(1) Where Airbus Helicopters ASB No. EC225-05A038, Revision 1; Airbus Helicopters ASB No. AS332-05.00.97, Revision 1; Airbus Helicopters SB No. AS332-53.01.97, Revision 0; and Airbus Helicopters SB No. EC 225-53-061, Revision 0; specify to perform dye-penetrant inspections "if in doubt" or "if any doubt," this AD requires performing a dye-penetrant inspection during inspections done on or after the effective date of this AD.

(2) Where Airbus Helicopters SB No. AS332-53.01.97, Revision 0; and Airbus Helicopters SB No. EC 225-53-061, Revision 0; specify discarding parts, this AD requires removing those parts from service.

(3) Where Airbus Helicopters SB No. AS332-53.01.97, Revision 0; and Airbus Helicopters SB No. EC 225-53-061, Revision 0, specify contacting Airbus Helicopter for corrective action or further procedures, this AD requires repair done in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(4) Airbus Helicopters SB No. AS332-53.01.97, Revision 0; and Airbus Helicopters SB No. EC 225-53-061, Revision 0, specify a visual check and dye penetrant inspection for cracks on the inside and outside of frame 5295. For this AD, if any cracking is found during any visual check or dye penetrant inspection on the inside and outside of frame 5295, before further flight, repair in accordance with a method approved by the

Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(i) Reporting Not Required**

Although Airbus Helicopters SB No. AS332-53.01.97, Revision 0; and Airbus Helicopters SB No. EC 225-53-061, Revision 0; specify to submit certain information to the manufacturer, this AD does not include that requirement.

**(j) Credit for Previous Actions**

(1) This paragraph provides credit for the installation of the rail support cut-out required by paragraph (g)(1)(i) of this AD, if that action was performed before June 27, 2018 (the effective date of AD 2018-11-01) using Airbus Helicopters MOD 0728090 or Airbus Helicopters SB No. 05-019, Revision 4, dated September 22, 2014.

(2) This paragraph provides credit for the actions required by paragraphs (g)(1) and (2) of this AD, if the actions were performed before the effective date of this AD using Airbus Helicopters ASB No. EC225-05A038, Revision 0, dated April 15, 2014; or Airbus Helicopters ASB No. AS332-05.00.97, Revision 0, dated April 15, 2014.

**(k) Special Flight Permits**

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the actions can be performed, provided no passengers are onboard.

**(l) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(m) Related Information**

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov).

(2) For service information identified in this AD, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this

referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(3) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2021-0075, dated March 16, 2021. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2021-0873.

Issued on October 4, 2021.

**Lance T. Gant,**

Director, Compliance & Airworthiness  
Division, Aircraft Certification Service.

[FR Doc. 2021-22462 Filed 10-21-21; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2021-0851; Airspace  
Docket No. 19-AAL-42]

RIN 2120-AA66

#### Proposed Establishment of United States Area Navigation (RNAV) Route T-373; Bethel, AK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish United States Area Navigation (RNAV) route T-373 in the vicinity of Bethel, AK in support of a large and comprehensive T-route modernization project for the state of Alaska.

**DATES:** Comments must be received on or before December 6, 2021.

**ADDRESSES:** Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12-140, Washington, DC 20590; telephone: 1(800) 647-5527, or (202) 366-9826. You must identify FAA Docket No. FAA-2021-0851; Airspace Docket No. 19-AAL-42 at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>.

FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FAA Order JO 7400.11F is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order JO 7400.11F at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

#### FOR FURTHER INFORMATION CONTACT:

Christopher McMullin, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would expand the availability of RNAV in Alaska and improve the efficient flow of air traffic within the National Airspace System (NAS) by lessening the dependency on ground based navigation.

##### Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2021-0851; Airspace Docket No. 19-AAL-42) and be submitted in triplicate to the Docket Management Facility (see **ADDRESSES** section for address and phone number). You may also submit comments through the internet at <https://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped

postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2021-0851; Airspace Docket No. 19-AAL-42". The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified comment closing date will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the comment closing date. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

##### Availability of NPRM

An electronic copy of this document may be downloaded through the internet at <https://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at [https://www.faa.gov/air\\_traffic/publications/airspace\\_amendments/](https://www.faa.gov/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Western Service Center, Operations Support Group, Federal Aviation Administration, 2200 South 216th St., Des Moines, WA 98198.

##### Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

##### Background

In 2003, Congress enacted the Vision 100-Century of Aviation Reauthorization Act (Pub L., 108-176), which established a joint planning and development office in the FAA to manage the work related to the Next Generation Air Transportation System (NextGen). Today, NextGen is an