

helicopter as eligible to operate as a Model 47D1. The commenter explained that the Rebel Rotors S/N B-101-R helicopter is not a Scott's-Bell Model 47D1 helicopter, and as the proposed AD was written, would not be captured in the applicability, despite the fact that it likely had the same unsafe condition addressed in the proposed AD. The commenter suggested that the applicability be changed to mirror what is in the Scott's-Bell 47, Inc. service information "All Helicopters listed on Type Certificate Data Sheets H-1, 2H1, and 2H3, which have Marvel Schebler carburetors models . . . installed."

The FAA acknowledges this comment to the NPRM. However, because the FAA is withdrawing the NPRM, the commenter's request is no longer necessary.

Request To Clarify the Compliance Time

Scott's-Bell 47, Inc. also requested that the compliance time in paragraph (e)(3) of the proposed AD be revised to state "Within 100 hours time-in-service or at the next annual or 100-hour inspection, whichever occurs first, and thereafter any time the throttle linkage connection is disassembled." The commenter explained that, as written in the proposed AD, this compliance time does not address disassembly and, if disassembly were to occur after the first flight of the day and the helicopter was returned to service on the same day, the current wording would not require proper rigging to be performed for the second and subsequent flights of that day. The commenter suggested that its proposed wording would capture all variables and eliminate unnecessary re-rigging of the helicopter.

The FAA acknowledges this comment to the NPRM. However, because the FAA is withdrawing the NPRM, the commenter's request is no longer necessary.

Request To Include Additional Required Actions

Furthermore, Scott's-Bell 47, Inc. requested that paragraphs (e)(3)(i) and (ii) of the proposed AD be revised to include additional required actions. The commenter stated that paragraph (e)(3)(i) of the proposed AD requires operators to "adjust and secure the throttle linkage as specified in Appendix 1 of the Scott's-Bell Maintenance and Overhaul Instructions Temporary Revision . . ." but other vital functions, including a functionality check after adjusting and securing, followed by applying anti-sabotage lacquer, are not included, and, therefore, would not be required. The

commenter recommended that paragraph (e)(3)(i) be revised to "Adjust, secure, perform functionality check, and apply anti-sabotage lacquer to the throttle linkage, as specified in Appendix 1 of the Scott's-Bell Maintenance and Overhaul Instructions Temporary Revision that is applicable to your helicopter, as listed in Table 1 of Scott's-Bell Alert Service Bulletin 47-15-27 R1, dated November 1, 2016."

In regard to paragraph (e)(3)(ii) of the proposed AD, the commenter proposed that this paragraph be revised to state ". . . and 47K helicopters, adjust, secure, perform functionality check and apply anti-sabotage lacquer to the throttle linkage using a method approved . . ."

The FAA acknowledges this comment to the NPRM. However, because the FAA is withdrawing the NPRM, the commenter's request is no longer necessary.

FAA's Conclusions

Upon further consideration of the available information, the FAA has determined that the NPRM is unnecessary. Accordingly, the NPRM is withdrawn.

Regulatory Findings

Since this action only withdraws an NPRM, it is neither a proposed nor a final rule. This action therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Withdrawal

■ Accordingly, the notice of proposed rulemaking, Docket No. FAA-2018-0440, which was published in the **Federal Register** on May 18, 2018 (83 FR 23240), is withdrawn.

Issued on October 22, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-23514 Filed 10-28-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0570; Project Identifier 2019-SW-091-AD]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (SNPRM); reopening of comment period.

SUMMARY: The FAA is revising a notice of proposed rulemaking (NPRM) that applied to certain Leonardo S.p.a. Model AW169 helicopters. This action revises the NPRM by requiring modification of certain pilot and co-pilot yaw pedal assemblies with an improved design and re-identification of the affected parts, as specified in a European Union Aviation Safety Agency (EASA) airworthiness directive (AD), which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products. Since these actions would impose an additional burden over those in the NPRM, the agency is requesting comments on this SNPRM.

DATES: The comment period for the NPRM published in the **Federal Register** on July 28, 2021 (86 FR 40371), is reopened.

The FAA must receive comments on this SNPRM by December 13, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material that is proposed for IBR in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view the EASA material at the

FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of the EASA material at the FAA, call (817) 222-5110. The EASA material is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0570.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0570; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, this SNPRM, the EASA AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5485; email kristin.bradley@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0570; Project Identifier 2019-SW-091-AD" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM

contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5485; email kristin.bradley@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued an NPRM to amend 14 CFR part 39 by adding an AD that would apply to certain Leonardo S.p.a. Model AW169 helicopters. The NPRM published in the **Federal Register** on July 28, 2021 (86 FR 40371). In the NPRM, the FAA proposed to require modification of the pilot and co-pilot yaw pedal assemblies. The NPRM was prompted by EASA AD 2019-0252, dated October 10, 2019 (EASA AD 2019-0252), issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for Leonardo S.p.a. (formerly Finmeccanica S.p.A and AgustaWestland S.p.A) Model AW169 helicopters, all serial numbers. EASA advised that there was a report of a broken adjustable device that is part of the pilot and co-pilot yaw pedal assemblies. This condition, if not addressed, could result in failure of a yaw pedal adjuster, which could result in reduced yaw control of the helicopter.

Accordingly, EASA AD 2019-0252 required modification (rework) of the affected pilot and co-pilot assemblies and re-identification of each affected part after it has been modified. The modification included the installation of additional end stroke stops on the pilot and co-pilot pedal assemblies. EASA considered EASA AD 2019-0252 an interim action and stated that further EASA AD action may follow.

Actions Since the NPRM Was Issued

Since the NPRM was issued, EASA issued AD 2021-0199, dated August 27, 2021 (EASA AD 2021-0199), which

supersedes EASA AD 2019-0252. EASA advises that three additional events have been reported where the universal joint of the adjusting mechanism on the yaw pedals failed. Prompted by these findings, Leonardo S.p.a. developed a new modification that introduces upgraded pilot and co-pilot pedal assemblies with an improved design, which removes the failure modes. Accordingly, EASA AD 2021-0199 requires modification (rework) of the affected pilot and co-pilot assemblies and re-identification of each affected part after it has been modified. The modification includes replacing the pedal main support assembly, adjuster screw assembly, knob assembly, and spring pin, and removing the additional end stroke stops that were installed on the pilot and co-pilot pedal assemblies using the modification specified in EASA AD 2019-0252. EASA AD 2021-0199 also provides an option to replace an affected part with a non-affected part instead of doing the modification.

In addition, the FAA revised the applicability of this proposed AD from Leonardo S.p.a. Model AW169 helicopters with an affected part installed (as specified in the NPRM), to all Leonardo S.p.a. Model AW169 helicopters. This revised applicability matches EASA AD 2021-0199.

Comments

The FAA gave the public the opportunity to participate in developing this proposed AD. The FAA received no comments on the NPRM or on the determination of the cost.

FAA's Determination

This helicopter has been approved by EASA and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type design. Certain changes described above expand the scope of the NPRM. As a result, it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this SNPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2021-0199 requires modification of the affected pilot and co-pilot assemblies and re-identification of each affected part after it has been modified. EASA AD 2021-0199 also

provides an option to replace an affected part with a non-affected part instead of doing the modification. EASA AD 2021-0199 also prohibits the installation of affected parts.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Proposed AD Requirements in This SNPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2021-0199, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use certain civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2021-0199 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2021-0199 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021-

0199 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021-0199. Service information specified in EASA AD 2021-0199 that is required for compliance with it will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0570 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 10 helicopters of U.S. Registry. The FAA estimates the following costs to comply with this proposed AD.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modify and re-identify affected parts	25 work-hours × \$85 per hour = \$2,125	\$0	\$2,125	\$21,250

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not

have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Leonardo S.p.a.: Docket No. FAA-2021-0570; Project Identifier 2019-SW-091-AD.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 13, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Leonardo S.p.a. Model AW169 helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6700, Rotorcraft Flight Control.

(e) Unsafe Condition

This AD was prompted by a report of a broken adjustable device that is part of the pilot and co-pilot yaw pedal assemblies. The FAA is issuing this AD to address failure of a yaw pedal adjuster, which could result in reduced yaw control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in

accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0199, dated August 27, 2021 (EASA AD 2021–0199).

(h) Exceptions to EASA AD 2021–0199

(1) Where EASA AD 2021–0199 refers to flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2021–0199 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where the service information referenced in EASA AD 2021–0199 specifies discarding certain parts, this AD requires removing those parts from service.

(4) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021–0199.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021–0199 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (1)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For EASA AD 2021–0199, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0570.

(2) For more information about this AD, contact Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5485; email kristin.bradley@faa.gov.

Issued on October 20, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–23264 Filed 10–28–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0944; Project Identifier MCAI–2020–00800–G]

RIN 2120–AA64

Airworthiness Directives; Fibreglas-Technik Rudolf Lindner GmbH & Co. KG (Type Certificate Previously Held by GROB Aircraft AG, Grob Aerospace GmbH i.l., Grob Aerospace GmbH, Burkhart Grob Luft-und Raumfahrt GmbH & Co. KG) Gliders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Fibreglas-Technik Rudolf Lindner GmbH & Co. KG (type certificate previously held by GROB Aircraft AG, Grob Aerospace GmbH i.l., Grob Aerospace GmbH, Burkhart Grob Luft-und Raumfahrt GmbH & Co. KG) Model G102 ASTIR CS, G103 TWIN ASTIR, G103 TWIN II, G103A TWIN II ACRO, G103C TWIN III ACRO, and G 103 C TWIN III SL gliders. This proposed AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as corrosion on the elevator control pushrod. This proposed AD would require inspecting the elevator control pushrod for water and corrosion and replacing the pushrod if necessary. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by December 13, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Fibreglas-Technik Rudolf Lindner GmbH & Co. KG, Steige 3, D–88487 Walpertshofen, Germany; phone: +49 (0) 7353 22 43; email: info@LTB-Lindner.com; website: <https://www.ltb-lindner.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0944; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the MCAI, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4165; fax: (816) 329–4090; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2021–0944; Project Identifier MCAI–2020–00800–G” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any