

Rules and Regulations

Federal Register

Vol. 86, No. 222

Monday, November 22, 2021

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

FEDERAL DEPOSIT INSURANCE CORPORATION

12 CFR Part 363

RIN 3064-AF77

Applicability of Annual Independent Audits and Reporting Requirements for Fiscal Years Ending in 2021; Correction

AGENCY: Federal Deposit Insurance Corporation (FDIC).

ACTION: Correcting amendment.

SUMMARY: This document contains a correction to the authority citation and regulatory text regarding the applicability of annual independent audits and reporting requirements for fiscal years ending in 2021, which was published in an interim final rule (IFR) on October 23, 2020.

DATES: This correcting amendment is effective on November 22, 2021, except for instruction 3, which is effective November 22, 2021 through December 31, 2021.

FOR FURTHER INFORMATION CONTACT: Harrison E. Greene, Jr., Assistant Chief Accountant, (202) 898-8905, hgreene@fdic.gov; Shannon M. Beattie, Section Chief and Deputy Chief Accountant, (202) 898-3952, sbeattie@fdic.gov; John Rieger, Chief Accountant, (202) 898-3602, jrieger@fdic.gov; Mark G. Flanigan, Senior Counsel, (202) 898-7426, mflanigan@fdic.gov; Joyce M. Raidle, Counsel, (202) 898-6763, jraidle@fdic.gov, Legal Division, Federal Deposit Insurance Corporation, 550 17th Street NW, Washington, DC 20429. For the hearing impaired only, Telecommunication Device for the Deaf (TDD), (800) 925-4618.

SUPPLEMENTARY INFORMATION:

I. Background

On October 23, 2020, the FDIC issued an IFR allowing insured depository institutions (IDIs) to determine the applicability of part 363 of the FDIC's

regulations for fiscal years ending in 2021 based on the lesser of the IDI's (a) consolidated total assets as of December 31, 2019; or (b) consolidated total assets as of the beginning of their fiscal years ending in 2021.

Notwithstanding the temporary relief provided by the IFR, IDIs remain subject to any audit and reporting requirements applicable under other laws and regulations. Also, the FDIC reserves the authority to require an IDI to comply with one or more requirements under part 363 if the FDIC determines that asset growth was related to a merger or acquisition.

Need for Correction

This correcting amendment makes no change to the relief provided by the IFR originally published, but clarifies the authority citation and revises 12 CFR 363.1 by removing the temporary relief regarding the applicability of annual independent audits and reporting requirements for fiscal years ending in 2021 from paragraph (a) and adding the temporary relief into paragraph (e).

List of Subjects in 12 CFR Part 363

Accounting, Administrative practice and procedure, Banks, Banking, Reporting and recordkeeping requirements.

For the reasons stated in the preamble, the FDIC makes the following correcting amendment to 12 CFR part 363:

PART 363—ANNUAL INDEPENDENT AUDITS AND REPORTING REQUIREMENTS

■ 1. The authority citation for part 363 is revised to read as follows:

Authority: 12 U.S.C. 1831m.

■ 2. Amend § 363.1 by revising paragraph (a) to read as follows:

§ 363.1 Scope and definitions.

(a) *Applicability.* This part applies to any insured depository institution with respect to any fiscal year in which its consolidated total assets as of the beginning of such fiscal year are \$500 million or more. The requirements specified in this part are in addition to any other statutory and regulatory requirements otherwise applicable to an insured depository institution.

* * * * *

■ 3. Effective November 22, 2021 through December 31, 2021, further amend § 363.1 by adding paragraph (e) to read as follows:

§ 363.1 Scope and definitions.

* * * * *

(e) *Temporary relief.* (1) Notwithstanding paragraph (a) of this section and for all requirements in this part, with respect to any fiscal year ending in 2021, an insured depository institution's consolidated total assets shall be determined based on the lesser of an insured depository institution's consolidated total assets as of December 31, 2019, or an insured depository institution's consolidated total assets as of the beginning of its fiscal year ending in 2021.

(2) Until December 31, 2021, the FDIC reserves the authority to require an insured depository institution to comply with one or more requirements under this part if the FDIC determines that asset growth was related to a merger or acquisition.

Federal Deposit Insurance Corporation.

Dated at Washington, DC, on November 16, 2021.

James P. Sheesley,

Assistant Executive Secretary.

[FR Doc. 2021-25415 Filed 11-19-21; 8:45 am]

BILLING CODE 6714-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-1008; Project Identifier MCAI-2021-01210-T; Amendment 39-21828; AD 2021-24-07]

RIN 2120-AA64

Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain ATR—GIE Avions de Transport Régional Model ATR42 airplanes and Model ATR72 airplanes. This AD was prompted by a report of a certain procedure in the aircraft maintenance

manual (AMM) that incorrectly described a visual inspection of the fire handle. This AD requires a general visual inspection of both engine fire handles and applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective November 22, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 22, 2021.

The FAA must receive comments on this AD by January 6, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1008; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198;

telephone and fax 206-231-3220; email Shahram.Daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-1008; Project Identifier MCAI-2021-01210-T" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220; email Shahram.Daneshmandi@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA Emergency AD 2021-0237-E, dated November 4, 2021

(EASA AD 2021-0237-E) (also referred to as the MCAI), to correct an unsafe condition for certain ATR—GIE Avions de Transport Régional Model ATR42-200, -300, -320, -400, and -500 airplanes and Model ATR72-101, -102, -201, -202, -211, -212, and -212A airplanes. ATR—GIE Avions de Transport Régional Model ATR42-400 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

This AD was prompted by a report that the AMM maintenance procedure ATR-A-26-12-60-00ZZZ-281Z-A "Scheduled Inspection of the Engine Fire Detection Loops" incorrectly described a visual inspection of the fire handle. The maintenance procedure specified to verify that the snap wire material attaching the fire handle locking hold-plate was a stainless steel lockwire where it should have specified either an aluminum snap wire or a copper snap wire. If the engine fire handle fails, the flightcrew might not be able to extinguish an engine fire using the engine fire extinguisher system, which is the primary method for extinguishing engine fires. The FAA is issuing this AD to address this condition, which, if not detected and corrected, and combined with an engine fire, could lead to a failure of the engine fire handle to operate, possibly resulting in an uncontrolled engine fire and reduced control of the airplane. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2021-0237-E specifies procedures for a general visual inspection of both engine's fire handles for an incorrect snap wire, and applicable corrective actions. Corrective actions include removing the incorrect snap wire, installing the correct snap wire, and installing the safety seal. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI described above. The FAA is issuing this AD after determining that the unsafe condition

described previously is likely to exist or develop on other products of these same type designs.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2021-0237-E described previously, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2021-0237-E is incorporated by reference in this AD. This AD requires compliance with EASA AD 2021-0237-E in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021-0237-E does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is

not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021-0237-E. Service information required by EASA AD 2021-0237-E for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1008 after this AD is published.

FAA’s Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies foregoing notice and comment prior to adoption of this rule because if the installation of the incorrect snap wire material on the

engine’s fire handles is not detected and corrected, this condition, combined with an engine fire, could lead to a failure of the engine fire handle to operate, possibly resulting in an uncontrolled engine fire and reduced control of the airplane. In addition, the compliance time for the required action is shorter than the time necessary for the public to comment and for publication of the final rule. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forego notice and comment.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 71 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$6,035

The FAA estimates the following costs to do any necessary on-condition action that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need this on-condition action:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85	Negligible	\$85

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–24–07 ATR—GIE Avions de

Transport Régional: Amendment 39–21828; Docket No. FAA–2021–1008; Project Identifier MCAI–2021–01210–T.

(a) Effective Date

This airworthiness directive (AD) is effective November 22, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the ATR—GIE Avions de Transport Régional airplanes specified in paragraphs (c)(1) and (2) of this AD, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) Emergency AD 2021–0237–E, dated November 4, 2021 (EASA AD 2021–0237–E).

- (1) Model ATR42–200, –300, –320, and –500 airplanes.
- (2) Model ATR72–101, –102, –201, –202, –211, –212, and –212A airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire protection.

(e) Unsafe Condition

This AD was prompted by a report of a certain procedure in the aircraft maintenance manual (AMM) that incorrectly described a visual inspection of the fire handle. The FAA is issuing this AD to address snap wires made of incorrect material, which, if not detected and corrected, and combined with an engine fire, could lead to a failure of the engine fire handle to operate, possibly resulting in an uncontrolled engine fire and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021–0237–E.

(h) Exceptions to EASA AD 2021–0237–E

(1) Where EASA AD 2021–0237–E refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2021–0237–E does not apply to this AD.

(3) For this AD, the safety seal installation only may be deferred up to 750 flight hours or 6 months, whichever occurs first, after the effective date of this AD, if the safety seal is not available at the time of the snap wire installation.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021–0237–E specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or ATR—GIE Avions de Transport Régional’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3220; email Shahram.Daneshmandi@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of

the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2021–0237–E, dated November 4, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0237–E, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 12, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–25494 Filed 11–18–21; 11:15 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–1011; Project Identifier MCAI–2021–00867–R; Amendment 39–21830; AD 2021–24–09]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Canada Limited Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bell Textron Canada Limited Model 430 helicopters. This AD was prompted by an in-flight failure of the main rotor (M/R) pitch link clevis (clevis) due to fatigue damage and excessive wear. This AD requires a visual inspection of the M/R clevis, rod end, and a certain part-numbered universal bearing, performing a purge grease, and performing a magnetic particle inspection of each M/R clevis. Depending on the visual