

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

(1) For more information about this AD, contact Greg Johnson, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (720) 626-5462; fax: (816) 329-4090; email: [greg.johnson@faa.gov](mailto:greg.johnson@faa.gov).

(2) Refer to European Aviation Safety Agency (EASA) AD 2018-0133, dated June 22, 2018, and corrected June 25, 2018, for more information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2020-1069.

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Daher Aerospace Service Bulletin SB 70-254, dated April 2018.

(ii) [Reserved]

(3) For Daher Aerospace service information identified in this AD, contact Daher Aerospace Inc., Pompano Beach Airpark, 601 NE 10 Street, Pompano Beach, FL 33060; phone: (954) 893-1400; website: <https://www.tbm.aero>.

(4) You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 3, 2021.

**Lance T. Gant,**

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27408 Filed 12-17-21; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2021-1060; Project Identifier MCAI-2021-00340-R; Amendment 39-21851; AD 2021-25-08]

RIN 2120-AA64

**Airworthiness Directives; Leonardo S.p.a. Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Leonardo S.p.a. Model AW189 helicopters. This AD was prompted by the determination that certain part-numbered fairings were never introduced into the main rotor (MR) tip lights kit design definition and were not certified for icing conditions. This AD requires replacing affected parts. This AD also prohibits, after modification of the helicopter as required, installing any affected part on any helicopter as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD becomes effective January 4, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 4, 2022.

The FAA must receive comments on this AD by February 3, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA

website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of the EASA material at the FAA, call (817) 222-5110. The EASA material is also available at <https://www.regulations.gov> by searching for and locating Docket FAA-2021-1060.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1060; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the EASA AD, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:**

Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov).

**SUPPLEMENTARY INFORMATION:****Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0078, dated March 17, 2021 (EASA AD 2021-0078) to correct an unsafe condition for certain Leonardo S.p.A. (formerly Finmeccanica S.p.A., AgustaWestland S.p.A., Agusta S.p.A.; and AgustaWestland Philadelphia Corporation, formerly Agusta Aerospace Corporation) Model AW189 helicopters.

EASA AD 2021-0078 was prompted by a design review which identified that fairing part number (P/N) 8G3340A12532 left-hand (LH) and P/N 8G3340A12632 right-hand (RH) used during icing trials activity conducted for the certification of Full Ice Protection System and Limited Ice Protection System kits had never been introduced in the MR tip light kit P/N 8G3340F00411 design definition. The MR tip light kit P/N 8G3340F00411 is currently composed of two other fairing part numbers, P/N 8G3340A12531 LH and P/N 8G3340A12631 RH installed in the vicinity of each engine air intake. EASA AD 2021-0078 advises the fairing part numbers that are currently installed could cause significant ice accretion during operations in icing conditions.

The FAA is issuing this AD to address ice shedding ingestion by the engines,

which could lead to a double engine in-flight shut-down and consequent loss of control of the helicopter. See EASA AD 2021-0078 for additional background information.

#### Related Service Information Under 1 CFR Part 51

EASA AD 2021-0078 specifies procedures for installation of rescue hoist kit removable parts (temporary actions) and replacement of affected parts with serviceable parts in accordance with the manufacturer's service information. EASA AD 2021-0078 prohibits installing any affected part after modification as required by the EASA AD. EASA AD 2021-0078 considers the modification a terminating action for the temporary actions required by the EASA AD.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### Other Related Service Information

The FAA reviewed Leonardo Helicopters Alert Service Bulletin No.189-265, dated March 4, 2021. This service information provides instructions to install the rescue hoist kit "removable" parts as a temporary action until modification of the helicopter. This service information also provides instructions to install the MR tip light fairing modification P/N 8G3340P02411.

#### FAA's Determination

These products have been approved by the aviation authority of another country, and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in EASA AD 2021-0078 referenced above. The FAA is issuing this AD after evaluating all pertinent information and determining that the unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2021-0078, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under "Differences Between this AD and EASA AD 2021-0078."

#### Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities to use this process. As a result, EASA AD 2021-0078 is incorporated by reference in this AD. This AD, therefore, requires compliance with EASA AD 2021-0078 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD. Service information specified in EASA AD 2021-0078 that is required for compliance with EASA AD 2021-0078 is available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1060.

#### Differences Between This AD and EASA AD 2021-0078

Service information referenced in EASA AD 2021-0078 specifies sending compliance forms to the manufacturer; this AD does not. Paragraph (2) of EASA AD 2021-0078 specifies a compliance time of 400 flight hours or 12 months, whichever occurs first. However, this AD requires a compliance time of 400 hours time-in-service after the effective date of this AD. This AD does not require compliance with paragraph (1) or paragraph (4) of EASA AD 2021-0078. EASA AD 2021-0078 paragraph (4) considers modification of the helicopter a terminating action for installing the rescue hoist kit "removable" parts on the helicopter. As this AD does not require installing the rescue hoist kit "removable" parts, this AD does not provide a terminating action for installing the rescue hoist "removable" parts.

#### Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies

to dispense with notice and comment procedures for rules when the agency, for "good cause" finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

There are currently no domestic operators of these products affected by the unsafe condition addressed by this AD. Accordingly, notice and opportunity for prior public comment are unnecessary, pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the foregoing reasons, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

#### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-1060; Project Identifier MCAI-2021-00340-R" at the beginning of your comments. The most helpful comments reference a specific portion of the AD, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this AD because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this AD.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA

will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

### Costs of Compliance

There are no costs of compliance with this AD because there are currently no helicopters with this type certificate on the U.S. Registry that are affected by the unsafe condition addressed by this AD.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2021-25-08 Leonardo S.p.a.:** Amendment 39-21851; Docket No. FAA-2021-1060; Project Identifier MCAI-2021-00340-R.

#### (a) Effective Date

This airworthiness directive (AD) becomes effective January 4, 2022.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Leonardo S.p.a. Model AW189 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency AD 2021-0078, dated March 17, 2021 (EASA AD 2021-0078).

#### (d) Subject

Joint Aircraft System Component (JASC) Code 3300, Lighting System.

#### (e) Unsafe Condition

This AD was prompted by the determination that certain part-numbered fairings were never introduced into the main rotor tip lights kit design definition and were not certified for icing conditions. The FAA is issuing this AD to address ice shedding ingestion by the engines, which could lead to a double engine in-flight shut-down and consequent loss of control of the helicopter.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021-0078.

### (h) Exceptions to EASA AD 2021-0078

(1) Where EASA AD 2021-0078 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not mandate compliance with the "Remarks" section of EASA AD 2021-0078.

(3) Where EASA AD 2021-0078 refers to flight hours (FH), this AD requires using hours time-in-service (TIS).

(4) This AD does not mandate compliance with paragraph (1) of EASA AD 2021-0078.

(5) Where paragraph (4) of EASA AD 2021-0078 specifies that modification of a helicopter is a terminating action for the requirements of paragraph (1) of EASA AD 2021-0078, this AD does not provide a terminating action for the requirements of paragraph (1) of EASA AD 2021-0078 because this AD does not mandate compliance with paragraph (1) of EASA AD 2021-0078.

(6) Where paragraph (2) of EASA AD 2021-0078 specifies a compliance time of within 400 flight hours or 12 months, whichever occurs first, this AD requires compliance within 400 hours TIS after the effective date of this AD.

### (i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0078 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

### (j) Special Flight Permits

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be modified (if the operator elects to do so), provided it is not flown into known icing conditions.

### (k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

### (l) Related Information

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is

available at the addresses specified in paragraphs (m)(3) of this AD.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency AD 2021-0078, dated March 17, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0078, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1060.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 2, 2021.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021-27388 Filed 12-17-21; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF JUSTICE

### Parole Commission

#### 28 CFR Part 2

[Docket No. USPC-2021-01]

#### Paroling, Recommitting, and Supervising Federal Prisoners: Prisoners Serving Sentences Under the United States and District of Columbia Codes

**AGENCY:** United States Parole Commission, Justice.

**ACTION:** Final rule.

**SUMMARY:** The United States Parole Commission is revising its regulations to

eliminate a policy of imposing the maximum permissible term of supervised release as a consequence of the revocation of an earlier supervised release term for offenders sentenced under the D.C. Code.

**DATES:** This final rule is effective December 20, 2021.

**FOR FURTHER INFORMATION CONTACT:** Helen H. Krapels, General Counsel, U.S. Parole Commission, 90 K Street NE, Third Floor, Washington, DC 20530, telephone (202) 346-7030. Questions about this publication are welcome, but inquiries concerning individual cases cannot be answered over the telephone.

**SUPPLEMENTARY INFORMATION:** Based upon its experience with D.C. Code sentenced supervised releases for over 20 years, the Commission is repealing its policy, codified at 28 CFR 2.218(e), of imposing the maximum permissible term of supervised release after revoking an earlier term of supervised release. On August 17, 2021, the Parole Commission published an interim rule with request for comments. 86 FR 45861. The Parole Commission has not received any comments and is publishing the final rule with no changes to the interim rule.

Under the revised regulation the Commission will retain the discretion to impose the maximum permissible term when it finds that the offender would benefit from a lengthier period of supervision, but there will no longer be a policy guiding that decision.

#### Executive Orders 12866 and 13563

This regulation has been drafted and reviewed in accordance with Executive Order 12866, "Regulation Planning and Review," section 1(b), Principles of Regulation, and in accordance with Executive Order 13565, "Improving Regulation and Regulatory Review," section 1(b), General Principles of Regulation. The Commission has determined that this rule is not a "significant regulatory action" under Executive Order 12866, section 3(f), Regulation Planning and Review, and accordingly this rule has not been reviewed by the Office of Management and Budget.

#### Executive Order 13132

This rule will not have substantial direct effects on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government. Under Executive

Order 13132, this rule does not have sufficient federalism implications requiring a Federalism Assessment.

#### Regulatory Flexibility Act

This rule will not have a significant economic impact upon a substantial number of small entities within the meaning of the Regulatory Flexibility Act, 5 U.S.C. 605(b).

#### Unfunded Mandates Reform Act of 1995

This rule will not cause State, local, or tribal governments, or the private sector, to spend \$100,000,000 or more in any one year, and they will not significantly or uniquely affect small governments. No action under the Unfunded Mandates Reform Act of 1995 is necessary.

#### Small Business Regulatory Enforcement Fairness Act of 1996 (Subtitle E—Congressional Review Act)

This rule is not a "major rule" as defined by Section 804 of the Small Business Regulatory Enforcement Fairness Act of 1996 Subtitle E—Congressional Review Act, now codified at 5 U.S.C. 804(2). This rule will not result in an annual effect on the economy of \$100,000,000 or more; a major increase in costs or prices; or significant adverse effects on the ability of United States-based companies to compete with foreign-based companies. Moreover, this is a rule of agency practice or procedure that does not substantially affect the rights or obligations of non-agency parties, and does not come within the meaning of the term "rule" as used in Section 804(3)(C), now codified at 5 U.S.C. 804(3)(C). Therefore, the reporting requirement of 5 U.S.C. 801 does not apply.

#### List of Subjects in 28 CFR Part 2

Administrative practice and procedure, Prisoners, Probation and parole.

#### The Final Rule

■ Accordingly, the U.S. Parole Commission adopts the interim rule amending 28 CFR part 2, which was published at 86 FR 45861 on August 17, 2021, as final without change.

**Patricia K. Cushwa,**

*Chairman (Acting), U.S. Parole Commission.*

[FR Doc. 2021-27448 Filed 12-17-21; 8:45 am]

**BILLING CODE 4410-31-P**