

prohibited tasks were accomplished during or after compliance with paragraph (h)(1) or (2) of this AD, or if it cannot be conclusively confirmed that they were not accomplished during or after compliance with paragraph (h)(1) or (2) of this AD: Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first, do the actions required by paragraph (h)(1) or (2) of this AD, as applicable.

(2) For airplanes having serial numbers 4598 and subsequent, with an airplane date of manufacture, as identified on the identification plate of the airplane, dated before the effective date of this AD: Within 60 days after the effective date of this AD, review the airplane maintenance records to confirm if any of the prohibited tasks (defined in paragraph (g) of this AD) were accomplished on or after the airplane date of manufacture. If any of the prohibited tasks were accomplished on or after the airplane date of manufacture, or if it cannot be conclusively confirmed that they were not accomplished on or after the airplane date of manufacture: Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first, obtain and follow instructions for rework using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or De Havilland Aircraft of Canada Limited's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (j) Maintenance Task Prohibitions

For all airplanes: As of the effective date of this AD, comply with the prohibitions specified in paragraphs (j)(1) and (2) of this AD.

(1) It is prohibited to use the Bombardier aircraft maintenance manual (AMM) tasks identified in paragraphs (j)(1)(i) through (vii) of this AD, which are specified in the Bombardier Q400, PSM 1–84–2, Revision 63, dated October 5, 2018, or earlier revisions of these tasks. Temporary Revisions (TRs) including these AMM tasks, dated November 2, 2018, or earlier, are also prohibited for use except as specified in paragraph (j)(1)(i) through (vii) of this AD.

(i) Task 28–12–01–000–801, Removal of the Inboard Vent Line, with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–170, dated November 2, 2018.

(ii) Task 28–12–01–400–801, Installation of the Inboard Vent Line, with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–171, dated November 2, 2018.

(iii) Task 28–11–06–000–801, Removal of the Motive Flow Lines, with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–166, dated November 2, 2018.

(iv) Task 28–11–06–400–801, Installation of the Motive Flow Lines, with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–167, dated November 2, 2018.

(v) Task 28–11–16–000–801, Removal of the Scavenge Flow Lines, with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–168, dated November 2, 2018.

(vi) Task 28–11–16–400–801, Installation of the Scavenge Flow Lines, with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–169 dated November 2, 2018.

(vii) Task 28–10–00–280–806, Detailed Inspection of the Teflon™ Sleeve on the Fuel Tank Vent Line, LH and RH (FSL #284000–406), with the exception of (Bombardier) Q400 Dash 8 AMM TR 28–163, dated August 1, 2018.

(2) It is prohibited to use the Bombardier Q400 Dash 8 Maintenance Task Card Manual (MTCM) task cards identified in paragraphs (j)(2)(i) and (ii) of this AD that are specified in the Bombardier Q400 Dash 8 MTCM, PSM 1–84–7TC, Revision 43, dated May 5, 2018, or earlier revisions or amendments of these task cards. MTCM task card revisions or amendments dated August 1, 2018, or earlier, are also prohibited for use, except as specified in paragraphs (j)(2)(i) and (ii) of this AD.

(i) Bombardier Q400 Dash 8 MTCM Maintenance Task Card 000–28–520–704 (Config A01), Detailed Inspection of the Teflon™ Sleeve on the Fuel Tank Vent Line (LH), with the exception of (Bombardier) Q400 Dash 8 MTCM Maintenance Task Card 000–28–520–704 (Config A01), Detailed Inspection of the Teflon™ Sleeve on the Fuel Tank Vent Line (LH), Revision 43, Amendment 0001, dated August 1, 2018.

(ii) Bombardier Q400 Dash 8 MTCM Maintenance Task Card 000–28–620–704 (Config A01), Detailed Inspection of the Teflon™ Sleeve on the Fuel Tank Vent Line (RH), with the exception of (Bombardier) Q400 Dash 8 MTCM Maintenance Task Card 000–28–620–704 (Config A01), Detailed Inspection of the Teflon™ Sleeve on the Fuel Tank Vent Line (RH), Revision 43, Amendment 0001, dated August 1, 2018.

#### (k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or De Havilland Aircraft of Canada Limited's TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

#### (l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF–2020–01, dated January 14, 2020, for related information. This MCAI may be

found in the AD docket at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA–2022–1151.

(2) For more information about this AD, contact Joseph Catanzaro, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7366; email [9-avs-nyacos@faa.gov](mailto:9-avs-nyacos@faa.gov).

(3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Dash 8 Series Customer Response Centre, 5800 Explorer Drive, Mississauga, Ontario, L4W 5K9, Canada; North America (toll-free): 855–310–1013, Direct: 647–277–5820; email [thd@dehavilland.com](mailto:thd@dehavilland.com); internet [dehavilland.com](http://dehavilland.com). You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued on August 31, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022–19232 Filed 9–8–22; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2022–0815; Project Identifier AD–2021–00679–T]

RIN 2120–AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes. This proposed AD was prompted by reports of missing shims, a wrong type of shims, shanked fasteners, fastener head gaps, and incorrect hole sizes common to the left and right side at a certain station (STA) frame inner chord and web. This proposed AD would require inspecting for existing repairs, inspecting the area for cracking, and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by October 24, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet [www.myboeingfleet.com](http://www.myboeingfleet.com). You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at [www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA–2022–0815.

#### Examining the AD Docket

You may examine the AD docket at [www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA–2022–0815; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3520; email: [bill.ashforth@faa.gov](mailto:bill.ashforth@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2022–0815; Project Identifier AD–2021–00679–T” at the beginning of your comments. The most helpful comments

reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [www.regulations.gov](http://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3520; email: [bill.ashforth@faa.gov](mailto:bill.ashforth@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

The FAA has received a report indicating that a Boeing quality investigation found missing shims, a wrong type of shims, shanked fasteners, fastener head gaps, and incorrect hole sizes common to the left and right side STA 727 frame inner chord and S–18A web. These conditions could exist on delivered airplanes. The FAA is proposing this AD to address cracking in the left and right side of STA 727 frame inner chord and S–18A web

before the cracking reaches a critical length. This condition, if not addressed, could result in cracks in fatigue critical baseline structure (FCBS) and the inability of a principal structural element (PSE) to sustain limit load, which could adversely affect the structural integrity of the airplane.

#### FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

#### Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021. This service information specifies procedures for a general visual inspection of the left and right side STA 727 frame inner chord at S–18A for existing repairs, an open hole high frequency eddy current (HFEC) inspection of the left and right side entire stackup of the STA 727 frame inner chord at S–18A for cracking (for certain configurations), a surface HFEC inspection of the left and right side STA 727 frame inner chord at S–18A web for cracking, and applicable on-condition actions. On-condition actions include installing a new shim, a surface HFEC inspection of the STA 727 frame inner chord at S–18A for cracking, and repair.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

#### Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the service information already described, except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this service information at [www.regulations.gov](http://www.regulations.gov) by searching for and locating Docket No. FAA–2022–0815.

#### Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 1,925 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
General visual inspection .....	2 work-hours × \$85 per hour = \$170 .....	\$0	\$170	\$327,250
HFEC inspection and shim installation .....	5 work-hours × \$85 per hour = \$425 .....	0	425	818,125

The FAA estimates the following costs to do any necessary repairs or inspections that would be required

based on the results of the proposed inspection. The agency has no way of

determining the number of aircraft that might need these repairs or inspections:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Inspection .....	3 work hours × \$85 per hour = \$255 .....	\$0	\$255

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**The Boeing Company:** Docket No. FAA–2022–0815; Project Identifier AD–2021–00679–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by October 24, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by reports of missing shims, a wrong type of shims, shanked fasteners, fastener head gaps, and incorrect hole sizes common to the left and right side station (STA) 727 frame inner chord and S–18A web. The FAA is issuing this AD to address cracking in the left and right side of STA 727 frame inner chord and S–18A web before it reaches a critical length. This condition, if not addressed, could result in cracks in fatigue critical baseline structure (FCBS) and the inability of a principal structural element (PSE) to sustain limit load, which could adversely affect the structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–53A1402, dated July 2, 2021, which is referred to in Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021.

**(h) Exceptions to Service Information Specifications**

(1) Where the Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021, use the phrase “the original issue date of the Requirements Bulletin 737–53A1402 RB,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Requirements Bulletin 737–53A1402 RB, dated July 2, 2021, specifies contacting Boeing for repair instructions or for alternative inspections:

This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3520; email: [bill.ashforth@faa.gov](mailto:bill.ashforth@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet [www.myboeingfleet.com](http://www.myboeingfleet.com). You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued on July 1, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022-19298 Filed 9-8-22; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2022-0978; Project Identifier AD-2022-00460-E]

**RIN 2120-AA64**

**Airworthiness Directives; General Electric Company Turbofan Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) GEnx-1B and GEnx-2B model turbofan engines. This proposed AD was prompted by a manufacturer investigation that revealed that certain high-pressure turbine (HPT) stage 2 disks, forward seals, and stages 6-10 compressor rotor spools were manufactured from powder metal material suspected to contain iron inclusion. This proposed AD would require the replacement of the affected HPT stage 2 disks, forward seals, and stages 6-10 compressor rotor spools. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by October 24, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com); website: <https://www.ge.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this

material at the FAA, call (817) 222-5110.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0978; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:**

Alexei Marqueen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7178; email: [Alexei.T.Marqueen@faa.gov](mailto:Alexei.T.Marqueen@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0978; Project Identifier AD-2022-00460-E" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be