

be accomplished using a method approved by the Manager, International Validation Branch, FAA; or the United Kingdom Civil Aviation Authority (U.K. CAA); or BAE Systems (Operations) Limited's U.K. CAA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(p) Additional Information**

(1) Refer to U.K. CAA AD G-2022-0006, dated March 30, 2022, for related information. This U.K. CAA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1298.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3228; email [todd.thompson@faa.gov](mailto:todd.thompson@faa.gov).

**(q) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR.

(i) Chapter 05 of BAE Systems (Operations) Limited J41 Aircraft Maintenance Manual (AMM), Revision 44, dated June 15, 2021, for effectivity group 403;

(ii) Chapter 05 of BAE Systems (Operations) Limited J41 AMM, Revision 44, dated June 15, 2021, for effectivity group 408.

(4) The following service information was approved for IBR on November 7, 2018 (83 FR 49786, October 3, 2018).

(i) BAE Systems (Operations) Limited Alert Service Bulletin J41-A53-058, dated December 6, 2016.

(ii) BAE Systems (Operations) Limited Service Bulletin J41-51-001, Revision 4, dated July 11, 2017.

(5) The following service information was approved for IBR on May 16, 2016 (81 FR 21263, April 11, 2016).

(i) Chapter 05, "Airworthiness Limitations," of the BAE Systems (Operations) Limited J41 Aircraft Maintenance Manual (AMM), Revision 38, dated September 15, 2013. Page 1 of the "Publications Transmittal" is the only page that shows the revision level of this document.

(A) Subject 05-10-10, "Airworthiness Limitations."

(B) Subject 05-10-20, "Certification Maintenance Requirements."

(C) Subject 05-10-30, "Critical Design Configuration Control Limitations (CDCCL)—Fuel System."

(ii) [Reserved]

(6) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RAPublications@baesystems.com](mailto:RAPublications@baesystems.com);

website [baesystems.com/website baesystems.com/Businesses/RegionalAircraft/index.htm](https://www.baesystems.com/Businesses/RegionalAircraft/index.htm).

(7) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](https://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on October 6, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022-22202 Filed 10-20-22; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2022-1297; Project Identifier MCAI-2022-00570-T]**

**RIN 2120-AA64**

**Airworthiness Directives; Dassault Aviation Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 7X airplanes. This proposed AD was prompted by a report of smoke in the flightdeck and loss of the right-hand (RH) primary display unit (PDU) and the secondary flight display (SFD). This proposed AD would require inspecting the two electrical power feeders for damage (deterioration), measuring the clearance between the two electrical power feeders and the forward lavatory bulkhead, and applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 5, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**AD Docket:** You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1297; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**Material Incorporated by Reference:**

- For material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); website [easa.europa.eu](https://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](https://ad.easa.europa.eu). It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA-2022-1297.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3226; email [Tom.Rodriguez@faa.gov](mailto:Tom.Rodriguez@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-1297; Project Identifier MCAI-2022-00570-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the

following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3226; email *Tom.Rodriguez@faa.gov*. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022–0073, dated April 27, 2022 (EASA AD 2022–0073) (also referred to as the MCAI), to correct an unsafe condition for certain Dassault Aviation Model FALCON 7X airplanes.

This proposed AD was prompted by a report of smoke in the flightdeck and loss of the RH PDU and the SFD. The subsequent investigation determined that chafing and arcing of the electrical power feeders with the forward lavatory

bulkhead led to smoke and loss of the RH PDU and the SFD power supply. The FAA is proposing this AD to address chafing and arcing of the electrical power feeders with the forward lavatory bulkhead, which could lead to loss of systems supporting flight automation and flight displays and reduced situational awareness, possibly resulting in a significant increase of flightcrew workload and injury to occupants. See the MCAI for additional background information.

**Related Service Information Under 1 CFR Part 51**

EASA AD 2022–0073 specifies procedures for inspecting the two electrical power feeders for damage (deterioration), measuring the clearance between the two electrical power feeders and the forward lavatory bulkhead, and applicable corrective actions. The corrective actions include repairing any electrical power feeder with deterioration and modifying the forward lavatory bulkhead. If a clearance of more than 1 millimeter (mm) but less than or equal to 13 mm is detected, the corrective action includes installing ROUNDIT200NX sheath on the affected electrical power feeder using white binding braid. If a clearance of more than 13 mm is detected, the corrective action includes looking for the presence of a blue cable grip around the electrical power feeders and installing it if it is missing. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop

in other products of the same type design.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in EASA AD 2022–0073 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

**Explanation of Required Compliance Information**

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2022–0073 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2022–0073 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2022–0073 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2022–0073. Service information required by EASA AD 2022–0073 for compliance will be available at *regulations.gov* by searching for and locating Docket No. FAA–2022–1297 after the FAA final rule is published.

**Costs of Compliance**

The FAA estimates that this proposed AD would affect 45 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170 .....	\$0	\$170	\$7,650

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 33 work-hours × \$85 per hour = \$2,805 .....	Up to \$431 .....	Up to \$3,236.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Dassault Aviation:** Docket No. FAA–2022–1297; Project Identifier MCAI–2022–00570–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by December 5, 2022.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2022–0073, dated April 27, 2022 (EASA AD 2022–0073).

**(d) Subject**

Air Transport Association (ATA) of America Code 24, Electrical power.

**(e) Unsafe Condition**

This AD was prompted by a report of smoke in the flightdeck and loss of the right-hand primary display unit (PDU) and the secondary flight display (SFD). The FAA is issuing this AD to address chafing and arcing of the electrical power feeders with the forward lavatory bulkhead, which could lead to loss of systems supporting flight automation and flight displays and reduced situational awareness, possibly resulting in a significant increase of flightcrew workload and injury to occupants.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0073.

**(h) Exceptions to EASA AD 2022–0073**

(1) Where EASA AD 2022–0073 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2022–0073 does not apply to this AD.

**(i) Additional AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(j) Related Information**

(1) For EASA AD 2022–0073, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu). You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket at [regulations.gov](http://regulations.gov) by searching for and locating Docket No. FAA–2022–1297.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3226; email [Tom.Rodriguez@faa.gov](mailto:Tom.Rodriguez@faa.gov).

Issued on October 6, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022–22203 Filed 10–20–22; 8:45 am]

**BILLING CODE 4910–13–P**