

products, macroeconomic factors, and any other considerations that may be pertinent to the balance of petroleum product supply and demand.

(5) Market analysis:

(i) DOE shall establish a market value for each petroleum product to be acquired based on a market analysis at the time of contract award.

(ii) DOE may consider prices on futures markets, spot markets, recent price movements, current and projected shipping rates, forecasts by the DOE Energy Information Administration, and any other analytic tools available to DOE to determine the most desirable purchase profile.

(iii) DOE may also consider factors including recent price changes, private inventory levels, petroleum product acquisition by other stockpiling entities, the outlook for world petroleum product production, disruptions of supply or refining capability, logistical problems for moving petroleum products, macroeconomic factors, and any other considerations that may be pertinent relevant to the balance of petroleum product supply and demand.

§ 626.8 Deferrals of contractually scheduled deliveries.

(a) *General.* (1) DOE prefers to take deliveries of petroleum products for the SPR at times scheduled under applicable contracts. However, in the event the market is distorted by disruption to supply or other factors, DOE may defer scheduled deliveries or consider deferral requests from awardees.

(2) An awardee seeking to defer scheduled deliveries of petroleum products to the SPR may submit a deferral request to DOE.

(b) *Deferral criteria.* DOE shall only grant a deferral request for negotiation under paragraph (c) of this section if it determines that DOE can receive a premium for the deferral and, based on DOE's deferral analysis, that at least one of the following conditions exists:

(1) DOE can reduce the cost of its petroleum products acquisition per barrel and increase the volume of petroleum products being delivered to the SPR by means of the premium barrels required by the deferral process;

(2) DOE anticipates private inventories are approaching a point where unscheduled outages may occur;

(3) There is evidence that refineries are reducing their run rates for lack of feedstock; or

(4) There is an unanticipated disruption to petroleum product supply.

(c) *Negotiating terms.* (1) If DOE decides to negotiate a deferral of deliveries, DOE shall estimate the

market value of the deferral and establish a strategy for negotiating with suppliers the minimum percentage of the market value to be taken by the Government. During these negotiations, if the deferral request was initiated by DOE, DOE may consider any reasonable, customary, and applicable costs already incurred by the supplier in the performance of a valid contract for delivery. In no event shall such consideration account for any consequential damages or lost profits suffered by the supplier as a result of such deferral.

(2) DOE shall only agree to amend the contract if the negotiation results in an agreement to give the Government a fair and reasonable share of the market value.

§ 626.9 Suspension and pre-drawdown diversion.

Where the Secretary has found that a severe energy supply interruption may be imminent, the Secretary may suspend any previously announced or contracted acquisition of any petroleum product by the SPR or injection of petroleum products into the SPR; or sell any petroleum product acquired for injection into the SPR that has not yet been injected into the SPR.

[FR Doc. 2022-23184 Filed 10-24-22; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0678; Project Identifier MCAI-2022-00067-T; Amendment 39-22147; AD 2022-17-09]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2021-16-03, which applied to certain Airbus SAS Model A350-941 and -1041 airplanes. AD 2021-16-03 required an inspection for missing or incorrect application of the lightning strike edge glow sealant protection at certain locations in the wing tanks, and corrective action. This AD was prompted by in-production findings of missing or incorrect application of the lightning strike edge glow sealant protection at specific

locations in the wing tanks and by the development of a modification to restore two independent layers of lightning strike protection on the wing upper cover. This AD continues to require the actions of AD 2021-16-03 and requires a modification to restore two independent layers of lightning strike protection, as specified in a European Union Aviation Safety Agency (EASA), which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 29, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 29, 2022.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0678.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0678; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3225; email dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0011,

dated January 21, 2022 (EASA AD 2022-0011) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus SAS Model A350-941 and -1041 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2021-16-03, Amendment 39-21665 (86 FR 47555, August 26, 2021) (AD 2021-16-03). AD 2021-16-03 applied to certain Airbus SAS Model A350-941 and -1041 airplanes. The NPRM published in the **Federal Register** on June 16, 2022 (87 FR 36276). The NPRM was prompted by in-production findings of missing or incorrect application of the lightning strike edge glow sealant protection at specific locations in the wing tanks and by the development of a modification to restore two independent layers of lightning strike protection on the wing upper cover. The NPRM proposed to continue to require the actions of AD 2021-16-03 and to require a modification to restore two independent layers of lightning strike protection, as specified in EASA AD 2022-0011.

The FAA is issuing this AD to address missing or incorrectly applied sealant, which in combination with an undetected incorrect installation of an adjacent fastener and a lightning strike in the immediate area, could result in ignition of the fuel-air mixture inside the affected fuel tanks and loss of the airplane. See the MCAI for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from the Air Line Pilots Association, International (ALPA), who supported the NPRM without change.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator. Accordingly, the FAA is issuing this AD

to address the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

EASA AD 2022-0011 specifies procedures for an inspection for missing or incorrect application of the lightning strike edge glow sealant protection at certain locations in the wing tanks (discrepancies), and corrective action. Corrective actions include applying sealant in areas where sealant was found to be missing or incorrectly applied. EASA AD 2022-0011 also specifies procedures for a modification to restore two independent layers of lightning strike protection on the wing upper cover.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 27 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2021-16-03 ...	Up to 67 work-hours × \$85 per hour = \$5,695.	\$0	Up to \$5,695	Up to \$153,765.
New actions (modification)	Up to 55 work-hours × \$85 per hour = 4,675.	Up to 500	Up to 5,175	Up to \$139,725.

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85	\$0	\$85

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

■ a. Removing Airworthiness Directive (AD) 2021–16–03, Amendment 39–21665 (86 FR 47555, August 26, 2021); and

■ b. Adding the following new AD:

2022–17–09 Airbus SAS: Amendment 39–22147; Docket No. FAA–2022–0678; Project Identifier MCAI–2022–00067–T.

(a) Effective Date

This airworthiness directive (AD) is effective November 29, 2022.

(b) Affected ADs

This AD replaces AD 2021–16–03, Amendment 39–21665 (86 FR 47555, August 26, 2021) (AD 2021–16–03).

(c) Applicability

This AD applies to Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2022–0011, dated January 21, 2022 (EASA AD 2022–0011).

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by in-production findings of missing or incorrect application of the lightning strike edge glow sealant protection at specific locations in the wing tanks and by the development of a modification to restore two independent layers of lightning strike protection on the wing upper cover. The FAA is issuing this AD to address missing or incorrectly applied sealant, which in combination with an undetected incorrect installation of an adjacent fastener and a lightning strike in the immediate area, could result in ignition of the fuel-air mixture inside the affected fuel tanks and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0011.

(h) Exceptions to EASA AD 2022–0011

(1) Where EASA AD 2022–0011 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2022–0011 refers to October 27, 2020 (the effective date of EASA AD 2020–0220), this AD requires using September 30, 2021 (the effective date of AD 2021–16–03).

(3) Where paragraph (1) of EASA AD 2022–0011 gives a compliance time of “the next scheduled maintenance tank entry, or before exceeding 78 months since Airbus date of manufacture, whichever occurs first after 27 October 2020 [the effective date of EASA AD 2020–0220],” for this AD, the compliance time is the later of the times specified in paragraphs (h)(3)(i) and (ii) of this AD.

(i) The next scheduled maintenance tank entry, or before exceeding 78 months since Airbus date of manufacture, whichever occurs first after September 30, 2021 (the effective date of AD 2021–16–03).

(ii) Within 12 months after September 30, 2021 (the effective date of AD 2021–16–03).

(4) Where paragraph (2) of EASA AD 2022–0011 refers to “discrepancies,” for this AD, discrepancies include missing or incorrectly applied sealant.

(5) Where paragraph (3) of EASA AD 2022–0011 gives a compliance time of “the next scheduled maintenance tank entry, or before exceeding 78 months since Airbus date of manufacture, whichever occurs first after the effective date of this [EASA] AD,” for this AD, the compliance time is the later of the times specified in paragraphs (h)(5)(i) and (ii) of this AD.

(i) The next scheduled maintenance tank entry, or before exceeding 78 months since Airbus date of manufacture, whichever occurs first after the effective date of this AD.

(ii) Within 12 months after the effective date of this AD.

(6) The “Remarks” section of EASA AD 2022–0011 does not apply to this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any

approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email dan.rodina@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0011, dated January 21, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0011, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on August 10, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-22720 Filed 10-24-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-1310; Project Identifier MCAI-2022-01261-A; Amendment 39-22220; AD 2022-22-05]

RIN 2120-AA64

Airworthiness Directives; NZSkydive Limited (Type Certificate Previously Held by Pacific Aerospace Ltd.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for NZSkydive Limited (type certificate previously held by Pacific Aerospace Ltd.) Model FBA-2C1, FBA-2C2, FBA-2C3, and FBA-2C4 airplanes. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as a batch of aileron control chain sprockets being manufactured with a non-metallic sleeve insert in the sprocket bore, which can cause cracks to develop and affect the integrity of the aileron control chain sprockets. This AD requires inspecting the sprockets to determine if they have a non-metallic sleeve in the sprocket bore and replacing any sprocket found with a non-metallic sleeve in the sprocket bore with one with a metallic sleeve, and prohibits installation of aileron control chain sprockets with non-metallic sleeves in the sprocket bore. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 9, 2022.

The FAA must receive comments on this AD by December 9, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2022-1310; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Mike Kiesov, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4144; email: *mike.kiesov@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-1310; Project Identifier MCAI-2022-01261-A" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and

that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Mike Kiesov, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The Civil Aviation Authority (CAA) of New Zealand, which is the aviation authority for New Zealand, has issued CAA of New Zealand AD DCA/FBA/5, dated September 23, 2022 (referred to after this as "the MCAI"), to correct an unsafe condition on Pacific Aerospace (the type certificate holder on the FAA type certificate data sheet is NZSkydive Limited) Model FBA-2C1, FBA-2C2, FBA-2C3, and FBA-2C4 airplanes delivered after November 2012, fitted with an aileron control chain sprocket part number (P/N) C446 received and installed after November 2012, and sprockets with P/N C446 received after November 2012 as spare parts for all serial numbers. The MCAI states that it was prompted by reports of cracks found at the roll pin holes in an affected batch of sprockets having P/N C446 that were manufactured with non-metallic sleeve inserts in the sprocket bore. These cracks can affect the integrity of the aileron control chain sprockets and have the potential to produce binding of the aileron flight controls. The unsafe condition, if not addressed, could lead to loss of integrity of the aileron control chain sprockets with consequent loss of control of the airplane.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2022-1310.

Related Service Information

The FAA reviewed Pacific Aerospace Mandatory Service Bulletin PACSB/2C/002, Issue 1, dated September 20, 2022, which specifies inspecting the aileron control chain sprockets to determine if they have a non-metallic sleeve in the sprocket bore and replacing any aileron control chain sprocket found with a non-metallic sleeve in the sprocket bore with one with a metallic sleeve.