

## Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:  
**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2022–24–02 Airbus SAS:** Amendment 39–22242; Docket No. FAA–2022–0890; Project Identifier MCAI–2022–00391–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective January 9, 2023.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Airbus SAS Model A300 F4–605R and F4–622R airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2022–0048, dated March 18, 2022 (EASA AD 2022–0048).

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Unsafe Condition

This AD was prompted by a determination that the forward cargo door compartment between frames 21 through 25 forks is

susceptible to widespread fatigue damage (WFD). The FAA is issuing this AD to address this condition, which if not corrected, could result in reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0048.

#### (h) Exceptions to EASA AD 2022–0048

(1) Where the service information referenced in EASA AD 2022–0048 specifies installing a label (placard) having part number (P/N) ABS2127B01 on the forward cargo compartment door, this AD allows installing an equivalent label provided the label contains the same information as the label having P/N ABS2127B01.

(2) The “Remarks” section of EASA AD 2022–0048 does not apply to this AD.

#### (i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (j) Additional Information

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0048, dated March 18, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0048, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on November 9, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022–26355 Filed 12–2–22; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2022–0677; Project Identifier MCAI–2021–01378–T; Amendment 39–22230; AD 2022–23–03]

RIN 2120–AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD–700–2A12 airplanes. This AD was prompted by the investigation of erroneous radio altimeter data that was displayed on an in-service airplane. It was revealed that certain radio altimeter coaxial cables used by the radio altimeter systems, in the aft fuselage equipment bay, were damaged. This AD requires replacing affected radio altimeter coaxial cables. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective January 9, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 9, 2023.

**ADDRESSES:**

*AD Docket:* You may examine the AD docket at *regulations.gov* under Docket No. FAA-2022-0677; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For service information identified in this final rule, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 1-514-855-2999; email *ac.yul@aero.bombardier.com*; internet *bombardier.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at *regulations.gov* under Docket No. FAA-2022-0677.

**FOR FURTHER INFORMATION CONTACT:**

Thomas Niczky, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7347; email *9-avs-nyaco-cos@faa.gov*.

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model BD-700-2A12 airplanes. The NPRM published in the **Federal Register** on June 13, 2022 (87 FR 35686). The NPRM was prompted by AD CF-2021-45, dated December 7, 2021, issued by Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada (referred to after this as the

MCAI). The MCAI states that the erroneous radio altimeter data was displayed on an in-service airplane. It was revealed that certain radio altimeter coaxial cables in the aft fuselage equipment bay had been reported damaged (from radio altimeters A28 and A29 to antennas), due their light weight construction, and their proximity to the access door on the eBay. The damage to or kinks in the radio altimeter coaxial cables, if not corrected, could lead to signal loss or degradation, and possibly un-announced loss of terrain awareness warning system aural cues during approach.

In the NPRM, the FAA proposed to require replacing affected radio altimeter coaxial cables. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2022-0677.

**Discussion of Final Airworthiness Directive**

**Comments**

The FAA received a comment from Netjets. The following presents the comment received on the NPRM and the FAA’s response to the comment.

**Request To Refer to Updated Bombardier Service Bulletin**

Netjets stated Bombardier Service Bulletin 700-91-7502, Revision 02, dated April 5, 2022, has been released. The FAA infers that Netjets is requesting that the proposed AD be revised to refer to Bombardier Service Bulletin 700-91-7502, Revision 02, dated April 5, 2022 (the proposed AD refers to Bombardier Service Bulletin 700-91-7502, Revision 01, dated August 31, 2020, as the appropriate source of service information).

The FAA agrees with the request. Bombardier Service Bulletin 700-91-7502, Revision 02, dated April 5, 2022, adds minor changes that do not affect the substantive requirements proposed in the NPRM, including adding references to an advisory document and the MCAI AD. The FAA has revised this final rule to refer to Bombardier Service Bulletin 700-91-7502, Revision 02,

dated April 5, 2022. The FAA has also revised paragraph (i) of this AD to provide credit for actions done in accordance with Bombardier Service Bulletin 700-91-7502, Revision 01, dated August 31, 2020.

**Conclusion**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed Bombardier Service Bulletin 700-91-7502, Revision 02, dated April 5, 2022. This service information specifies procedures for replacing affected radio altimeter coaxial cables. The replacement includes removing the existing radio altimeter coaxial cables, replacing with new coaxial cables, installing new clamps to accommodate the coaxial bend radius along the coaxial routing, and re-routing new radio altimeter coaxial cables from the wing to fuselage fairing, in the left and right aft fuselage, and in the aft fuselage belly fairing.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

The FAA estimates that this AD affects 27 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

| Labor cost                                    | Parts cost | Cost per product | Cost on U.S. operators |
|---|------------|------------------|------------------------|
| 70 work-hours × \$85 per hour = \$5,950 ..... | \$13,808   | \$19,758         | \$533,466              |

The FAA has included all known costs in its cost estimate. According to

the manufacturer, however, some or all of the costs of this AD may be covered

under warranty, thereby reducing the cost impact on affected operators.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2022–23–03 Bombardier, Inc.:** Amendment 39–22230; Docket No. FAA–2022–0677; Project Identifier MCAI–2021–01378–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective January 9, 2023.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc., Model BD–700–2A12 airplanes, serial numbers 70006 through 70053 inclusive, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

#### (e) Unsafe Condition

This AD was prompted by the investigation of erroneous radio altimeter data that was displayed on an in-service airplane. It was revealed that certain radio altimeter coaxial cables in the aft fuselage equipment bay were damaged. The FAA is issuing this AD to address damage to or kinks in the radio altimeter coaxial cables, which could lead to signal loss or degradation, and possibly unannounced loss of terrain awareness warning system aural cues during approach.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Replacement of Radio Altimeter Coaxial Cables

Within 12 months after the effective date of this AD, replace affected radio altimeter coaxial cables, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 700–91–7502, Revision 02, dated April 5, 2022, except as specified in paragraph (h) of this AD.

#### (h) No Reporting Requirement

Although Bombardier Service Bulletin 700–91–7502, Revision 02, dated April 5, 2022, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the service information identified in Bombardier Service Bulletin 700–91–7502, dated February 6, 2020; or Bombardier Service Bulletin 700–91–7502, Revision 01, dated August 31, 2020.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as

appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (k) Additional Information

(1) Refer to TCCA AD CF–2021–45, dated December 7, 2021, for related information. This TCCA AD may be found in the AD docket at *regulations.gov* under Docket No. FAA–2022–0677.

(2) For more information about this AD, contact Thomas Niczky, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7347; email *9-avs-nyacos@faa.gov*.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (4) of this AD.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 700–91–7502, Revision 02, dated April 5, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 1–514–855–2999; email *ac.yul@aero.bombardier.com*; internet *bombardier.com*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fr.inspection@nara.gov*, or go to: *www.archives.gov/federal-register/cfr/ibr-locations.html*.

Issued on October 27, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness  
Division, Aircraft Certification Service.*

[FR Doc. 2022-26354 Filed 12-2-22; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2022-0797; Airspace  
Docket No. 20-ANM-44]

RIN 2120-AA66

#### Amendment of Class D Airspace and Establishment of Class E Airspace; Butts Army Airfield (AAF) (Fort Carson) Airport, CO

**AGENCY:** Federal Aviation  
Administration (FAA), Department of  
Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** This action modifies the Class D surface area, and establishes Class E airspace extending upward from 700 feet above the surface at Butts AAF (Fort Carson) Airport, CO. Additionally, this action makes administrative changes to update the airport's existing Class D legal description. These actions will support the safety and management of instrument flight rules (IFR) and visual flight rules (VFR) operations at the airport.

**DATES:** Effective 0901 UTC, February 23, 2023. The Director of the Federal Register approves this incorporation by reference under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11, Airspace Designations and Reporting Points, and publication of conforming amendments.

**ADDRESSES:** FAA Order JO 7400.11G, and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

**FOR FURTHER INFORMATION CONTACT:** Nathan A. Chaffman, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231-3460.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code.

Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it would modify the Class D airspace and establish Class E airspace at Butts AAF (Fort Carson) Airport, CO, to support IFR and VFR operations at the airport.

##### History

The FAA published a notice of proposed rulemaking (NPRM) in the **Federal Register** for FAA-2022-0797 (87 FR 47150; August 2, 2022) to modify the Class D surface area, and establish Class E airspace extending upward from 700 feet above the surface at Butts AAF (Fort Carson) Airport, CO. Additionally, the NPRM proposed administrative changes to update the airport's legal description. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. One comment was received which claimed: "A proper environmental study was not done for these airspace changes or procedures for Fort Carson." This comment is inaccurate as proposed airspace changes were granted a categorical exclusion. See the "Environmental Review" section for further details.

Subsequent to the publication of the NPRM, the FAA discovered that the removal of the southeast extension to the Class D airspace was not mentioned in the proposed actions. This airspace area is no longer needed to contain departures until reaching 700 feet above the ground to the south, as the existing 4.3-mile radius of airspace surrounding the airport is sufficient. Additionally, the Iron Horse Nondirectional Beacon (NDB) previously used to describe the southeast extension is no longer needed, and can be removed from the legal description's text header. The geographical coordinates of the airport are more appropriate for describing the airspace at Butts AAF, and will be used in the final Class D airspace legal description.

Class D and Class E5 airspace designations are published in paragraphs 5000 and 6005, respectively, of FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022, which is

incorporated by reference in 14 CFR 71.1. The Class D and Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11.

##### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11G, Airspace Designations and Reporting Points, dated August 19, 2022, and effective September 15, 2022. FAA Order JO 7400.11G is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11G lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

##### The Rule

The FAA is amending 14 CFR part 71 by modifying the Class D surface area, and establishing Class E airspace extending upward from 700 feet above the surface at Butts AAF (Fort Carson) Airport, CO.

Class D airspace is extended to the northwest to contain Runway 31 departures until reaching 700 feet above the surface due to rising terrain in that area. The extension southeast of the airport is removed, as it is no longer needed to contain departures until reaching 700 feet above the ground to the south, and the existing 4.3-mile radius of airspace surrounding the airport is sufficient.

Class E airspace extending upward from 700 feet above the surface is established southeast and north of the airport to properly contain departures until reaching 1,200 feet above the surface in those areas.

Finally, this action makes several administrative modifications to the Class D airspace legal description. The airport name in the text header is corrected to read: "Butts AAF (Fort Carson) Airport, CO." The other airport referenced in the Class D legal description is corrected to read: "City of Colorado Springs Municipal Airport, CO." The geographic coordinates for both Butts AAF (Fort Carson) Airport, CO and the City of Colorado Springs Municipal Airport, CO, are updated to match the FAA's database. Additionally, the outdated terms "Notice to Airmen" and "Airport/Facility Directory" have been replaced with the terms "Notice to Air Missions" and "Chart Supplement" respectively, to better match the FAA's current nomenclature. Lastly, reference to the "Iron Horse NDB, CO" is removed from the Class D legal description's text header, as it's no longer required to describe the airspace, and its removal simplifies the legal description.