(h) Retained Exceptions to EASA AD 2019– 0288 With No Changes

This paragraph restates the exceptions specified in paragraph (j) of AD 2020–15–20, with no changes.

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2019– 0288 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2019–0288 specifies revising "the approved AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the "maintenance tasks and associated thresholds and intervals" specified in paragraph (3) of EASA AD 2019–0288 within 90 days after October 2, 2020 (the effective date of AD 2020–15– 20).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2019–0288 is at the applicable "associated thresholds" specified in paragraph (3) of EASA AD 2019–0288, or within 90 days after October 2, 2020 (the effective date of AD 2020–15–20).

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2019–0288 do not apply to this AD.

(5) The "Remarks" section of EASA AD 2019–0288 does not apply to this AD.

(i) Retained Restrictions on Alternative Actions and Intervals With a New Exception

This paragraph restates the requirements of paragraph (k) of AD 2020–15–20, with a new exception. Except as required by paragraph (j) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) or intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2019–0288.

(j) New Revision of the Existing Maintenance or Inspection Program

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0126, dated June 28, 2022 (EASA AD 2022–0126). Accomplishing the maintenance or inspection program revision required by this paragraph terminates the requirements of paragraph (g) of this AD.

(k) Exceptions to EASA AD 2022-0126

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2022– 0126 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2022–0126 specifies revising "the approved AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable within 90 days after the effective date of this AD

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0126 is at the applicable "associated thresholds" as incorporated by the requirements of paragraph (3) of EASA AD 2022–0126, or within 90 days after the effective date of this AD, whichever occurs later. (4) The provisions specified in paragraphs (4) and (5) of EASA AD 2022–0126 do not apply to this AD.

(5) The ''Remarks'' section of EASA AD 2022–0126 does not apply to this AD.

(l) New Provisions for Alternative Actions and Intervals

After the maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (*e.g.*, inspections) or intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2022– 0126.

(m) Additional AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (n) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Additional Information

For more information about this AD, contact Dat Le, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 516–228– 7317; email Dat.V.Le@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on [DATE 35 DAYS AFTER PUBLICATION OF THE FINAL RULE].

(i) European Union Aviation Safety Agency (EASA) AD 2022–0126, dated June 28, 2022. (ii) [Reserved]

(4) The following service information was approved for IBR on October 2, 2020 (85 FR 53156, August 28, 2020).

(i) European Union Aviation Safety Agency (EASA) AD 2019–0288, dated November 28, 2019.

(ii) [Reserved]

(5) For EASA ADs 2022–0126 and 2019– 0288, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*; website *easa.europa.eu*. You may find these EASA ADs on the EASA website at *ad.easa.europa.eu*.

(6) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fr.inspection@nara.gov*, or go to: *www.archives.gov/federal-register/cfr/ibrlocations.html*.

Issued on December 2, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–26595 Filed 12–8–22; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-1479; Project Identifier AD-2022-00703-T]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 737-100, 737-200, 737-200C, 737-300, 737-400, 737-500, 737-600, 737-700, 737-700C, 737-800, 737-900, 737-900ER, 757-200, 757-200PF, 757-200CB, 757-300, 767-200, 767-300, 767-300F, and 767-400ER series airplanes. This proposed AD was prompted by reports indicating premature aging of certain passenger chemical oxygen generators. This proposed AD would require repetitively replacing affected chemical oxygen generators with serviceable parts. This proposed AD would also limit the installation of affected parts. The FAA is proposing this AD to address the unsafe condition on these products. DATES: The FAA must receive comments on this proposed AD by January 23, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

• Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.

Fax: 202–493–2251.
Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket at *regulations.gov* by searching for and locating Docket No. FAA-2022-1479; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Nicole S. Tsang, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3959; email: nicole.s.tsang@faa.gov. SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send vour comments to an address listed under ADDRESSES. Include "Docket No. FAA-2022-1479; Project Identifier AD-2022-00703-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act

(FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Nicole S. Tsang, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3959; email: nicole.s.tsang@ faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA has been notified by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, of an issue with the B/E Aerospace 117042–XX series chemical oxygen generators installed on certain Airbus airplanes. The units may fail to deliver oxygen to passengers during an emergency on the airplane. To address this issue on certain Airbus airplanes, EASA issued AD 2015-0117, dated June 24, 2015, corrected August 7, 2015, and AD 2019-0140, dated June 12, 2019. The FAA issued corresponding AD 2016-16-02, Amendment 39-18600 (81 FR 53255, August 12, 2016), and AD 2020-04-18, Amendment 39-19855 (85 FR 14409, March 12, 2020), respectively, which require the replacement of units older than 10 years and impose a 10-year life limit on all 117042-XX series generators.

The FAA released Special **Airworthiness Information Bulletin** NM-17-17, dated June 19, 2017, which indicated that the FAA and B/E Aerospace Systems planned to conduct further investigation of chemical oxygen generators in the 117080 series that are 10 to 15 years old since date of manufacture, to determine if these generators have an issue similar to the 117042 series generators.

The reduction of useful life was changed for 117080-02, 117080-03, and 117080–04 series chemical oxygen generators from 15 years to 10 years. **Collins** Aerospace has Parts Manufacturer Approval (PMA) for 117080-02, 117080-03, and 117080-04

series chemical oxygen generators on all Boeing Model 737-100, 737-200, 737-200C, 737-300, 737-400, 737-500, 737-600, 737-700, 737-700C, 737-800, 737-900, 757-200, 757-200PF, 757-200CB, 757-300, 767-200, 767-300, 767-300F, and 767-400ER series airplanes. However, the applicability of this proposed AD also includes Boeing Model 737–900ER series airplanes. The FAA determined that Boeing Model 737–900ER series airplanes are affected because there is concern that operators might mistake the 737–900ER as a submodel of the 737–900, and the 117080– 0X series of chemical oxygen generators might be installed on Boeing Model 737–900ER series airplanes.

Collins Aerospace has observed that mis-actuations are possible 10 years after the manufacturing date and increase in likelihood as the 15-year life is approached. The mis-actuations are associated with the tin-based chemistry used to manufacture the generators and specifically appear to be caused by oxidation of tin fuel added to the chemical core. Collins Aerospace's investigation and analysis concluded that the chemical core oxidizes in a manner similar to the 117042-XX series chemical oxygen generators. This condition, if not addressed, could lead to failure of the generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to airplane occupants.

FAA's Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design. This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the AD and service information referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information

Collins Aerospace Service Information Letter (SIL) 117080-SIL-002, dated May 4, 2022, specifies procedures for replacing affected chemical oxygen generators.

Proposed AD Requirements in This NPRM

This proposed AD would require inspecting the date of manufacture of chemical oxygen generators having part numbers 117080–02, 117080–03, and 117080–04, and replacing affected generators with serviceable units. This proposed AD would also limit the installation of passenger chemical oxygen generators to serviceable units.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 3,419 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators		
	4 work-hours × \$85 per hour = \$340 0.50 work-hour × \$85 per hour = \$43 per re- placement cycle.			\$1,162,460. \$1,668,472 cycle.	per	replacement

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866, (2) Would not affect intrastate

aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

The Boeing Company: Docket No. FAA– 2022–1479; Project Identifier AD–2022– 00703–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 23, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 737–100, 737–200, 737– 200C, 737–300, 737–400, 737–500, 737–600, 737–700, 737–700C, 737–800, 737–900, 737– 900ER, 757–200, 757–200PF, 757–200CB, 757–300, 767–200, 767–300, 767–300F, and 767–400ER series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Unsafe Condition

This AD was prompted by reports of premature aging of certain chemical oxygen generators. The FAA is issuing this AD to address this premature aging that resulted in the generators failing to activate, which could fail to deliver oxygen during an emergency, possibly resulting in injury to the airplane occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Oxygen Generator Part Number Inspection

Within 30 days after the effective date of this AD: Inspect passenger chemical oxygen generators having part numbers 117080–02, 117080–03, and 117080–04 to determine their date of manufacture. A review of airplane maintenance records is acceptable for the inspection, provided the date of manufacture can be conclusively determined by that review.

(h) Definition

For purposes of this AD, a serviceable unit is a passenger chemical oxygen generator that meets the condition specified in either paragraph (h)(1) or (2) of this AD.

(1) Part numbers 117080–02, 117080–03, and 117080–04, with a manufacturing date not older than 10 years.

(2) Approved part numbers other than 117080–02, 117080–03, and 117080–04, provided the generator has not exceeded the life limit established for that generator by the manufacturer.

(i) Oxygen Generator Replacement

For any passenger chemical oxygen generators having part numbers 117080–02, 117080–03, and 117080–04: At the applicable time specified in paragraph (i)(1) through (3) of this AD, replace the chemical oxygen generator with a serviceable unit, as defined in this AD. Thereafter, replace chemical oxygen generators having part numbers 117080–02, 117080–03, and 117080–04 before exceeding 10 years since date of manufacture.

Note 1 to paragraph (i): Additional guidance for replacing the affected passenger chemical oxygen generators can be found in Collins Aerospace Service Information Letter 117080–SIL–002, dated May 4, 2022, and approved maintenance procedures.

(1) For passenger chemical oxygen generators that have a date of manufacture in 2008 or earlier: Replace within 6 months after the effective date of this AD or 15 years since the date of manufacture, whichever occurs earlier.

(2) For passenger chemical oxygen generators that have a date of manufacture in 2009 or 2010: Replace within 12 months after the effective date of this AD.

(3) For passenger chemical oxygen generators that have a date of manufacture in 2011, 2012, or 2013: Replace within 24 months after the effective date of this AD.

(j) Parts Installation Limitation

As of the effective date of this AD, no person may install a passenger chemical oxygen generator, unless the oxygen generator is a serviceable unit, as defined in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (I)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact Nicole S. Tsang, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3959; email: *nicole.s.tsang@ faa.gov.*

(2) For Collins Aerospace service information identified in this AD that is not incorporated by reference, contact Collins Aerospace, 15701 West 95th Street, Lenexa, KS 66219; email *ISPublications@collins.com*; website *tpi.beaerospace.com/Authentication*. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(m) Material Incorporated by Reference

None

Issued on November 10, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–26592 Filed 12–8–22; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2022-1556; Airspace Docket No. 22-ASW-25]

RIN 2120-AA66

Proposed Amendment of Class D and E Airspace; Mesquite and Dallas-Fort Worth, TX

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend the Class D at Mesquite, TX, and the Class E airspace at Dallas-Fort Worth, TX. The FAA is proposing this action due to an airspace review conducted as part of the decommissioning of the Mesquite localizer (LOC). The geographic coordinates of Granbury Regional Airport, Granbury, TX, would also be updated to coincide with the FAA's aeronautical database.

DATES: Comments must be received on or before January 23, 2023.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366-9826, or (800) 647-5527. You must identify FAA Docket No. FAA-2022-1556/Airspace Docket No. 22-ASW-25 at the beginning of your comments. You may also submit comments through the internet at www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order JO 7400.11G, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at *www.faa.gov/air_traffic/ publications/*. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT: Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711. **SUPPLEMENTARY INFORMATION:**

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend the Class D airspace at Mesquite Metro Airport, Mesquite, TX, and the Class E airspace extending upward form 700 feet above the surface at Mesquite Metro Airport, contained within the Dallas-Fort Worth, TX airspace legal description, to support instrument flight rule operations at this airport.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2022-1556/Airspace Docket No. 22-ASW-25." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the