

website at <https://www.regulations.gov> under Docket ID NRC–2020–0036. In addition, the Federal rulemaking website allows members of the public to receive alerts when changes or additions occur in a docket folder. To subscribe: (1) navigate to the docket folder (NRC–2020–0036); (2) click the “Subscribe” link; and (3) enter an email address and click on the “Subscribe” link.

Dated: December 19, 2022.

For the Nuclear Regulatory Commission.

Christopher M. Regan,

*Director, Division of Rulemaking,
Environmental, and Financial Support Office
of Nuclear Material Safety and Safeguards.*

[FR Doc. 2022–27979 Filed 12–23–22; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1654; Project Identifier MCAI–2022–01165–T]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL–600–1A11 (600), CL–600–2A12 (601), and CL–600–2B16 (601–3A, 601–3R, and 604 Variants) airplanes. This proposed AD was prompted by reports of some passenger oxygen mask dispensing units (MDUs) with lanyards that are too long to meet the proper length specifications of the airplane. This proposed AD would require replacing the affected MDUs with units that meet the proper length specifications, replacing the placards, and re-identifying the assemblies. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by February 10, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–

30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1654; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

• For service information identified in this NPRM, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email ac.yul@aero.bombardier.com; website bombardier.com.

• You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT:

Elizabeth M. Dowling, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–361–8046; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2022–1654; Project Identifier MCAI–2022–01165–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency

will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Elizabeth M. Dowling, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–361–8046; email 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF–2022–50, dated August 25, 2022 (also referred to after this as the MCAI), to correct an unsafe condition on certain Bombardier, Inc., Model CL–600–1A11 (600), CL–600–2A12 (601), and CL–600–2B16 (601–3A, 601–3R, and 604 Variants) airplanes. The MCAI states that lanyards of passenger mask dispensing units installed in the affected airplanes are too long to meet the proper length specifications of the aircraft. This condition, if not corrected, could result in the inability to initiate the flow of oxygen to the mask when required in an emergency situation, with no indication to the passenger that they are not receiving oxygen.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1654.

Related Service Information Under 14 CFR Part 51

Bombardier has issued the following service information, which describes procedures for identifying part numbers of the drop-down oxygen boxes, performing drop-down oxygen mask

reach testing, marking failed seats as inoperative with placards, and replacing affected oxygen masks:

- Service Bulletin 600–0777, dated December 13, 2021.
- Service Bulletin 601–1109, Revision 01, dated May 6, 2022.
- Service Bulletin 604–35–007, Revision 01, dated May 6, 2022.

These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products are approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would accomplishing the actions specified in the service information already described.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 301 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$25,585

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
2 work-hours × \$85 per hour = \$170	\$100	\$270

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the

national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Bombardier, Inc.: Docket No. FAA–2022–1654; Project Identifier MCAI–2022–01165–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by February 10, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., airplanes, certificated in any category, with serial numbers as identified in the service information specified in paragraphs (c)(1) through (4) of this AD.

(1) Model CL–600–1A11 (600) airplanes: Bombardier Service Bulletin 600–0777, dated December 13, 2021.

(2) Model CL–600–2A12 (601) airplanes: Bombardier Service Bulletin 601–1109, Revision 01, dated May 6, 2022.

(3) Model CL–600–2B16 (601–3A, 601–3R) airplanes: Bombardier Service Bulletin 601–1109, Revision 01, dated May 6, 2022.

(4) Model CL–600–2B16 (604) airplanes: Bombardier Service Bulletin 604–35–007, Revision 01, dated May 6, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen System.

(e) Unsafe Condition

This AD was prompted by reports of passenger oxygen mask dispensing units installed in the affected airplanes with lanyards that are too long to meet the proper length specifications of the airplane. The FAA is issuing this AD to address the inability to initiate flow of oxygen to the mask. The unsafe condition, if not addressed, could result in no indication to the passenger that they are not receiving oxygen in an emergency situation.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Replacement

Within 5 years after the effective date of this AD, determine the part number of the drop-down oxygen box, in accordance with Section 2.B. of the Accomplishment Instructions of the applicable service information identified in paragraphs (c)(1) through (4) of this AD.

(1) If any drop-down oxygen box part number (P/N) installed on the airplane matches any P/N listed in Table 1 of Section 2.B. of the applicable service information: Before further flight, perform drop-down oxygen mask reach testing in accordance with Section 2.B.(2) of the Accomplishment Instructions of the applicable service information identified in paragraphs (c)(1) through (4) of this AD.

(i) If the test result is PASS: Before further flight, replace the drop-down oxygen box assembly in accordance with Section 2.C., and test the passenger oxygen supply system in accordance with Section 2.D.(2), of the applicable service information identified in paragraphs (c)(1) through (4) of this AD.

(ii) If the test result is FAIL for any individual seat: Before further flight, mark the failed seat as inoperative in accordance with Section 2.B.(3) of the applicable service information specified in paragraphs (c)(1) through (4) of this AD.

(2) If the part number of any drop-down oxygen box assembly installed on the airplane is not found in Table 1 of Section 2.B. of the applicable service information identified in paragraphs (c)(1) through (4) of this AD: Before further flight, do actions to correct the unsafe condition using a method approved in accordance with the procedures specified in paragraph (i)(1) of this AD.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 601-1109, dated December 13, 2021; or Bombardier Service Bulletin 604-35-007, dated December 13, 2021; as applicable.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO

Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the New York ACO Branch, mail it to ATTN: Program Manager, Continuing Operational Safety, at the address identified in paragraph (j)(2) of this AD or email to: 9-avs-nyaco-cos@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada; or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

(1) Refer to Transport Canada AD CF-2022-50, dated August 25, 2022, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1654.

(2) For more information about this AD, contact Elizabeth M. Dowling, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-361-8046; email 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 600-0777, dated December 13, 2022.

(ii) Bombardier Service Bulletin 601-1109, Revision 01, dated May 6, 2022.

(iii) Bombardier Service Bulletin 604-35-007, Revision 01, dated May 6, 2022.

(3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email ac.yul@aero.bombardier.com; website bombardier.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA,

email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on December 20, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-28063 Filed 12-23-22; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY**40 CFR Part 52**

[EPA-R04-OAR-2022-0727; FRL-10421-01-R4]

Air Plan Approval; Kentucky; Revision to Federally Enforceable District Origin Operating Permits

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to approve a revision to the Jefferson County portion of the Kentucky State Implementation Plan (SIP) submitted by the Commonwealth of Kentucky through the Kentucky Energy and Environment Cabinet (Cabinet) on June 15, 2022. The changes were submitted by the Cabinet on behalf of the Louisville Metro Air Pollution Control District (District, also referred to herein as Jefferson County). The District's revision modifies the permit application timing requirements in the Federally Enforceable District Origin Operating Permits (FEDOOP) rule in the Jefferson County portion of the Kentucky SIP (Jefferson County Local Implementation Plan, or LIP). EPA is proposing to approve these changes pursuant to the Clean Air Act (CAA or Act).

DATES: Comments must be received on or before January 26, 2023.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-R04-OAR-2022-0727 at [regulations.gov](https://www.regulations.gov). Follow the online instructions for submitting comments. Once submitted, comments cannot be edited or removed from [Regulations.gov](https://www.regulations.gov). EPA may publish any comment received to its public docket. Do not submit electronically any information you consider to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Multimedia submissions (audio, video, etc.) must be accompanied by a written comment. The written comment is considered the official comment and should include discussion of all points you wish to