

from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (k) Additional Information

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3229; email [vladimir.ulyanov@faa.gov](mailto:vladimir.ulyanov@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022-0025R2, dated August 9, 2022.

(ii) [Reserved]

(3) For EASA AD 2022-0025R2, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on January 5, 2023.

#### Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-00262 Filed 1-12-23; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-1661; Project Identifier MCAI-2022-00714-T]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. This proposed AD was prompted by a report that in case of a flap, slat, or slat-flap failure in flight, resetting the slat flap control unit (SFCU) to clear the error using the airplane flight manual (AFM) could result in the stall protection computer (SPC) setting the low-speed cue to the most conservative stall advance mode. This proposed AD would require revising the non-normal procedures section of the existing AFM to provide the flightcrew with procedures for addressing failure warnings in the slat and flap control systems. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by February 27, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to [regulations.gov](http://regulations.gov). Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket*: You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2022-1661; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and

other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference*:

- For service information identified in this NPRM, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); website [bombardier.com](http://bombardier.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### FOR FURTHER INFORMATION CONTACT:

Elizabeth Dowling, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-1661; Project Identifier MCAI-2022-00714-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](http://regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

##### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or

responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Elizabeth Dowling, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2022-30, dated June 3, 2022 (Transport Canada AD CF-2022-30) (also referred to after this as the MCAI), to correct an unsafe condition on certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states in case of a flap, slat, or slat-flap failure in flight, resetting the SFCU to clear the error using the AFM could result in the SPC setting the low-speed cue to the most conservative stall advance mode instead of that published in the AFM. This condition could result in unexpected stall warnings (aural and visual) as well as stick shaker activation during approach for a landing, increasing flightcrew workload during a critical phase of flight. The higher landing speed could consequently require a greater landing distance and possible diversion to a longer runway.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1661.

### Related Service Information Under 14 CFR Part 51

The FAA reviewed the following Bombardier service information. This service information specifies procedures for revising the non-normal procedures section of the existing AFM to provide the flightcrew with procedures for addressing failure warnings in the slat and flap control systems. These documents are distinct since they apply to different airplane models.

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedure, of

the Bombardier Global Express AFM, Publication No. CSP 700-1, Revision 112, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-1, use Document Identification No. GL 700 AFM-1.)

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedure, of the Bombardier Global Express XRS AFM, Publication No. CSP 700-1A, Revision 112, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express XRS AFM, Publication No. CSP 700-1A, use Document Identification No. GL 700 AFM-1A.)

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedure, of the Bombardier Global 5000 AFM, Publication No. CSP 700-5000-1, Revision 73, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1, use Document Identification No. GL 5000 AFM.)

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedure, of the Bombardier Global 5000 AFM, Publication No. CSP 700-5000-1V, Revision 42, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1V, use Document Identification No. GL 5000 GVFD AFM.)

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedure, of the Bombardier Global 5500 AFM, Publication No. CSP 700-5500-1, Revision 14, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1V, use Document Identification No. GL 5500 AFM.)

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls,

Chapter 5—Non Normal Procedure, of the Bombardier Global 6000 AFM, Publication No. CSP 700-1V, Revision 42, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-1V, use Document Identification No. GL 6000 AFM.)

- C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedure, of the Bombardier Global 6500 AFM, Publication No. CSP 700-6500-1, Revision 14, dated May 19, 2022. (For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1V, use Document Identification No. GL 6500 AFM.)

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

### FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

### Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the service information already described.

Transport Canada AD CF-2022-30 requires operators to "advise all flight crews" of revisions to the AFM, and thereafter to "operate the aeroplane accordingly." However, this proposed AD would not specifically require those actions as those actions are already required by FAA regulations. FAA regulations require operators furnish to pilots any changes to the AFM (for example, 14 CFR 121.137), and to ensure the pilots are familiar with the AFM (for example, 14 CFR 91.505). As with any other flightcrew training requirement, training on the updated AFM content is tracked by the operators and recorded in each pilot's training record, which is available for the FAA to review. FAA regulations also require

pilots to follow the procedures in the existing AFM including all updates. 14 CFR 91.9 requires that any person operating a civil aircraft must comply with the operating limitations specified in the AFM. Therefore, including a

requirement in this proposed AD to operate the airplane according to the revised AFM would be redundant and unnecessary.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 450 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85 .....	\$0	\$85	\$38,250

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Bombardier, Inc.:** Docket No. FAA–2022–1661; Project Identifier MCAI–2022–00714–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by February 27, 2023.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes, certificated in any category, having

serial numbers 9001 through 9998 inclusive and 60001 through 60097 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 27, Flight controls.

**(e) Unsafe Condition**

This AD was prompted by a report that in case of a flap, slat, or slat-flap failure in flight, resetting the slat flap control unit (SFCU) to clear the error using the airplane flight manual (AFM) could result in the stall protection computer (SPC) setting the low-speed cue to the most conservative stall advance mode. The FAA is issuing this AD to address a flap, slat, or slat-flap failure warning. The unsafe condition, if not addressed, could result in unexpected stall warnings (aural and visual) as well as stick shaker activation during approach for a landing, increasing flightcrew workload during a critical phase of flight. The higher landing speed could consequently require a greater landing distance and possible diversion to a longer runway.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Revision of the Existing AFM**

Within 30 days after the effective date of this AD: Revise the existing AFM to incorporate the information specified in the AFM sections of the applicable AFM revisions specified in figure 1 to paragraph (g) of this AD.

**Figure 1 to paragraph (g)—AFM References**

**BILLING CODE 4910–13–P**

<b>Bombardier Airplane Model (Marketing Designation)</b>	<b>AFM</b>	<b>AFM Section</b>	<b>AFM Revision and Issue Date</b>
BD-700-1A10 (Global Express)	Bombardier Global Express AFM, Publication No. CSP 700-1 <sup>1</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat- Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat- Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 112, dated May 19, 2022
BD-700-1A10 (Global Express XRS)	Bombardier Global Express AFM, Publication No. CSP 700- 1A <sup>2</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat- Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat- Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 112, dated May 19, 2022
BD-700-1A11 (Global 5000)	Bombardier Global 5000 AFM, Publication No. CSP 700- 5000-1 <sup>3</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat- Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat- Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 73, dated May 19, 2022

<b>Bombardier Airplane Model (Marketing Designation)</b>	<b>AFM</b>	<b>AFM Section</b>	<b>AFM Revision and Issue Date</b>
BD-700-1A11 (Global 5000 ft. GVFD)	Bombardier Global 5000 Featuring Global Vision Flight Deck AFM, Publication No. CSP 700- 5000-1V <sup>4</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat- Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat- Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 42, dated May 19, 2022
BD-700-1A11 (Global 5500)	Bombardier Global 5500 AFM, Publication No. CSP 700- 5500-1 <sup>5</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat- Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat- Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 14, dated May 19, 2022
BD-700-1A10 (Global 6000)	Bombardier Global 6000 AFM, Publication No. CSP 700- 1V <sup>6</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat- Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat- Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 42, dated May 19, 2022

<b>Bombardier Airplane Model (Marketing Designation)</b>	<b>AFM</b>	<b>AFM Section</b>	<b>AFM Revision and Issue Date</b>
BD-700-1A10 (Global 6500)	Bombardier Global 6500 AFM, Publication No. CSP 700-6500-1 <sup>7</sup>	C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5 - Non Normal Procedures	Revision 14, dated May 19, 2022
<p><sup>1</sup> For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-1, use Document Identification No. GL 700 AFM-1.</p> <p><sup>2</sup> For obtaining the procedures for Bombardier Global Express XRS AFM, Publication No. CSP 700-1A, use Document Identification No. GL 700 AFM-1A.</p> <p><sup>3</sup> For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1, use Document Identification No. GL 5000 AFM.</p> <p><sup>4</sup> For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1V, use Document Identification No. GL 5000 GVFD AFM.</p> <p><sup>5</sup> For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-5000-1V, use Document Identification No. GL 5500 AFM.</p> <p><sup>6</sup> For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700-1V, use Document Identification No. GL 6000 AFM.</p> <p><sup>7</sup> For obtaining the procedures for Bombardier Global 6500 AFM, Publication No. CSP 700-6500-1, use Document Identification No. GL 6500 AFM.</p>			

**BILLING CODE 4910-13-C****(h) Additional AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the New York ACO Branch, mail it to ATTN: Program Manager, Continuing Operational Safety, at the address identified in paragraph (i)(2) of this AD or email to: [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov). If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada; or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(i) Additional Information**

(1) Refer to Transport Canada AD CF-2022-30, dated June 3, 2022, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1661.

(2) For more information about this AD, contact Elizabeth Dowling, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New

York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05-10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global Express AFM, Publication No. CSP 700-1, Revision 112, dated May 19, 2022.

**Note 1 to paragraph (j)(2)(i):** For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700–1, use Document Identification No. GL 700 AFM–1.

(ii) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05–10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global Express XRS AFM, Publication No. CSP 700–1A, Revision 112, dated May 19, 2022.

**Note 2 to paragraph (j)(2)(ii):** For obtaining the procedures for Bombardier Global Express XRS AFM, Publication No. CSP 700–1A, use Document Identification No. GL 700 AFM–1A.

(iii) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05–10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global 5000 AFM, Publication No. CSP 700–5000–1, Revision 73, dated May 19, 2022.

**Note 3 to paragraph (j)(2)(iii):** For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700–5000–1, use Document Identification No. GL 5000 AFM.

(iv) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05–10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global 5000 AFM, Publication No. CSP 700–5000–1V, Revision 42, dated May 19, 2022.

**Note 4 to paragraph (j)(2)(iv):** For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700–5000–1V, use Document Identification No. GL 5000 GVFD AFM.

(v) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05–10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global 5500 AFM, Publication No. CSP 700–5500–1, Revision 14, dated May 19, 2022.

**Note 5 to paragraph (j)(2)(v):** For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700–5000–1V, use Document Identification No. GL 5500 AFM.

(vi) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F. Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05–10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global 6000 AFM, Publication No. CSP 700–1V, Revision 42, dated May 19, 2022.

**Note 6 to paragraph (j)(2)(vi):** For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700–1V, use Document Identification No. GL 6000 AFM.

(vii) C. Flap Fail (Caution), D. Slat Fail (Caution), E. Slat-Flap Fail (Caution), and F.

Slat Fault (Caution) or Flap Fault (Caution) or Slat-Flap Fault (Caution) procedures of the Slat and Flap Control System, Section 05–10, Flight Controls, Chapter 5—Non Normal Procedures, of the Bombardier Global 6500 AFM, Publication No. CSP 700–6500–1, Revision 14, dated May 19, 2022.

**Note 7 to paragraph (j)(2)(vii):** For obtaining the procedures for Bombardier Global Express AFM, Publication No. CSP 700–5000–1V, use Document Identification No. GL 6500 AFM.

(3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); website [bombardier.com](http://bombardier.com).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on January 2, 2023.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023–00077 Filed 1–12–23; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2023–0013; Project Identifier MCAI–2022–01085–T]

RIN 2120–AA64

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 2017–09–03 and AD 2018–20–07, which apply to all Dassault Aviation Model MYSTERE–FALCON 50 airplanes. AD 2017–09–03 and AD 2018–20–07 require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. Since the FAA issued AD 2017–09–03 and AD 2018–20–07, the FAA has determined that new or more restrictive

airworthiness limitations are necessary. This proposed AD would continue to require the actions in AD 2018–20–07 and would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by February 27, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](http://regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**AD Docket:** You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA–2023–0013; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**Material Incorporated by Reference:**

- For material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu). It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA–2023–0013.

- For service information identified in this NPRM, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; website [dassaultfalcon.com](http://dassaultfalcon.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.